

- A small but significant amount of product was escaping the oil-water separator, flowing into the wet well and was being pumped to the distribution box and gallery. This was evidenced by heavy oil staining of the area surrounding the manway and by stained sorbent pads which had been placed in the distribution box. There was a distinct smell of weathered product throughout the trench/pump station/gallery area. There was little staining along the path of the discharge down the bank nor on the shell ice in the river, suggesting that only small amounts of oil were passing the separator.

It's not possible to be sure of all the problems with this system based on what I could observe and learn from interviews. Here are some possibilities:

- At the very least, it's clear that the infiltration gallery is badly clogged, probably with iron precipitates and possibly with heavy oil as well. The problem may have arisen from poor design, it may be a natural consequence of trying to infiltrate groundwater with dissolved minerals, or it may be a combination of both. In our experience at DEP, it is difficult to re-infiltrate groundwater with any significant mineral content after it has been oxygenated. Groundwater flowing through a contaminated formation typically becomes anoxic. Under anoxic (reducing) conditions, the solubility of many metals present in the soil matrix (iron, manganese, arsenic) increases and their concentrations in groundwater also increase. When the groundwater is later aerated – in the separator, pump station, or distribution box – oxidizing conditions are produced, metals' solubility decreases, and the dissolved minerals precipitate. This often produces clogging in equipment or in receiving soils. Addition of sequestrants is sometimes sufficient to keep minerals soluble while still within remediation equipment such as blowers and strippers. We have not found a satisfactory fix to prevent a soil formation from clogging. Rehabilitative measures such as shocking with hypochlorite or industrial strength hydrogen peroxide have seldom improved performance except in the short term. If it is necessary to continue infiltrating treated groundwater, we have usually had to develop a new infiltration site, knowing that it too will have a limited life.
- It is not clear that the gallery's initial design was adequate. I understand that the gallery has not been able to accept all the flow from the interceptor system almost since its installation, and that water has intermittently discharged from the distribution box manway for years. Discharge from the wet well pumps is unmetered, so it is currently not possible to estimate the fraction of the flow being accepted by the gallery. Also, I understand that the volume collected by the trench varies seasonally. During my inspection, the pumps ran continuously. A few weeks earlier Gordon Fuller watched the system through several on-off cycles during an inspection. During late summer and low water table conditions, it's possible that the pumps cycle only occasionally. The 1991 O/M Plan included as-built drawings of the gallery, but its design and hydraulic loading rate were not discussed. In addition, there is no information as to the soils the gallery was placed in: whether these were coarse-grained alluvial deposits or fine-grained, organic, or soils otherwise unsuitable for infiltration. These areas would need to be

evaluated before serious consideration was given to reconstruction of the existing gallery.

- The oil-water separator is apparently not removing 100% of the separate-phase product that reaches it. According to the as-built drawings, the separator is a Model HT-500 manufactured by Highland Tank, modified slightly for the Farwell Mills application by removal of an extension of its pump-out pipe. It is not clear to me why this modification was made, unless to gain more volume for oil accumulation when the separator was still collecting more than 100 gallons of product per month. It is also not clear how this modification would affect separator performance. The manufacturer's technical information states that this model should be adequate for flows of up to 50 gpm for DNAPLs having a specific gravity of 0.95 or less. According to specifications, the API specific gravity of unweathered #6 oil is 12.3, which converts to about 0.98. The specific gravity of the weathered product that reaches the separator is probably slightly higher, making this piece of equipment marginal for the job. As with the gallery, the separator's initial design and current performance would need to be evaluated if it is to remain in service at this site.

RECOMMENDATION

In my opinion this system is still serving a valuable function, in that it continues to collect annually 200 to 300 gallons of free product that would otherwise discharge to the Sabattus River. I believe a collection system should be operated here until a truly *de minimus* volume of product is being collected.

The existing system is nearly completely passive, operating with minimal oversight, and at a cost of only the energy to operate its pumps, periodically remove and dispose of collected product, analyze a grab sample, and an annual letter report. However, the malfunction of this system has resulted in an unlicensed overboard discharge to the Sabattus River. This needs to be addressed and corrected by the owner, as it is a direct violation of 38 MRSA §413, which prohibits unlicensed discharges to surface waters. If the status quo conditions continued uncorrected, the owner would be subject to enforcement action.

The owner's options here are limited to eliminating the discharge or licensing it. Eliminating the discharge could be done by finding a means to infiltrate the collected and treated groundwater into the formation, either by rehabilitating/reconstructing the existing infiltration gallery or constructing a new one. Alternatively, the owner could propose a means of intercepting and collecting the free product *insitu*, without withdrawing –and therefore having to dispose of – groundwater discharging from this site.

Licensing the discharge is also not out of the question. To do this the owner would need to obtain a discharge license from DEP's Bureau of Land and Water Quality (BLWQ). To

March 30, 2001

obtain a license, the owner would need to fully characterize the proposed discharge and demonstrate that its constituents – including both petroleum and inorganic compounds – will not violate the receiving water's classification standards nor impair its intended uses. BLWQ would almost certainly require a monitorable outfall pipe to the river, as an alternative to the existing bank discharge. If the owner wishes to investigate this option, he should contact BLWQ's licensing staff. I suggest Gregg Wood.

I'd be happy to meet with you, the owner, and his consultant if you'd like to discuss this situation and the possibilities for solution further. I'm sure Gregg would be willing to attend if a discharge license is to be considered.

I will return the O/M Manual and recent operating reports to your mailslot.

Cc: Gordon Fuller
Gregg Wood