

**Inspector:** Harris, Scott  
**Inspection Date:** 09/12/2023

**Structure Number:** 5812  
**Facility Carried:** TRAFTON RD

**Highway Bridge Inspection Report**

**Inspection Type(s): Routine**

**Bridge Name:** TRAFTON ROAD / I 95


**Town:** Waterville



Inspector: Harris, Scott  
Inspection Date: 09/12/2023

Structure Number: 5812  
Facility Carried: TRAFTON RD

### Highway Bridge Inspection Report



Latitude: 44.50824

Longitude: -69.70322

Inspector: Harris,Scott  
Inspection Date: 09/12/2023

Structure Number: 5812  
Facility Carried: TRAFTON RD

Highway Bridge Inspection Report  
National Bridge Inventory

Status: 2 - FO

Bridge Name: TRAFTON ROAD / I 95

Sufficiency Rating: 77.0

Inspections

(90) INSPECTION DATE	& (91) DESIGNATED INSPECTION FREQUENCY	24	09/12/2023
(92) CRITICAL FEATURE INSPECTION	& (93) CFI DATE		
(92A) FRACTURE CRITICAL DETAIL		N	
(92B) UNDERWATER INSPECTION		N	
(92C) OTHER SPECIAL INSPECTION		N	

Identification

(1) STATE CODE	231 - Maine
(8) STRUCTURE NUMBER	5812
(5) INVENTORY ROUTE	
(5A) RECORD TYPE	1: Route carried "on" the structure
(5B) ROUTE SIGNING PREFIX	5 - CITY STREET
(5C) DESIGNATED LEVEL OF SERVICE	0 - None
(5) INVENTORY ROUTE	0
(5) INVENTORY ROUTE	0 - NOT APPLICABLE
(2) HIGHWAY AGENCY DISTRICT	02 - Mid-Coast
(3) COUNTY CODE	011 Kennebec
(4) PLACE CODE	80740
(6) FEATURES INTERSECTED	INTERSTATE 95 NB & SB
(7) FACILITY CARRIED	TRAFTON RD
(9) LOCATION	OVER 95 0.3 MI N OF TL
(11) MILEPOINT	1.460
(12) BASE HIGHWAY NETWORK	Inventory Route is not on the Base Network
(13) LRS INVENTORY ROUTE, SUBROUTE	
(13A) LRS INVENTORY ROUTE	0001102252
(13B) SUBROUTE NUMBER	00
(16) LATITUDE	44.50824
(17) LONGITUDE	-69.70322
(98A) BORDER BRIDGE CODE	
(98B) PERCENT RESPONSIBILITY	0
(99) BORDER BRIDGE STRUCT NO.	n/a

Structure Type and Material

(43) STRUCTURE TYPE, MAIN	
(43A) KIND OF MATERIAL/DESIGN	3 - Steel
(43B) TYPE OF DESIGN/CONSTR	02 - Stringer/Multi-beam or Girder
(44) STRUCTURE TYPE, APPROACH SPANS	
(44A) KIND OF MATERIAL/DESIGN	0 - Other
(44B) TYPE OF DESIGN/CONSTRUCTION	00 - Other
(45) NUMBER OF SPANS IN MAIN UNIT	6
(46) NUMBER OF APPROACH SPANS	0
(107) DECK STRUCTURE TYPE	1 - Concrete Cast-in-Place
(108) WEARING SURFACE/PROTECTIVE SYSTEMS	
(108A) WEARING SURFACE	6 - Bituminous
(108B) DECK MEMBRANE	2 - Preformed Fabric
(108C) DECK PROTECTION	0 - None

Age of Service

(27) YEAR BUILT	1959
(106) YEAR RECONSTRUCTED	1993
(42) TYPE OF SERVICE	
(42A) TYPE OF SERVICE ON BRIDGE	1 - Highway
(42B) TYPE OF SERVICE UNDER BRIDGE	1 - Highway, with or w/out pedestrian
(28) LANES	
(28A) LANES ON THE STRUCTURE	02
(28B) LANES UNDER THE STRUCTURE	04

Inspector: Harris,Scott  
Inspection Date: 09/12/2023

Structure Number: 5812  
Facility Carried: TRAFTON RD

### Highway Bridge Inspection Report

(29) AVERAGE DAILY TRAFFIC	292
(30) YEAR OF AVERAGE DAILY TRAFFIC	2016
(109) AVERAGE DAILY TRUCK TRAFFIC	5
(19) BYPASS DETOUR LENGTH	2

#### Geometric Data

(48) LENGTH OF MAXIMUM SPAN (ft.)	71.5
(49) STRUCTURE LENGTH (ft.)	350.4
(50) CURB/SIDEWALK WIDTHS	
(50A) LEFT CURB SIDEWALK (ft.)	1.4
(50B) RIGHT CURB SIDEWALK (ft.)	1.4
(51) BRDG RDWY WIDTH CURB-TO-CURB (ft.)	24.3
(52) DECK WIDTH, OUT-TO-OUT (ft.)	29.1
(32) APPROACH ROADWAY WIDTH (ft.)	28.0
(33) BRIDGE MEDIAN	0 - No median
(34) SKEW (deg.)	7
(35) STRUCTURE FLARED	0 - No flare
(10) INV RTE, MIN VERT CLEARANCE (ft.)	328.05
(47) TOTAL HORIZONTAL CLEARANCE (ft.)	24.0
(53) VERTICAL CLEARANCE OVER BRIDGE ROADWAY (ft.)	327.76
(54) MIN VERTICAL UNDERCLEARANCE	
(54A) REFERENCE FEATURE	H - Highway beneath structure
(54B) MIN VERTICAL UNDERCAREANCE (ft.)	14.58
(55) MIN LATERAL UNDER CLEARANCE RIGHT	
(55A) REFERENCE FEATURE	H - Highway beneath structure
(55B) MIN LATERAL UNDER CLEARANCE RIGHT (ft.)	11.15
(56) MIN LATERAL UNDER CLEARANCE (ft.)	8.9

#### Classification

(112) NBIS BRIDGE LENGTH	Yes
(104) HIGHWAY SYSTEM OF THE INVENTORY ROUTE	0 - Structure/Route is NOT on NHS
(26) FUNCTIONAL CLASSIFICATION OF INVENTORY ROUTE	09 - Rural - Local
(100) STRAHNET HIGHWAY DESIGNATION	Not a STRAHNET route
(101) PARALLEL STRUCTURE DESIGNATION	N - No parallel structure
(102) DIRECTION OF TRAFFIC	2-way traffic
(103) TEMP STRUCTURE	
(105) FEDERAL LANDS HIGHWAYS	Not Applicable
(110) DESIGNATED NATIONAL NETWORK	Inventory route not on network
(20) TOLL	3 - On Free Road
(21) MAINTENANCE RESPONSIBILITY	01 - State Highway Agency
(22) OWNER	01 - State Highway Agency
(37) HISTORICAL SIGNIFICANCE	4 - Not determinable

#### Condition

(58) DECK	5 - Fair Condition (minor section loss)
(59) SUPERSTRUCTURE	6 - Satisfactory Condition (minor deterioration)
(60) SUBSTRUCTURE	6 - Satisfactory Condition (minor deterioration)
(61) CHANNEL & CHANNEL PROTECTION	N - Not Applicable
(62) CULVERT	N - Not Applicable

#### Load Rating and Posting

(31) DESIGN LOAD	4 - H 20
(63) METHOD USED TO DETERMINE OPERATING RATING	8 - Load and Resistance Factor Rating (LRFR) rating report by rating factor (RF) method using HL-93 loadings.
(64) OPERATING RATING	1.5
(65) METHOD USED TO DETERMINE INVENTORY RATING	8 - Load and Resistance Factor Rating (LRFR) rating report by rating factor (RF) method using HL-93 loadings.
(66) INVENTORY RATING	1.15
(70) BRIDGE POSTING	5 - Equal to or above legal loads
(41) STRUCTURE OPEN/POSTED/CLOSED	A - Open

**Inspector:** Harris,Scott  
**Inspection Date:** 09/12/2023

**Structure Number:** 5812  
**Facility Carried:** TRAFTON RD

### Highway Bridge Inspection Report

#### Appraisal

(67) STRUCTURAL EVALUATION	6
(68) DECK GEOMETRY	5
(69) UNDERCLEARANCES, VERTICAL & HORIZONTAL	3
(71) WATERWAY ADEQUACY	N - Not Applicable
(72) APPROACH ROADWAY ALIGNMENT	7 - Better than present minimum criteria
(36) TRAFFIC SAFETY FEATURE	
36A) BRIDGE RAILINGS:	0 - Does not meet acceptable standards/safety feature is required
36B) TRANSITIONS:	0 - Does not meet acceptable standards/safety feature is required
36C) APPROACH GUARDRAIL	0 - Does not meet acceptable standards/safety feature is required
36D) APPROACH GUARDRAIL ENDS	0 - Does not meet acceptable standards/safety feature is required
(113) SCOUR CRITICAL BRIDGES	N - Not over waterway

#### Proposed Improvements

(75) TYPE OF WORK	
(75A) TYPE OF WORK PROPOSED	
(75B) WORK DONE BY	
(76) LENGTH OF STRUCTURE IMPROVEMENT (ft.)	
(94) BRIDGE IMPROVEMENT COST (\$K)	
(95) ROADWAY IMPROVEMENT COST (\$K)	
(96) TOTAL PROJECT COST	
(97) YEAR OF IMPROVEMENT COST ESTIMATE	
(114) FUTURE ADT	467
(115) YEAR OF FUTURE ADT	2036

#### Navigation Data

(38) NAVIGATION CONTROL	N - Not applicable, no waterway
(111) PIER OR ABUTMENT PROTECTION	
(39) NAV VERT CLEARANCE	0
(116) MIN NAVIGATION VERT CLEARANCE, VERT LIFT BRIDGE	0
(40) NAV HORIZONTAL CLEARANCE	0

**Inspector:** Harris,Scott  
**Inspection Date:** 09/12/2023

**Structure Number:** 5812  
**Facility Carried:** TRAFTON RD

**Highway Bridge Inspection Report**

## **7.1 Component Condition Ratings**

<b>(B.C.05) Bridge Railings</b>	<b>8</b>
<b>(B.C.06) Bridge Railing Transitions</b>	<b>8</b>
<b>(B.C.07) Bridge Bearings</b>	<b>6</b>
<b>(B.C.07) Bridge Joints</b>	<b>8</b>
<b>Bridge Joint Seal</b>	<b>6</b>

Inspector: Harris,Scott  
Inspection Date: 09/12/2023

Structure Number: 5812  
Facility Carried: TRAFTON RD

## Highway Bridge Inspection Report

### Inspection Notes

Structure Number: 5812

Town: Waterville

Structure Name: TRAFTON ROAD / I 95

---

#### Structure Notes

1959 Six span steel painted girders. Concrete deck, abutments, piers and wing walls. Bituminous wearing surface.  
1993 Deck Rehab  
1998 Superstructure Repair  
2016 Substructure Repair

#### Wearing Surface

Bituminous wearing surface is in satisfactory condition. No potholes.

#### Deck

NBI Item 58: 5

Concrete curb, fascia's, and exterior bays have minor cracking with efflo staining. Blocking areas of I95 under spans have minor spalling but no areas of active delaminated concrete over travel lanes. Interior bays have minor areas of spalling with exposed rebar. Small areas of wet staining. Rail has been retrofitted with Thri beam system.

#### Superstructure

NBI Item 59: 6

Existing collision damage to the North beam over the SB travel lanes was unchanged.  
Paint on the beams over the travel lanes has speckle rust and edge failure.  
Bearings on the piers have minor paint deterioration.  
Paint loss on bearings and beam ends at the abutments.  
Beam ends at each of the abutments have had preventative treatments.  
All joint seals above each of the piers are intact but appear to be leaking.

#### Substructure

NBI Item 60: 6

Concrete abutments have minor cracking and staining of breastwalls and backwalls with rust staining. Concrete bridge seats have minor to moderate cracking. Concrete pier columns have only very minor cracking. Minor isolated scaling on top of the piers. New protective concrete barriers in front of the piers closest to the NB and SB travel lanes have no issues.

#### Culvert

NBI Item 62: N

**Inspector:** Harris,Scott  
**Inspection Date:** 09/12/2023

**Structure Number:** 5812  
**Facility Carried:** TRAFTON RD

### Highway Bridge Inspection Report

**Channel**

**NBI Item 61:** N

**Other**

#### Special Inspection

Collision damage unchanged - 2020,2021

On October 22nd Bridge Maintenance became aware of new damage to the repaired beam on Trafton Road above Southbound traffic. This damage was reported to the Maine DOT by David Gress, who was hired by Hanover Insurance in relation to the impact damage incurred by Boulet's Wrecker Service on January 9th, 2018 (State of Maine Case #185002339). Alan Farrington, Civil Engineer II from Maine DOT Bridge Maintenance visited the bridge on October 23rd to review the newest damage. The previous sweep in the beam measured approximately 1" by Brent Snowden on 1/16/2018 (Photo 3). Currently the Sweep looks to be approximately 2" (Photo 4), but was unable to be measured directly due to traffic restraints. New damage also includes a bend in the bottom flange approximately 2" up (Photo 6). There are also two new gouges in the bottom flange, slightly East of the prior gouge (Photo 8). Maine DOT is currently unaware of when this damage may have occurred, but it is certainly between the dates of January 10th, 2018 during Brent Snowden's special inspection and September 18th, 2018 during Jamie Hannum's Routine inspection. The bridge is currently posted for height at 14ft-5in (Photo 6).

#### Monitoring

#### Pontis Notes



Inspector: Harris,Scott  
 Inspection Date: 09/12/2023

Structure Number: 5812  
 Facility Carried: TRAFTON RD

### Highway Bridge Inspection Report

	Environment	Total Quantity	Units	Condition State 1	Condition State 2	Condition State 3	Condition State 4
<b>12-Reinforced Concrete Deck</b>	3 - Mod.	10185	sq. ft.	3000	7000	185	0
<b>107-Steel Open Girder/Beam</b>	4 - Sev.	1400	ft.	660	700	40	0
515-Steel Protective Coating		1400	sq. ft.	300	1000	100	0
<b>205-Reinforced Concrete Column</b>	3 - Mod.	15	each	11	4	0	0
<b>215-Reinforced Concrete Abutment</b>	3 - Mod.	58	ft.	50	8	0	0
<b>234-Reinforced Concrete Pier Cap</b>	3 - Mod.	146	ft.	141	5	0	0
<b>302-Compression Joint Seal</b>	3 - Mod.	146	ft.	86	60	0	0
<b>311-Movable Bearing</b>	3 - Mod.	32	each	16	16	0	0
515-Steel Protective Coating		32	sq. ft.	0	20	8	4
<b>313-Fixed Bearing</b>	3 - Mod.	16	each	12	4	0	0
515-Steel Protective Coating		16	sq. ft.	4	4	4	4
<b>801-Beam End</b>	3 - Mod.	48	each	48	0	0	0
515-Steel Protective Coating		48	sq. ft.	18	10	10	10
809-Steel Preventative Coating (Fluid Film)		48	sq. ft.	48	0	0	0
<b>815-Joint Seal</b>	4 - Sev.	5	each	1	3	1	0
<b>820-Reinforced Concrete Wall</b>	3 - Mod.	48	ft.	40	8	0	0
<b>841-Asphalt Wearing Surface with Membrane</b>	3 - Mod.	8505	sq. ft.	8505	0	0	0

Inspector: Harris,Scott  
Inspection Date: 09/12/2023

Structure Number: 5812  
Facility Carried: TRAFTON RD

### Highway Bridge Inspection Report

## Over Limit Report

Bridge #: 5812  
Bridge Name: TRAFTON ROAD / I 95  
Owner: 01 - State Highway Agency  
Co-Owner: N Not applicable  
Region: 02 - Mid-Coast

Town1: Waterville  
Town2:  
Maintainer: 01 - State Highway Agency  
Co-Maintainer: N Not applicable

#### Vertical Clearance - Under

*Left, Center, and Right is based on the direction of travel*

##### Roadway - Heading North or East

##### Actual Heights in Feet-Inches

Date Measured: 05/27/2020

	<u>Left</u>	<u>Center</u>	<u>Right</u>	<u>Posted</u>	<u>Deficient Sign</u>
Main: INTERSTATE 95 NB & SB	17 - 1	16 - 5	16 - 2	Main -	
Other:	-	-	-	Other -	
Ramps:			16 - 3	Ramp -	

##### Roadway - Heading South or West

##### Actual Heights in Feet-Inches

Date Measured: 05/27/2020

	<u>Left</u>	<u>Center</u>	<u>Right</u>	<u>Posted</u>	<u>Deficient Sign</u>
Main: INTERSTATE 95 NB & SB	14 - 8	14 - 5	14 - 6	✓ Main 14 - 5	Wrong Height
Other:	-	-	-	Other -	
Ramps:	-		14 - 5	✓ Ramp 14 - 5	Wrong Height

#### Vertical Clearance - Portal

Roadway: TRAFTON RD

##### Heading North or East

##### Actual Heights in Feet-Inches

Date Measured:  
Deficient Sign

<u>Left</u>	<u>Center</u>	<u>Right</u>	<u>Posted</u>
-	-	-	Portal -

##### Heading South or West

##### Actual Heights in Feet-Inches

Date Measured:  
Deficient Sign  
Wrong Height

<u>Left</u>	<u>Center</u>	<u>Right</u>	<u>Posted</u>
-	-	-	Portal -

#### Permitting

##### Pointer

Red Flag Comments

Heading North Height: 16 - 3 2037191-BRPT  
Heading South Height: 14 - 5 2037192-BRPT  
Left Ramp Height: 14 - 5 2037192-BRPT  
Right Ramp Height: -  
Portal North Height: -  
Portal South Height: -  
  
Other Road Height: -  
  
Bridge Width: 24.3 ft  
Roadway Width: 28.0 ft

*Underclearance heights are signed if less than 14 ft 6 in*

*Check with Maine Turnpike Authority for load heights over 13 ft 6 in*

*Always check 511*

#### Load Restrictions

Posted	tons	Date posted:
Posted One Truck at aTime		
Posted for 4 axle only		
Operating Load Rating	1.5	
Permit Load Ratings		axles
		axles

**Inspector:** Harris,Scott  
**Inspection Date:** 09/12/2023

**Structure Number:** 5812  
**Facility Carried:** TRAFTON RD

**Highway Bridge Inspection Report**

axles

**Inspector:** Harris,Scott  
**Inspection Date:** 09/12/2023

**Structure Number:** 5812  
**Facility Carried:** TRAFTON RD

### Highway Bridge Inspection Report

### Underwater Dive Inspection Report

**Structure Number:** 5812

**Bridge Name:** TRAFTON ROAD/I95

**Town 1:** 11240 - Waterville

**Town 2:**

**Division:** Fairfield

**DiveID:** 4104

**Tidal:**

**Location:** OVER 95 0.3 MI N OF TL

**Photos:**

**Tide Information:**

**Dive Entry Location:**

**Scour:**

**Comments/Hazards:**

**Streambed Description:**

**Channel Description:**

**Substructure Description:**

**Inspection Team:**

**Role:**

**Dive Conditions:**

Time: Entry: AM/PM

Time: Exit: AM/PM

Water Temp:

Visibility (ft):

Max Depth (ft):

Current:

Weather:

Underwater Inspection Date:

Channel Condition:

Substr/Culvert Condition:

Inspection Cycle:

**Ratings Comments:**

Inspector: Scott Harris  
Inspection Date: 09/12/2023

Structure Number: 5812  
Facility Carried: TRAFTON RD

### Highway Bridge Inspection Report

## Pictures



PHOTO 1

Description Pier bearings



PHOTO 2

Description SB span north end collision damage

Inspector: Scott Harris  
Inspection Date: 09/12/2023

Structure Number: 5812  
Facility Carried: TRAFTON RD

### Highway Bridge Inspection Report

## Pictures



PHOTO 3

Description SB span north end collision damage



PHOTO 4

Description SB span north end collision damage diaphragm

Inspector: Scott Harris  
Inspection Date: 09/12/2023

Structure Number: 5812  
Facility Carried: TRAFTON RD

### Highway Bridge Inspection Report

## Pictures



PHOTO 5

Description SB span north end collision damage



PHOTO 6

Description West pier beam ends



Inspector: Scott Harris  
Inspection Date: 09/12/2023

Structure Number: 5812  
Facility Carried: TRAFTON RD

### Highway Bridge Inspection Report

## Pictures



PHOTO 7

Description Pier bearings



PHOTO 8

Description Beam ends at pier



Inspector: Scott Harris  
Inspection Date: 09/12/2023

Structure Number: 5812  
Facility Carried: TRAFTON RD

### Highway Bridge Inspection Report

## Pictures



PHOTO 9

Description SB span north end collision damage looking west



PHOTO 10

Description North girder inside diaphragm damaged

Inspector: Scott Harris  
Inspection Date: 09/12/2023

Structure Number: 5812  
Facility Carried: TRAFTON RD

### Highway Bridge Inspection Report

## Pictures



PHOTO 11

Description roadway looking east



PHOTO 12

Description north rail

Inspector: Scott Harris  
Inspection Date: 09/12/2023

Structure Number: 5812  
Facility Carried: TRAFTON RD

### Highway Bridge Inspection Report

## Pictures



PHOTO 13

Description north rail



PHOTO 14

Description wearing surface view



Inspector: Scott Harris  
Inspection Date: 09/12/2023

Structure Number: 5812  
Facility Carried: TRAFTON RD

### Highway Bridge Inspection Report

## Pictures



PHOTO 15

Description south rail



PHOTO 16

Description spalling at north joint curb area

Inspector: Scott Harris  
Inspection Date: 09/12/2023

Structure Number: 5812  
Facility Carried: TRAFTON RD

### Highway Bridge Inspection Report

## Pictures



PHOTO 17

Description pier joint



PHOTO 18

Description pushed down pier joint seal

Inspector: Scott Harris  
Inspection Date: 09/12/2023

Structure Number: 5812  
Facility Carried: TRAFTON RD

### Highway Bridge Inspection Report

## Pictures



PHOTO 19

Description joint seal



PHOTO 20

Description curb spall



Inspector: Scott Harris  
Inspection Date: 09/12/2023

Structure Number: 5812  
Facility Carried: TRAFTON RD

### Highway Bridge Inspection Report

## Pictures



PHOTO 21

Description spalling at curb joint armor



PHOTO 22

Description NE beam end

Inspector: Scott Harris  
Inspection Date: 09/12/2023

Structure Number: 5812  
Facility Carried: TRAFTON RD

### Highway Bridge Inspection Report

## Pictures



PHOTO 23

Description east beam end oil treatment



PHOTO 24

Description north side view



Inspector: Scott Harris  
Inspection Date: 09/12/2023

Structure Number: 5812  
Facility Carried: TRAFTON RD

### Highway Bridge Inspection Report

## Pictures



PHOTO 25

Description cracking east abutment



PHOTO 26

Description east slope pavement

Inspector: Scott Harris  
Inspection Date: 09/12/2023

Structure Number: 5812  
Facility Carried: TRAFTON RD

### Highway Bridge Inspection Report

## Pictures



PHOTO 27

Description east pier east face



PHOTO 28

Description east pier bearing

Inspector: Scott Harris  
Inspection Date: 09/12/2023

Structure Number: 5812  
Facility Carried: TRAFTON RD

### Highway Bridge Inspection Report

## Pictures



PHOTO 29

Description east span view



PHOTO 30

Description I-95 NB span

Inspector: Scott Harris  
Inspection Date: 09/12/2023

Structure Number: 5812  
Facility Carried: TRAFTON RD

### Highway Bridge Inspection Report

## Pictures



PHOTO 31

Description span view



PHOTO 32

Description center spans view



Inspector: Scott Harris  
Inspection Date: 09/12/2023

Structure Number: 5812  
Facility Carried: TRAFTON RD

### Highway Bridge Inspection Report

## Pictures



PHOTO 33

Description cracking at pier cap



PHOTO 34

Description weird patched area

Inspector: Scott Harris  
Inspection Date: 09/12/2023

Structure Number: 5812  
Facility Carried: TRAFTON RD

### Highway Bridge Inspection Report

## Pictures



PHOTO 35

Description pier beam ends



PHOTO 36

Description I-95 SB span view

Inspector: Scott Harris  
Inspection Date: 09/12/2023

Structure Number: 5812  
Facility Carried: TRAFTON RD

### Highway Bridge Inspection Report

## Pictures



PHOTO 37

Description I-95 SB span view



PHOTO 38

Description west pier east face

Inspector: Scott Harris  
Inspection Date: 09/12/2023

Structure Number: 5812  
Facility Carried: TRAFTON RD

### Highway Bridge Inspection Report

## Pictures



PHOTO 39

Description Collision sweep I-95 SB north girder



PHOTO 40

Description I-95 SB span south girder



Inspector: Scott Harris  
Inspection Date: 09/12/2023

Structure Number: 5812  
Facility Carried: TRAFTON RD

### Highway Bridge Inspection Report

## Pictures



PHOTO 41

Description west pier east face



PHOTO 42

Description clearance posted north girder

Inspector: Scott Harris  
Inspection Date: 09/12/2023

Structure Number: 5812  
Facility Carried: TRAFTON RD

### Highway Bridge Inspection Report

## Pictures



PHOTO 43

Description north girder I-95 BSD span impact damage



PHOTO 44

Description West pier cap

Inspector: Scott Harris  
Inspection Date: 09/12/2023

Structure Number: 5812  
Facility Carried: TRAFTON RD

### Highway Bridge Inspection Report

## Pictures



PHOTO 45

Description I-95 SB span



PHOTO 46

Description west span view

Inspector: Scott Harris  
Inspection Date: 09/12/2023

Structure Number: 5812  
Facility Carried: TRAFTON RD

### Highway Bridge Inspection Report

## Pictures



PHOTO 47

Description west abutment bearing



PHOTO 48

Description west pier west face

**Inspector:** Harris,Scott  
**Inspection Date:** 09/12/2023

**Structure Number:** 5812  
**Facility Carried:** TRAFTON RD

**Highway Bridge Inspection Report**

**Maintenance Work Items**

**Structure Number:** 5812

**Structure Name:** TRAFTON ROAD / I 95

**Town:** 11240

**Owner:** Harris,Scott

---

Type	Work Item	Priority	Notes
Preservation	Seal Joint		
Capital	Coat Beam Ends		
Capital	Paint		
Maintenance	Remove Delams Over Traffic		Monitor for deck spalls over traffic
Capital	Rehab Superstructure		Repair collision damage SB



Inspector: Harris,Scott  
Inspection Date: 09/12/2023

Structure Number: 5812  
Facility Carried: TRAFTON RD

### Highway Bridge Inspection Report

## MaineDOT NBIS Bridge Safety Inspection JSA

Inspector: Harris,Scott  
Team Lead: Scott Harris  
Structure Number: 5812  
Structure Name: TRAFTON ROAD / I 95  
Town: Waterville

#### Additional Team Members/Visitors:

- |                 |     |
|-----------------|-----|
| 1.) Randy Perry | 6.) |
| 2.)             | 7.) |
| 3.)             | 8.) |
| 4.)             | 9.) |
| 5.)             |     |

#### Job being performed:

Bridge inspection

#### Potential Hazard:

☑ Exposure to traffic

#### Potential Hazard:

☑ Steep slopes and uneven working areas  
(rip rap, mud, loose fill, etc)

#### Potential Hazard:

☑ Chipped Concrete or Steel (hand tools only)

#### Potential Hazard:

☑ 6' Vertical drops

#### Potential Hazard:

- ☐ ☐ Water Hazards
  - ☐ ☐ Water depth under 1 foot
  - ☐ ☐ Water depth 1 to 4 feet
  - ☐ ☐ Water depth over 4 feet
  - ☐ ☐ Water flow calm/slow moving
  - ☐ ☐ Water flow visible/not rapid
  - ☐ ☐ Water flow rapid with some short falls
  - ☐ ☐ Tidal Water

#### Controls:

- ☑ ☑ Parked off road with strobe
- ☑ ☑ Less than 1 hour on bridge
- ☑ ☑ Wear standard reflective clothing and hard hat
- ☐ ☐ Spotter ☐ ☐ Traffic Control Crew

#### Controls:

- ☑ ☑ Wear appropriate, prudent footwear
- ☐ ☐ Rope or fall protection

#### Controls:

- ☑ ☑ Wear appropriate, prudent eye/hand protection

#### Controls:

- ☑ ☑ Stay away from areas

#### Controls:

- ☐ ☐ Evaluate Water Hazard conditions
- ☐ ☐ Use/Wear appropriate PPE
- ☐ ☐ Buddy System

Inspector: Harris,Scott  
Inspection Date: 09/12/2023

Structure Number: 5812  
Facility Carried: TRAFTON RD

### Highway Bridge Inspection Report

No water exists at the bridge

Potential Hazard:

☐ Insects, Poision Ivy, or other environmental hazards

Controls:

☐ Apply insect repellant and/or sunscreen  
☐ Protect skin with appropriate, prudent clothing

Potential Hazard:

☒ Lead paint and Avian excrement

Controls:

☒ Wear gloves, do not scrape

Potential Hazard:

☐ Heavy Manual Lifting

Controls:

☐ Ask for assistance in donning dive gear,  
lifting equipment

Potential Hazard:

☐ DCS, Lung Expansion

Controls:

☐ Ascend slowly, user computers, Safety Stops  
(15' mark for 3 min.)

Potential Hazard:

☐ Entanglement U/W

Controls:

☐ Use knife, Comm gear

Potential Hazard:

☐ Boat Traffic

Controls:

☐ Fly Dive Flag, user spotter, contact bridge  
on Chan. 13

Potential Hazard:

☐ Cold Water

Controls:

☐ Use adequate dry suit underwear  
for water temperature

Potential Hazard:

☐ Live Boating

Controls:

☐ Keep track of divers, avoid powering during  
drop-off/pick-up

Other Potential Hazards:

Other Controls:

Inspector: Harris, Scott  
Inspection Date: 09/12/2023

Structure Number: 5812  
Facility Carried: TRAFTON RD

### Highway Bridge Inspection Report


Safety Equipment Required:

<input checked="" type="checkbox"/> Hard hat	<input checked="" type="checkbox"/> Sunscreen
<input checked="" type="checkbox"/> Vest	<input type="checkbox"/> First Aid
<input checked="" type="checkbox"/> Glasses	<input type="checkbox"/> O2
<input checked="" type="checkbox"/> Gloves	<input type="checkbox"/> AED
<input type="checkbox"/> PFD	<input type="checkbox"/> Comm Gear
<input type="checkbox"/> Rain Gear	<input checked="" type="checkbox"/> Cell Phone
<input type="checkbox"/> Bug Spray	<input type="checkbox"/> Boat

<input type="checkbox"/> Throw Ring
<input type="checkbox"/> Throw Rope
<input type="checkbox"/> Positioning Device

Emergency Action Plan:

<input checked="" type="checkbox"/> Call 911
<input checked="" type="checkbox"/> First Aid Kit
<input type="checkbox"/> Fall Rescue Plan
<input type="checkbox"/> Water Rescue Plan
<input type="checkbox"/> Dan 1-919-684-9111
<input type="checkbox"/> USCG 741-5465

Other Safety Equipment:

--

Other Emergency Action Plan:

--

I certify that the MaineDOT NBIS Bridge Safety Inspection JSA has been completed according to all proper procedures required by the Maine Department of Transportation.

☒ Complete      Scott B. Harris

Inspector: Harris,Scott  
Inspection Date: 09/12/2023

Structure Number: 5812  
Facility Carried: TRAFTON RD

## Highway Bridge Inspection Report

### Bridge Components

Bridge #: 5812  
Bridge Name: TRAFTON ROAD / I 95  
Owner: 01 - State Highway Agency  
Co-Owner: N Not applicable  
Region: 02 - Mid-Coast

Town1: Waterville  
Town2:  
Maintainer: 01 - State Highway Agency  
Co-Maintainer: N Not applicable

#### Deck

##### Joint Seal Type/MFG:

☐ Emseal  
☐ V Seal  
☐ Watson Bowman  
☐ Hot Rubber  
☐ Pour-in-Place  
☐ DS Brown

##### Joint Types:

☐ Finger  
☐ Asphaltic Plug  
☐ Compression  
☐ Modular  
☐ Gland  
☐ Waybo Crete

☐ Sliding  
☐ Transflex  
☐ Open

##### Joint HDR Mat:

☐ Concrete  
☐ Delcrete  
☐ Elastomeric  
☐ LP Concrete  
☐ Phoscrete  
☐ Plycrete

##### Other:

☐ Curtain  
☐ Troughs  
☐ Armor

##### Rebar Type:

#### Superstructure

##### Left Side Rail:

Material Concrete ☒ Retrofit  
Shape Parapet ☒ Safety Walk  
Attached To Deck ☐ Pales  
Number of Bars 0 ☐ Snow Fence  
Extra Height N

##### Right Side Rail:

Material Concrete ☒ Retrofit  
Shape Parapet ☒ Safety Walk  
Attached To Deck ☐ Pales  
Number of Bars 0 ☐ Snow Fence  
Extra Height N

##### Bearing Type Quantity:

☐ Disk ☐ Elastomeric  
☐ Pot ☐ Rocker  
☐ Roller ☒ Sliding Plate

##### Fatigue Prone Detail:

☐ Narrow Cover Plate - Sq End Welded  
☐ Narrow Cover Plate - Sq End w/o Weld  
☐ Wide Cover Plate - Sq End Welded  
☐ Wide Cover Plate - Sq End w/o Weld  
☐ Lateral Connection Plate - Welded  
☐ Narrow Cover Plate - Tapered End Welded  
☐ Narrow Cover Plate - Tapered End w/o Weld  
☐ Longitudinal Stiffener - Welded with Radius  
☐ Longitudinal Stiffener - Welded w/o Radius  
☐ Hoan Detail

##### Other:

☐ Pin Quantity  
☐ Pin and Link Quantity

#### Substructure

☐ Pier Collars  
☐ Abutment Collars  
☐ Wood Piles  
☐ Steel Piles  
☐ Blocked Bridge

##### Retaining Wall Type:

#### Other

☐ Confined Space  
☐ Bridge Lighting  
☐ Cat Walk  
☐ Navigational Lighting  
☐ Signs Attached

#### General Notes

Inspector: Harris,Scott  
Inspection Date: 09/12/2023

Structure Number: 5812  
Facility Carried: TRAFTON RD

### Highway Bridge Inspection Report

## Bridge Preservation

Bridge #: 5812  
Bridge Name: TRAFTON ROAD / I 95  
Owner: 01 - State Highway Agency  
Co-Owner: N Not applicable  
Region: 02 - Mid-Coast

Town1: Waterville  
Town2:  
Maintainer: 01 - State Highway Agency  
Co-Maintainer: N Not applicable

#### Deck

##### NBI Deck Information:

Deck Type 1 - Concrete Cast-in-Place  
Deck Protection 0 - None  
Membrane Type 2 - Preformed Fabric

##### Wearing Surface:

Type 6 - Bituminous  
Last Date 1993  
Lifespan (Yrs) 25  
Next Date Est. 2018  
Mill & Fill Date 0

#### Common Preservation

##### Paint Information:

Type  
Last Date 1993  
Lifespan (Yrs)  
Next Date Est. 2018

##### Anodes:

☐ ☐ Installed  
☐ ☐ Detached  
☐ ☐ Replace

#### Superstructure

##### Beam Ends Paint:

Last Date  
Next Date Est.

##### Bearings Paint:

Last Date 2018  
Next Date Est. 2

##### Bearings Lubrication:

Last Date 0  
Next Date Est. 2028

##### Beam Ends Fluid Film:

Last Date 0  
Next Date Est.

##### Bearings Fluid Film:

Last Date  
Next Date Est. 10

##### Treatment:

☐ ☐ Core 10  
☐ ☐ Galvanized  
☐ ☐ Metalized

##### Concrete-Silane:

Last Date  
Next Date Est. 1993

##### Washing:

☐ ☐ Required  
☐ ☐ UBIT

##### Concrete-Linseed

Last Date  
Next Date Est. 0  
☐ ☐ Alkali-Silica reactivity

#### Substructure

#### General Notes



Inspector: Harris,Scott  
Inspection Date: 09/12/2023

Structure Number: 5812  
Facility Carried: TRAFTON RD

## Highway Bridge Inspection Report

### Critical Finding Form

#### Critical Finding History

Bridge #: 5812  
Bridge Name: TRAFTON ROAD / I 95  
Owner: 01 - State Highway Agency  
Co-Owner: N Not applicable  
CF on NSTM Member ?

Date of Discovery

Bridge Operational Status Due to CF(s)

General Cause of CF(s)

Detailed Description of Critical Finding

If "Other" Selected, Please Explain

Immediate Action(s)  
Taken to Address Critical Finding?

#### Conclusion

Is the Critical Finding Resolved ?

Date Resolved

Which NBI general condition rating is affected ?

Detail the response type, resolution, timelines and long term plan for the bridge

Date (or anticipated date) of Permanent Resolution

#### Critical Finding Reference

##### FHWA criteria for reporting Critical Findings

FHWA shall be notified within 24 hours of any critical finding and the activities taken, underway, or planned to resolve or monitor the critical finding. Update FHWA regularly or as requested on the status of each critical finding until it is resolved. Monthly make available the information to provide a written report to FHWA with a summary of the status of the resolutions for each critical finding identified within that month or unresolved from previous months.

##### Maine DOT Critical Finding notification procedure

The following procedures are to be used when a critical inspection finding is reported by the Bridge Inspector, Bridge Maintenance Manager, or other source when the Deck, Superstructure, or Substructure or Culvert having a NBI rating of 2 or less.

1. The Bridge Inspector or Bridge Manager shall report any finding that may be of a critical nature to their immediate supervisor, the Assistant Bridge Maintenance Engineer, and the Bridge Maintenance Engineer.
2. The Assistant Bridge Maintenance Engineer or the Bridge Maintenance Engineer will assess the finding and take the appropriate action.
3. If the action requires restricting or closing the bridge, the following will be notified:

- Director of Maintenance and Operations
- Division Engineer
- Permit Section
- Federal Highway Bridge Engineer

1. If the bridge is not under State jurisdiction, the bridge owner will be notified by the Bridge Inspector, Bridge Maintenance Manager, Assistant Bridge Maintenance Engineer, or the Bridge Maintenance Engineer by telephone or in writing, depending on the urgency.
2. Follow-up on action taken by the bridge owner will be made depending on the seriousness of the findings as determined by the Assistant Bridge Maintenance Engineer or the Bridge Maintenance Engineer.
3. Bridges under State jurisdiction will be restricted and/or repaired through the direction of the Assistant Bridge Maintenance Engineer.
4. Reports of deficiencies (critical or otherwise) from other sources will be handled in the same manner.

Note: A critical finding is a major defect in the superstructure or substructure which, if not repaired immediately, may require the closing or partial closing of a bridge, and could lead to the total collapse of the structure. Repairs should be completed within a few days.