

Maine Department of Transportation
 Field Inspection of Road Systems, Inc.
 FLEAT-SP-MGS Terminal Ends on Maine Highways

Project No.		Date		Inspector	
LAT		LONG		Installer	Repairs Only

Ensure that proper installation procedures were used during initial installation and/or maintenance:

Scoring

- 1 - Meets all requirements and/or within tolerances
- 2 - Meets all but one of the requirements and/or within 1in. of tolerances
- 3 - More than one part of the criteria not met and/or more than an 1in. outside tolerances

1. The rail height as measured from the finished grade to the top of rail is approximately 31". A

Score _____

2. Is installed with a straight flare (offset between 2'-6" & 4'0") over a 37'-6" terminal length.

Score _____

3. No ground strut on system.

Score _____

4. There is no curved rail within the terminal limits on either system.

Score _____

5. The rail splice is at mid-splice for FLEAT-SP-MGS.

Score _____

6. Rail not attached to Post 3 but is attached to posts and blockouts from location #4 and beyond (within the terminal limit).

Score _____

7. No blockouts are used on Post 1 & 2 on either system.

Score _____

8. 12" Offset blocks (blockouts) from Post 3 and beyond within the terminal limits.

Score _____

9. The end rail section is not attached to Post 1.

Score _____

10. Impact head installed with rail exit slot on the traffic side.

Score _____

Maine Department of Transportation
Field Inspection of Road Systems, Inc.
FLEAT-SP-MGS Terminal Ends on Maine Highways

11. FLEAT-SP-MGS cable NOT to be fed inside the feeder chute.

Score _____

12. The end rail panel has special slots and all rails are lapped in the proper direction.

Score _____

13. The $\frac{3}{4}$ " x 8-1/2" hinge bolt at Post 2 is on the downstream side of the post.

Score _____

14. The 5/8" x 9" hinge bolt at Post 1 is on the upstream side of the post.

Score _____

15. Posts 1 & 2 – are hinged steel posts and are plumb and w/o damage.

Score _____

16. The lower sections of Post 1& 2 do not protrude more than 4" above the ground line (measured by the AASHTO 5' cord method).

Score _____

17. At Post 2, the open-ended slot at the post bolt is on the upstream side of the post. (If Post is universal use upper slots.)

Score _____

18. Standard steel W6x9# x 6'-0" guardrail posts are used at Post 3 and beyond.

Score _____

19. All posts within the FLEAT-SP-MGS are spaced at 6'- 3" centers.

Score _____

20. The two 5/16" x 1" hex bolts holding the impact head to Post 1 are secured.

Score _____

21. W-beam is fully seated into Impact Head making sure the two 5/16" x 1" hex bolts holding the impact head are secured to Post 1.

Score _____

22. The 8" x 8" bearing plate is correctly positioned at Post 1 with the 5" dimension up and the 3" dimension down.

Score _____

Maine Department of Transportation
Field Inspection of Road Systems, Inc.
FLEAT-SP-MGS Terminal Ends on Maine Highways

23. The anchor cable is taut and correctly installed.

Score _____

24. A retainer/tie has been placed over the bearing plate to prevent rotation.

Score _____

25. The cable anchor bracket special shoulder bolts are properly attached to the W-beam guardrail and the cable anchor bracket is fully seated on the shoulder portion of the bolts (backside of rail).

Score _____

26. If posts were augured, the backfill material around the posts is properly compacted.

Score _____

27. No washers are used on the face of rail, except for the cable anchor bracket bolts.

Score _____

28. The slope of the area immediately behind the guardrail widening is a 3:1 or flatter.

Score _____

29. Existing damage to w-beam from impact head through last post should be noted.

Score _____

30. If there is previous impact damage was it repaired correctly?

Score _____

31. Ensure guardrail delineation is in place and reflective sheeting on the extruder face is oriented correctly.

Score _____

32. Grading is 5' behind Post#1 tapering to 2' behind back of post downstream. Cross slope should be 1V:10H throughout.

Score _____