

Highway Bridge Inspection Report

**I95 SB / SOUADABSCOOK CENTER
I 95 SB
over
SOUADABSCOOK STREAM**



Asset Code: 1432

Inspection Date: 04/06/2017

Inspected By: Jamie Hannum

Inspection Type(s): Routine

TABLE OF CONTENTS

	PAGE NUMBER
EXECUTIVE SUMMARY	3
LOCATION MAP	4
NATIONAL BRIDGE INVENTORY REPORT - MAINE	5
GENERAL DATA REPORT	8
INSPECTION NOTES REPORT	10
NATIONAL BRIDGE INVENTORY	12
ELEMENTS	13
LOAD RATING REPORT	14
DIVE - REPORT	15
PHOTOS	16
WORK ITEMS REPORT	24
JOB SAFETY REPORT	25

Inspector: Jamie Hannum

Inspection Date: 04/06/2017

Structure Number: 1432

Facility Carried: I 95 SB

Highway Bridge Inspection Report


Executive Summary

Inspector: Jamie Hannum
Inspection Date: 04/06/2017

Structure Number: 1432
Facility Carried: I 95 SB

Highway Bridge Inspection Report

Location Map



Latitude: 44.76298
Longitude: -68.90944

National Bridge Inventory

Status: 0 - ND

Bridge Name: I95 SB / SOUADABSCOOK CENTER

Sufficiency Rating: 89.6

Inspections

(90) INSPECTION DATE	& (91) DESIGNATED INSPECTION FREQUENCY	24	04/06/2017
(92) CRITICAL FEATURE INSPECTION	& (93) CFI DATE		
(92A) FRACTURE CRITICAL DETAIL		N	
(92B) UNDERWATER INSPECTION		Y	60
(92C) OTHER SPECIAL INSPECTION		N	09/01/2015

Identification

(1) STATE CODE	231 - Maine
(8) STRUCTURE NUMBER	1432
(5) INVENTORY ROUTE	
(5A) RECORD TYPE	1: Route carried "on" the structure
(5B) ROUTE SIGNING PREFIX	3 - STATE HIGHWAY
(5C) DESIGNATED LEVEL OF SERVICE	1 - MAINLINE
(5) INVENTORY ROUTE	95
(5) INVENTORY ROUTE	3 - SOUTH
(2) HIGHWAY AGENCY DISTRICT	04 - Eastern
(3) COUNTY CODE	019 Penobscot
(4) PLACE CODE	30795
(6) FEATURES INTERSECTED	SOUADABSCOOK STREAM
(7) FACILITY CARRIED	I 95 SB
(9) LOCATION	2.5 MI E TL/ 95 MI 177.1
(11) MILEPOINT	127.631
(12) BASE HIGHWAY NETWORK	Inventory Route is on the Base Network
(13) LRS INVENTORY ROUTE, SUBROUTE	
(13A) LRS INVENTORY ROUTE	000000095S
(13B) SUBROUTE NUMBER	00
(16) LATITUDE	44.76298
(17) LONGITUDE	-68.90944
(98A) BORDER BRIDGE CODE	
(98B) PERCENT RESPONSIBILITY	0
(99) BORDER BRIDGE STRUCT NO.	n/a

Structure Type and Material

(43) STRUCTURE TYPE, MAIN	
(43A) KIND OF MATERIAL/DESIGN	4 - Steel continuous
(43B) TYPE OF DESIGN/CONSTR	02 - Stringer/Multi-beam or Girder
(44) STRUCTURE TYPE, APPROACH SPANS	
(44A) KIND OF MATERIAL/DESIGN	0 - Other
(44B) TYPE OF DESIGN/CONSTRUCTION	00 - Other
(45) NUMBER OF SPANS IN MAIN UNIT	3
(46) NUMBER OF APPROACH SPANS	0
(107) DECK STRUCTURE TYPE	1 - Concrete Cast-in-Place
(108) WEARING SURFACE/PROTECTIVE SYSTEMS	
(108A) WEARING SURFACE	2 - Integral Concrete (separate non-modified layer of concrete added to
(108B) DECK MEMBRANE	0 - None
(108C) DECK PROTECTION	0 - None

Age of Service

(27) YEAR BUILT	1961
(106) YEAR RECONSTRUCTED	-4
(42) TYPE OF SERVICE	
(42A) TYPE OF SERVICE ON BRIDGE	1 - Highway
(42B) TYPE OF SERVICE UNDER BRIDGE	5 - Waterway
(28) LANES	
(28A) LANES ON THE STRUCTURE	02
(28B) LANES UNDER THE STRUCTURE	00
(29) AVERAGE DAILY TRAFFIC	12570
(30) YEAR OF AVERAGE DAILY TRAFFIC	2015
(109) AVERAGE DAILY TRUCK TRAFFIC	11
(19) BYPASS DETOUR LENGTH	1

Geometric Data

(48) LENGTH OF MAXIMUM SPAN (ft.)	50
(49) STRUCTURE LENGTH (ft.)	135
(50) CURB/SIDEWALK WIDTHS	
(50A) LEFT CURB SIDEWALK (ft.)	0.2
(50B) RIGHT CURB SIDEWALK (ft.)	0.2
(51) BRDG RDWY WIDTH CURB-TO-CURB (ft.)	40
(52) DECK WIDTH, OUT-TO-OUT (ft.)	42.4
(32) APPROACH ROADWAY WIDTH (ft.)	40
(33) BRIDGE MEDIAN	0 - No median
(34) SKEW (deg.)	0
(35) STRUCTURE FLARED	0 - No flare
(10) INV RTE, MIN VERT CLEARANCE (ft.)	328.05
(47) TOTAL HORIZONTAL CLEARANCE (ft.)	40
(53) VERTICAL CLEARANCE OVER BRIDGE ROADWAY (ft.)	327.76
(54) MIN VERTICAL UNDERCLEARANCE	
(54A) REFERENCE FEATURE	N - Feature not a highway or railroad
(54B) MIN VERTICAL UNDERCLEARENCE (ft.)	0
(55) MIN LATERAL UNDER CLEARANCE RIGHT	
(55A) REFERENCE FEATURE	N - Feature not a highway or railroad
(55B) MIN LATERAL UNDER CLEARANCE RIGHT (ft.)	327.76
(56) MIN LATERAL UNDER CLEARANCE (ft.)	99.9

Classification

(112) NBIS BRIDGE LENGTH	Yes
(104) HIGHWAY SYSTEM OF THE INVENTORY ROUTE	1 - Structure/Route is on NHS
(26) FUNCTIONAL CLASSIFICATION OF INVENTORY ROUTE	01 - Rural - Principal Arterial - Interstate
(100) STRAHNET HIGHWAY DESIGNATION	Is on an Interstate STRAHNET route
(101) PARALLEL STRUCTURE DESIGNATION	L - Left structure (South or West)
(102) DIRECTION OF TRAFFIC	1-way traffic
(103) TEMP STRUCTURE	
(105) FEDERAL LANDS HIGHWAYS	Not Applicable
(110) DESIGNATED NATIONAL NETWORK	Inventory route on National Truck Network
(20) TOLL	3 - On Free Road
(21) MAINTENANCE RESPONSIBILITY	01 - State Highway Agency
(22) OWNER	01 - State Highway Agency
(37) HISTORICAL SIGNIFICANCE	5 - Not eligible

Condition

(58) DECK	6 - Satisfactory Condition (minor deterioration)
(59) SUPERSTRUCTURE	7 - Good Condition (some minor problems)
(60) SUBSTRUCTURE	7 - Good Condition (some minor problems)
(61) CHANNEL & CHANNEL PROTECTION	6 - Bank slump. widespread minor damage
(62) CULVERT	N - Not Applicable

Load Rating and Posting

(31) DESIGN LOAD	6 - HS 20+Mod
(63) METHOD USED TO DETERMINE OPERATING RATING	8 - Load and Resistance Factor
(64) OPERATING RATING	1.08
(65) METHOD USED TO DETERMINE INVENTORY RATING	8 - Load and Resistance Factor
(66) INVENTORY RATING	0.83
(70) BRIDGE POSTING	5 - Equal to or above legal
(41) STRUCTURE OPEN/POSTED/CLOSED	A - Open

Appraisal

(67) STRUCTURAL EVALUATION	6
(68) DECK GEOMETRY	7
(69) UNDERCLEARANCES, VERTICAL & HORIZONTAL	N
(71) WATERWAY ADEQUACY	9 - Bridge Above Flood Water Elevations
(72) APPROACH ROADWAY ALIGNMENT	8 - Equal to present desirable criteria
(36) TRAFFIC SAFETY FEATURE	
36A) BRIDGE RAILINGS:	0 - Does not meet acceptable standards/safety feature is required
36B) TRANSITIONS:	0 - Does not meet acceptable standards/safety feature is required
36C) APPROACH GUARDRAIL	0 - Does not meet acceptable standards/safety feature is required
36D) APPROACH GUARDRAIL ENDS	0 - Does not meet acceptable standards/safety feature is required
(113) SCOUR CRITICAL BRIDGES	5 - Scour within limits of footing or piles

Proposed Improvements

(75) TYPE OF WORK	
-------------------	--

(75A) TYPE OF WORK PROPOSED
(75B) WORK DONE BY
(76) LENGTH OF STRUCTURE IMPROVEMENT (ft.)
(94) BRIDGE IMPROVEMENT COST (\$K)
(95) ROADWAY IMPROVEMENT COST (\$K)
(96) TOTAL PROJECT COST
(97) YEAR OF IMPROVEMENT COST ESTIMATE
(114) FUTURE ADT 17598
(115) YEAR OF FUTURE ADT 2035

Navigation Data	
-----------------	--

(38) NAVIGATION CONTROL	0 - No navigation control on waterway (bridge
(111) PIER OR ABUTMENT PROTECTION	
(39) NAV VERT CLEARANCE	0
(116) MIN NAVIGATION VERT CLEARANCE, VERT LIFT BRIDGE	0
(40) NAV HORIZONTAL CLEARANCE	0

General Bridge Data

Structure Number: 1432

Structure Name: I95 SB / SOUADABSCOOK CENTER

Owner: 1 State DOT

Town: Hampden

Co-Owner: N Not applicable

Town2:

Region: 04 Eastern

Maintainer: 1 State DOT

Bridge Plans:

Co-Maintainer: N Not applicable

Structure Type

Main Span

Type: 1 Girder

Sub Type: 1 Deck

Construction: 1 Rolled

Material: 1 Steel

Continuity: 2 Continuous

Composite: 1 Non Composite

Moveable: 0 No

Deck Area: 5724.28507560 (SF)
000000

Curb Reveal Lt: 9.0 (in)

Curb Reveal Rt: 9.0 (in)

Approach Span

Type: _

Sub Type: _

Construction: _

Material: _

Continuity: _

Composite: _

Moveable: _

Repairs Done:

Year

How

Scope

2007 Maintenance

Deck Rehab

2007 Maintenance

Substructure Rehab

Substructures

	Shaft	Notes
Abutment 1		
Pier		
Pier		
Pier		
Abutment 2		

	Foundation	Notes
Abutment 1		
Pier		
Pier		
Pier		
Abutment 2		

Roadway

Road/Route Name	I 95 SB
Abut-Abut Detour	1.0
Corridor Priority	1

Inspection Notes

Structure Number: 1432

Town: Hampden

Structure Name: I95 SB / SOUADABSCOOK CENTER

Inspection Date: 04/06/2017

Structure Notes

Three span steel painted girders. Concrete deck, piers, abutments, wing-walls and wearing surface.

Wearing Surface

Approach bituminous settlement with nested cracking at both ends of the bridge. Concrete wearing surface has loss of tining in the wheel path areas. Minor transverse cracking. Nested cracking and minor settlement at the South approach pavement, see photo. Half of the aluminum bridge posts have plow damage (up stream end) the remainder are in good condition.

Deck

NBI Item 58: 6

Deck rehab in 2007 included deck patches, sections of curb and end posts and bearing pedestals. Bridge rail on the down stream side has multiple gouged rail posts, broken posts that involve at least one bolt, a completely severed post and a torn rail, see photos.

Superstructure

NBI Item 59: 7

North abutment center bearing is not bearing on the masonry plate and bouncing 1/4", see photo. Possibilities for this issue include abutment settlement or excessive pack rust under the remaining bearings. Painted steel girders are in good condition with moderate paint deterioration.

Substructure

NBI Item 60: 7

Substructure rehab in 2007 included bearing block/pedestal rehab. Minor cracking of the wing walls and back walls. Concrete piers are in good condition with only very minor cracking.

Culvert

NBI Item 62: N

Channel

NBI Item 61: 6

Other

Special Inspection

Monitoring

Pontis Notes

Inspector: Jamie Hannum
 Inspection Date: 04/06/2017

Structure Number: 1432
 Facility Carried: I 95 SB

Highway Bridge Inspection Report

National Bridge Inventory

IDENTIFICATION				INSPECTIONS			
(1) STATE CODE	231 - Maine			(90) INSPECTION DATE	04/06/2017		
(8) STRUCTURE NUMBER	1432			(91) DESIGNATED INSPECTION FREQUENCY	24		
(5) INV. ROUTE (ON/UNDER)	1	3	1 95 3	(92) CRITICAL FEATURE INSPECTION	(93) CFI DATE		
(2) HIGHWAY AGENCY	04	(3) COUNTY CODE	019	A. FRACTURE CRITICAL DETAIL	N		
(4) PLACE CODE	30795			B. UNDERWATER INSPECTION	Y	60	09/01/2015
(6) FEATURES INTERSECTED	SOUADABSCOOK STREAM			C. OTHER SPECIAL	N		
(7) FACILITY CARRIED	I 95 SB			CONDITION			
(9) LOCATION	2.5 MI E TL/ 95 MI 177.1			(58) DECK	6		
(11) MILEPOINT 127.631	(12) BASE HIGHWAY NETWORK 1			(59) SUPERSTRUCTURE 7	(60) SUBSTRUCTURE 7		
(13A) LRS INVENTORY ROUTE 000000095S	(13B) SUBROUTE NUMBER 00			(61) CHANNEL & CHANNEL PROTECTION 6	(62) CULVERT N		
(16) LATITUDE 44.76298	(17) LONGITUDE -68.90944			LOAD RATING AND POSTING			
(98A) BORDER BRIDGE CODE				(31) DESIGN LOAD	6		
PERCENT RESPONSIBILITY 0	(99) BORDER BRIDGE STRUCT n/a			(63) METHOD USED TO DETERMINE OPERATING RATING	8		
STRUCTURE TYPE AND MATERIAL				(64) OPERATING RATING	1.08		
(43) STRUCTURE TYPE, MAIN				(65) METHOD USED TO DETERMINE INVENTORY RATING	8		
A) KIND OF MATERIAL/DESIGN:	4 - Steel continuous			(66) INVENTORY RATING	0.83		
B) TYPE OF DESIGN/CONSTR:	02 - Stringer/Multi-beam or Girder			(70) BRIDGE POSTING	5		
(44) STRUCTURE TYPE, APPROACH SPANS				(41) STRUCTURE OPEN/POSTED/CLOSED	A		
A) KIND OF MATERIAL/DESIGN:	0 - Other			APPRAISAL			
B) TYPE OF DESIGN/CONSTR:	00 - Other			(67) STRUCTURAL EVALUATION	6		
(45) NUMBER OF SPANS IN MAIN 3	(46) NUMBER OF APPROACH 0			(68) DECK GEOMETRY	7		
(107) DECK STRUCTURE TYPE 1	(108A) WEARING SURFACE 2			(69) UNDERCLEARANCES, VERTICAL & HORIZONTAL	N		
(108B) DECK MEMBRANE 0	(108C) DECK PROTECTION 0			(71) WATERWAY ADEQUACY	9		
AGE OF SERVICE				(72) APPROACH ROADWAY ALIGNMENT	8		
(27) YEAR BUILT 1961	(106) YEAR RECONSTRUCTED -4			(36) TRAFFIC SAFETY FEATURE			
(42) TYPE OF SERVICE ON 1	UNDER 5			36A) BRIDGE RAILINGS:	0		
(28) LANES ON 02	UNDER 00			36B) TRANSITIONS:	0		
(29) AVERAGE DAILY TRAFFIC 12570	(19) BYPASS DETOUR LENGTH 1			36C) APPROACH GUARDRAIL:	0		
(30) YEAR OF AVERAGE DAILY TRAFFIC 2015				36D) APPROACH GUARDRAIL ENDS:	0		
(109) AVERAGE DAILY TRUCK TRAFFIC 11				(113) SCOUR CRITICAL BRIDGES	5		
GEOMETRIC DATA				SUFFICIENCY RATING 0	STATUS 89.6		
(48) LENGTH OF MAX SPAN (ft.) 50	(49) STRUCTURE LENGTH (ft.) 135			CLASSIFICATION			
(50) CURB/SIDEWALK WIDTHS (ft.) LEFT 0.2	RIGHT 0.2			(112) NBIS BRIDGE LENGTH	Y		
(51) BRDG RDWY WIDTH CURB-TO-CURB (ft.)	40			(104) HIGHWAY SYSTEM OF THE INVENTORY ROUTE	1		
(52) DECK WIDTH, OUT-TO-OUT (ft.)	42.4			(26) FUNCTIONAL CLASSIFICATION OF INVENTORY ROUTE	01		
(32) APPROACH ROADWAY WIDTH (ft.)	40			(100) STRAHNET HIGHWAY DESIGNATION	1		
(33) BRIDGE MEDIAN 0	(34) SKEW (DEG.) 0			(101) PARALLEL STRUCTURE DESIGNATION	L		
(35) STRUCTURE FLARED 0	(10) INV RTE, MIN VERT CLEAR (ft.) 328.05			(102) DIRECTION OF TRAFFIC	1		
(47) TOTAL HORIZONTAL CLEARANCE (ft.)	40			(103) TEMP STRUCTURE			
(53) VERTICAL CLEARANCE OVER BRIDGE ROADWAY (ft.)	327.76			(105) FEDERAL LANDS HIGHWAYS	0		
(54) VERTICAL UNDER CLEARANCE (ft.)	N 0			(110) DESIGNATED NATIONAL NETWORK	1		
(55) LATERAL UNDER CLEARANCE RIGHT (ft.)	N 327.76			(20) TOLL	3		
(56) MIN LATERAL UNDER CLEARANCE (ft.)	99.9			(21) MAINTENANCE RESPONSIBILITY	01		
PROPOSED IMPROVEMENTS				(22) OWNER	01		
(75A) TYPE OF WORK PROPOSED	(75B) WORK DONE BY			(37) HISTORICAL	5		
(76) LENGTH OF STRUCTURE IMPROVEMENT (ft.)				NAVIGATION DATA			
(94) BRIDGE IMPROVEMENT COST (\$)				(38) NAVIGATION CONTROL	0		
(95) ROADWAY IMPROVEMENT COST (\$)				(111) PIER OR ABUTMENT PROTECTION			
(96) TOTAL PROJECT COST				(39) NAV VERT CLEARANCE (ft.)	0		
(97) YEAR OF IMPROVEMENT COST ESTIMATE				(116) MIN NAVIGATION VERT CLEARANCE, VERT LIFT BRIDGE (ft.)	0		
(114) FUTURE ADT 17598	(115) YEAR OF FUTURE ADT 2035			(40) NAV HORIZONTAL CLEARANCE (ft.)	0		

Inspector: Jamie Hannum
 Inspection Date: 04/06/2017

Structure Number: 1432
 Facility Carried: I 95 SB

Highway Bridge Inspection Report

Element Inspection

	Environment	Total Quantity	Units	Condition State 1	Condition State 2	Condition State 3	Condition State 4
12 - Reinforced Concrete Deck	3 - Mod.	5724	sq. ft.	0	5724		
107 - Steel Open Girder/Beam	2 - Low	810	ft.	710	100		
515 - Steel Protective Coating		810	sq. ft.	410	300	100	
210 - Reinforced Concrete Pier Wall	2 - Low	85	ft.	80	5		
215 - Reinforced Concrete Abutment	2 - Low	100	ft.	50	50		
302 - Compression Joint Seal	2 - Low	85	ft.	85			
311 - Movable Bearing	2 - Low	12	each	12			
515 - Steel Protective Coating		12	sq. ft.	0	6	6	
313 - Fixed Bearing	2 - Low	6	each	6			
515 - Steel Protective Coating		6	sq. ft.	0		6	
801 - Beam End	2 - Low	12	each	6	6		
843 - Rigid Wearing Surface	2 - Low	5400	sq. ft.	5400			
861 - Beam End – Protective Coating	2 - Low	12	each	0	6	6	
871 - Aluminum Bridge Railing	2 - Low	270	ft	140	100		30

MaineDOT Load Rating and Posting

Structure Number: 1432

Town 1: Hampden

Bridge Name: I95 SB / SOUADABSCOOK CENTER

Town 2:

Owner: 1 State DOT

Design Load

Vehicle:	Operating Rating:	Inventory Rating:
HL-93	1.08	0.83
HL-93 Modified		

Legal Load

Configuration:	Axles:	Weight (Tons):	Rating:	Tons:
1	6	50	1.35	
2	6	47	1.42	
3	5	44	1.28	
4	5	44	1.30	
5	5	44	1.29	
6	4	38	1.00	
7	3	29.5	1.21	
8	2	18.7	1.76	

Routine Permit Loads

Configuration:	Axles:	Weight (Tons):	Rating:	Tons:	Status:
Tractor w/semi trailor	4	60			

Load Rating

TEDOC Reference:
Controlling Member:
Controlling Stress: negative moment

Posting Committee

Discussion:

TEDOC Reference:

Load Test

Type:
Load Test Date:
TEDOC Reference:
Load Test Results:

Posting Status

- | | |
|---------------------------------|---|
| <input type="checkbox"/> Posted | <input type="checkbox"/> Posted for one truck at a time |
| Weight in tons: | <input type="checkbox"/> Posted for 4 axle |
| | <input type="checkbox"/> Posted for spacing |

Underwater Dive Inspection Report

Structure Number: 1432

Bridge Name: SOUADABSCOOK CENTER SB

Town 1: 19280 - Hampden

Town 2:

Division: Bangor

DiveID: 5155

Tidal:

Location: 2.5 MI E TL/ 95 MI 177.1

Tide Information:

Photos:

Dive Entry Location: Swin down from Southbound bridge

None

Scour: 7

Comments/Hazards:

Debris, Brush on lft. pier.

Streambed Description:

Gravel, stoney, very silty.

Channel Description:

Channel is very irregular and continually changing as exposed footing measurements indicate.

Substructure Description:

2 mass concrete piers. Both of the footings are exposed from 20 to 30" on the channel side and buried to 8" exposure on the shore side. According to plans, footings are 6'-6" in height and shown to be sitting on piles. Debris at the nose of the left pier. Hairline crack in right pier footing on channel side, 6' from downstream end. Concrete is otherwise in good condition with no spalling. Right pier footing exposed up to 26" max.. Left pier footing exposed 0" to 24". 2011: Rt. pier footing exposed up to 40" max. Lft pier footing exposed up to 26" max. Vertical crack thru Rt footing - 1/8"W. Lowered Subst rating from 8 to 7. 2015: Right pier footing exposed up to 28" Left pier footing exposed up to 28". Upstream Left pier corner exposed now where previously buried.

Inspection Team:

Edwards

Role:

TL,SD

Dive Conditions:

Time: Entry: 2:00 AM/PM PM

Amero

SD

Time: Exit: 2:25 AM/PM PM

Merrithew

D

Water Temp: 70

Hannum

D

Visibility (ft): 1

T

Max Depth (ft): 7

Current: none

Weather: sunny

Underwater Inspection Date: 09012015

Channel Condition: 5

Substr/Culvert Condition: 7

Inspection Cycle: Y60

Ratings Comments:

scour

Inspector: Jamie Hannum
Inspection Date: 04/06/2017

Structure Number: 1432
Facility Carried: I 95 SB

Highway Bridge Inspection Report

Pictures



PHOTO 1

Description Completely severed bridge rail post



PHOTO 2

Description Bridge rail post damage with broken base

Inspector: Jamie Hannum
Inspection Date: 04/06/2017

Structure Number: 1432
Facility Carried: I 95 SB

Highway Bridge Inspection Report

Pictures



PHOTO 3

Description Split in bridge rail



PHOTO 4

Description Bridge rail post broken

Inspector: Jamie Hannum
Inspection Date: 04/06/2017

Structure Number: 1432
Facility Carried: I 95 SB

Highway Bridge Inspection Report

Pictures



PHOTO 5

Description Roadway looking South



PHOTO 6

Description Down stream end

Inspector: Jamie Hannum
Inspection Date: 04/06/2017

Structure Number: 1432
Facility Carried: I 95 SB

Highway Bridge Inspection Report

Pictures



PHOTO 7

Description North deck joint



PHOTO 8

Description North abutment

Inspector: Jamie Hannum
Inspection Date: 04/06/2017

Structure Number: 1432
Facility Carried: I 95 SB

Highway Bridge Inspection Report

Pictures



PHOTO 9

Description North abutment and beam ends



PHOTO 10

Description Bottom of the deck, North span

Inspector: Jamie Hannum
Inspection Date: 04/06/2017

Structure Number: 1432
Facility Carried: I 95 SB

Highway Bridge Inspection Report

Pictures



PHOTO 11

Description Center bearing, North end, is not bearing on the masonry plate and bounces 1/4" when live load is applied



PHOTO 12

Description Up stream end

Inspector: Jamie Hannum
Inspection Date: 04/06/2017

Structure Number: 1432
Facility Carried: I 95 SB

Highway Bridge Inspection Report

Pictures



PHOTO 13

Description South deck joint



PHOTO 14

Description South abutment

Inspector: Jamie Hannum
Inspection Date: 04/06/2017

Structure Number: 1432
Facility Carried: I 95 SB

Highway Bridge Inspection Report

Pictures



PHOTO 15

Description Looking South pier

Maintenance Work Items

Structure Number: 1432

Structure Name: I95 SB / SOUADABSCOOK
CENTER

Town: 19280

Owner: Hannum, Jamie

Type	Work Item	Priority	Notes
Maintenance	Stabilize Substructure	3	Grout Bag
Maintenance	Repair Bridge Rail		Multiple rail and post issues
Maintenance	Reset Bearings		North abutment center bearing is bouncing

MaineDOT NBIS Bridge Safety Inspection JSA

Inspection Date: 04/07/2017

Structure Number: 1432

Inspector: Hannum, Jamie

Structure Name: I95 SB / SOUADABSCOOK CENTER

Team Lead: Jamie Hannum

Town: Hampden

Additional Team Members/Visitors:

- | | |
|-----|-----|
| 1.) | 6.) |
| 2.) | 7.) |
| 3.) | 8.) |
| 4.) | 9.) |
| 5.) | |

Job being performed:

Bridge inspection

Potential Hazard:

- Exposure to traffic

Controls:

- Parked off road with strobe
 Less than 1 hour on bridge
 Wear standard reflective clothing and hard hat
 Spotter Traffic Control Crew

Potential Hazard:

- Steep slopes and uneven working areas
(rip rap, mud, loose fill, etc)

Controls:

- Wear appropriate, prudent footwear
 Rope or fall protection

Potential Hazard:

- Chipped Concrete or Steel (hand tools only)

Controls:

- Wear appropriate, prudent eye/hand protection

Potential Hazard:

- 6' Vertical drops

Controls:

- Stay away from areas

Potential Hazard:

- Water Hazards
- Water depth under 1 foot
 - Water depth 1 to 4 feet
 - Water depth over 4 feet
 - Water flow calm/slow moving
 - Water flow visible/not rapid
 - Water flow rapid with some short falls
 - Tidal Water

Controls:

- Evaluate Water Hazard conditions
 Use/Wear appropriate PPE
 Buddy System

Potential Hazard:

- Insects, Poison Ivy, or other environmental hazards

Controls:

- Apply insect repellent and/or sunscreen
 Protect skin with appropriate, prudent clothing

Potential Hazard:

- Lead paint and Avian excrement

Controls:

- Wear gloves, do not scrape

Potential Hazard:

Heavy Manual Lifting

Controls:

Ask for assistance in donning dive gear, lifting equipment

Potential Hazard:

DCS, Lung Expansion

Controls:

Ascend slowly, user computers, Safety Stops (15' mark for 3 min.)

Potential Hazard:

Entanglement U/W

Controls:

Use knife, Comm gear

Potential Hazard:

Boat Traffic

Controls:

Fly Dive Flag, user spotter, contact bridge on Chan. 13

Potential Hazard:

Cold Water

Controls:

Use adequate dry suit underwear for water temperature

Potential Hazard:

Live Boating

Controls:

Keep track of divers, avoid powering during drop-off/pick-up

Other Potential Hazards:

Other Controls:

Safety Equipment Required:

- Hard hat
- Vest
- Glasses
- Gloves
- PFD
- Rain Gear
- Bug Spray

- Sunscreen
- First Aid
- O2
- AED
- Comm Gear
- Cell Phone
- Boat

- Throw Ring
- Throw Rope
- Positioning Device

Emergency Action Plan:

- Call 911
- First Aid Kit
- Fall Rescue Plan
- Water Rescue Plan
- Dan 1-919-684-9111
- USCG 741-5465

Other Safety Equipment:

Other Emergency Action Plan:

I certify that the MaineDOT NBIS Bridge Safety Inspection JSA has been completed according to all proper procedures required by the Maine Department of Transportation.

Complete Jamie Hannum