

Section 26 Shadow Flicker

There is no shadow flicker associated with the generator lead transmission line.