

Structures in the Municipality of Beddington

CONDITION RATINGS

TOWN1: <input type="text" value="Beddington"/>	TOWN2: <input type="text" value="No town 2"/>	SUBSTRUCTURE CONDITION: <input type="text" value="8"/> <input type="text" value="Very Good"/>	
BRIDGE NO.: <input type="text" value="5648"/>	BRIDGE REGION: <input type="text" value="Eastern"/>	SUPERSTRUCTURE CONDITION: <input type="text" value="8"/> <input type="text" value="Very Good"/>	
LOCATION: <input type="text" value="0.5 M NE OF T22 MD"/>	YEAR BUILT: <input type="text" value="1957"/>	DECK CONDITION: <input type="text" value="8"/> <input type="text" value="Very Good"/>	
BRDGNAME: <input type="text" value="BLACKS TANNERY"/>	SPAN MATERIAL: <input type="text" value="1 Steel"/>	CHANNEL CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/>	
OWNER: <input type="text" value="1 State DOT"/>	SPAN TYPE: <input type="text" value="1 Girder"/>	CULVERT CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>	
MAINTAINER: <input type="text" value="1 State DOT"/>	NUMBER OF MAIN SPANS: <input type="text" value="1"/>	APPROACH CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/>	
FEATURE ON: <input type="text" value="ROUTE US 9"/>	STRUCTURE LENGTH IN FEET: <input type="text" value="70"/>	DATE OF INSPECTION: <input type="text" value="7/24/2012"/>	
FEATURE UNDER: <input type="text" value="NARRAGUAGUS RIVER"/>	POSTING STATUS: <input type="text" value="1 Open"/>	FEDERAL SUFFICIENCY RATING: <input type="text" value="87.6"/>	
ROAD INV NO: <input type="text" value="000000009X"/>	POSTING TYPE: <input type="text" value="0 None needed"/>		
ROUTE NO: <input type="text" value="00009"/>			
ROAD WIDTH: <input type="text" value="40"/> FEET	FEDERAL BRIDGE INDICATOR: <input type="text" value="Y"/>		
CLASS: <input type="text" value="BRIDGE ON STATE HIGHWAY"/>			