


EAST ELEVATION
SCALE: NOT TO SCALE



WEST ELEVATION
SCALE: NOT TO SCALE

THE ELEVATIONS ARE PROVIDED TO SHOW APPROXIMATE QUANTITIES AND CONFIGURATIONS.
THE ACTUAL SIZES AND CONFIGURATION WILL VARY FROM THOSE SHOWN. THE CONTRACTOR
SHALL BASE THE BID AND CONTRACT AMOUNTS ON ACTUAL FIELD CONDITIONS.

ELEVATION NOTES

- GRAPHIC HATCHING AND SYMBOLS ARE USED ON THE ELEVATION DRAWINGS TO INDICATE AREAS INCLUDED IN THE SCOPE OF WORK, ACTUAL DIMENSIONS AND QUANTITIES SHALL BE FIELD VERIFIED. REFER TO THE LEGEND ON THIS SHEET FOR THE CORRESPONDING SCOPE OF WORK ASSOCIATED WITH A PARTICULAR HATCH OR SYMBOL.
- 3. CONTRACTOR IS RESPONSIBLE FOR DESTROYING AND REMOVING BEES/HORNETS/WASPS.
- 4. HATCH PATTERNS ARE FOR REPRESENTATION ONLY AND SHOULD NOT BE USED AS A MEANS FOR QUANTIFYING.
- THE PHOTOGRAPHS USED ON THIS SHEET ARE INTENDED TO REPRESENT THE EXISTING CONDITIONS. THE PHOTOGRAPHS MAY BE SLIGHTLY SKEWED AND ARE NOT TO SCALE. REFER TO SHEET A101 FOR OVERALL BUILDING DIMENSIONS.

REPAIR LEGEND

MASONRY


- AS ATMOSPHERIC STAINING TO BE CLEANED;
 # INDICATES SQUARE FEET
- EFFLORESCENCE TO BE CLEANED;
 # INDICATES SQUARE FEET
- RUST STAIN TO BE CLEANED; # INDICATES SQUARE FEET
- CB CRACKED BRICK TO BE REPLACED; # INDICATES UNITS
- DB DISPLACED BRICK TO BE REPLACED; #INDICATES LINEAR FEET
- DETERIORATED MORTAR JOINT TO BE REPAIRED, REFER TO DETAIL 2/A701; # INDICATES LINEAR FEET
- DETERIORATED MORTAR JOINT TO BE REPAIRED, REFER TO DETAIL 2/A701; # INDICATES SQUARE FEET
- SB SPALLED BRICK TO BE REPLACED; # INDICATES UNITS
- EXISTING ANCHOR / METAL STUB TO BE REMOVED AND PATCHED
- STEP CRACK TO BE REPAIRED;
 # INDICATES LINEAR FEET

 BRICK MASONRY TO BE REBUILT

SEALANT CONCRETE/STONE

- FS FAILED SEALANT TO BE REPAIRED, REFER TO DETAIL 5/A701; # INDICATES LINEAR FEET
- FAILED PERIMETER SEALANT TO BE REPAIRED, REFER TO DETAIL 5/A701; # INDICATES LINEAR FEET
- CRACKED CONCRETE TO BE
 REPAIRED, REFER TO DETAIL 3/A701;
 # INDICATES LINEAR FEET
- SPALLED CONCRETE TO BE REPAIRED, REFER TO DETAIL 4/A701; # INDICATES SQUARE FEET
- CRACKED STUCCO TO BE REPAIRED, REFER TO DETAIL 3/A701; # INDICATES LINEAR FEET

NOTE: NOT ALL DEFECTS IN THE LEGEND ARE SHOWN ON THIS SHEET.





Gale Associates, Inc. Engineers and Planners

www.gainc.com

5 Moulton Street Portland, ME 04101 P 207.536.1092

Boston Baltimore Orlando Hartford
Manchester Portland

This drawing and the design and construction features disclosed are proprietary to Gale Associates, Inc. and shall not be altered or reused in whole or part without the express written permission of Gale Associates, Inc. Copyright©2021

FOR CONSTRUCTION

IRS ER CAMPUS

OWNER
SIMAN ASSOCIATES
JGE STREET, 3RD FLOOR
RTLAND, ME 04101

OWNER
HARRIMAN ASSC
80 EXCHANGE STREE

NO. DATE DESCRIPTION
PROJECT NO. 839940

CADD FILE 839940 A200's IF&W
DESIGNED BY JVL

DRAWN BY JVL

CHECKED BY ACP/CM/JFL


DATE 12/4/2023

DRAWING SCALE NOT TO SCALE

GRAPHIC SCALE

SHEET TITLE

EAST AND WEST ELEVATIONS









NORTH ELEVATION A202 SCALE: NOT TO SCALE



Gale Associates, Inc. Engineers and Planners

5 Moulton Street Portland, ME 04101 P 207.536.1092

www.gainc.com Boston Baltimore Orlando Hartford Manchester Portland

This drawing and the design and construction features disclosed are proprietary to Gale Associates, Inc. and shall not be altered or reused in whole or part without the express written permission of Gale Associates, Inc. Copyright@2021

CAMPU

AT THE IF&W BUILDING
A DIX PSYCHIATRIC CENTER C
BANGOR, ME 04401

X

DOROTHE

DESCRIPTION

839940

JVL JVL

DRAWING SCALE NOT TO SCALE

GRAPHIC SCALE

SHEET TITLE

839940 A200's IF&V

ACP/CM/JFL

12/4/2023

BUIL

NO. DATE

PROJECT NO.

DESIGNED BY

CADD FILE

DRAWN BY

DATE

CHECKED BY

DETERIORATED MORTAR JOINT TO BE REPAIRED, REFER TO DETAIL 2/A701; # INDICATES SQUARE FEET SPALLED BRICK TO BE REPLACED; # INDICATES UNITS

DETERIORATED MORTAR JOINT TO BE REPAIRED, REFER TO DETAIL 2/A701; # INDICATES LINEAR FEET

EXISTING ANCHOR / METAL STUB TO BE REMOVED AND PATCHED

STEP CRACK TO BE REPAIRED; # INDICATES LINEAR FEET BRICK MASONRY TO BE REBUILT

DISPLACED BRICK TO BE REPLACED; #INDICATES LINEAR FEET

SEALANT

FS FAILED SEALANT TO BE REPAIRED, REFER TO DETAIL 5/A701; # INDICATES LINEAR FEET

PS FAILED PERIMETER SEALANT TO BE REPAIRED, REFER TO DETAIL 5/A701; # INDICATES LINEAR FEET

CRACKED CONCRETE TO BE REPAIRED, REFER TO DETAIL 3/A701; # INDICATES LINEAR FEET

CONCRETE/STONE

SPALLED CONCRETE TO BE REPAIRED, REFER TO DETAIL 4/A701; # INDICATÉS SQUARE FEET

CRACKED STUCCO TO BE REPAIRED, REFER TO DETAIL 3/A701; # INDICATES LINEAR FEET

NOTE: NOT ALL DEFECTS IN THE LEGEND ARE SHOWN ON THIS SHEET.

ELEVATION NOTES

GRAPHIC HATCHING AND SYMBOLS ARE USED ON THE ELEVATION DRAWINGS TO INDICATE AREAS INCLUDED IN THE SCOPE OF WORK. ACTUAL DIMENSIONS AND QUANTITIES SHALL BE FIELD VERIFIED. REFER TO THE LEGEND ON THIS SHEET FOR THE CORRESPONDING SCOPE OF

CONTRACTOR IS RESPONSIBLE FOR DESTROYING AND REMOVING BEES/HORNETS/WASPS.

4. HATCH PATTERNS ARE FOR REPRESENTATION ONLY AND SHOULD NOT BE USED AS A MEANS

THE PHOTOGRAPHS USED ON THIS SHEET ARE INTENDED TO REPRESENT THE EXISTING

CONDITIONS. THE PHOTOGRAPHS MAY BE SLIGHTLY SKEWED AND ARE NOT TO SCALE. REFER

REPAIR LEGEND

MASONRY

SHALL BASE THE BID AND CONTRACT AMOUNTS ON ACTUAL FIELD CONDITIONS

WORK ASSOCIATED WITH A PARTICULAR HATCH OR SYMBOL.

TO SHEET A101 FOR OVERALL BUILDING DIMENSIONS.

ATMOSPHERIC STAINING TO BE CLEANED; # INDICATES SQUARE FEET


EFFLORESCENCE TO BE CLEANED; # INDICATES SQUARE FEET

CRACKED BRICK TO BE REPLACED; # INDICATES UNITS

RUST STAIN TO BE CLEANED; # INDICATES SQUARE FEET

FOR QUANTIFYING.

THE ELEVATIONS ARE PROVIDED TO SHOW APPROXIMATE QUANTITIES AND CONFIGURATIONS. THE ACTUAL SIZES AND CONFIGURATION WILL VARY FROM THOSE SHOWN. THE CONTRACTOR




LEGEND:

ELEVATION SHOWN ON THIS PLAN


NORTH AND SOUTH **ELEVATIONS**

DRAWING NO. Lindberg




CHIMNEY AND PARAPET ELEVATION

SCALE: NOT TO SCALE



CHIMNEY AND PARAPET ELEVATION

SCALE: NOT TO SCALE



CHIMNEY AND PARAPET ELEVATION
SCALE: NOT TO SCALE

ELEVATION NOTES

- 1. THE ELEVATIONS ARE PROVIDED TO SHOW APPROXIMATE QUANTITIES AND CONFIGURATIONS. THE ACTUAL SIZES AND CONFIGURATION WILL VARY FROM THOSE SHOWN. THE CONTRACTOR SHALL BASE THE BID AND CONTRACT AMOUNTS ON ACTUAL FIELD CONDITIONS.
- GRAPHIC HATCHING AND SYMBOLS ARE USED ON THE ELEVATION DRAWINGS TO INDICATE AREAS INCLUDED IN THE SCOPE OF WORK. ACTUAL DIMENSIONS AND QUANTITIES SHALL BE FIELD VERIFIED. REFER TO THE LEGEND ON THIS SHEET FOR THE CORRESPONDING SCOPE OF WORK ASSOCIATED WITH A PARTICULAR HATCH OR SYMBOL.
- 3. CONTRACTOR IS RESPONSIBLE FOR DESTROYING AND REMOVING BEES/HORNETS/WASPS.
- 4. HATCH PATTERNS ARE FOR REPRESENTATION ONLY AND SHOULD NOT BE USED AS A MEANS FOR QUANTIFYING.
- THE PHOTOGRAPHS USED ON THIS SHEET ARE INTENDED TO REPRESENT THE EXISTING CONDITIONS. THE PHOTOGRAPHS MAY BE SLIGHTLY SKEWED AND ARE NOT TO SCALE. REFER TO SHEET A101 FOR OVERALL BUILDING DIMENSIONS.

REPAIR LEGEND

MASONRY

- AS # ATMOSPHERIC STAINING TO BE CLEANED; # INDICATES SQUARE FEET
 - EFFLORESCENCE TO BE CLEANED; DM # INDICATES SQUARE FEET #
- RS RUST STAIN TO BE CLEANED; # INDICATES SQUARE FEET
- CB CRACKED BRICK TO BE REPLACED; # INDICATES UNITS
- DB DISPLACED BRICK TO BE REPLACED; #INDICATES LINEAR FEET
- DETERIORATED MORTAR JOINT TO BE REPAIRED, REFER TO DETAIL 2/A701; # INDICATES LINEAR FEET
- DETERIORATED MORTAR JOINT TO BE REPAIRED, REFER TO DETAIL 2/A701; # INDICATES SQUARE FEET
- SPALLED BRICK TO BE REPLACED;
 # INDICATES UNITS
- EXISTING ANCHOR / METAL STUB TO BE REMOVED AND PATCHED
- STEP CRACK TO BE REPAIRED;
 # INDICATES LINEAR FEET

 BRICK MASONRY TO BE REBUILT


SEALANT CONCRETE/STONE

- FS FAILED SEALANT TO BE REPAIRED, REFER TO DETAIL 5/A701; # INDICATES LINEAR FEET
- PS FAILED PERIMETER SEALANT TO BE REPAIRED, REFER TO DETAIL 5/A701; # INDICATES LINEAR FEET
- CRACKED CONCRETE TO BE
 REPAIRED, REFER TO DETAIL 3/A701;
 # INDICATES LINEAR FEET
- SPALLED CONCRETE TO BE
 REPAIRED, REFER TO DETAIL 4/A701;
 # INDICATES SQUARE FEET
- CRACKED STUCCO TO BE REPAIRED,
 REFER TO DETAIL 3/A701;
 # INDICATES LINEAR FEET

NOTE: NOT ALL DEFECTS IN THE LEGEND ARE SHOWN ON THIS SHEET.

KEY PLAN

TRUE



LEGEND:

ELEVATION SHOWN ON THIS PLAN



Gale Associates, Inc. Engineers and Planners

5 Moulton Street Portland, ME 04101 P 207.536.1092 www.gainc.com

This drawing and the design and construction features disclosed are proprietary to Gale Associates, Inc. and shall not be altered or

reused in whole or part without the express written permission of Gale Associates, Inc. Copyright©2021

Boston Baltimore Orlando Hartford Manchester Portland

FOR CONSTRUCTION

ILDING ENVELOPE REPAIRS
AT THE IF&W BUILDING
DIX PSYCHIATRIC CENTER CAMPUS
BANGOR, ME 04401

OWNER

HARRIMAN ASSOCIATES
80 EXCHANGE STREET, 3RD FLOOR

NO. DATE DESCRIPTION BY
PROJECT NO. 839940
CADD FILE 839940 A200's IF&V
DESIGNED BY JVL
DRAWN BY JVL
CHECKED BY ACP/CM/JFL

BUIL


DRAWING SCALE NOT TO SCALE

GRAPHIC SCALE

12/4/2023


SHEET TITLE

CHIMNEY AND PARAPET ELEVATIONS





Es CENSULATION THE PROPERTY OF THE PROPERTY OF

- CONTRACTOR TO TEMPORARILY REMOVE, STORE, AND REINSTALL ANTENNA AS REQUIRED TO PERFORM MASONRY REPAIR WORK.




CHIMNEY ELEVATION A204 SCALE: NOT TO SCALE





CHIMNEY ELEVATION A204 SCALE: NOT TO SCALE



ELEVATION NOTES

- THE ELEVATIONS ARE PROVIDED TO SHOW APPROXIMATE QUANTITIES AND CONFIGURATIONS. THE ACTUAL SIZES AND CONFIGURATION WILL VARY FROM THOSE SHOWN. THE CONTRACTOR SHALL BASE THE BID AND CONTRACT AMOUNTS ON ACTUAL FIELD CONDITIONS.
- GRAPHIC HATCHING AND SYMBOLS ARE USED ON THE ELEVATION DRAWINGS TO INDICATE AREAS INCLUDED IN THE SCOPE OF WORK. ACTUAL DIMENSIONS AND QUANTITIES SHALL BE FIELD VERIFIED. REFER TO THE LEGEND ON THIS SHEET FOR THE CORRESPONDING SCOPE OF WORK ASSOCIATED WITH A PARTICULAR HATCH OR SYMBOL.
- CONTRACTOR IS RESPONSIBLE FOR DESTROYING AND REMOVING BEES/HORNETS/WASPS.
- HATCH PATTERNS ARE FOR REPRESENTATION ONLY AND SHOULD NOT BE USED AS A MEANS FOR QUANTIFYING.
- THE PHOTOGRAPHS USED ON THIS SHEET ARE INTENDED TO REPRESENT THE EXISTING CONDITIONS. THE PHOTOGRAPHS MAY BE SLIGHTLY SKEWED AND ARE NOT TO SCALE. REFER TO SHEET A101 FOR OVERALL BUILDING DIMENSIONS.

REPAIR LEGEND

MASONRY


- ATMOSPHERIC STAINING TO BE CLEANED; # INDICATES SQUARE FEET
 - EFFLORESCENCE TO BE CLEANED; # INDICATES SQUARE FEET
- RUST STAIN TO BE CLEANED; # INDICATES SQUARE FEET
- CRACKED BRICK TO BE REPLACED; # INDICATES UNITS
- DISPLACED BRICK TO BE REPLACED; #INDICATES LINEAR FEET
- DETERIORATED MORTAR JOINT TO BE REPAIRED, REFER TO DETAIL 2/A701; # INDICATES LINEAR FEET
- DETERIORATED MORTAR JOINT TO BE REPAIRED, REFER TO DETAIL 2/A701; # INDICATES SQUARE FEET
- SPALLED BRICK TO BE REPLACED; # INDICATES UNITS
- EXISTING ANCHOR / METAL STUB TO BE REMOVED AND PATCHED
- STEP CRACK TO BE REPAIRED; # INDICATES LINEAR FEET
- BRICK MASONRY TO BE REBUILT

SEALANT

FS FAILED SEALANT TO BE REPAIRED, REFER TO DETAIL 5/A701; # INDICATES LINEAR FEET

- PS FAILED PERIMETER SEALANT TO BE REPAIRED, REFER TO DETAIL 5/A701; # # INDICATES LINEAR FEET
- CRACKED CONCRETE TO BE REPAIRED, REFER TO DETAIL 3/A701; # INDICATES LINEAR FEET
- SPALLED CONCRETE TO BE REPAIRED, REFER TO DETAIL 4/A701; # INDICATES SQUARE FEET
- CRACKED STUCCO TO BE REPAIRED, REFER TO DETAIL 3/A701; # INDICATES LINEAR FEET

CONCRETE/STONE



LEGEND:

ELEVATION SHOWN ON THIS PLAN



Gale Associates, Inc. Engineers and Planners

5 Moulton Street Portland, ME 04101 P 207.536.1092 www.gainc.com

This drawing and the design and construction features disclosed are proprietary to Gale Associates, Inc. and shall not be altered or reused in whole or part without the express written permission of Gale Associates, Inc.
Copyright©2021

Boston Baltimore Orlando Hartford Manchester Portland

REPAIRS DING CENTER (ILDING EN AT THE I DIX PSY(BANG(

BUIL


 \triangleleft

DOROTI DESCRIPTION NO. DATE PROJECT NO. 839940 CADD FILE 839940 A200's IF&V DESIGNED BY JVL


JVL DRAWN BY ACP/CM/JFL CHECKED BY 12/4/2023 DRAWING SCALE NOT TO SCALE **GRAPHIC SCALE**

SHEET TITLE


CHIMNEY **ELEVATIONS**




CHIMNEY AND PARAPET ELEVATION



CHIMNEY AND PARAPET ELEVATION A205 SCALE: NOT TO SCALE



CHIMNEY AND PARAPET ELEVATION SCALE: NOT TO SCALE



CHIMNEY AND PARAPET ELEVATION SCALE: NOT TO SCALE



- THE ELEVATIONS ARE PROVIDED TO SHOW APPROXIMATE QUANTITIES AND CONFIGURATIONS. THE ACTUAL SIZES AND CONFIGURATION WILL VARY FROM THOSE SHOWN. THE CONTRACTOR SHALL BASE THE BID AND CONTRACT AMOUNTS ON ACTUAL FIELD CONDITIONS
- GRAPHIC HATCHING AND SYMBOLS ARE USED ON THE ELEVATION DRAWINGS TO INDICATE AREAS INCLUDED IN THE SCOPE OF WORK. ACTUAL DIMENSIONS AND QUANTITIES SHALL BE FIELD VERIFIED. REFER TO THE LEGEND ON THIS SHEET FOR THE CORRESPONDING SCOPE OF WORK ASSOCIATED WITH A PARTICULAR HATCH OR SYMBOL.
- CONTRACTOR IS RESPONSIBLE FOR DESTROYING AND REMOVING BEES/HORNETS/WASPS.
- 4. HATCH PATTERNS ARE FOR REPRESENTATION ONLY AND SHOULD NOT BE USED AS A MEANS FOR QUANTIFYING.
- THE PHOTOGRAPHS USED ON THIS SHEET ARE INTENDED TO REPRESENT THE EXISTING CONDITIONS. THE PHOTOGRAPHS MAY BE SLIGHTLY SKEWED AND ARE NOT TO SCALE. REFER TO SHEET A101 FOR OVERALL BUILDING DIMENSIONS.

REPAIR LEGEND

MASONRY

- ATMOSPHERIC STAINING TO BE CLEANED; # INDICATES SQUARE FEET
- DETERIORATED MORTAR JOINT TO BE REPAIRED, REFER TO DETAIL 2/A701; # INDICATES LINEAR FEET
- EFFLORESCENCE TO BE CLEANED; # INDICATES SQUARE FEET
- DETERIORATED MORTAR JOINT TO BE REPAIRED, REFER TO DETAIL 2/A701; # INDICATES SQUARE FEET
- RUST STAIN TO BE CLEANED; # INDICATES SQUARE FEET
- SPALLED BRICK TO BE REPLACED; # INDICATES UNITS EXISTING ANCHOR / METAL STUB TO BE REMOVED AND PATCHED
- CRACKED BRICK TO BE REPLACED; # INDICATES UNITS DISPLACED BRICK TO BE REPLACED; #INDICATES LINEAR FEET
- STEP CRACK TO BE REPAIRED; # INDICATES LINEAR FEET

CONCRETE/STONE

BRICK MASONRY TO BE REBUILT

SEALANT


FS FAILED SEALANT TO BE REPAIRED, REFER TO DETAIL 5/A701; # INDICATES LINEAR FEET

- CRACKED CONCRETE TO BE REPAIRED, REFER TO DETAIL 3/A701; # INDICATES LINEAR FEET
- FAILED PERIMETER SEALANT TO BE REPAIRED, REFER TO DETAIL 5/A701; # INDICATES LINEAR FEET
- SPALLED CONCRETE TO BE REPAIRED, REFER TO DETAIL 4/A701; # INDICATES SQUARE FEET
 - CRACKED STUCCO TO BE REPAIRED, REFER TO DETAIL 3/A701; # INDICATES LINEAR FEET

NOTE: NOT ALL DEFECTS IN THE LEGEND ARE SHOWN ON THIS SHEET.

KEY PLAN

NOT TO SCALE



LEGEND:

ELEVATION SHOWN ON THIS PLAN



Gale Associates, Inc. Engineers and Planners

5 Moulton Street Portland, ME 04101 P 207.536.1092 www.gainc.com

Boston Baltimore Orlando Hartford Manchester Portland This drawing and the design and construction

features disclosed are proprietary to Gale Associates, Inc. and shall not be altered or reused in whole or part without the express written permission of Gale Associates, Inc. Copyright@2021

ORO.


NO. DATE DESCRIPTION PROJECT NO. 839940 CADD FILE 839940 A200's IF&V **DESIGNED BY** JVL DRAWN BY JVL CHECKED BY ACP/CM/JFL

12/4/2023 DRAWING SCALE NOT TO SCALE **GRAPHIC SCALE**

DATE

SHEET TITLE CHIMNEY

AND PARAPET **ELEVATIONS**












ELEVATION NOTES

- THE ELEVATIONS ARE PROVIDED TO SHOW APPROXIMATE QUANTITIES AND CONFIGURATIONS. THE ACTUAL SIZES AND CONFIGURATION WILL VARY FROM THOSE SHOWN. THE CONTRACTOR SHALL BASE THE BID AND CONTRACT AMOUNTS ON ACTUAL FIELD CONDITIONS.
- GRAPHIC HATCHING AND SYMBOLS ARE USED ON THE ELEVATION DRAWINGS TO INDICATE
 AREAS INCLUDED IN THE SCOPE OF WORK. ACTUAL DIMENSIONS AND QUANTITIES SHALL BE
 FIELD VERIFIED. REFER TO THE LEGEND ON THIS SHEET FOR THE CORRESPONDING SCOPE OF
 WORK ASSOCIATED WITH A PARTICULAR HATCH OR SYMBOL.
- 3. CONTRACTOR IS RESPONSIBLE FOR DESTROYING AND REMOVING BEES/HORNETS/WASPS.
- HATCH PATTERNS ARE FOR REPRESENTATION ONLY AND SHOULD NOT BE USED AS A MEANS FOR QUANTIFYING.
- THE PHOTOGRAPHS USED ON THIS SHEET ARE INTENDED TO REPRESENT THE EXISTING CONDITIONS. THE PHOTOGRAPHS MAY BE SLIGHTLY SKEWED AND ARE NOT TO SCALE. REFER TO SHEET A101 FOR OVERALL BUILDING DIMENSIONS.





Gale Associates, Inc. Engineers and Planners

5 Moulton Street Portland, ME 04101 P 207.536.1092

www.gainc.com

Boston Baltimore Orlando Hartford

Manchester Portland

This drawing and the design and construct

This drawing and the design and construction features disclosed are proprietary to Gale Associates, Inc. and shall not be altered or reused in whole or part without the express written permission of Gale Associates, Inc.

Copyright©2021

FOR CONSTRUCTION

BUILDING ENVELOPE REPAIRS
AT THE IF&W BUILDING
DOROTHEA DIX PSYCHIATRIC CENTER CAMPI
BANGOR, ME 04401

OWNER


HARRIMAN ASSOCIATES
80 EXCHANGE STREET, 3RD FLOOR


			2	-
			2	
NO.	DATE	D	ESCRIPTION	В
PROJECT NO.			839940	
CADD FILE			839940 A200's IF8	
DESIGNED BY			JVL	
DRAWN BY			JVL	
CHECKED BY			ACP/CM/JFL	
DATE			12/4/2023	
DRAWING SCALE			NOT TO SCALE	

GRAPHIC SCALE

SHEET TITLE

ELEVATIONS





MORTAR COLOR VARIES ACROSS ELEVATION, COLOR TO BE SELECTED BY THE OWNER. COLOR PUCKS MAY BE REQUIRED FOR COMPARISON OF INDIVIDUAL AREAS BRICK MASONRY IS TO BE SPOT REPOINTED. TOOL JOINTS TO MATCH THE EXISTING SURROUNDING JOINT PROFILES. REMOVE EXISTING CEMENT MORTAR -UP TO 1" OR 3 X WIDTH, OR TO ORIGINAL SOUND MORTAR, WHICH **EVER IS GREATER** GRIND OUT NARROW LINE ALONG -THE CENTER OF JOINT. EDGES AND SIDES OF BRICK UNIT SHALL NOT BE DAMAGED DURING MORTAR GRINDING EXISTING BRICK FACING -EXISTING MORTAR -GRIND OUT NARROW LINE ALONG THE CENTER OF JOINT. EDGES AND SIDES OF BRICK UNIT SHALL NOT BE DAMAGED DURING MORTAR GRINDING. REMOVE EXISTING CEMENT MORTAR UP TO 1" OR 3 X WIDTH, OR TO ORIGINAL SOUND MORTAR, WHICH **EVER IS GREATER** STEP 1 REMOVE EXISTING CEMENT MORTAR UP TO 1" OR 3 X WIDTH, OR TO ORIGINAL SOUND MORTAR. **EXISTING MORTAR**

EXISTING BRICK FACING

REMOVE CEMENT MORTAR FROM WIDTH OF JOINT BY CUTTING, USING HAND HELD OR LIGHT PNEUMATIC

TOOLS ONLY. REMOVE ALL MORTAR

WITHOUT DAMAGING OR REMOVING THE BRICK EDGES OR WIDENING


REMOVE EXISTING CEMENT MORTAR


UP TO 1" OR 3 X WIDTH, OR TO


ORIGINAL

SOUND MORTAR.

EXISTING BRICK FACING -APPLY PRE HYDRATED POINTING MORTAR IN 1/4" DEEP LAYERS AFTER PREVIOUS LAYER HAS BEEN TOOLED. TOOL MORTAR WHEN IT BECOMES "THUMBPRINT" HARD. MOISTEN ALL JOINTS AND ALLOW SURFACE TO DRY PRIOR TO THE APPLICATION OF THE FIRST LAYER OF MORTAR, MORTAR TO BE TOOLED WHEN "THUMBPRINT" HARD APPLY PRE HYDRATED POINTING 1/2"± MORTAR IN 1/4" DEEP LAYERS AFTER PREVIOUS LAYER HAS BEEN TOOLED. TOOL MORTAR WHEN IT BECOMES "THUMBPRINT" HARD.







CONTINUOUS SEALANT SAWCUT CRACK TO PROVIDE UNIFORM WIDTH AND DEPTH, REMOVE ALL DUST FROM CRACK PRIOR TO INSTALLING SEALANT -1/4" SAWCUT **EXISTING CONCRETE** 1/2" DEPTH BOND BREAKER TAPE EXISTING CRACK

GALE

Gale Associates, Inc.

Engineers and Planners

P 207.536.1092

www.gainc.com

5 Moulton Street Portland, ME 04101

Boston Baltimore Orlando Hartford

This drawing and the design and construction

features disclosed are proprietary to Gale

Associates, Inc. and shall not be altered or

reused in whole or part without the express written permission of Gale Associates, Inc.

Copyright@2021

Manchester Portland

REPAIR DING CENTER 4401 ILDING ENVELOPE F AT THE IF&W BUILI DIX PSYCHIATRIC (BANGOR, ME 044 BUIL

0

DESCRIPTION

839940

JVL

JVL

DRAWING SCALE | AS NOTED

GRAPHIC SCALE

SHEET TITLE

DETAILS

839940 A700s

ACP/CM/JFL

12/4/2023

NO. DATE

CADD FILE

DRAWN BY

DATE

CHECKED BY

PROJECT NO.

DESIGNED BY

1 REGLET FLASHING DETAIL TYPE

A701 SCALE: 3"=1'-0" (ALL ITEMS ARE NEW UNLESS DESIGNATED AS EXISTING)

REPAIR AREA -

CONCRETE


SUBSTRATE

(SHOWN SCHEMATIC)




TYPICAL REPOINTING DETAIL


SCALE: NOT TO SCALE (ALL ITEMS ARE NEW UNLESS DESIGNATED AS EXISTING)




GENERAL PROCEDURES FOR SPALL REPAIR

- BACK-ANGLE SAWCUT PERIMETER POLYGON SHAPE (DO NOT CUT REINFORCEMENT)
- CHIP OUT ALL DETERIORATED CONCRETE, EXTENDING 3/4" MINIMUM AROUND REBAR (OR MINIMUM AGGREGATE SIZE, IF NECESSARY: AS INDICATED IN NOTES BELOW SECTION).
- CLEAN ALL EXPOSED REINFORCING STEEL TO BARE METAL CONDITION. (SSPC - SP11).
- REMOVE ADDITIONAL SUBSTRATE TO EXPOSE AND CLEAN CORRODED STEEL WHICH HAS SCALED RUST (BARS WITH ONLY LIGHT SURFACE RUST AND SOLID CONCRETE COVER MAY BE LEFT ALONE.)
- EXAMINE REBAR AND DETERMINE SECTION LOSS. BARS WITH 25% OR GREATER LOSS SHALL RECEIVE SUPPLEMENTARY REINFORCEMENT. (REFER TO DETAIL). REMOVAL OF ADDITIONAL SOUND CONCRETÈ TO ALLOW PLACÉMENT OF SUPPLEMENTAL STEEL SHALL NOT BE INCLUDED IN SPALL REPAIR QUANTITIES. EXAMINE SUBSTRATE FOR CRACKS, REFER TO CRACK REPAIR AS
- SCARIFY SUBSTRATE TO 1/8" MINIMUM SURFACE PROFILE (ICRI-CSP 8 OR 9). WASH SUBSTRATE AND LEAVE SSD (SATURATED SURFACE DRY) CONDITION.
- APPLY EPOXY MODIFIED CEMENTITIOUS PRIMER/ BOND AGENT TO ALL CONCRETE SUBSTRATE (1 COAT) AND EMBEDDED STEEL OR REBAR (2 COATS).
- AT VERTICAL SPALLS WITH A DEPTH GREATER THAN 1-1/2", DRILL AND EPOXY 1/4" MIN. DIAMETER STAINLESS STEEL PINS INTO SUBSTRATE OF REPAIR AREA. MAINTAIN 2" MIN. EDGE DISTANCE FOR EACH PIN. SPACE PINS 6" O.C. EACH WAY. DRAPE PINS WITH 2" x 2"x 14 (MIN.) GAUGE STAINLESS STEEL OR EPOXY COATED WIRE MESH WITH 1-1/2" COVER. MESH IS REQUIRED AT EACH 1-1/2" DEPTH OF REPAIR. TIE ALL MESH TO EACH PIN. PINNING IS ALSO REQUIRED AT CORNER AND PANEL PERIMETER SPALL REPAIRS, REGARDLESS OF SPALL DEPTH.
- PREPARE SAMPLE OF REPAIR MORTAR FOR APPROVAL OF COLOR. ADJUST MIX UNTIL COLOR IS ACCEPTABLE. APPLY SPECIFIED REPAIR MORTAR AFTER BONDING AGENT TO ACHIEVE A "WET-ON-WET" APPLICATION.
- WHERE CORRODED STEEL IS EVIDENT, OR WHEN MORE THAN HALF OF THE REBAR DIAMETER IS EXPOSED, SUBSTRATE SHALL BE CHIPPED 3/4" MINIMUM TO 1-1/2" MAXIMUM BEHIND REBAR.
- CONCRETE SECTION SHOWN SCHEMATICALLY.













TYPICAL SEALANT JOINTS SCALE: NOT TO SCALE (ALL ITEMS ARE NEW UNLESS DESIGNATED AS EXISTING)



TYPICAL ROUT AND SEAL DETAIL

(ALL ITEMS ARE NEW UNLESS DESIGNATED AS EXISTING)

SCALE: NOT TO SCALE




MATE OF MA. Lindberg


DRAWING NO.

TYPICAL SPALL REPAIR SCALE: NOT TO SCALE (ALL ITEMS ARE NEW UNLESS DESIGNATED AS EXISTING) TYPICAL CONCRETE STAIR TREAD REPAIR

A701 SCALE: 3"=1'-0" (ALL ITEMS ARE NEW UNLESS DESIGNATED AS EXISTING)



THIS DETAIL SHALL BE UTILIZED AT ALL EMBEDDED RAIL BASE PENETRATIONS.



TYPICAL RAILING BASE REPAIR

GALE

Gale Associates, Inc. Engineers and Planners

5 Moulton Street Portland, ME 04101 P 207.536.1092

www.gainc.com Boston Baltimore Orlando Hartford Manchester Portland

This drawing and the design and construction features disclosed are proprietary to Gale Associates, Inc. and shall not be altered or reused in whole or part without the express written permission of Gale Associates, Inc. Copyright©2021

CAMPU! AT THE IF&W BUILDING
A DIX PSYCHIATRIC CENTER C
BANGOR, ME 04401

OROT NO. DATE DESCRIPTION

BOI

PROJECT NO. CADD FILE 839940 A700s **DESIGNED BY** JVL DRAWN BY JVL ACP/CM/JFL CHECKED BY 12/4/2023

DRAWING SCALE | AS NOTED **GRAPHIC SCALE**

SHEET TITLE

DETAILS

