




**SYMBOL KEY**

|                                                  |               |             |                     |              |                |                                  |
|--------------------------------------------------|---------------|-------------|---------------------|--------------|----------------|----------------------------------|
| Flow Field Boundary                              | Stream        | Storm Sewer | Shallow Groundwater | Plant        | Stream Gage    | Shallow Bedrock Groundwater Well |
| Potential Aqueous Film Forming Foam Release Area | Surface Water | Flow Meter  | Sediment            | Invertebrate | Lysimeter      | Deep Bedrock Groundwater Well    |
| Former Installation Boundary                     |               | Porewater   | Hydric Soil         | Rodent       | Soil           | Overburden Groundwater Well      |
|                                                  |               |             | Surface Water       | Fish         | Drinking Water |                                  |

**Air Force Civil Engineer Center**  
2261 Hughes Ave., Suite 163  
JBSA Lackland, TX 78236

**Remedial Investigation Data Collection Summary**  
Remedial Investigation Site Characterization Summary Report  
Former Loring Air Force Base, Limestone, ME

**SOURCES:**  
Aerial Imagery obtained from NADP, USDA-FSA  
Published September, 2021

**Drawn:**  
AFA  
1/7/2026

**Checked:**  
MEG  
1/12/2026

**PROJ:** 775361701