Stiffening Girders on West Side of Bridge.

Diagram giving ordinates and dimensions of girders on Vertical Curve, for assembling girders in Shop, for reaming of holes at Splices.

Stiffening Girders on East Side of Bridge.

Ordinates and dimensions same as given above for Girders on West Side.

Shop Note! Stiffening Girder for reaming of less than four Marks at Stiffeni and P3.