

Brownfield

This report shows the 2017-2019 Work Plan entries for Brownfield. The costs listed are the total cost of these projects – some of which may extend into neighboring towns. It also shows a listing of maintenance work specifically recorded to Brownfield in 2016, as well as any 2016 Local Road Assistance payments. Activities that are managed on a larger scale, such as snow & ice control, and maintenance work done by contract are not listed. The maintenance accomplishments may also extend into neighboring towns, but are listed in the first town where the work was reported. Finally, any capital projects that were completed in 2016 are also listed.

Planned Capital and Maintenance Work 2017-2019

Work Plan Year: 2017

Municipalities(s): Baldwin, Bridgton, Brownfield, Cornish, Hiram, Hollis, Limington, Porter, Sebago, Standish, Waterboro

Asset(s): Route 107, Route 11, Plains Road, Route 114, South Hiram Road, Route 160, Route 117

Description: Baldwin Area 2017 LCP.

ID	Scope of Work	Highway Corridor Priority	Estimated Funding
024001.00	Light Capital Paving	Varies	\$1,265,100

Work Plan Year: 2017

Municipalities(s): Brownfield

Asset(s): River Road

Description: Bridge Improvement Seavey Bridge (No. 5485)

ID	Scope of Work	Highway Corridor Priority	Estimated Funding
WR 33365	Maintenance	Corridor 5	\$10,000

Local Road Assistance – Fiscal Year 2016

\$51,328

Maintenance Accomplishments – 2016

Activities managed on a larger scale, such as snow & ice control, and work done by contract are not listed. *The maintenance accomplishments may extend into neighboring towns, but are listed in the first town where the work was reported.*

- 4.0 Bridge(s) Washed
- 5,885.4 Ton(s) of Hot Mix Paving
- 3.0 Drainage Structures Repaired
- 180.0 Linear Feet of Guardrail or Fence Maintained
- 6.0 Bridge(s) Cleaned
- 3.0 Bridge(s) Sealed
- 9.0 Mile(s) of Shoulder Graded
- 1.0 Emergency Event Responses
- 68.0 Center Lane Mile(s) Patrolling and Inspecting
- 29.1 Miles of Striping Applied
- 1.0 Drainage Structures Installed or Replaced
- 10.0 Linear Feet of Bridge Rail Repaired or Replaced
- 24.0 Mile(s) of Shoulder prepared for LCP
- 160.0 Sq Feet of Pavement Legend Applied
- 50.0 Trees Removed
- 17,325.0 Linear Feet of Brush Removed
- 1.0 Bridge Inspection(s) Performed
- 240.0 Linear Feet of Shoulder Rebuilt
- 42,080.0 Linear Feet of Grader Ditching

Completed Capital Projects – 2016

022667.00	DENMARK, ROUTE 160 Beginning at Brownfield town line and extending easterly 3.04 miles.
022072.00	HIRAM - FRYEBURG Fog Seal
018601.00	DENMARK AREA 2016 LCP DENMARK AREA 2016 LCP