

Byron

This report shows the 2017-2019 Work Plan entries for Byron. The costs listed are the total cost of these projects – some of which may extend into neighboring towns. It also shows a listing of maintenance work specifically recorded to Byron in 2016, as well as any 2016 Local Road Assistance payments. Activities that are managed on a larger scale, such as snow & ice control, and maintenance work done by contract are not listed. The maintenance accomplishments may also extend into neighboring towns, but are listed in the first town where the work was reported. Finally, any capital projects that were completed in 2016 are also listed.

Planned Capital and Maintenance Work 2017-2019

Work Plan Year: 2017

Municipalities(s): Byron

Asset(s): Byron Village Road

Description: Coos Bridge (No.2176) over Swift River. Located 0.06 of a mile northeast of Route 17.

ID	Scope of Work	Highway Corridor	Priority	Estimated Funding
021668.00	Bridge Superstructure Replacement	6		\$1,000,000

Local Road Assistance – Fiscal Year 2016

\$7,692

Maintenance Accomplishments – 2016

Activities managed on a larger scale, such as snow & ice control, and work done by contract are not listed. *The maintenance accomplishments may extend into neighboring towns, but are listed in the first town where the work was reported.*

- 6.8 Mile(s) of Shoulder Graded
- 1.0 Emergency Event Responses
- 3.0 Trees Removed
- 350.0 Linear Feet of Brush Removed
- 35.0 Linear Feet of Shoulder Rebuilt
- 271.2 Center Lane Mile(s) Patrolling and Inspecting
 - 1.0 Channel(s) Maintained
- 60.3 Ton(s) of Cold Patch Applied
- 0.5 Shoulder Miles of Herbicide Applied
- 6.0 Bridge(s) Washed
- 13.1 Miles of Striping Applied
- 26.0 Linear Feet of Guardrail or Fence Maintained
- 3.0 Drainage Structures Installed or Replaced
- 490.0 Sq Feet of Bridge Painting
 - 1.0 Bridge Inspection(s) Performed
- 14.0 Minor Sign(s) Installed or Maintained
- 66.0 Linear Feet of Bridge Joints Repaired or Replaced
- 47,548.0 Linear Feet of Grader Ditching
 - 1.0 Bridge(s) Sealed
- 36.1 Shoulder Miles of Sweeping
- 52.0 Linear Feet of Bridge/Main Support Members Replaced or Repaired