

## Kingsbury Plt

This report shows the 2017-2019 Work Plan entries for Kingsbury Plt. The costs listed are the total cost of these projects – some of which may extend into neighboring towns. It also shows a listing of maintenance work specifically recorded to Kingsbury Plt in 2016, as well as any 2016 Local Road Assistance payments. Activities that are managed on a larger scale, such as snow & ice control, and maintenance work done by contract are not listed. The maintenance accomplishments may also extend into neighboring towns, but are listed in the first town where the work was reported. Finally, any capital projects that were completed in 2016 are also listed.

### Planned Capital and Maintenance Work 2017-2019

**Work Plan Year:** 2017

**Municipalities(s):** Athan, Bingham, Brighton Plt, Cambridge, Canaan, Corinna, Cornville, Dexter, Harmony, Hartland, Kingsbury Plt, Madison, Mayfield Twp, Moscow, Palmyra, Ripley, Saint Albans, Skowhegan, Wellington

**Asset(s):** White Schoolhouse Road, St. Albans Road, Route 23, Palmyra Road, West Ridge Road, Route 154, Parkman

**Description:** Athens Area 2017 LCP.

ID	Scope of Work	Highway Corridor Priority	Estimated Funding
024008.00	Light Capital Paving	Varies	\$3,758,500

**Work Plan Year:** 2018/19

**Municipalities(s):** Kingsbury Plt

**Asset(s):** Route 16

**Description:** Large culvert (No.46502) located 0.22 of a mile east of the Mayfield Twp town line.

ID	Scope of Work	Highway Corridor Priority	Estimated Funding
021794.00	Large Culvert Replacement	4	\$200,000

### Local Road Assistance – Fiscal Year 2016

\$4,448

### Maintenance Accomplishments – 2016

Activities managed on a larger scale, such as snow & ice control, and work done by contract are not listed. *The maintenance accomplishments may extend into neighboring towns, but are listed in the first town where the work was reported.*

- 148.3 Center Lane Mile(s) Patrolling and Inspecting
- 14.0 Trees Removed
- 480.0 Linear Feet of Brush Removed
- 3.0 Emergency Event Responses
- 3.0 Sq Feet of Bridge Wearing Surface Repaired
- 35.0 Shoulder Miles of Sweeping
- 25.0 Shoulder Miles of Mowing
- 22.2 Mile(s) of Shoulder Graded
- 3.0 Bridge Inspection(s) Performed
- 42.5 Ton(s) of Cold Patch Applied