

New Sharon

This report shows the 2017-2019 Work Plan entries for New Sharon. The costs listed are the total cost of these projects – some of which may extend into neighboring towns. It also shows a listing of maintenance work specifically recorded to New Sharon in 2016, as well as any 2016 Local Road Assistance payments. Activities that are managed on a larger scale, such as snow & ice control, and maintenance work done by contract are not listed. The maintenance accomplishments may also extend into neighboring towns, but are listed in the first town where the work was reported. Finally, any capital projects that were completed in 2016 are also listed.

Planned Capital and Maintenance Work 2017-2019

Work Plan Year: 2018/19

Municipalities(s): New Sharon

Asset(s): Route 2

Description: Located 1.57 miles west of Route 134.

ID	Scope of Work	Highway Corridor Priority	Estimated Funding
019178.10	Bridge Culvert Replacement	1	\$580,000

Work Plan Year: 2018/19

Municipalities(s): New Sharon

Asset(s): Route 27

Description: Large culvert (No.47113) located 0.55 of a mile northwest of the York Hill Road.

ID	Scope of Work	Highway Corridor Priority	Estimated Funding
022934.00	Large Culvert Replacement	2	\$120,000

Local Road Assistance – Fiscal Year 2016

\$43,680

Maintenance Accomplishments – 2016

Activities managed on a larger scale, such as snow & ice control, and work done by contract are not listed. *The maintenance accomplishments may extend into neighboring towns, but are listed in the first town where the work was reported.*

- 1,204.0 Ton(s) of Cold Patch Applied
- 812.0 Linear Feet of Backhoe Ditching
- 2.0 Underwater Inspection(s) Performed
- 72.0 Linear Feet of Guardrail or Fence Maintained
- 1,500.0 Linear Feet of Grader Ditching
- 7.0 Shoulder Miles of Sweeping
- 33.0 Shoulder Miles of Herbicide Applied
- 32.0 Minor Sign(s) Installed or Maintained
- 1,350.0 Linear Feet of Shoulder Rebuilt
- 3.0 Emergency Event Responses
- 1,015.6 Center Lane Mile(s) Patrolling and Inspecting
- 16.0 Linear Feet of Bridge Joints Repaired or Replaced
- 6.0 Bridge(s) Washed
- 24.6 Miles of Striping Applied
- 26.2 Shoulder Miles of Mowing
- 2.5 Ton(s) of Cold Patch Applied
- 4.0 Trees Removed