

Stockton Springs

This report shows the 2017-2019 Work Plan entries for Stockton Springs. The costs listed are the total cost of these projects – some of which may extend into neighboring towns. It also shows a listing of maintenance work specifically recorded to Stockton Springs in 2016, as well as any 2016 Local Road Assistance payments. Activities that are managed on a larger scale, such as snow & ice control, and maintenance work done by contract are not listed. The maintenance accomplishments may also extend into neighboring towns, but are listed in the first town where the work was reported. Finally, any capital projects that were completed in 2016 are also listed.

Planned Capital and Maintenance Work 2017-2019

Work Plan Year: 2017

Municipalities(s): Stockton Springs

Asset(s): Cape Jellison Road

Description: Cape Jellison Bridge (No.3176) over Tidal Inlet. Located 1.02 miles south of Main Street.

ID	Scope of Work	Highway Corridor	Priority	Estimated Funding
016665.00	Bridge Superstructure Replacement	6		\$400,000

Work Plan Year: 2017

Municipalities(s): Stockton Springs

Asset(s): Route 1

Description: Large culvert (No.94451) located 0.52 of a mile west of Denslow Road.

ID	Scope of Work	Highway Corridor	Priority	Estimated Funding
018852.00	Large Culvert Replacement	1		\$405,000

Work Plan Year: 2017

Municipalities(s): Stockton Springs

Asset(s): Main Street, Cape Jellison Road

Description: 71228 Ditching Stockton Springs

ID	Scope of Work	Highway Corridor	Priority	Estimated Funding
WR 33609	Maintenance	Corridor 4, Corridor 5		\$13,000

Work Plan Year: 2017

Municipalities(s): Belfast, Prospect, Stockton Springs

Asset(s): Route 1

Description: 71228 RT 1 Guard Rail Cleaning and culvert repair

ID	Scope of Work	Highway Corridor	Priority	Estimated Funding
WR 33071	Maintenance	Corridor 1		\$18,000

Work Plan Year: 2018/19

Municipalities(s): Searsport, Stockton Springs

Asset(s): Route 1

Description: Beginning 0.13 of a mile northeast of Trundy Road and extending northeasterly 4.43 miles.

ID	Scope of Work	Highway Corridor	Priority	Estimated Funding
022468.00	1 1/4" Overlay	1		\$1,787,300

Work Plan Year: 2018/19

Municipalities(s): Stockton Springs

Asset(s): Route 1

Description: Large culvert (No.94441) located 0.09 of a mile north of Muskrat Farm Road.

ID	Scope of Work	Highway Corridor	Priority	Estimated Funding
021831.00	Large Culvert Replacement	1		\$1,275,000

Local Road Assistance – Fiscal Year 2016

\$34,632

Maintenance Accomplishments – 2016

Activities managed on a larger scale, such as snow & ice control, and work done by contract are not listed. *The maintenance accomplishments may extend into neighboring towns, but are listed in the first town where the work was reported.*

- 975.0 Linear Feet of Shoulder Rebuilt
 - 320.0 Center Lane Mile(s) Patrolling and Inspecting
 - 2.0 Drainage Structures Cleaned
 - 53.6 Miles of Striping Applied
 - 511.0 Sq Feet of Pavement Legend Applied
 - 1.0 Trees Removed
 - 54.0 Shoulder Miles of Sweeping
 - 1.0 Bridge(s) Cleaned
 - 3,725.0 Linear Feet of Backhoe Ditching
 - 2.0 Bridge(s) Washed
 - 9.5 Ton(s) of Cold Patch Applied
 - 9.0 Drainage Structures Installed or Replaced
 - 37.2 Shoulder Miles of Mowing
 - 50.0 Linear Feet of Guardrail or Fence Maintained
 - 1.0 Emergency Event Responses
 - 34.0 Shoulder Miles of Litter and Debris Removal
-