

Temple

This report shows the 2017-2019 Work Plan entries for Temple. The costs listed are the total cost of these projects – some of which may extend into neighboring towns. It also shows a listing of maintenance work specifically recorded to Temple in 2016, as well as any 2016 Local Road Assistance payments. Activities that are managed on a larger scale, such as snow & ice control, and maintenance work done by contract are not listed. The maintenance accomplishments may also extend into neighboring towns, but are listed in the first town where the work was reported. Finally, any capital projects that were completed in 2016 are also listed.

Planned Capital and Maintenance Work 2017-2019

Work Plan Year: 2017

Municipalities(s): Farmington, Temple

Asset(s): Route 43

Description: 71304 - WP 17 Ditching on Route 43 Temple Road

ID	Scope of Work	Highway Corridor Priority	Estimated Funding
WR 33013	Maintenance	Corridor 5	\$134,000

Work Plan Year: 2018/19

Municipalities(s): Temple

Asset(s): Day Mountain Road

Description: Blodgett Bridge (No.3974) over Temple Stream. Located 0.06 of a mile north of Intervale Road.

ID	Scope of Work	Highway Corridor Priority	Estimated Funding
018953.00	Bridge Rehabilitation	6	\$400,000

Local Road Assistance – Fiscal Year 2016

\$20,516

Maintenance Accomplishments – 2016

Activities managed on a larger scale, such as snow & ice control, and work done by contract are not listed. *The maintenance accomplishments may extend into neighboring towns, but are listed in the first town where the work was reported.*

- 3.0 Bridge(s) Washed
- 15.4 Miles of Striping Applied
- 8.2 Shoulder Miles of Herbicide Applied
- 863.3 Linear Feet of Shoulder Rebuilt
- 200.0 Sq Feet of Bridge Wearing Surface Repaired
- 60.0 Sq Feet of Bridge Painting
- 4.5 Ton(s) of Cold Patch Applied
- 5.0 Mile(s) of Shoulder Graded
- 2,265.5 Linear Feet of Guardrail or Fence Maintained
- 792.5 Center Lane Mile(s) Patrolling and Inspecting
- 32.0 Shoulder Miles of Sweeping
- 2.0 Bridge Inspection(s) Performed
- 36.0 Linear Feet of Bridge Rail Repaired or Replaced