

Assessment for: Fall Line Condos@ Sunday River, ME0092005
Location: Newry
Date: June 25, 2009

Summary of the Data used in our Assessment

Well type: Drilled Well
Well identification number: 92005102
Well description: 500 Ft Drilled Well
Overburden thickness (feet): Not Known
Positive bacteria test result(s): Yes
Nitrate test result(s) greater than 5 ppm: No
Septic system(s) within 300 feet of the well: No
Animal feedlots/manure piles(s) within 300 feet of the well: No

Risk Based on Well Type and Site Geology

Ranking:

Well type: Drilled Well
Overburden thickness (feet): Unknown

*Existing risk of contamination
based on well type & site geology:*

Moderate risk

Existing Risk of Acute Contamination

Ranking:

Positive coliform test(s): Yes
Nitrate test(s) greater than 5 ppm: No
Septic system(s) within 300 feet of the well: No
Animal feedlot(s)/manure pile(s) within 300 feet of the well: No

Existing risk of acute contamination:

High risk

Future Risk for Acute Contamination

Ranking:

Status of land control: *The owner owns the land within 300 ft of the well. The well head protection radius is 700 ft.*

Future risk of acute contamination:

Low risk