



JUNIPER RIDGE LANDFILL

**Operated By
NEWSME Landfill Operations, LLC**

February 11th, 2021

Mike Barden
Bureau of General Services
77 State House Station
Augusta, Maine 04333

RE: Monthly Report of Landfill Complaints

Dear Mr. Barden:

During the month of January 2021 Juniper Ridge Landfill received three complaints from area residents regarding landfill operations. All three complaints have been confirmed to be landfill related.

If you have any questions or concerns, please do not hesitate to contact me at 862-4200, ext. 221.

Sincerely,
NEWSME Landfill Operations, LLC

Wendy Plissey
Assistant Controller

enc.

JUNIPER RIDGE LANDFILL
-LANDFILL COMPLAINT RECORD FORM-
January 2021

Date	Time	Nature of Complaint	Description of Complaint	Caller	Location of Complaint	Real Time?	Wind Direction / Speed at JRL	Complaint Downwind from JRL?	Call or Site Visit Made By	Potential Odor Source?	Off-site H2S reading (if applicable)	Landfill Odor Confirmed?	Caller / Responder Comments
01/07/21	4:30 PM	Odor	Gas Smell	Roland Dupuis	159 West Old Town Road	Yes	W/0 MPH	Yes	A call back/site visit was performed by the Compliance Manager at 5:14 PM and 5:35 PM respectfully.	Landfill	3.2 ppb	Yes	The caller stated that he hadn't smelled it for a long time but it was making him sick. JRL Compliance Manager and Site Supervisor were notified. The odor was discovered to have come from the flare loosing ignition during the restart of the Thiopaq Facility.
01/08/21	4:50 PM	Odor	Trash/Gas	Laura Sanborn	I-95	Yes	W/0 MPH	Yes	A call back was performed by the Compliance Manager at 5:11 PM.	Landfill	0 ppb	Yes	Odor was confirmed by the Compliance Manager on the I-95. The Site Supervisor and General Manager were notified of the complaint. The odor was discovered to have been coming from the top of the landfill where new vacuum lines were being installed with the excavator.
01/31/21	5:25 PM	Odor	Sludge/Gas Smell	Ed Spencer	1140 Kirkland Road	Yes	NE/0 MPH	Yes	No call back or site visit was requested.	Landfill	0 ppb	Yes	Odor was confirmed by the Compliance Manager. The Site Supervisor, General Manager, and Landfill Technician were notified of the complaint. JRL staff identified several wells that lost vacuum on to of the landfill. The pipe crew was notified to help restore vacuum to those locations.

Number of Complaints Confirmed to be Landfill Related: 3

Number of Complaints Not Confirmed as Originating from landfill or Possibly from Other Sources: 0

