



RAMP REPORT REGION 2 ADA 2026

Hills to Sea Trailhead,  
Unity

CR12756

44.610304, -69.335138

Loam and seed.

Construct 4'x4' Turning Area


Crosswalk signpost

DWF 2x4

Move Crosswalk

Remove 8' bituminous curb then place new tip down.

Saw cut 2' from face of curb/gutterline. Base and repave after curb install.



CR12757

44.610398, -69.335215

Loam  
and  
seed.

4'x4'  
Turning  
area

Remove and regrade  
sidewalk.

Crosswalk  
signpost




Remove 15' bituminous  
curb then place new tip  
down.


Saw cut 2' from face of  
curb/gutterline. Base and  
repave after curb install.

DWF 2x5

Remove 15' bituminous  
curb then place new tip  
down.

Move  
Crosswalk





RAMP REPORT REGION 2 ADA 2026

Unity House of Pizza,  
Unity

CR12759

44.611465, -69.334083

Eat in Take Out

UNITY House of Pizza

Pizza & Bar

Delivery 948-3810

Remove and regrade sidewalk.

DWF 2x5

4'x4'  
Turning  
Area

Crosswalk  
signpost


Saw cut 2' from face of  
curb/gutterline. Base and  
repave after curb install.

Remove 8' bituminous  
curb then place new tip  
down.



CR12758

44.611493, -69.333909



Loam and seed.

Add bituminous curb, tip up and tip down.

Remove and regrade sidewalk.

4'x4' Turning Area

DWF 2x4

Crosswalk signpost

Saw cut 2' from face of curb/gutterline. Base and repave after curb install.



RAMP REPORT REGION 2 ADA 2026

Dunkin' Donuts,  
Unity

CR12761

44.612919, -69.332624

Remove and regrade sidewalk.

4'x4'  
Turning  
Area


Loam  
&  
Seed

Crosswalk  
signpost

DWF 2x5

Saw cut 2' from face of  
curb/gutterline. Base and  
repave after curb install.

Remove 15' bituminous  
curb then place new tip  
down.



CR12760

44.612877, -69.332506

Remove and regrade sidewalk.

Loam and seed.

4'x4'  
Turning Area

Crosswalk signpost



DWF 2x5

Saw cut 2' from face of curb/gutterline. Base and repave after curb install.

Remove 15' bituminous curb then place new tip down.



## RAMP REPORT REGION 2 ADA 2026

Ecology Learning Center,  
Unity

CR12764

44.614405, -69.331164

Remove and regrade sidewalk.

4'x4'  
Turning  
Area


DWF 2x5

Loam  
&  
Seed

Remove 15' bituminous  
curb then place new tip  
down.

Saw cut 2' from face of  
curb/gutterline. Base and  
repave after curb install.

Remove 8' bituminous  
curb then place new tip  
down.



CR12765


44.614312, -69.331003

Remove and regrade sidewalk.

4'x4'  
Turning  
Area

The design may need to be revised to ensure the pedestrian push button is located on a level landing that meets ADA/PROWAG accessibility requirements. The landing should provide a stable, and firm, surface with appropriate cross slope and running slope to allow safe and independent use by wheelchair users.

Loam  
and  
seed.



DWF 2x6

Remove 8' bituminous  
curb then place new tip  
down.

Saw cut 2' from face of  
curb/gutterline. Base and  
repave after curb install.

