



MARK	Nº READ	LOCATION	E	F	G	H	J	K	MARK	Nº READ	LOCATION	E	F	G	H	J	K
BR150-6AA	4	L7-U9	75-9 ²⁵	75-7 ²⁵	74-2 ²⁵	30-6	52-3 ³	—	BR150-6AL	4	L27-U25	69-2 ²⁵	69-8 ²⁵	68-4 ²⁵	27-6	47-1 ²⁵	—
BR150-6AB	4	L8-U10	81-6 ²⁵	81-5 ²⁵	80-4 ²⁵	13-11	39-8 ²⁵	57-0 ²⁵	BR150-6AM	4	L26-U24	75-3 ²⁵	75-9 ²⁵	74-1 ²⁵	12-3	32-8	52-3 ²⁵
BR150-6AC	4	L9-U11	82-5 ²⁵	82-7 ²⁵	81-3 ²⁵	15-6	37-2 ²⁵	65-5 ²⁵	BR150-6AN	4	L25-U23	82-0 ²⁵	82-2 ²⁵	80-10	14-0	34-1 ²⁵	60-5 ²⁵
BR150-6AD	4	L10-U13	110-2 ²⁵	125-0 ²⁵	121-8 ²⁵	17-3	48-10 ²⁵	81-2 ²⁵	BR150-6AP	4	L24-U22	114-5 ²⁵	114-7 ²⁵	113-3 ²⁵	3-8	15-0 ²⁵	75-3 ²⁵
BR150-6AE	4	L11-Tower	225-8	225-7	224-2 ²⁵	32-8	75-0 ²⁵	110-1 ²⁵	BR150-6AR	4	L23-Tower	211-7 ²⁵	211-9 ²⁵	200-3 ²⁵	30-8	63-7 ²⁵	102-3 ²⁵
BR150-6AF	4	L13-Tower	183-9 ²⁵	183-11 ²⁵	182-7 ²⁵	46-4	72-3	—	BR150-6AS	4	L21-Tower	172-3 ²⁵	172-7 ²⁵	171-2 ²⁵	42-14	67-3 ²⁵	—
BR150-6AG	4	L13-U10	96-9 ²⁵	96-11 ²⁵	95-7 ²⁵	32-8	57-1 ²⁵	82-1 ²⁵	BR150-6AT	4	L21-U24	102-3 ²⁵	102-5 ²⁵	101-2 ²⁵	42-0 ²⁵	60-9 ²⁵	86-11 ²⁵
BR150-6AH	4	L11-U9	70-6 ²⁵	70-8 ²⁵	69-3 ²⁵	17-1 ²⁵	39-3 ²⁵	57-0 ²⁵	BR150-6AU	4	L23-U25	74-4 ²⁵	74-6 ²⁵	73-2 ²⁵	18-4 ²⁵	42-8 ²⁵	60-5 ²⁵
BR150-6AJ	4	L10-U8	65-7 ²⁵	65-9 ²⁵	64-5 ²⁵	18-6 ²⁵	37-4 ²⁵	53-6 ²⁵	BR150-6AV	4	L24-U26	69-0 ²⁵	69-2 ²⁵	67-10 ²⁵	13-9 ²⁵	39-7 ²⁵	56-5 ²⁵
BR150-6AK	4	L9-U7	61-7 ²⁵	61-9 ²⁵	60-4 ²⁵	17-10 ²⁵	35-5 ²⁵	—	BR150-6AW	4	L25-U27	14-6 ²⁵	14-8 ²⁵	63-4 ²⁵	18-5 ²⁵	37-6 ²⁵	—

PAINT - sockets one stop coat red lead after socketing

lead after socketing		5-2-5	
MARK	REQ'D	MAT'L	REQ. NO.
BILL OF MATERIAL			
JOHN A. ROEBLING'S SONS CO., TRENTON, N. J.			
END	Lengths changed	3-11-44	
END	Stresses removed. Rupt. bars added	3-6-44	
END	Pin changed from 3J to 3G	3-1-44	
END	Approval Date Added	3-12-44	
BY	REVISIONS		DATE
APPROVED ROBINSON AND STEINMAN MARCH 16, 1944			
CH. DR.		SCALE	SERIAL
ENG'R.		DES. <i>BR 150 2-11-44</i>	TR.
		CH.	9

