

<b>Cementitious</b>		Latest NTPEP Testing	Min. Temperature (F)	Recertification Due:
<b>BASF Corporation</b>		<a href="http://www.master-builders-solutions.basf.us">www.master-builders-solutions.basf.us</a>		
16-005	MasterEmaco T 1060	RSCP-2013-01-003	40	1/27/2021
<b>Kaufman Products, Inc.</b>		<a href="http://www.kaufmanproducts.net">www.kaufmanproducts.net</a>		
19-047	Duracrete II VOFT	RSCP-2018-01-002	45	8/14/2024
19-048	HiCap FT	RSCP-2018-01-003	35*	8/14/2024
<b>MAPEI Corp.</b>		<a href="http://www.mapei.com">www.mapei.com</a>		
19-046	Planitop 18 TG	RSCP-2018-01-001	32*	5/7/2024
15-025	Planitop 18	RSCP-2014-01-015	32	10/23/2020
16-043	Planitop 18 ES	RSCP-2015-01-011	45	11/14/2021
<b>Phoscrete Corporation</b>		<a href="http://www.phoscrete.com">www.phoscrete.com</a>		
16-038	Phoscrete HC	RSCP-2015-01-002	-5*	11/14/2021
<b>SILPRO, LLC</b>		<a href="http://www.silpro.com">www.silpro.com</a>		
14-066	SilproRepair VOH	RSCP-2014-01-002	50	6/8/2020
14-067	SilproRapid	RSCP-2014-01-001	50	6/8/2020
<b>The QUIKRETE Companies</b>		<a href="http://www.quikrete.com">www.quikrete.com</a>		
14-077	Comm. Grd. FastSet Concrete Mix	RSCP-2013-01-009	40	2/27/2020
15-007	Comm. Grd. FastSet Concrete Mix w/ Fibers	RSCP-2013-01-010	40	6/8/2020
<b>Polymer</b>		Latest NTPEP Testing	Min. Temperature (F)	Recertification Due:
<b>Roklin Systems, Inc.</b>		<a href="http://www.roklinsystems.com">www.roklinsystems.com</a>		
14-075	Concrete Welder Gray	RSCP-2014-01-014	40	6/8/2020
14-076	Polyflex DS Gray	RSCP-2014-01-013	40	6/8/2020
<b>Polymer-Modified</b>		Latest NTPEP Testing	Min. Temperature (F)	Recertification Due:

\* Contact Manufacturer for low temperature mixing instructions.

<b>United States Gypsum Co.</b>		<a href="http://www.usg.com">www.usg.com</a>		
17-064	EcoFix Rapid Repair	RSCP-2015-01-010	32	12/28/2022
17-062	EcoFix Xtend Rapid Repair	RSCP-2016-01-008	32	12/28/2022
<b>CTS Cement Manufacturing Corp.</b>		<a href="http://www.ctscement.com">www.ctscement.com</a>		
15-035	Rapid Set DOT Concrete Mix	RSCP-2014-01-010	45	7/5/2023
<b>Dayton Superior Corporation</b>		<a href="http://www.daytonsuperior.com">www.daytonsuperior.com</a>		
95-004	HD 50	RSCP-2014-01-007	40	9/27/2021
<b>MAPEI Corp.</b>		<a href="http://www.mapei.com">www.mapei.com</a>		
19-041	Planitop X	RSCP-2015-01-012	55	5/7/2024
19-042	Planitop XS	RSCP-2014-01-016	55	5/8/2024
<b>Sika Corporation (NJ)</b>		<a href="http://www.usa.sika.com">www.usa.sika.com</a>		
16-003	SikaQuick VOH	RSCP-2014-01-004	45	1/27/2021
18-049	Sikacrete 421 CI Rapid	RSCP-2017-01-005	45	6/25/2023
<b>SpecChem, LLC</b>		<a href="http://www.specchemllc.com">www.specchemllc.com</a>		
12-069	RepCon 928	RSCP-2014-01-008	55	9/11/2023
<b>The QUIKRETE Companies</b>		<a href="http://www.quikrete.com">www.quikrete.com</a>		
58-000	Rapid Road Repair (fibered)	RSCP-2013-01-012	40*	9/24/2023

See Product Acceptance Criteria for more information: [RSCP Product Acceptance Criteria and Information](#)