EXHIBIT 7-5 USACE PAIRED PLOT FORMS

TETRA TECH

WETLAND DETERMINATION DATA FORM
Northeast and Northcentral Region

Project/Site:	Western Maine Renewable Energy Project	Project #:	194-7130
Applicant:	Western Maine Renewables, LLC		
Investigator #1:	Emmy Irvin	Investigator #2:	
Soil Unit:	Telos-Chesuncook association, 3 to 15 percent slopes	NWI/WWI Classification:	Upland
Landform:	Terrace	Local Relief:	Linear
Slope (%):	See topo map	Latitude: 45.153047	Longitude: -69.85613539 Datum: NAD 83

Date:	09/09/20
County:	Somerset
State:	ME
Wetland ID:	W12EI
Sample Point:	**Upland**

Are climatic/hydrologic conditions on the site typical for this time of year? (If no, explain in remarks) ☐ Yes ☑ No

Are Vegetation ☐ , Soil ☐ , or Hydrology ☐ significantly disturbed?
Are Vegetation ☐ , Soil ☐ , or Hydrology ☐ naturally problematic?

Are normal circumstances present? ☐ Yes ☑ No

Hydrophytic Vegetation Present?	☐ Yes ☑ No	Hydric Soils Present?	☐ Yes ☑ No
Wetland Hydrology Present?	☐ Yes ☑ No	Is This Sampling Point Within A Wetland?	☐ **Yes** ☑ **No**

Remarks: Statewide drought

Wetland Hydrology Indicators (Check here if indicators are not present ☑)

Primary:
- ☐ A1 - Surface Water
- ☐ A2 - High Water Table
- ☐ A3 - Saturation
- ☐ B1 - Water Marks
- ☐ B2 - Sediment Deposits
- ☐ B3 - Drift Deposits
- ☐ B4 - Algal Mat or Crust
- ☐ B5 - Iron Deposits
- ☐ B7 - Inundation Visible on Aerial Imagery
- ☐ B8 - Sparsely Vegetated Concave Surface
- ☐ B9 - Water-Stained Leaves
- ☐ B13 - Aquatic Fauna
- ☐ B15 - Marl Deposits
- ☐ C1 - Hydrogen Sulfide Odor
- ☐ C3 - Oxidized Rhizospheres on Living Roots
- ☐ C4 - Presence of Reduced Iron
- ☐ C6 - Recent Iron Reduction in Tilled Soils
- ☐ C7 - Thin Muck Surface
- ☐ Other (Explain in Remarks)

Secondary:
- ☐ B6 - Surface Soil Cracks
- ☐ B10 - Drainage Patterns
- ☐ B16 - Moss Trim Lines
- ☐ C2 - Dry-Season Water Table
- ☐ C8 - Crayfish Burrows
- ☐ C9 - Saturation Visible on Aerial Imagery
- ☐ D1 - Stunted or Stressed Plants
- ☐ D2 - Geomorphic Position
- ☐ D3 - Shallow Aquitard
- ☐ D4 - Microtopographic Relief
- ☐ D5 - FAC-Neutral Test

Field Observations:

Surface Water Present?	☐ Yes ☑ No	Depth:	(in.)
Water Table Present?	☐ Yes ☑ No	Depth:	(in.)
Saturation Present?	☐ Yes ☑ No	Depth:	(in.)

Wetland Hydrology Present? ☐ Yes ☑ No

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available: N/A

Remarks: Statewide drought

Map Unit Name: Telos-Chesuncook association, 3 to 15 percent slopes Series Drainage Class: Somewhat poorly drained

Taxonomy (Subgroup): Loamy, isotic, frigid, shallow Aquic Haplorthods

Profile Description (Describe to the depth needed to document the indicator or confirm the absence of indicators.) (Type: C=Concentration, D=Depletion, RM=Reduced Matrix, CS=Covered/Coated Sand Grains; Location: PL=Pore Lining, M=Matrix)

Top Depth	Bottom Depth	Horizon	Matrix Color (Moist)		Matrix %	Mottles Color (Moist)		Mottles %	Mottles Type	Mottles Location	Texture (e.g. clay, sand, loam)
0	12	1	10YR	5/3	100	--	--	--	--	--	fine sandy loam
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--

NRCS Hydric Soil Field Indicators (check here if indicators are not present ☐):
- ☐ A1- Histosol
- ☐ A2 - Histic Epipedon
- ☐ A3 - Black Histic
- ☐ A4 - Hydrogen Sulfide
- ☐ A5 - Stratified Layers
- ☐ A11 - Depleted Below Dark Surface
- ☐ A12 - Thick Dark Surface
- ☐ S1 - Sandy Muck Mineral
- ☐ S4 - Sandy Gleyed Matrix
- ☐ S5 - Sandy Redox
- ☐ S6 - Stripped Matrix
- ☐ S7 - Dark Surface (LRR R, MLRA 149B)
- ☐ S8 - Polyvalue Below Surface (LRR R, MLRA 149B)
- ☐ S9 - Thin Dark Surface (LRR R, MLRA 149B)
- ☐ F1 - Loamy Mucky Mineral (LRR K, L)
- ☐ F2 - Loamy Gleyed Matrix
- ☐ F3 - Depleted Matrix
- ☐ F6 - Redox Dark Surface
- ☐ F7 - Depleted Dark Surface
- ☐ F8 - Redox Depressions

Indicators for Problematic Soils [1]
- ☐ A10 - 2 cm Muck (LRR K, L, MLRA 149B)
- ☐ A16 - Coast Prairie Redox (LRR K, L, R)
- ☐ S3 - 5cm Mucky Peat of Peat (**LRR K, L, R**)
- ☐ S7 - Dark Surface (LRR K, L, M)
- ☐ S8 - Polyvalue Below Surface (**LRR K, L**)
- ☐ S9 - Thin Dark Surface (**LRR K, L**)
- ☐ F12 - Iron-Manganese Masses (**LRR K, L, R**)
- ☐ F19 - Piedmont Floodplain Soils (**MLRA 149B**)
- ☐ TA6 - Mesic Spodic (**MLRA 144A, 145, 149B**)
- ☐ TF2 - Red Parent Material
- ☐ TF12 - Very Shallow Dark Surface
- ☐ Other (Explain in Remarks)

[1] Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (If Observed) Type: Ledge Depth: 12

Hydric Soil Present? ☐ Yes ☑ No

Remarks:

TETRA TECH

WETLAND DETERMINATION DATA FORM

Northeast and Northcentral Region

Project/Site: Western Maine Renewable Energy Project Wetland ID: W12EI Sample Point **Upland**

Tree Stratum (Plot size: 10 meter radius)

	Species Name	% Cover	Dominant	Ind.Status
1.	*Thuja occidentalis*	1	N	FACW
2.	*Betula alleghaniensis*	5	N	FAC
3.	*Picea rubens*	50	Y	FACU
4.	*Betula papyrifera*	1	N	FACU
5.	*Acer rubrum*	5	N	FAC
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	62		

Sapling/Shrub Stratum (Plot size: 5 meter radius)

1.	*Picea rubens*	15	Y	FACU
2.	*Betula alleghaniensis*	5	N	FAC
3.	*Betula papyrifera*	1	N	FACU
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	21		

Herb Stratum (Plot size: 2 meter radius)

1.	*Medeola virginiana*	50	Y	FACU
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
6	--	--	--	--
7.	'--	--	--	0
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
11.	--	--	--	--
12.	--	--	--	--
13.	--	--	--	--
14.	--	--	--	--
15.	--	--	--	--
	Total Cover =	50		

Woody Vine Stratum (Plot size: 10 meter radius)

1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
	Total Cover =	0		

Dominance Test Worksheet

Number of Dominant Species that are OBL, FACW, or FAC: 0 (A)

Total Number of Dominant Species Across All Strata: 3 (B)

Percent of Dominant Species That Are OBL, FACW, or FAC: ***0.0%*** (A/B)

Prevalence Index Worksheet

Total % Cover of:		Multiply by:	
OBL spp.	0	x 1 =	0
FACW spp.	1	x 2 =	2
FAC spp.	15	x 3 =	45
FACU spp.	117	x 4 =	468
UPL spp.	0	x 5 =	0
Total	133 (A)		515 (B)

Prevalence Index = B/A = ***3.872***

Hydrophytic Vegetation Indicators:

- ☐ Yes ☐ No Rapid Test for Hydrophytic Vegetation
- ☐ Yes ☐ No Dominance Test is > 50%
- ☐ Yes ☐ No Prevalence Index is ≤ 3.0 *
- ☐ Yes ☐ No Morphological Adaptations (Explain) *
- ☐ Yes ☐ No Problem Hydrophytic Vegetation (Explain) *

* Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic.

Definitions of Vegetation Strata:

Tree - Woody plants 3 in. (7.6cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/Shrub - Woody plants less than 3 in. DBH and greater than 3.28 ft. tall.

Herb - All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft. tall.

Woody Vines - All woody vines greater than 3.28 ft. in height.

Hydrophytic Vegetation Present ☐ Yes ☑ No

Remarks:

Additional Remarks:

TETRA TECH

WETLAND DETERMINATION DATA FORM
Northeast and Northcentral Region

Project/Site:	Western Maine Renewable Energy Project	Project #:	194-7130
Applicant:	Western Maine Renewables, LLC		
Investigator #1:	Emmy Irvin	Investigator #2:	
Soil Unit:	Telos-Chesuncook association, 3 to 15 percent slc	NWI/WWI Classification:	PFO
Landform:	Terrace	Local Relief:	Linear
Slope (%):	See topo map	Latitude: 45.153047	Longitude: -69.856135 Datum: NAD 83

Are climatic/hydrologic conditions on the site typical for this time of year? (If no, explain in remarks) ☐ Yes ☑ No

Are Vegetation ☐ , Soil ☐ , or Hydrology ☐ significantly disturbed?
Are Vegetation ☐ , Soil ☐ , or Hydrology ☐ naturally problematic?

Are normal circumstances present? ☐ Yes ☑ No

Date:	09/09/20
County:	Somerset
State:	ME
Wetland ID:	W12EI
Sample Point:	**Wetland**

SUMMARY OF FINDINGS

Hydrophytic Vegetation Present?	☑ Yes ☐ No	Hydric Soils Present?	☑ Yes ☐ No
Wetland Hydrology Present?	☑ Yes ☐ No	Is This Sampling Point Within A Wetland?	☑ **Yes** ☐ **No**

Remarks: Statewide drought

HYDROLOGY

Wetland Hydrology Indicators (Check here if indicators are not present ☐)

Primary:
- ☐ A1 - Surface Water
- ☐ A2 - High Water Table
- ☑ A3 - Saturation
- ☐ B1 - Water Marks
- ☐ B2 - Sediment Deposits
- ☐ B3 - Drift Deposits
- ☐ B4 - Algal Mat or Crust
- ☐ B5 - Iron Deposits
- ☐ B7 - Inundation Visible on Aerial Imagery
- ☐ B8 - Sparsely Vegetated Concave Surface
- ☐ B9 - Water-Stained Leaves
- ☐ B13 - Aquatic Fauna
- ☐ B15 - Marl Deposits
- ☐ C1 - Hydrogen Sulfide Odor
- ☐ C3 - Oxidized Rhizospheres on Living Roots
- ☐ C4 - Presence of Reduced Iron
- ☐ C6 - Recent Iron Reduction in Tilled Soils
- ☐ C7 - Thin Muck Surface
- ☐ Other (Explain in Remarks)

Secondary:
- ☐ B6 - Surface Soil Cracks
- ☐ B10 - Drainage Patterns
- ☐ B16 - Moss Trim Lines
- ☐ C2 - Dry-Season Water Table
- ☐ C8 - Crayfish Burrows
- ☐ C9 - Saturation Visible on Aerial Imagery
- ☐ D1 - Stunted or Stressed Plants
- ☐ D2 - Geomorphic Position
- ☐ D3 - Shallow Aquitard
- ☐ D4 - Microtopographic Relief
- ☐ D5 - FAC-Neutral Test

Field Observations:

Surface Water Present?	☐ Yes	☑ No	Depth:	(in.)
Water Table Present?	☐ Yes	☑ No	Depth:	(in.)
Saturation Present?	☑ Yes	☐ No	Depth: 6	(in.)

Wetland Hydrology Present? ☑ Yes ☐ No

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available: N/A

Remarks: Statewide drout

SOILS

Map Unit Name: Telos-Chesuncook association, 3 to 15 percent slopes Series Drainage Class: Somewhat poorly drained

Taxonomy (Subgroup): Loamy, isotic, frigid, shallow Aquic Haplorthods

Profile Description (Describe to the depth needed to document the indicator or confirm the absence of indicators.) (Type: C=Concentration, D=Depletion, RM=Reduced Matrix, CS=Covered/Coated Sand Grains; Location: PL=Pore Lining, M=Matrix)

Top Depth	Bottom Depth	Horizon	Matrix Color (Moist)		Matrix %	Mottles Color (Moist)		Mottles %	Mottles Type	Mottles Location	Texture (e.g. clay, sand, loam)
0	12	1	10YR	4/1	85	10YR	3/2	10	D	M	sandy loam
--	--	--	--	--	--	10YR	5/8	5	C	PL	sandy loam
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--

NRCS Hydric Soil Field Indicators (check here if indicators are not present ☐):
- ☐ A1- Histosol
- ☐ A2 - Histic Epipedon
- ☐ A3 - Black Histic
- ☐ A4 - Hydrogen Sulfide
- ☐ A5 - Stratified Layers
- ☐ A11 - Depleted Below Dark Surface
- ☐ A12 - Thick Dark Surface
- ☐ S1 - Sandy Muck Mineral
- ☐ S4 - Sandy Gleyed Matrix
- ☐ S5 - Sandy Redox
- ☐ S6 - Stripped Matrix
- ☐ S7 - Dark Surface (LRR R, MLRA 149B)
- ☐ S8 - Polyvalue Below Surface (LRR R, MLRA 149B)
- ☐ S9 - Thin Dark Surface (LRR R, MLRA 149B)
- ☐ F1 - Loamy Mucky Mineral (LRR K, L)
- ☐ F2 - Loamy Gleyed Matrix
- ☑ F3 - Depleted Matrix
- ☐ F6 - Redox Dark Surface
- ☐ F7 - Depleted Dark Surface
- ☐ F8 - Redox Depressions

Indicators for Problematic Soils [1]
- ☐ A10 - 2 cm Muck (LRR K, L, MLRA 149B)
- ☐ A16 - Coast Prairie Redox (LRR K, L, R)
- ☐ S3 - 5cm Mucky Peat of Peat (**LRR K, L, R**)
- ☐ S7 - Dark Surface (LRR K, L, M)
- ☐ S8 - Polyvalue Below Surface (**LRR K, L**)
- ☐ S9 - Thin Dark Surface (**LRR K, L**)
- ☐ F12 - Iron-Manganese Masses (**LRR K, L, R**)
- ☐ F19 - Piedmont Floodplain Soils (**MLRA 149B**)
- ☐ TA6 - Mesic Spodic (**MLRA 144A, 145, 149B**)
- ☐ TF2 - Red Parent Material
- ☐ TF12 - Very Shallow Dark Surface
- ☐ Other (Explain in Remarks)

[1] Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (If Observed) Type: Ledge Depth: 12

Hydric Soil Present? ☑ Yes ☐ No

Remarks:

TETRA TECH

WETLAND DETERMINATION DATA FORM

Northeast and Northcentral Region

Project/Site: Western Maine Renewable Energy Project | Wetland ID: W12EI | Sample Point **Wetland**

VEGETATION (Species identified in all uppercase are non-native species.)

Tree Stratum (Plot size: 10 meter radius)

	Species Name	% Cover	Dominant	Ind.Status
1.	*Thuja occidentalis*	25	Y	FACW
2.	*Betula alleghaniensis*	5	N	FAC
3.	*Picea mariana*	25	Y	FACW
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	55		

Sapling/Shrub Stratum (Plot size: 5 meter radius)

1.	*Alnus incana*	35	Y	FACW
2.	*Betula alleghaniensis*	5	N	FAC
3.	*Betula papyrifera*	1	N	FACU
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	41		

Herb Stratum (Plot size: 2 meter radius)

1.	*Osmunda claytoniana*	5	N	FAC
2.	*Onoclea sensibilis*	5	N	FACW
3.	*Symphyotrichum novae-angliae*	2	N	FACW
4.	*Osmunda spectabilis*	5	N	OBL
5.	*Rubus hispidoides*	10	Y	FACW
6	*Gaultheria procumbens*	10	Y	FACU
7.	'--	--	--	0
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
11.	--	--	--	--
12.	--	--	--	--
13.	--	--	--	--
14.	--	--	--	--
15.	--	--	--	--
	Total Cover =	37		

Woody Vine Stratum (Plot size: 10 meter radius)

1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
	Total Cover =	0		

Dominance Test Worksheet

Number of Dominant Species that are OBL, FACW, or FAC: 4 (A)

Total Number of Dominant Species Across All Strata: 5 (B)

Percent of Dominant Species That Are OBL, FACW, or FAC: ***80.0%*** (A/B)

Prevalence Index Worksheet

Total % Cover of:		Multiply by:	
OBL spp.	5	x 1 =	5
FACW spp.	102	x 2 =	204
FAC spp.	15	x 3 =	45
FACU spp.	11	x 4 =	44
UPL spp.	0	x 5 =	0
Total	133 (A)		298 (B)

Prevalence Index = B/A = ***2.241***

Hydrophytic Vegetation Indicators:

- ☐ Yes ☑ No Rapid Test for Hydrophytic Vegetation
- ☑ Yes ☐ No Dominance Test is > 50%
- ☑ Yes ☐ No Prevalence Index is ≤ 3.0 *
- ☐ Yes ☑ No Morphological Adaptations (Explain) *
- ☐ Yes ☑ No Problem Hydrophytic Vegetation (Explain) *

* Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic.

Definitions of Vegetation Strata:

Tree - Woody plants 3 in. (7.6cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/Shrub - Woody plants less than 3 in. DBH and greater than 3.28 ft. tall.

Herb - All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft. tall.

Woody Vines - All woody vines greater than 3.28 ft. in height.

Hydrophytic Vegetation Present ☑ Yes ☐ No

Remarks:

Additional Remarks:

TETRA TECH

WETLAND DETERMINATION DATA FORM
Northeast and Northcentral Region

Project/Site:	Western Maine Renewable Energy Project	Project #:	194-7130
Applicant:	Western Maine Renewables, LLC		
Investigator #1:	Emmy Irvin	Investigator #2:	
Soil Unit:	Monarda Telos Complex 0-8 % slopes	NWI/WWI Classification:	Upland
Landform:	Terrace	Local Relief:	Linear
Slope (%):	See topo map	Latitude: 45.158284	Longitude: -69.844436 Datum: NAD 83

Are climatic/hydrologic conditions on the site typical for this time of year? (If no, explain in remarks) ☐ Yes ☑ No

Are Vegetation ☐, Soil ☐, or Hydrology ☐ significantly disturbed?
Are Vegetation ☐, Soil ☐, or Hydrology ☐ naturally problematic?

Are normal circumstances present? ☐ Yes ☑ No

Date:	09/09/20
County:	Somerset
State:	ME
Wetland ID:	W19DS
Sample Point:	**Upland**

SUMMARY OF FINDINGS

Hydrophytic Vegetation Present?	☐ Yes ☑ No	Hydric Soils Present?	☐ Yes ☑ No
Wetland Hydrology Present?	☐ Yes ☑ No	Is This Sampling Point Within A Wetland?	☐ **Yes** ☑ **No**

Remarks: Statewide drought

HYDROLOGY

Wetland Hydrology Indicators (Check here if indicators are not present ☑)

Primary:
- ☐ A1 - Surface Water
- ☐ A2 - High Water Table
- ☐ A3 - Saturation
- ☐ B1 - Water Marks
- ☐ B2 - Sediment Deposits
- ☐ B3 - Drift Deposits
- ☐ B4 - Algal Mat or Crust
- ☐ B5 - Iron Deposits
- ☐ B7 - Inundation Visible on Aerial Imagery
- ☐ B8 - Sparsely Vegetated Concave Surface
- ☐ B9 - Water-Stained Leaves
- ☐ B13 - Aquatic Fauna
- ☐ B15 - Marl Deposits
- ☐ C1 - Hydrogen Sulfide Odor
- ☐ C3 - Oxidized Rhizospheres on Living Roots
- ☐ C4 - Presence of Reduced Iron
- ☐ C6 - Recent Iron Reduction in Tilled Soils
- ☐ C7 - Thin Muck Surface
- ☐ Other (Explain in Remarks)

Secondary:
- ☐ B6 - Surface Soil Cracks
- ☐ B10 - Drainage Patterns
- ☐ B16 - Moss Trim Lines
- ☐ C2 - Dry-Season Water Table
- ☐ C8 - Crayfish Burrows
- ☐ C9 - Saturation Visible on Aerial Imagery
- ☐ D1 - Stunted or Stressed Plants
- ☐ D2 - Geomorphic Position
- ☐ D3 - Shallow Aquitard
- ☐ D4 - Microtopographic Relief
- ☐ D5 - FAC-Neutral Test

Field Observations:

Surface Water Present?	☐ Yes ☑ No	Depth:	(in.)
Water Table Present?	☐ Yes ☑ No	Depth:	(in.)
Saturation Present?	☐ Yes ☑ No	Depth:	(in.)

Wetland Hydrology Present? ☐ Yes ☑ No

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available: N/A

Remarks: Statewide drought

SOILS

Map Unit Name: Monarda Telos Complex 0-8 % slopes — Series Drainage Class: Somewhat poorly drained

Taxonomy (Subgroup): Loamy, isotic, frigid, shallow Aquic Haplorthods

Profile Description (Describe to the depth needed to document the indicator or confirm the absence of indicators.) (Type: C=Concentration, D=Depletion, RM=Reduced Matrix, CS=Covered/Coated Sand Grains; Location: PL=Pore Lining, M=Matrix)

Top Depth	Bottom Depth	Horizon	Matrix Color (Moist)		Matrix %	Mottles Color (Moist)		Mottles %	Mottles Type	Mottles Location	Texture (e.g. clay, sand, loam)
0	12	--	10YR	4/3	100	--	--	--	--	--	sandy loam
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--

NRCS Hydric Soil Field Indicators (check here if indicators are not present ☑):
- ☐ A1- Histosol
- ☐ A2 - Histic Epipedon
- ☐ A3 - Black Histic
- ☐ A4 - Hydrogen Sulfide
- ☐ A5 - Stratified Layers
- ☐ A11 - Depleted Below Dark Surface
- ☐ A12 - Thick Dark Surface
- ☐ S1 - Sandy Muck Mineral
- ☐ S4 - Sandy Gleyed Matrix
- ☐ S5 - Sandy Redox
- ☐ S6 - Stripped Matrix
- ☐ S7 - Dark Surface (LRR R, MLRA 149B)
- ☐ S8 - Polyvalue Below Surface (LRR R, MLRA 149B)
- ☐ S9 - Thin Dark Surface (LRR R, MLRA 149B)
- ☐ F1 - Loamy Mucky Mineral (LRR K, L)
- ☐ F2 - Loamy Gleyed Matrix
- ☐ F3 - Depleted Matrix
- ☐ F6 - Redox Dark Surface
- ☐ F7 - Depleted Dark Surface
- ☐ F8 - Redox Depressions

Indicators for Problematic Soils [1]
- ☐ A10 - 2 cm Muck (LRR K, L, MLRA 149B)
- ☐ A16 - Coast Prairie Redox (LRR K, L, R)
- ☐ S3 - 5cm Mucky Peat of Peat (**LRR K, L, R**)
- ☐ S7 - Dark Surface (LRR K, L, M)
- ☐ S8 - Polyvalue Below Surface (**LRR K, L**)
- ☐ S9 - Thin Dark Surface (**LRR K, L**)
- ☐ F12 - Iron-Manganese Masses (**LRR K, L, R**)
- ☐ F19 - Piedmont Floodplain Soils (**MLRA 149B**)
- ☐ TA6 - Mesic Spodic (**MLRA 144A, 145, 149B**)
- ☐ TF2 - Red Parent Material
- ☐ TF12 - Very Shallow Dark Surface
- ☐ Other (Explain in Remarks)

[1] Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (If Observed) Type: ledge Depth: 12

Hydric Soil Present? ☐ Yes ☑ No

Remarks:

TETRA TECH

WETLAND DETERMINATION DATA FORM

Northeast and Northcentral Region

Project/Site: Western Maine Renewable Energy Project | Wetland ID: W19DS | Sample Point **Upland**

VEGETATION (Species identified in all uppercase are non-native species.)

Tree Stratum (Plot size: 10 meter radius)

	Species Name	% Cover	Dominant	Ind.Status
1.	*Acer rubrum*	15	Y	FAC
2.	*Betula alleghaniensis*	25	Y	FAC
3.	*Picea rubens*	15	Y	FACU
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	55		

Sapling/Shrub Stratum (Plot size: 5 meter radius)

1.	*Picea rubens*	5	Y	FACU
2.	*Acer rubrum*	2	N	FAC
3.	*Viburnum acerifolium*	10	Y	UPL
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	17		

Herb Stratum (Plot size: 2 meter radius)

1.	*Dryopteris marginalis*	15	Y	FACU
2.	*Cornus canadensis*	15	Y	FAC
3.	*Medeola virginiana*	10	Y	FACU
4.	*Coptis trifolia*	2	N	FACW
5.	*Acer rubrum*	2	N	FAC
6	*Rubus hispidus*	2	N	FACW
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
11.	--	--	--	--
12.	--	--	--	--
13.	--	--	--	--
14.	--	--	--	--
15.	--	--	--	--
	Total Cover =	46		

Woody Vine Stratum (Plot size: 10 meter radius)

1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
	Total Cover =	0		

Remarks:

Dominance Test Worksheet

Number of Dominant Species that are OBL, FACW, or FAC: 3 (A)

Total Number of Dominant Species Across All Strata: 8 (B)

Percent of Dominant Species That Are OBL, FACW, or FAC: ***37.5%*** (A/B)

Prevalence Index Worksheet

Total % Cover of:		Multiply by:	
OBL spp.	0	x 1 =	0
FACW spp.	4	x 2 =	8
FAC spp.	59	x 3 =	177
FACU spp.	45	x 4 =	180
UPL spp.	10	x 5 =	50
Total	118 (A)		415 (B)

Prevalence Index = B/A = ***3.517***

Hydrophytic Vegetation Indicators:

- ☐ Yes ☑ No Rapid Test for Hydrophytic Vegetation
- ☐ Yes ☑ No Dominance Test is > 50%
- ☐ Yes ☑ No Prevalence Index is ≤ 3.0 *
- ☐ Yes ☑ No Morphological Adaptations (Explain) *
- ☐ Yes ☑ No Problem Hydrophytic Vegetation (Explain) *

* Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic.

Definitions of Vegetation Strata:

Tree - Woody plants 3 in. (7.6cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/Shrub - Woody plants less than 3 in. DBH and greater than 3.28 ft. tall.

Herb - All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft. tall.

Woody Vines - All woody vines greater than 3.28 ft. in height.

Hydrophytic Vegetation Present ☐ Yes ☑ No

Additional Remarks:

TETRA TECH

WETLAND DETERMINATION DATA FORM
Northeast and Northcentral Region

Project/Site:	Western Maine Renewable Energy Project	Project #:	194-7130
Applicant:	Western Maine Renewables, LLC		
Investigator #1:	Dave Santillo	Investigator #2:	Emmy Irvin
Soil Unit:	Monarda Telos Complex 0-8 % slopes	NWI/WWI Classification:	PFO
Landform:	Terrace	Local Relief:	Linear
Slope (%):	See topo map	Latitude: 45.158284	Longitude: -69.849353 Datum: NAD 83

Are climatic/hydrologic conditions on the site typical for this time of year? (If no, explain in remarks) ☐ Yes ☐ No

Are Vegetation ☐, Soil ☐, or Hydrology ☐ significantly disturbed?
Are Vegetation ☐, Soil ☐, or Hydrology ☐ naturally problematic?

Are normal circumstances present? ☐ Yes ☑ No

Date:	09/09/20
County:	Somerset
State:	ME
Wetland ID:	W19DS
Sample Point:	**Wetland**

SUMMARY OF FINDINGS

Hydrophytic Vegetation Present?	☑ Yes ☐ No	Hydric Soils Present?	☑ Yes ☐ No
Wetland Hydrology Present?	☑ Yes ☐ No	Is This Sampling Point Within A Wetland?	☑ **Yes** ☐ **No**

Remarks: Statewide drought

HYDROLOGY

Wetland Hydrology Indicators (Check here if indicators are not present ☐)

Primary:
- ☐ A1 - Surface Water
- ☐ A2 - High Water Table
- ☑ A3 - Saturation
- ☐ B1 - Water Marks
- ☐ B2 - Sediment Deposits
- ☐ B3 - Drift Deposits
- ☐ B4 - Algal Mat or Crust
- ☐ B5 - Iron Deposits
- ☐ B7 - Inundation Visible on Aerial Imagery
- ☐ B8 - Sparsely Vegetated Concave Surface
- ☐ B9 - Water-Stained Leaves
- ☐ B13 - Aquatic Fauna
- ☐ B15 - Marl Deposits
- ☐ C1 - Hydrogen Sulfide Odor
- ☐ C3 - Oxidized Rhizospheres on Living Roots
- ☐ C4 - Presence of Reduced Iron
- ☐ C6 - Recent Iron Reduction in Tilled Soils
- ☐ C7 - Thin Muck Surface
- ☐ Other (Explain in Remarks)

Secondary:
- ☐ B6 - Surface Soil Cracks
- ☑ B10 - Drainage Patterns
- ☐ B16 - Moss Trim Lines
- ☐ C2 - Dry-Season Water Table
- ☐ C8 - Crayfish Burrows
- ☐ C9 - Saturation Visible on Aerial Imagery
- ☐ D1 - Stunted or Stressed Plants
- ☐ D2 - Geomorphic Position
- ☐ D3 - Shallow Aquitard
- ☑ D4 - Microtopographic Relief
- ☐ D5 - FAC-Neutral Test

Field Observations:

Surface Water Present?	☐ Yes	☑ No	Depth:	(in.)
Water Table Present?	☐ Yes	☑ No	Depth:	(in.)
Saturation Present?	☑ Yes	☐ No	Depth: 0	(in.)

Wetland Hydrology Present? ☑ Yes ☐ No

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available: N/A

Remarks: Statewide drought

SOILS

Map Unit Name: Monarda Telos Complex 0-8 % slopes Series Drainage Class: poorly drained

Taxonomy (Subgroup): Loamy, mixed, active, acid, frigid, shallow Aeric Endoaquepts

Profile Description (Describe to the depth needed to document the indicator or confirm the absence of indicators.) (Type: C=Concentration, D=Depletion, RM=Reduced Matrix, CS=Covered/Coated Sand Grains; Location: PL=Pore Lining, M=Matrix)

Top Depth	Bottom Depth	Horizon	Matrix Color (Moist)		Matrix %	Mottles Color (Moist)		Mottles %	Mottles Type	Mottles Location	Texture (e.g. clay, sand, loam)
0	4	--	10YR	2/1	100	--	--	--	--	--	muck
4	12	--	10YR	5/1	80	10YR	4/4	20	C	M	fine sandy loam
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--

NRCS Hydric Soil Field Indicators (check here if indicators are not present ☐):
- ☐ A1- Histosol
- ☐ A2 - Histic Epipedon
- ☐ A3 - Black Histic
- ☐ A4 - Hydrogen Sulfide
- ☐ A5 - Stratified Layers
- ☐ A11 - Depleted Below Dark Surface
- ☐ A12 - Thick Dark Surface
- ☐ S1 - Sandy Muck Mineral
- ☐ S4 - Sandy Gleyed Matrix
- ☐ S5 - Sandy Redox
- ☐ S6 - Stripped Matrix
- ☐ S7 - Dark Surface (LRR R, MLRA 149B)
- ☐ S8 - Polyvalue Below Surface (LRR R, MLRA 149B)
- ☐ S9 - Thin Dark Surface (LRR R, MLRA 149B)
- ☐ F1 - Loamy Mucky Mineral (LRR K, L)
- ☐ F2 - Loamy Gleyed Matrix
- ☑ F3 - Depleted Matrix
- ☐ F6 - Redox Dark Surface
- ☐ F7 - Depleted Dark Surface
- ☐ F8 - Redox Depressions

Indicators for Problematic Soils [1]
- ☐ A10 - 2 cm Muck (LRR K, L, MLRA 149B)
- ☐ A16 - Coast Prairie Redox (LRR K, L, R)
- ☐ S3 - 5cm Mucky Peat of Peat (**LRR K, L, R**)
- ☐ S7 - Dark Surface (LRR K, L, M)
- ☐ S8 - Polyvalue Below Surface (**LRR K, L**)
- ☐ S9 - Thin Dark Surface (**LRR K, L**)
- ☐ F12 - Iron-Manganese Masses (**LRR K, L, R**)
- ☐ F19 - Piedmont Floodplain Soils (**MLRA 149B**)
- ☐ TA6 - Mesic Spodic (**MLRA 144A, 145, 149B**)
- ☐ TF2 - Red Parent Material
- ☐ TF12 - Very Shallow Dark Surface
- ☐ Other (Explain in Remarks)

[1] Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (If Observed) Type: ledge Depth: 12

Hydric Soil Present? ☑ Yes ☐ No

Remarks:

TETRA TECH

WETLAND DETERMINATION DATA FORM

Northeast and Northcentral Region

Project/Site: Western Maine Renewable Energy Project Wetland ID: W19DS Sample Point **Wetland**

VEGETATION (Species identified in all uppercase are non-native species.)

Tree Stratum (Plot size: 10 meter radius)

	Species Name	% Cover	Dominant	Ind.Status
1.	*Thuja occidentalis*	20	y	FACW
2.	*Acer rubrum*	15	y	FAC
3.	*Abies balsamea*	15	y	FAC
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	50		

Sapling/Shrub Stratum (Plot size: 5 meter radius)

1.	*Spiraea alba*	10	y	FACW
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	10		

Herb Stratum (Plot size: 2 meter radius)

1.	*Onoclea sensibilis*	20	y	FACW
2.	*Coptis trifolia*	5	n	FACW
3.	*Osmundastrum cinnamomeum*	15	y	FACW
4.	*Fragaria vesca*	10	n	UPL
5.	*Clintonia borealis*	5	n	FAC
6	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
11.	--	--	--	--
12.	--	--	--	--
13.	--	--	--	--
14.	--	--	--	--
15.	--	--	--	--
	Total Cover =	55		

Woody Vine Stratum (Plot size: 10 meter radius)

1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
	Total Cover =	0		

Dominance Test Worksheet

Number of Dominant Species that are OBL, FACW, or FAC: 6 (A)

Total Number of Dominant Species Across All Strata: 6 (B)

Percent of Dominant Species That Are OBL, FACW, or FAC: ***100.0%*** (A/B)

Prevalence Index Worksheet

Total % Cover of:		Multiply by:	
OBL spp.	0	x 1 =	0
FACW spp.	70	x 2 =	140
FAC spp.	35	x 3 =	105
FACU spp.	0	x 4 =	0
UPL spp.	10	x 5 =	50
Total	115 (A)		295 (B)

Prevalence Index = B/A = ***2.565***

Hydrophytic Vegetation Indicators:

- ☑ Yes ☐ No Rapid Test for Hydrophytic Vegetation
- ☑ Yes ☐ No Dominance Test is > 50%
- ☑ Yes ☐ No Prevalence Index is ≤ 3.0 *
- ☐ Yes ☑ No Morphological Adaptations (Explain) *
- ☐ Yes ☑ No Problem Hydrophytic Vegetation (Explain) *

* Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic.

Definitions of Vegetation Strata:

Tree - Woody plants 3 in. (7.6cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/Shrub - Woody plants less than 3 in. DBH and greater than 3.28 ft. tall.

Herb - All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft. tall.

Woody Vines - All woody vines greater than 3.28 ft. in height.

Hydrophytic Vegetation Present ☑ Yes ☐ No

Remarks:

Additional Remarks:

TETRA TECH

WETLAND DETERMINATION DATA FORM
Northeast and Northcentral Region

Project/Site:	Western Maine Renewable Energy Project	Project #:	194-7130
Applicant:	Western Maine Renewables, LLC		
Investigator #1:	Emmy Irvin	Investigator #2:	
Soil Unit:	Telos-Chesuncook association, 3 to 15 % slopes	NWI/WWI Classification:	Upland
Landform:	Terrace	Local Relief:	Linear
Slope (%):	See topo map	Latitude: 45.150130°	Longitude: -69.856510° Datum: NAD 83

Are climatic/hydrologic conditions on the site typical for this time of year? (If no, explain in remarks) ☐ Yes ☑ No

Are Vegetation ☐ , Soil ☐ , or Hydrology ☐ significantly disturbed?
Are Vegetation ☐ , Soil ☐ , or Hydrology ☐ naturally problematic?

Are normal circumstances present? ☐ Yes ☑ No

Date:	09/09/20
County:	Somerset
State:	ME
Wetland ID:	W18EI
Sample Point:	**Upland**

Hydrophytic Vegetation Present? ☐ Yes ☑ No
Wetland Hydrology Present? ☐ Yes ☑ No
Hydric Soils Present? ☐ Yes ☑ No
Is This Sampling Point Within A Wetland? ☐ **Yes** ☑ **No**

Remarks: Statewide drought

Wetland Hydrology Indicators (Check here if indicators are not present ☑)

Primary:
- ☐ A1 - Surface Water
- ☐ A2 - High Water Table
- ☐ A3 - Saturation
- ☐ B1 - Water Marks
- ☐ B2 - Sediment Deposits
- ☐ B3 - Drift Deposits
- ☐ B4 - Algal Mat or Crust
- ☐ B5 - Iron Deposits
- ☐ B7 - Inundation Visible on Aerial Imagery
- ☐ B8 - Sparsely Vegetated Concave Surface
- ☐ B9 - Water-Stained Leaves
- ☐ B13 - Aquatic Fauna
- ☐ B15 - Marl Deposits
- ☐ C1 - Hydrogen Sulfide Odor
- ☐ C3 - Oxidized Rhizospheres on Living Roots
- ☐ C4 - Presence of Reduced Iron
- ☐ C6 - Recent Iron Reduction in Tilled Soils
- ☐ C7 - Thin Muck Surface
- ☐ Other (Explain in Remarks)

Secondary:
- ☐ B6 - Surface Soil Cracks
- ☐ B10 - Drainage Patterns
- ☐ B16 - Moss Trim Lines
- ☐ C2 - Dry-Season Water Table
- ☐ C8 - Crayfish Burrows
- ☐ C9 - Saturation Visible on Aerial Imagery
- ☐ D1 - Stunted or Stressed Plants
- ☐ D2 - Geomorphic Position
- ☐ D3 - Shallow Aquitard
- ☐ D4 - Microtopographic Relief
- ☐ D5 - FAC-Neutral Test

Field Observations:

Surface Water Present?	☐ Yes ☑ No	Depth:	(in.)
Water Table Present?	☐ Yes ☑ No	Depth:	(in.)
Saturation Present?	☐ Yes ☑ No	Depth:	(in.)

Wetland Hydrology Present? ☐ Yes ☑ No

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available: N/A

Remarks: Statewide drought

Map Unit Name: Telos-Chesuncook association, 3 to 15 % slopes — Series Drainage Class: Somewhat poorly drained

Taxonomy (Subgroup): Loamy, isotic, frigid, shallow Aquic Haplorthods

Profile Description (Describe to the depth needed to document the indicator or confirm the absence of indicators.) (Type: C=Concentration, D=Depletion, RM=Reduced Matrix, CS=Covered/Coated Sand Grains; Location: PL=Pore Lining, M=Matrix)

Top Depth	Bottom Depth	Horizon	Matrix Color (Moist)		Matrix %	Mottles Color (Moist)		Mottles %	Mottles Type	Mottles Location	Texture (e.g. clay, sand, loam)
0	17	--	10YR	4/2	100	--	--	--	--	--	sandy loam
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--

NRCS Hydric Soil Field Indicators (check here if indicators are not present ☑):
- ☐ A1- Histosol
- ☐ A2 - Histic Epipedon
- ☐ A3 - Black Histic
- ☐ A4 - Hydrogen Sulfide
- ☐ A5 - Stratified Layers
- ☐ A11 - Depleted Below Dark Surface
- ☐ A12 - Thick Dark Surface
- ☐ S1 - Sandy Muck Mineral
- ☐ S4 - Sandy Gleyed Matrix
- ☐ S5 - Sandy Redox
- ☐ S6 - Stripped Matrix
- ☐ S7 - Dark Surface (LRR R, MLRA 149B)
- ☐ S8 - Polyvalue Below Surface (LRR R, MLRA 149B)
- ☐ S9 - Thin Dark Surface (LRR R, MLRA 149B)
- ☐ F1 - Loamy Mucky Mineral (LRR K, L)
- ☐ F2 - Loamy Gleyed Matrix
- ☐ F3 - Depleted Matrix
- ☐ F6 - Redox Dark Surface
- ☐ F7 - Depleted Dark Surface
- ☐ F8 - Redox Depressions

Indicators for Problematic Soils [1]
- ☐ A10 - 2 cm Muck (LRR K, L, MLRA 149B)
- ☐ A16 - Coast Prairie Redox (LRR K, L, R)
- ☐ S3 - 5cm Mucky Peat of Peat (**LRR K, L, R**)
- ☐ S7 - Dark Surface (LRR K, L, M)
- ☐ S8 - Polyvalue Below Surface (**LRR K, L**)
- ☐ S9 - Thin Dark Surface (**LRR K, L**)
- ☐ F12 - Iron-Manganese Masses (**LRR K, L, R**)
- ☐ F19 - Piedmont Floodplain Soils (**MLRA 149B**)
- ☐ TA6 - Mesic Spodic (**MLRA 144A, 145, 149B**)
- ☐ TF2 - Red Parent Material
- ☐ TF12 - Very Shallow Dark Surface
- ☐ Other (Explain in Remarks)

[1] Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (If Observed) Type: None Depth: N/A

Hydric Soil Present? ☐ Yes ☑ No

Remarks:

TETRA TECH

WETLAND DETERMINATION DATA FORM

Northeast and Northcentral Region

Project/Site: Western Maine Renewable Energy Project Wetland ID: W18EI Sample Point **Upland**

Tree Stratum (Plot size: 10 meter radius)

	Species Name	% Cover	Dominant	Ind.Status
1.	*Betula papyrifera*	5	N	FACU
2.	*Betula alleghaniensis*	20	Y	FAC
3.	*Picea rubens*	10	Y	FACU
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	35		

Sapling/Shrub Stratum (Plot size: 5 meter radius)

1.	*Picea rubens*	10	Y	FACU
2.	*Acer rubrum*	2	N	FAC
3.	*Viburnum acerifolium*	10	Y	UPL
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	22		

Herb Stratum (Plot size: 2 meter radius)

1.	*Dryopteris marginalis*	5	N	FACU
2.	*Cornus canadensis*	20	Y	FAC
3.	*Medeola virginiana*	10	Y	FACU
4.	*Coptis trifolia*	2	N	FACW
5.	*Clintonia borealis*	2	N	FAC
6	*Osmunda claytoniana*	5	N	FAC
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
11.	--	--	--	--
12.	--	--	--	--
13.	--	--	--	--
14.	--	--	--	--
15.	--	--	--	--
	Total Cover =	44		

Woody Vine Stratum (Plot size: 10 meter radius)

1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
	Total Cover =	0		

Dominance Test Worksheet

Number of Dominant Species that are OBL, FACW, or FAC: 2 (A)

Total Number of Dominant Species Across All Strata: 6 (B)

Percent of Dominant Species That Are OBL, FACW, or FAC: ***33.3%*** (A/B)

Prevalence Index Worksheet

Total % Cover of:		Multiply by:	
OBL spp.	0	x 1 =	0
FACW spp.	2	x 2 =	4
FAC spp.	49	x 3 =	147
FACU spp.	40	x 4 =	160
UPL spp.	10	x 5 =	50
Total	101 (A)		361 (B)

Prevalence Index = B/A = ***3.574***

Hydrophytic Vegetation Indicators:

- ☐ Yes ☑ No Rapid Test for Hydrophytic Vegetation
- ☐ Yes ☑ No Dominance Test is > 50%
- ☐ Yes ☑ No Prevalence Index is ≤ 3.0 *
- ☐ Yes ☑ No Morphological Adaptations (Explain) *
- ☐ Yes ☑ No Problem Hydrophytic Vegetation (Explain) *

* Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic.

Definitions of Vegetation Strata:

Tree - Woody plants 3 in. (7.6cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/Shrub - Woody plants less than 3 in. DBH and greater than 3.28 ft. tall.

Herb - All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft. tall.

Woody Vines - All woody vines greater than 3.28 ft. in height.

Hydrophytic Vegetation Present ☐ Yes ☑ No

Remarks:

Additional Remarks:

TETRA TECH

WETLAND DETERMINATION DATA FORM
Northeast and Northcentral Region

Project/Site:	Western Maine Renewable Energy Project	Project #:	194-7130
Applicant:	Western Maine Renewables, LLC		
Investigator #1:	Emmy Irvin	Investigator #2:	
Soil Unit:	Telos-Chesuncook association, 3 to 15 % slopes	NWI/WWI Classification:	PFO
Landform:	Terrace	Local Relief:	Linear
Slope (%):	See topo map	Latitude: 45.150087°	Longitude: -69.856604° Datum: NAD 83

Are climatic/hydrologic conditions on the site typical for this time of year? (If no, explain in remarks) ☐ Yes ☑ No

Are Vegetation ☐ , Soil ☐ , or Hydrology ☐ significantly disturbed?
Are Vegetation ☐ , Soil ☐ , or Hydrology ☐ naturally problematic?

Are normal circumstances present? ☐ Yes ☑ No

Date:	09/09/20
County:	Somerset
State:	ME
Wetland ID:	W18EI
Sample Point:	**Wetland**

SUMMARY OF FINDINGS

Hydrophytic Vegetation Present?	☑ Yes ☐ No	Hydric Soils Present?	☑ Yes ☐ No
Wetland Hydrology Present?	☑ Yes ☐ No	Is This Sampling Point Within A Wetland?	☑ **Yes** ☐ **No**

Remarks: Drought

HYDROLOGY

Wetland Hydrology Indicators (Check here if indicators are not present ☐)

Primary:
- ☐ A1 - Surface Water
- ☐ A2 - High Water Table
- ☑ A3 - Saturation
- ☐ B1 - Water Marks
- ☐ B2 - Sediment Deposits
- ☐ B3 - Drift Deposits
- ☐ B4 - Algal Mat or Crust
- ☐ B5 - Iron Deposits
- ☐ B7 - Inundation Visible on Aerial Imagery
- ☐ B8 - Sparsely Vegetated Concave Surface
- ☑ B9 - Water-Stained Leaves
- ☐ B13 - Aquatic Fauna
- ☐ B15 - Marl Deposits
- ☐ C1 - Hydrogen Sulfide Odor
- ☐ C3 - Oxidized Rhizospheres on Living Roots
- ☐ C4 - Presence of Reduced Iron
- ☐ C6 - Recent Iron Reduction in Tilled Soils
- ☐ C7 - Thin Muck Surface
- ☐ Other (Explain in Remarks)

Secondary:
- ☐ B6 - Surface Soil Cracks
- ☑ B10 - Drainage Patterns
- ☐ B16 - Moss Trim Lines
- ☐ C2 - Dry-Season Water Table
- ☐ C8 - Crayfish Burrows
- ☐ C9 - Saturation Visible on Aerial Imagery
- ☐ D1 - Stunted or Stressed Plants
- ☐ D2 - Geomorphic Position
- ☐ D3 - Shallow Aquitard
- ☐ D4 - Microtopographic Relief
- ☐ D5 - FAC-Neutral Test

Field Observations:

Surface Water Present?	☐ Yes	☑ No	Depth:	(in.)
Water Table Present?	☐ Yes	☑ No	Depth:	(in.)
Saturation Present?	☑ Yes	☐ No	Depth: 0	(in.)

Wetland Hydrology Present? ☑ Yes ☐ No

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available: N/A

Remarks: Seep wetland

SOILS

Map Unit Name: Telos-Chesuncook association, 3 to 15 % slopes Series Drainage Class: Somewhat poorly drained

Taxonomy (Subgroup): Loamy, isotic, frigid, shallow Aquic Haplorthods

Profile Description (Describe to the depth needed to document the indicator or confirm the absence of indicators.) (Type: C=Concentration, D=Depletion, RM=Reduced Matrix, CS=Covered/Coated Sand Grains; Location: PL=Pore Lining, M=Matrix)

Top Depth	Bottom Depth	Horizon	Matrix Color (Moist)		Matrix %	Mottles Color (Moist)		Mottles %	Mottles Type	Mottles Location	Texture (e.g. clay, sand, loam)
0	10	--	10YR	2/1	100	--	--	--	--	--	mucky loam
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--

NRCS Hydric Soil Field Indicators (check here if indicators are not present ☐):
- ☑ A1- Histosol
- ☐ A2 - Histic Epipedon
- ☐ A3 - Black Histic
- ☐ A4 - Hydrogen Sulfide
- ☐ A5 - Stratified Layers
- ☐ A11 - Depleted Below Dark Surface
- ☐ A12 - Thick Dark Surface
- ☐ S1 - Sandy Muck Mineral
- ☐ S4 - Sandy Gleyed Matrix
- ☐ S5 - Sandy Redox
- ☐ S6 - Stripped Matrix
- ☐ S7 - Dark Surface (LRR R, MLRA 149B)
- ☐ S8 - Polyvalue Below Surface (LRR R, MLRA 149B)
- ☐ S9 - Thin Dark Surface (LRR R, MLRA 149B)
- ☐ F1 - Loamy Mucky Mineral (LRR K, L)
- ☐ F2 - Loamy Gleyed Matrix
- ☐ F3 - Depleted Matrix
- ☐ F6 - Redox Dark Surface
- ☐ F7 - Depleted Dark Surface
- ☐ F8 - Redox Depressions

Indicators for Problematic Soils [1]
- ☐ A10 - 2 cm Muck (LRR K, L, MLRA 149B)
- ☐ A16 - Coast Prairie Redox (LRR K, L, R)
- ☐ S3 - 5cm Mucky Peat of Peat (**LRR K, L, R**)
- ☐ S7 - Dark Surface (LRR K, L, M)
- ☐ S8 - Polyvalue Below Surface (**LRR K, L**)
- ☐ S9 - Thin Dark Surface (**LRR K, L**)
- ☐ F12 - Iron-Manganese Masses (**LRR K, L, R**)
- ☐ F19 - Piedmont Floodplain Soils (**MLRA 149B**)
- ☐ TA6 - Mesic Spodic (**MLRA 144A, 145, 149B**)
- ☐ TF2 - Red Parent Material
- ☐ TF12 - Very Shallow Dark Surface
- ☐ Other (Explain in Remarks)

[1] Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (If Observed) Type: Ledge Depth: 10

Hydric Soil Present? ☑ Yes ☐ No

Remarks:

TETRA TECH

WETLAND DETERMINATION DATA FORM

Northeast and Northcentral Region

Project/Site: Western Maine Renewable Energy Project Wetland ID: W18EI Sample Point **Wetland**

VEGETATION (Species identified in all uppercase are non-native species.)

Tree Stratum (Plot size: 10 meter radius)

	Species Name	% Cover	Dominant	Ind.Status
1.	*Thuja occidentalis*	30	Y	FACW
2.	*Picea mariana*	10	N	FACW
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	40		

Sapling/Shrub Stratum (Plot size: 5 meter radius)

1.	*Thuja occidentalis*	10	Y	FACW
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	10		

Herb Stratum (Plot size: 2 meter radius)

1.	*Clintonia borealis*	10	Y	FAC
2.	*Viola cucullata*	10	Y	OBL
3.	*Rubus hispidus*	5	N	FACW
4.	*Uvularia sessilifolia*	5	N	FACU
5.	*Geum rivale*	10	Y	OBL
6	*Osmunda claytoniana*	10	Y	FAC
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
11.	--	--	--	--
12.	--	--	--	--
13.	--	--	--	--
14.	--	--	--	--
15.	--	--	--	--
	Total Cover =	50		

Woody Vine Stratum (Plot size: 10 meter radius)

1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
	Total Cover =	0		

Dominance Test Worksheet

Number of Dominant Species that are OBL, FACW, or FAC: 6 (A)

Total Number of Dominant Species Across All Strata: 6 (B)

Percent of Dominant Species That Are OBL, FACW, or FAC: ***100.0%*** (A/B)

Prevalence Index Worksheet

Total % Cover of:		Multiply by:	
OBL spp.	20	x 1 =	20
FACW spp.	55	x 2 =	110
FAC spp.	20	x 3 =	60
FACU spp.	5	x 4 =	20
UPL spp.	0	x 5 =	0
Total	100 (A)		210 (B)

Prevalence Index = B/A = ***2.100***

Hydrophytic Vegetation Indicators:

- ☐ Yes ☑ No Rapid Test for Hydrophytic Vegetation
- ☑ Yes ☐ No Dominance Test is > 50%
- ☑ Yes ☐ No Prevalence Index is ≤ 3.0 *
- ☐ Yes ☑ No Morphological Adaptations (Explain) *
- ☐ Yes ☑ No Problem Hydrophytic Vegetation (Explain) *

* Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic.

Definitions of Vegetation Strata:

Tree - Woody plants 3 in. (7.6cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/Shrub - Woody plants less than 3 in. DBH and greater than 3.28 ft. tall.

Herb - All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft. tall.

Woody Vines - All woody vines greater than 3.28 ft. in height.

Hydrophytic Vegetation Present ☑ Yes ☐ No

Remarks:

Additional Remarks:

TETRA TECH

WETLAND DETERMINATION DATA FORM
Northeast and Northcentral Region

Project/Site:	Western Maine Renewable Energy Project	Project #:	194-7130
Applicant:	Western Maine Renewables, LLC		
Investigator #1:	Emmy Irvin	Investigator #2:	
Soil Unit:	Telos-Chesuncook-Elliottsville association, 3 to 15% slopes	NWI/WWI Classification:	Upland
Landform:	Terrace	Local Relief:	Linear
Slope (%):	See topo map	Latitude: 45.147302	Longitude: -69.862359 Datum: NAD 83

Are climatic/hydrologic conditions on the site typical for this time of year? (If no, explain in remarks) ☐ Yes ☑ No

Are Vegetation ☐ , Soil ☐ , or Hydrology ☐ significantly disturbed?
Are Vegetation ☐ , Soil ☐ , or Hydrology ☐ naturally problematic?

Are normal circumstances present? ☐ Yes ☑ No

Date:	09/09/20
County:	Somerset
State:	ME
Wetland ID:	W30EI
Sample Point:	**Upland**

SUMMARY OF FINDINGS

Hydrophytic Vegetation Present?	☐ Yes ☑ No	Hydric Soils Present?	☐ Yes ☑ No
Wetland Hydrology Present?	☐ Yes ☑ No	Is This Sampling Point Within A Wetland?	☐ **Yes** ☑ **No**

Remarks: Statewide drought

HYDROLOGY

Wetland Hydrology Indicators (Check here if indicators are not present ☑)

Primary:
- ☐ A1 - Surface Water
- ☐ A2 - High Water Table
- ☐ A3 - Saturation
- ☐ B1 - Water Marks
- ☐ B2 - Sediment Deposits
- ☐ B3 - Drift Deposits
- ☐ B4 - Algal Mat or Crust
- ☐ B5 - Iron Deposits
- ☐ B7 - Inundation Visible on Aerial Imagery
- ☐ B8 - Sparsely Vegetated Concave Surface
- ☐ B9 - Water-Stained Leaves
- ☐ B13 - Aquatic Fauna
- ☐ B15 - Marl Deposits
- ☐ C1 - Hydrogen Sulfide Odor
- ☐ C3 - Oxidized Rhizospheres on Living Roots
- ☐ C4 - Presence of Reduced Iron
- ☐ C6 - Recent Iron Reduction in Tilled Soils
- ☐ C7 - Thin Muck Surface
- ☐ Other (Explain in Remarks)

Secondary:
- ☐ B6 - Surface Soil Cracks
- ☐ B10 - Drainage Patterns
- ☐ B16 - Moss Trim Lines
- ☐ C2 - Dry-Season Water Table
- ☐ C8 - Crayfish Burrows
- ☐ C9 - Saturation Visible on Aerial Imagery
- ☐ D1 - Stunted or Stressed Plants
- ☐ D2 - Geomorphic Position
- ☐ D3 - Shallow Aquitard
- ☐ D4 - Microtopographic Relief
- ☐ D5 - FAC-Neutral Test

Field Observations:

Surface Water Present?	☐ Yes ☑ No	Depth:	(in.)
Water Table Present?	☐ Yes ☑ No	Depth:	(in.)
Saturation Present?	☐ Yes ☑ No	Depth:	(in.)

Wetland Hydrology Present? ☐ Yes ☑ No

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available: N/A

Remarks: Statewide drought

SOILS

Map Unit Name: Telos-Chesuncook-Elliottsville association, 3 to 15% slopes Series Drainage Class: Somewhat poorly drained

Taxonomy (Subgroup): Loamy, isotic, frigid, shallow Aquic Haplorthods

Profile Description (Describe to the depth needed to document the indicator or confirm the absence of indicators.) (Type: C=Concentration, D=Depletion, RM=Reduced Matrix, CS=Covered/Coated Sand Grains; Location: PL=Pore Lining, M=Matrix)

Top Depth	Bottom Depth	Horizon	Matrix Color (Moist)		Matrix %	Mottles Color (Moist)		Mottles %	Mottles Type	Mottles Location	Texture (e.g. clay, sand, loam)
0	2	--	--	--	--	--	--	--	--	--	SAPRIC
2	6	--	10YR	3/2	100	--	--	--	--	--	fine sandy loam
6	14	--	10YR	5/3	100	--	--	--	--	--	fine sandy loam
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--

NRCS Hydric Soil Field Indicators (check here if indicators are not present ☑):
- ☐ A1- Histosol
- ☐ A2 - Histic Epipedon
- ☐ A3 - Black Histic
- ☐ A4 - Hydrogen Sulfide
- ☐ A5 - Stratified Layers
- ☐ A11 - Depleted Below Dark Surface
- ☐ A12 - Thick Dark Surface
- ☐ S1 - Sandy Muck Mineral
- ☐ S4 - Sandy Gleyed Matrix
- ☐ S5 - Sandy Redox
- ☐ S6 - Stripped Matrix
- ☐ S7 - Dark Surface (LRR R, MLRA 149B)
- ☐ S8 - Polyvalue Below Surface (LRR R, MLRA 149B)
- ☐ S9 - Thin Dark Surface (LRR R, MLRA 149B)
- ☐ F1 - Loamy Mucky Mineral (LRR K, L)
- ☐ F2 - Loamy Gleyed Matrix
- ☐ F3 - Depleted Matrix
- ☐ F6 - Redox Dark Surface
- ☐ F7 - Depleted Dark Surface
- ☐ F8 - Redox Depressions

Indicators for Problematic Soils [1]
- ☐ A10 - 2 cm Muck (LRR K, L, MLRA 149B)
- ☐ A16 - Coast Prairie Redox (LRR K, L, R)
- ☐ S3 - 5cm Mucky Peat of Peat (**LRR K, L, R**)
- ☐ S7 - Dark Surface (LRR K, L, M)
- ☐ S8 - Polyvalue Below Surface (**LRR K, L**)
- ☐ S9 - Thin Dark Surface (**LRR K, L**)
- ☐ F12 - Iron-Manganese Masses (**LRR K, L, R**)
- ☐ F19 - Piedmont Floodplain Soils (**MLRA 149B**)
- ☐ TA6 - Mesic Spodic (**MLRA 144A, 145, 149B**)
- ☐ TF2 - Red Parent Material
- ☐ TF12 - Very Shallow Dark Surface
- ☐ Other (Explain in Remarks)

[1] Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (If Observed) Type: LEDGE Depth: 12

Hydric Soil Present? ☐ Yes ☑ No

Remarks:

TETRA TECH

WETLAND DETERMINATION DATA FORM

Northeast and Northcentral Region

Project/Site: Western Maine Renewable Energy Project Wetland ID: W30EI Sample Point **Upland**

VEGETATION (Species identified in all uppercase are non-native species.)

Tree Stratum (Plot size: 10 meter radius)

	Species Name	% Cover	Dominant	Ind.Status
1.	*Acer rubrum*	20	Y	FAC
2.	*Picea rubens*	50	Y	FACU
3.	*Betula alleghaniensis*	20	Y	FAC
4.	*Acer pensylvanicum*	15	Y	FACU
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	105		

Sapling/Shrub Stratum (Plot size: 5 meter radius)

1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	0		

Herb Stratum (Plot size: 2 meter radius)

1.	*Osmunda claytoniana*	1	N	FAC
2.	*Coptis trifolia*	2	N	FACW
3.	*Athyrium angustum*	5	N	FAC
4.	*Maianthemum canadense*	15	Y	FACU
5.	*Medeola virginiana*	10	Y	FACU
6	*Viola palmata*	15	Y	FACU
7.	*Nabalus albus*	5	N	FACU
8.	*Dryopteris campyloptera*	10	Y	FACU
9.	--	--	--	--
10.	--	--	--	--
11.	--	--	--	--
12.	--	--	--	--
13.	--	--	--	--
14.	--	--	--	--
15.	--	--	--	--
	Total Cover =	63		

Woody Vine Stratum (Plot size: 10 meter radius)

1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
	Total Cover =	0		

Remarks:

Dominance Test Worksheet

Number of Dominant Species that are OBL, FACW, or FAC: 2 (A)

Total Number of Dominant Species Across All Strata: 8 (B)

Percent of Dominant Species That Are OBL, FACW, or FAC: ***25.0%*** (A/B)

Prevalence Index Worksheet

Total % Cover of:		Multiply by:	
OBL spp.	0	x 1 =	0
FACW spp.	2	x 2 =	4
FAC spp.	46	x 3 =	138
FACU spp.	120	x 4 =	480
UPL spp.	0	x 5 =	0
Total	168 (A)		622 (B)

Prevalence Index = B/A = ***3.702***

Hydrophytic Vegetation Indicators:

- ☐ Yes ☑ No Rapid Test for Hydrophytic Vegetation
- ☐ Yes ☑ No Dominance Test is > 50%
- ☐ Yes ☑ No Prevalence Index is ≤ 3.0 *
- ☐ Yes ☑ No Morphological Adaptations (Explain) *
- ☐ Yes ☑ No Problem Hydrophytic Vegetation (Explain) *

* Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic.

Definitions of Vegetation Strata:

Tree - Woody plants 3 in. (7.6cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/Shrub - Woody plants less than 3 in. DBH and greater than 3.28 ft. tall.

Herb - All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft. tall.

Woody Vines - All woody vines greater than 3.28 ft. in height.

Hydrophytic Vegetation Present ☐ Yes ☑ No

Additional Remarks:

TETRA TECH

WETLAND DETERMINATION DATA FORM
Northeast and Northcentral Region

Project/Site:	Western Maine Renewable Energy Project	Project #: 194-7130	Date: 09/09/20
Applicant:	Western Maine Renewables, LLC		County: Somerset
Investigator #1:	Emmy Irvin	Investigator #2:	State: ME
Soil Unit:	Telos-Chesuncook association, 3 to 15 percent slopes, very stony	NWI/WWI Classification: PEM	Wetland ID: W30EI
Landform:	Terrace	Local Relief: Linear	Sample Point: **Wetland**
Slope (%):	see topo map	Latitude: 45.147302 Longitude: -69.8623594 Datum: NAD 83	

Are climatic/hydrologic conditions on the site typical for this time of year? (If no, explain in remarks) ☐ Yes ☑ No

Are Vegetation ☐ , Soil ☐ , or Hydrology ☐ significantly disturbed?
Are Vegetation ☐ , Soil ☐ , or Hydrology ☐ naturally problematic?

Are normal circumstances present? ☐ Yes ☑ No

SUMMARY OF FINDINGS

Hydrophytic Vegetation Present?	☑ Yes ☐ No	Hydric Soils Present?	☑ Yes ☐ No
Wetland Hydrology Present?	☑ Yes ☐ No	Is This Sampling Point Within A Wetland?	☑ **Yes** ☐ **No**

Remarks: Statewide drought

HYDROLOGY

Wetland Hydrology Indicators (Check here if indicators are not present ☐)

Primary:
- ☐ A1 - Surface Water
- ☐ A2 - High Water Table
- ☑ A3 - Saturation
- ☐ B1 - Water Marks
- ☐ B2 - Sediment Deposits
- ☐ B3 - Drift Deposits
- ☐ B4 - Algal Mat or Crust
- ☐ B5 - Iron Deposits
- ☐ B7 - Inundation Visible on Aerial Imagery
- ☐ B8 - Sparsely Vegetated Concave Surface
- ☐ B9 - Water-Stained Leaves
- ☐ B13 - Aquatic Fauna
- ☐ B15 - Marl Deposits
- ☐ C1 - Hydrogen Sulfide Odor
- ☐ C3 - Oxidized Rhizospheres on Living Roots
- ☐ C4 - Presence of Reduced Iron
- ☐ C6 - Recent Iron Reduction in Tilled Soils
- ☐ C7 - Thin Muck Surface
- ☐ Other (Explain in Remarks)

Secondary:
- ☐ B6 - Surface Soil Cracks
- ☑ B10 - Drainage Patterns
- ☐ B16 - Moss Trim Lines
- ☐ C2 - Dry-Season Water Table
- ☐ C8 - Crayfish Burrows
- ☐ C9 - Saturation Visible on Aerial Imagery
- ☐ D1 - Stunted or Stressed Plants
- ☐ D2 - Geomorphic Position
- ☐ D3 - Shallow Aquitard
- ☐ D4 - Microtopographic Relief
- ☐ D5 - FAC-Neutral Test

Field Observations:

Surface Water Present?	☐ Yes ☑ No	Depth:		(in.)
Water Table Present?	☐ Yes ☑ No	Depth:		(in.)
Saturation Present?	☑ Yes ☐ No	Depth:	0	(in.)

Wetland Hydrology Present? ☑ Yes ☐ No

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available: N/A

Remarks: Statewide drought

SOILS

Map Unit Name: Telos-Chesuncook association, 3 to 15 percent slopes, very stony — Series Drainage Class: somewhat poorly drained

Taxonomy (Subgroup): Loamy, isotic, frigid, shallow Aquic Haplorthods

Profile Description (Describe to the depth needed to document the indicator or confirm the absence of indicators.) (Type: C=Concentration, D=Depletion, RM=Reduced Matrix, CS=Covered/Coated Sand Grains; Location: PL=Pore Lining, M=Matrix)

Top Depth	Bottom Depth	Horizon	Matrix Color (Moist)		Matrix %	Mottles Color (Moist)		Mottles %	Mottles Type	Mottles Location	Texture (e.g. clay, sand, loam)
0	12	1	10YR	2/1	95	5YR	3/3	5	D	M	ERY FINE SANDY LOA
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--

NRCS Hydric Soil Field Indicators (check here if indicators are not present ☐):
- ☐ A1- Histosol
- ☐ A2 - Histic Epipedon
- ☐ A3 - Black Histic
- ☐ A4 - Hydrogen Sulfide
- ☐ A5 - Stratified Layers
- ☐ A11 - Depleted Below Dark Surface
- ☐ A12 - Thick Dark Surface
- ☐ S1 - Sandy Muck Mineral
- ☐ S4 - Sandy Gleyed Matrix
- ☐ S5 - Sandy Redox
- ☐ S6 - Stripped Matrix
- ☐ S7 - Dark Surface (LRR R, MLRA 149B)
- ☐ S8 - Polyvalue Below Surface (LRR R, MLRA 149B)
- ☐ S9 - Thin Dark Surface (LRR R, MLRA 149B)
- ☐ F1 - Loamy Mucky Mineral (LRR K, L)
- ☐ F2 - Loamy Gleyed Matrix
- ☐ F3 - Depleted Matrix
- ☑ F6 - Redox Dark Surface
- ☐ F7 - Depleted Dark Surface
- ☐ F8 - Redox Depressions

Indicators for Problematic Soils [1]
- ☐ A10 - 2 cm Muck (LRR K, L, MLRA 149B)
- ☐ A16 - Coast Prairie Redox (LRR K, L, R)
- ☐ S3 - 5cm Mucky Peat of Peat (**LRR K, L, R**)
- ☐ S7 - Dark Surface (LRR K, L, M)
- ☐ S8 - Polyvalue Below Surface (**LRR K, L**)
- ☐ S9 - Thin Dark Surface (**LRR K, L**)
- ☐ F12 - Iron-Manganese Masses (**LRR K, L, R**)
- ☐ F19 - Piedmont Floodplain Soils (**MLRA 149B**)
- ☐ TA6 - Mesic Spodic (**MLRA 144A, 145, 149B**)
- ☐ TF2 - Red Parent Material
- ☐ TF12 - Very Shallow Dark Surface
- ☐ Other (Explain in Remarks)

[1] Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (If Observed) Type: LEDGE Depth: 12

Hydric Soil Present? ☑ Yes ☐ No

Remarks: HIGH ORGANIC CONTENT

TETRA TECH

WETLAND DETERMINATION DATA FORM

Northeast and Northcentral Region

Project/Site: Western Maine Renewable Energy Project Wetland ID: W30EI Sample Point **Wetland**

VEGETATION (Species identified in all uppercase are non-native species.)

Tree Stratum (Plot size: 10 meter radius)

	Species Name	% Cover	Dominant	Ind.Status
1.	*Picea mariana*	5	Y	FACW
2.	*Acer rubrum*	5	Y	FAC
3.	*Fraxinus nigra*	5	Y	FACW
4.	*Larix laricina*	5	Y	FACW
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	20		

Sapling/Shrub Stratum (Plot size: 5 meter radius)

1.	*Alnus incana*	10	Y	FACW
2.	*Acer rubrum*	5	N	FAC
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	15		

Herb Stratum (Plot size: 2 meter radius)

1.	*Carex stricta*	90	Y	OBL
2.	*Symphyotrichum novae-angliae*	15	N	FACW
3.	*Onoclea sensibilis*	20	Y	FACW
4.	*Impatiens capensis*	25	Y	FACW
5.	*Spiraea alba*	15	N	FACW
6	*Calamagrostis canadensis*	20	Y	OBL
7.	*Osmunda claytoniana*	5	N	FAC
8.	*Solidago canadensis*	5	N	FACU
9.	*Rubus idaeus*	5	N	FACU
10.	*Scirpus cyperinus*	5	N	OBL
11.	--	--	--	--
12.	--	--	--	--
13.	--	--	--	--
14.	--	--	--	--
15.	--	--	--	--
	Total Cover =	205		

Woody Vine Stratum (Plot size: 10 meter radius)

1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
	Total Cover =	0		

Remarks:

Dominance Test Worksheet

Number of Dominant Species that are OBL, FACW, or FAC: 9 (A)

Total Number of Dominant Species Across All Strata: 9 (B)

Percent of Dominant Species That Are OBL, FACW, or FAC: ***100.0%*** (A/B)

Prevalence Index Worksheet

Total % Cover of:		Multiply by:	
OBL spp.	115	x 1 =	115
FACW spp.	100	x 2 =	200
FAC spp.	15	x 3 =	45
FACU spp.	10	x 4 =	40
UPL spp.	0	x 5 =	0
Total	240 (A)		400 (B)

Prevalence Index = B/A = ***1.667***

Hydrophytic Vegetation Indicators:

☐	Yes	☑	No	Rapid Test for Hydrophytic Vegetation
☑	Yes	☐	No	Dominance Test is > 50%
☑	Yes	☐	No	Prevalence Index is ≤ 3.0 *
☐	Yes	☑	No	Morphological Adaptations (Explain) *
☐	Yes	☑	No	Problem Hydrophytic Vegetation (Explain) *

* Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic.

Definitions of Vegetation Strata:

Tree - Woody plants 3 in. (7.6cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/Shrub - Woody plants less than 3 in. DBH and greater than 3.28 ft. tall.

Herb - All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft. tall.

Woody Vines - All woody vines greater than 3.28 ft. in height.

Hydrophytic Vegetation Present ☑ Yes ☐ No

Additional Remarks:

TETRA TECH

WETLAND DETERMINATION DATA FORM
Northeast and Northcentral Region

Project/Site:	Western Maine Renewable Energy Project	Project #: 194-7130	Date: 09/09/20
Applicant:	Western Maine Renewables, LLC		County: Somerset
Investigator #1:	Emmy Irvin	Investigator #2:	State: ME
Soil Unit:	Chesuncook-Elliottsville-Telos association, 3 to 15 % slopes	NWI/WWI Classification: Upland	Wetland ID: W35EI
Landform:	Terrace	Local Relief: Linear	Sample Point: **Upland**
Slope (%):	See topo map	Latitude: 45.144677° Longitude: -69.865045° Datum: NAD 83	

Are climatic/hydrologic conditions on the site typical for this time of year? (If no, explain in remarks) ☐ Yes ☑ No

Are Vegetation ☐, Soil ☐, or Hydrology ☐ significantly disturbed?
Are Vegetation ☐, Soil ☐, or Hydrology ☐ naturally problematic?

Are normal circumstances present? ☐ Yes ☑ No

SUMMARY OF FINDINGS

Hydrophytic Vegetation Present?	☐ Yes ☑ No	Hydric Soils Present?	☐ Yes ☑ No
Wetland Hydrology Present?	☐ Yes ☑ No	Is This Sampling Point Within A Wetland?	☐ **Yes** ☑ **No**

Remarks: Statewide drought

HYDROLOGY

Wetland Hydrology Indicators (Check here if indicators are not present ☑)

Primary:
- ☐ A1 - Surface Water
- ☐ A2 - High Water Table
- ☐ A3 - Saturation
- ☐ B1 - Water Marks
- ☐ B2 - Sediment Deposits
- ☐ B3 - Drift Deposits
- ☐ B4 - Algal Mat or Crust
- ☐ B5 - Iron Deposits
- ☐ B7 - Inundation Visible on Aerial Imagery
- ☐ B8 - Sparsely Vegetated Concave Surface
- ☐ B9 - Water-Stained Leaves
- ☐ B13 - Aquatic Fauna
- ☐ B15 - Marl Deposits
- ☐ C1 - Hydrogen Sulfide Odor
- ☐ C3 - Oxidized Rhizospheres on Living Roots
- ☐ C4 - Presence of Reduced Iron
- ☐ C6 - Recent Iron Reduction in Tilled Soils
- ☐ C7 - Thin Muck Surface
- ☐ Other (Explain in Remarks)

Secondary:
- ☐ B6 - Surface Soil Cracks
- ☐ B10 - Drainage Patterns
- ☐ B16 - Moss Trim Lines
- ☐ C2 - Dry-Season Water Table
- ☐ C8 - Crayfish Burrows
- ☐ C9 - Saturation Visible on Aerial Imagery
- ☐ D1 - Stunted or Stressed Plants
- ☐ D2 - Geomorphic Position
- ☐ D3 - Shallow Aquitard
- ☐ D4 - Microtopographic Relief
- ☐ D5 - FAC-Neutral Test

Field Observations:

Surface Water Present?	☐ Yes ☑ No	Depth:	(in.)
Water Table Present?	☐ Yes ☑ No	Depth:	(in.)
Saturation Present?	☐ Yes ☑ No	Depth:	(in.)

Wetland Hydrology Present? ☐ Yes ☑ No

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available: N/A

Remarks: Statewide drought

SOILS

Map Unit Name: Chesuncook-Elliottsville-Telos association, 3 to 15 % slopes Series Drainage Class: Moderately well drained

Taxonomy (Subgroup): Coarse-loamy, isotic, frigid Aquic Haplorthods

Profile Description (Describe to the depth needed to document the indicator or confirm the absence of indicators.) (Type: C=Concentration, D=Depletion, RM=Reduced Matrix, CS=Covered/Coated Sand Grains; Location: PL=Pore Lining, M=Matrix)

Top Depth	Bottom Depth	Horizon	Matrix Color (Moist)		Matrix %	Mottles Color (Moist)		Mottles %	Mottles Type	Mottles Location	Texture (e.g. clay, sand, loam)
2	6	--	10YR	3/2	100	--	--	--	--	--	fine sandy loam
6	12	--	10YR	5/3	100	--	--	--	--	--	fine sandy loam
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--

NRCS Hydric Soil Field Indicators (check here if indicators are not present ☑):
- ☐ A1- Histosol
- ☐ A2 - Histic Epipedon
- ☐ A3 - Black Histic
- ☐ A4 - Hydrogen Sulfide
- ☐ A5 - Stratified Layers
- ☐ A11 - Depleted Below Dark Surface
- ☐ A12 - Thick Dark Surface
- ☐ S1 - Sandy Muck Mineral
- ☐ S4 - Sandy Gleyed Matrix
- ☐ S5 - Sandy Redox
- ☐ S6 - Stripped Matrix
- ☐ S7 - Dark Surface (LRR R, MLRA 149B)
- ☐ S8 - Polyvalue Below Surface (LRR R, MLRA 149B)
- ☐ S9 - Thin Dark Surface (LRR R, MLRA 149B)
- ☐ F1 - Loamy Mucky Mineral (LRR K, L)
- ☐ F2 - Loamy Gleyed Matrix
- ☐ F3 - Depleted Matrix
- ☐ F6 - Redox Dark Surface
- ☐ F7 - Depleted Dark Surface
- ☐ F8 - Redox Depressions

Indicators for Problematic Soils [1]
- ☐ A10 - 2 cm Muck (LRR K, L, MLRA 149B)
- ☐ A16 - Coast Prairie Redox (LRR K, L, R)
- ☐ S3 - 5cm Mucky Peat of Peat (**LRR K, L, R**)
- ☐ S7 - Dark Surface (LRR K, L, M)
- ☐ S8 - Polyvalue Below Surface (**LRR K, L**)
- ☐ S9 - Thin Dark Surface (**LRR K, L**)
- ☐ F12 - Iron-Manganese Masses (**LRR K, L, R**)
- ☐ F19 - Piedmont Floodplain Soils (**MLRA 149B**)
- ☐ TA6 - Mesic Spodic (**MLRA 144A, 145, 149B**)
- ☐ TF2 - Red Parent Material
- ☐ TF12 - Very Shallow Dark Surface
- ☐ Other (Explain in Remarks)

[1] Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (If Observed) Type: LEDGE Depth: 12

Hydric Soil Present? ☐ Yes ☑ No

Remarks:

TETRA TECH

WETLAND DETERMINATION DATA FORM

Northeast and Northcentral Region

Project/Site: Western Maine Renewable Energy Project | Wetland ID: W35EI | Sample Point **Upland**

VEGETATION (Species identified in all uppercase are non-native species.)

Tree Stratum (Plot size: 10 meter radius)

	Species Name	% Cover	Dominant	Ind.Status
1.	*Acer rubrum*	20	Y	FAC
2.	*Picea rubens*	50	Y	FACU
3.	*Betula alleghaniensis*	20	Y	FAC
4.	*Acer pensylvanicum*	15	Y	FACU
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	105		

Sapling/Shrub Stratum (Plot size: 5 meter radius)

1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	0		

Herb Stratum (Plot size: 2 meter radius)

1.	*Osmunda claytoniana*	1	N	FAC
2.	*Coptis trifolia*	2	N	FACW
3.	*Athyrium angustum*	5	N	FAC
4.	*Maianthemum canadense*	15	Y	FACU
5.	*Medeola virginiana*	10	Y	FACU
6	*Viola palmata*	15	Y	FACU
7.	*Nabalus albus*	5	N	FACU
8.	*Dryopteris campyloptera*	10	Y	FACU
9.	--	--	--	--
10.	--	--	--	--
11.	--	--	--	--
12.	--	--	--	--
13.	--	--	--	--
14.	--	--	--	--
15.	--	--	--	--
	Total Cover =	63		

Woody Vine Stratum (Plot size: 10 meter radius)

1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
	Total Cover =	0		

Remarks:

Dominance Test Worksheet

Number of Dominant Species that are OBL, FACW, or FAC: 2 (A)

Total Number of Dominant Species Across All Strata: 8 (B)

Percent of Dominant Species That Are OBL, FACW, or FAC: ***25.0%*** (A/B)

Prevalence Index Worksheet

Total % Cover of:		Multiply by:	
OBL spp.	0	x 1 =	0
FACW spp.	2	x 2 =	4
FAC spp.	46	x 3 =	138
FACU spp.	120	x 4 =	480
UPL spp.	0	x 5 =	0
Total	168 (A)		622 (B)

Prevalence Index = B/A = ***3.702***

Hydrophytic Vegetation Indicators:

- ☐ Yes ☑ No Rapid Test for Hydrophytic Vegetation
- ☐ Yes ☑ No Dominance Test is > 50%
- ☐ Yes ☑ No Prevalence Index is ≤ 3.0 *
- ☐ Yes ☑ No Morphological Adaptations (Explain) *
- ☐ Yes ☑ No Problem Hydrophytic Vegetation (Explain) *

* Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic.

Definitions of Vegetation Strata:

Tree - Woody plants 3 in. (7.6cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/Shrub - Woody plants less than 3 in. DBH and greater than 3.28 ft. tall.

Herb - All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft. tall.

Woody Vines - All woody vines greater than 3.28 ft. in height.

Hydrophytic Vegetation Present ☐ Yes ☑ No

Additional Remarks:

TETRA TECH

WETLAND DETERMINATION DATA FORM
Northeast and Northcentral Region

Project/Site:	Western Maine Renewable Energy Project	Project #:	194-7130
Applicant:	Western Maine Renewables, LLC		
Investigator #1:	Emmy Irvin	Investigator #2:	
Soil Unit:	Chesuncook-Elliottsville-Telos association, 3 to 15%	NWI/WWI Classification:	PEM
Landform:	Summit	Local Relief:	Convex
Slope (%):	See topo map	Latitude: 45.144638	Longitude: -69.8652359 Datum: NAD 83

Are climatic/hydrologic conditions on the site typical for this time of year? (If no, explain in remarks) ☐ Yes ☐ No

Are Vegetation ☐, Soil ☐, or Hydrology ☐ significantly disturbed?
Are Vegetation ☐, Soil ☐, or Hydrology ☐ naturally problematic?

Are normal circumstances present? ☐ Yes ☑ No

Date:	09/09/20
County:	Somerset
State:	ME
Wetland ID:	W35EI
Sample Point:	**Wetland**

SUMMARY OF FINDINGS

Hydrophytic Vegetation Present?	☑ Yes ☐ No	Hydric Soils Present?	☑ Yes ☐ No
Wetland Hydrology Present?	☑ Yes ☐ No	Is This Sampling Point Within A Wetland?	☑ **Yes** ☐ **No**

Remarks: Statewide drought

HYDROLOGY

Wetland Hydrology Indicators (Check here if indicators are not present ☐)

Primary:
- ☐ A1 - Surface Water
- ☐ A2 - High Water Table
- ☑ A3 - Saturation
- ☐ B1 - Water Marks
- ☐ B2 - Sediment Deposits
- ☐ B3 - Drift Deposits
- ☐ B4 - Algal Mat or Crust
- ☐ B5 - Iron Deposits
- ☐ B7 - Inundation Visible on Aerial Imagery
- ☐ B8 - Sparsely Vegetated Concave Surface
- ☐ B9 - Water-Stained Leaves
- ☐ B13 - Aquatic Fauna
- ☐ B15 - Marl Deposits
- ☐ C1 - Hydrogen Sulfide Odor
- ☐ C3 - Oxidized Rhizospheres on Living Roots
- ☐ C4 - Presence of Reduced Iron
- ☐ C6 - Recent Iron Reduction in Tilled Soils
- ☐ C7 - Thin Muck Surface
- ☐ Other (Explain in Remarks)

Secondary:
- ☐ B6 - Surface Soil Cracks
- ☐ B10 - Drainage Patterns
- ☐ B16 - Moss Trim Lines
- ☐ C2 - Dry-Season Water Table
- ☐ C8 - Crayfish Burrows
- ☐ C9 - Saturation Visible on Aerial Imagery
- ☐ D1 - Stunted or Stressed Plants
- ☐ D2 - Geomorphic Position
- ☐ D3 - Shallow Aquitard
- ☑ D4 - Microtopographic Relief
- ☐ D5 - FAC-Neutral Test

Field Observations:

Surface Water Present?	☐ Yes	☑ No	Depth:	(in.)
Water Table Present?	☐ Yes	☑ No	Depth:	(in.)
Saturation Present?	☑ Yes	☐ No	Depth: 8	(in.)

Wetland Hydrology Present? ☑ Yes ☐ No

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available: N/A

Remarks: Statewide drought

SOILS

Map Unit Name: Chesuncook-Elliottsville-Telos association, 3 to 15% Series Drainage Class: moderately well drained

Taxonomy (Subgroup): Coarse-loamy, isotic, frigid Aquic Haplorthods

Profile Description (Describe to the depth needed to document the indicator or confirm the absence of indicators.) (Type: C=Concentration, D=Depletion, RM=Reduced Matrix, CS=Covered/Coated Sand Grains; Location: PL=Pore Lining, M=Matrix)

Top Depth	Bottom Depth	Horizon	Matrix Color (Moist)		Matrix %	Mottles Color (Moist)		Mottles %	Mottles Type	Mottles Location	Texture (e.g. clay, sand, loam)
0	10	--	10YR	2/1	100	--	--	--	--	--	fine sandy loam
10	18	--	10YR	5/1	75	10YR	4/6	25	C	M	silt loam
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--

NRCS Hydric Soil Field Indicators (check here if indicators are not present ☐):
- ☐ A1- Histosol
- ☐ A2 - Histic Epipedon
- ☐ A3 - Black Histic
- ☐ A4 - Hydrogen Sulfide
- ☐ A5 - Stratified Layers
- ☑ A11 - Depleted Below Dark Surface
- ☐ A12 - Thick Dark Surface
- ☐ S1 - Sandy Muck Mineral
- ☐ S4 - Sandy Gleyed Matrix
- ☐ S5 - Sandy Redox
- ☐ S6 - Stripped Matrix
- ☐ S7 - Dark Surface (LRR R, MLRA 149B)
- ☐ S8 - Polyvalue Below Surface (LRR R, MLRA 149B)
- ☐ S9 - Thin Dark Surface (LRR R, MLRA 149B)
- ☐ F1 - Loamy Mucky Mineral (LRR K, L)
- ☐ F2 - Loamy Gleyed Matrix
- ☐ F3 - Depleted Matrix
- ☐ F6 - Redox Dark Surface
- ☐ F7 - Depleted Dark Surface
- ☐ F8 - Redox Depressions

Indicators for Problematic Soils [1]
- ☐ A10 - 2 cm Muck (LRR K, L, MLRA 149B)
- ☐ A16 - Coast Prairie Redox (LRR K, L, R)
- ☐ S3 - 5cm Mucky Peat of Peat (**LRR K, L, R**)
- ☐ S7 - Dark Surface (LRR K, L, M)
- ☐ S8 - Polyvalue Below Surface (**LRR K, L**)
- ☐ S9 - Thin Dark Surface (**LRR K, L**)
- ☐ F12 - Iron-Manganese Masses (**LRR K, L, R**)
- ☐ F19 - Piedmont Floodplain Soils (**MLRA 149B**)
- ☐ TA6 - Mesic Spodic (**MLRA 144A, 145, 149B**)
- ☐ TF2 - Red Parent Material
- ☐ TF12 - Very Shallow Dark Surface
- ☐ Other (Explain in Remarks)

[1] Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (If Observed) Type: none Depth:

Hydric Soil Present? ☑ Yes ☐ No

Remarks:

TETRA TECH

WETLAND DETERMINATION DATA FORM

Northeast and Northcentral Region

Project/Site: Western Maine Renewable Energy Project Wetland ID: W35EI Sample Point **Wetland**

VEGETATION (Species identified in all uppercase are non-native species.)

Tree Stratum (Plot size: 10 meter radius)

	Species Name	% Cover	Dominant	Ind.Status
1.	*Picea mariana*	30	Y	FACW
2.	*Acer rubrum*	10	N	FAC
3.	*Acer pensylvanicum*	5	N	FACU
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	45		

Sapling/Shrub Stratum (Plot size: 5 meter radius)

1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	0		

Herb Stratum (Plot size: 2 meter radius)

1.	*Osmundastrum cinnamomeum*	20	Y	FACW
2.	*Calamagrostis canadensis*	25	Y	OBL
3.	*Eutrochium purpureum*	25	Y	FAC
4.	*Symphyotrichum novae-angliae*	10	N	FACW
5.	*Ribes lacustre*	10	N	FACW
6	*Dryopteris marginalis*	5	N	FACU
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
11.	--	--	--	--
12.	--	--	--	--
13.	--	--	--	--
14.	--	--	--	--
15.	--	--	--	--
	Total Cover =	95		

Woody Vine Stratum (Plot size: 10 meter radius)

1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
	Total Cover =	0		

Remarks:

Dominance Test Worksheet

Number of Dominant Species that are OBL, FACW, or FAC: 4 (A)

Total Number of Dominant Species Across All Strata: 4 (B)

Percent of Dominant Species That Are OBL, FACW, or FAC: ***100.0%*** (A/B)

Prevalence Index Worksheet

Total % Cover of:		Multiply by:	
OBL spp.	25	x 1 =	25
FACW spp.	70	x 2 =	140
FAC spp.	35	x 3 =	105
FACU spp.	10	x 4 =	40
UPL spp.	0	x 5 =	0
Total	140 (A)		310 (B)

Prevalence Index = B/A = ***2.214***

Hydrophytic Vegetation Indicators:

- ☐ Yes ☑ No Rapid Test for Hydrophytic Vegetation
- ☑ Yes ☐ No Dominance Test is > 50%
- ☑ Yes ☐ No Prevalence Index is ≤ 3.0 *
- ☐ Yes ☑ No Morphological Adaptations (Explain) *
- ☐ Yes ☑ No Problem Hydrophytic Vegetation (Explain) *

* Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic.

Definitions of Vegetation Strata:

Tree - Woody plants 3 in. (7.6cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/Shrub - Woody plants less than 3 in. DBH and greater than 3.28 ft. tall.

Herb - All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft. tall.

Woody Vines - All woody vines greater than 3.28 ft. in height.

Hydrophytic Vegetation Present ☑ Yes ☐ No

Additional Remarks:

TETRA TECH

WETLAND DETERMINATION DATA FORM
Northeast and Northcentral Region

Project/Site:	Western Maine Renewable Energy Project	Project #:	194-7130
Applicant:	Western Maine Renewables, LLC		
Investigator #1:	Emmy Irvin	Investigator #2:	
Soil Unit:	Chesuncook-Elliottsville-Telos association, 3 to 15	NWI/WWI Classification:	Upland
Landform:	Terrace	Local Relief:	Linear
Slope (%):	See topo map	Latitude: 45.143264°	Longitude: 45.143264° Datum: NAD 83

Are climatic/hydrologic conditions on the site typical for this time of year? (If no, explain in remarks) ☐ Yes ☑ No

Are Vegetation ☐, Soil ☐, or Hydrology ☐ significantly disturbed?
Are Vegetation ☐, Soil ☐, or Hydrology ☑ naturally problematic?

Are normal circumstances present? ☐ Yes ☑ No

Date:	09/09/20
County:	Somerset
State:	ME
Wetland ID:	W37EI
Sample Point:	**Upland**

SUMMARY OF FINDINGS

Hydrophytic Vegetation Present?	☐ Yes ☑ No	Hydric Soils Present?	☐ Yes ☑ No
Wetland Hydrology Present?	☐ Yes ☑ No	Is This Sampling Point Within A Wetland?	☐ **Yes** ☑ **No**

Remarks: Statewide drought

HYDROLOGY

Wetland Hydrology Indicators (Check here if indicators are not present ☑)

Primary:
- ☐ A1 - Surface Water
- ☐ A2 - High Water Table
- ☐ A3 - Saturation
- ☐ B1 - Water Marks
- ☐ B2 - Sediment Deposits
- ☐ B3 - Drift Deposits
- ☐ B4 - Algal Mat or Crust
- ☐ B5 - Iron Deposits
- ☐ B7 - Inundation Visible on Aerial Imagery
- ☐ B8 - Sparsely Vegetated Concave Surface
- ☐ B9 - Water-Stained Leaves
- ☐ B13 - Aquatic Fauna
- ☐ B15 - Marl Deposits
- ☐ C1 - Hydrogen Sulfide Odor
- ☐ C3 - Oxidized Rhizospheres on Living Roots
- ☐ C4 - Presence of Reduced Iron
- ☐ C6 - Recent Iron Reduction in Tilled Soils
- ☐ C7 - Thin Muck Surface
- ☐ Other (Explain in Remarks)

Secondary:
- ☐ B6 - Surface Soil Cracks
- ☐ B10 - Drainage Patterns
- ☐ B16 - Moss Trim Lines
- ☐ C2 - Dry-Season Water Table
- ☐ C8 - Crayfish Burrows
- ☐ C9 - Saturation Visible on Aerial Imagery
- ☐ D1 - Stunted or Stressed Plants
- ☐ D2 - Geomorphic Position
- ☐ D3 - Shallow Aquitard
- ☐ D4 - Microtopographic Relief
- ☐ D5 - FAC-Neutral Test

Field Observations:

Surface Water Present?	☐ Yes ☑ No	Depth:	(in.)
Water Table Present?	☐ Yes ☑ No	Depth:	(in.)
Saturation Present?	☐ Yes ☑ No	Depth:	(in.)

Wetland Hydrology Present? ☐ Yes ☑ No

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available: N/A

Remarks: Statewide drought

SOILS

Map Unit Name: Chesuncook-Elliottsville-Telos association, 3 to 15% Series Drainage Class: moderately well drained

Taxonomy (Subgroup): Coarse-loamy, isotic, frigid Aquic Haplorthods

Profile Description (Describe to the depth needed to document the indicator or confirm the absence of indicators.) (Type: C=Concentration, D=Depletion, RM=Reduced Matrix, CS=Covered/Coated Sand Grains; Location: PL=Pore Lining, M=Matrix)

Top Depth	Bottom Depth	Horizon	Matrix Color (Moist)		Matrix %	Mottles Color (Moist)		Mottles %	Mottles Type	Mottles Location	Texture (e.g. clay, sand, loam)
2	6	--	10YR	3/2	100	--	--	--	--	--	fine sandy loam
6	12	--	10YR	5/3	100	--	--	--	--	--	fine sandy loam
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--

NRCS Hydric Soil Field Indicators (check here if indicators are not present ☑):
- ☐ A1- Histosol
- ☐ A2 - Histic Epipedon
- ☐ A3 - Black Histic
- ☐ A4 - Hydrogen Sulfide
- ☐ A5 - Stratified Layers
- ☐ A11 - Depleted Below Dark Surface
- ☐ A12 - Thick Dark Surface
- ☐ S1 - Sandy Muck Mineral
- ☐ S4 - Sandy Gleyed Matrix
- ☐ S5 - Sandy Redox
- ☐ S6 - Stripped Matrix
- ☐ S7 - Dark Surface (LRR R, MLRA 149B)
- ☐ S8 - Polyvalue Below Surface (LRR R, MLRA 149B)
- ☐ S9 - Thin Dark Surface (LRR R, MLRA 149B)
- ☐ F1 - Loamy Mucky Mineral (LRR K, L)
- ☐ F2 - Loamy Gleyed Matrix
- ☐ F3 - Depleted Matrix
- ☐ F6 - Redox Dark Surface
- ☐ F7 - Depleted Dark Surface
- ☐ F8 - Redox Depressions

Indicators for Problematic Soils [1]
- ☐ A10 - 2 cm Muck (LRR K, L, MLRA 149B)
- ☐ A16 - Coast Prairie Redox (LRR K, L, R)
- ☐ S3 - 5cm Mucky Peat of Peat (**LRR K, L, R**)
- ☐ S7 - Dark Surface (LRR K, L, M)
- ☐ S8 - Polyvalue Below Surface (**LRR K, L**)
- ☐ S9 - Thin Dark Surface (**LRR K, L**)
- ☐ F12 - Iron-Manganese Masses (**LRR K, L, R**)
- ☐ F19 - Piedmont Floodplain Soils (**MLRA 149B**)
- ☐ TA6 - Mesic Spodic (**MLRA 144A, 145, 149B**)
- ☐ TF2 - Red Parent Material
- ☐ TF12 - Very Shallow Dark Surface
- ☐ Other (Explain in Remarks)

[1] Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (If Observed) Type: LEDGE Depth: 12

Hydric Soil Present? ☐ Yes ☑ No

Remarks:

TETRA TECH

WETLAND DETERMINATION DATA FORM

Northeast and Northcentral Region

Project/Site: Western Maine Renewable Energy Project | Wetland ID: W37EI | Sample Point **Upland**

VEGETATION (Species identified in all uppercase are non-native species.)

Tree Stratum (Plot size: 10 meter radius)

	Species Name	% Cover	Dominant	Ind.Status
1.	*Acer rubrum*	15	Y	FAC
2.	*Picea rubens*	25	Y	FACU
3.	*Betula alleghaniensis*	20	Y	FAC
4.	*Acer pensylvanicum*	10	Y	FACU
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	70		

Sapling/Shrub Stratum (Plot size: 5 meter radius)

1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	0		

Herb Stratum (Plot size: 2 meter radius)

1.	*Osmunda claytoniana*	1	N	FAC
2.	*Coptis trifolia*	2	N	FACW
3.	*Athyrium angustum*	5	N	FAC
4.	*Maianthemum canadense*	15	Y	FACU
5.	*Medeola virginiana*	10	Y	FACU
6	*Viola palmata*	15	Y	FACU
7.	*Nabalus albus*	5	N	FACU
8.	*Dryopteris campyloptera*	10	Y	FACU
9.	--	--	--	--
10.	--	--	--	--
11.	--	--	--	--
12.	--	--	--	--
13.	--	--	--	--
14.	--	--	--	--
15.	--	--	--	--
	Total Cover =	63		

Woody Vine Stratum (Plot size: 10 meter radius)

1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
	Total Cover =	0		

Remarks:

Dominance Test Worksheet

Number of Dominant Species that are OBL, FACW, or FAC: 2 (A)

Total Number of Dominant Species Across All Strata: 8 (B)

Percent of Dominant Species That Are OBL, FACW, or FAC: ***25.0%*** (A/B)

Prevalence Index Worksheet

Total % Cover of:		Multiply by:	
OBL spp.	0	x 1 =	0
FACW spp.	2	x 2 =	4
FAC spp.	41	x 3 =	123
FACU spp.	90	x 4 =	360
UPL spp.	0	x 5 =	0
Total	133 (A)		487 (B)

Prevalence Index = B/A = ***3.662***

Hydrophytic Vegetation Indicators:

- ☐ Yes ☑ No Rapid Test for Hydrophytic Vegetation
- ☐ Yes ☑ No Dominance Test is > 50%
- ☐ Yes ☑ No Prevalence Index is ≤ 3.0 *
- ☐ Yes ☑ No Morphological Adaptations (Explain) *
- ☐ Yes ☑ No Problem Hydrophytic Vegetation (Explain) *

* Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic.

Definitions of Vegetation Strata:

Tree - Woody plants 3 in. (7.6cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/Shrub - Woody plants less than 3 in. DBH and greater than 3.28 ft. tall.

Herb - All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft. tall.

Woody Vines - All woody vines greater than 3.28 ft. in height.

Hydrophytic Vegetation Present ☐ Yes ☑ No

Additional Remarks:

TETRA TECH

WETLAND DETERMINATION DATA FORM
Northeast and Northcentral Region

Project/Site:	Western Maine Renewable Energy Project		Project #: 194-7130	Date:	09/09/20
Applicant:	Western Maine Renewables, LLC			County:	Somerset
Investigator #1:	Emmy Irvin	Investigator #2:		State:	ME
Soil Unit:	Chesuncook-Elliottsville-Telos association, 3 to 15%		NWI/WWI Classification: PEM	Wetland ID:	W37EI
Landform:	Terrace		Local Relief: Linear	Sample Point:	**Wetland**
Slope (%):	see topo map	Latitude: 45.143200	Longitude: -69.8669641	Datum: NAD 83	

Are climatic/hydrologic conditions on the site typical for this time of year? (If no, explain in remarks) ☐ Yes ☑ No

Are Vegetation ☐, Soil ☐, or Hydrology ☐ significantly disturbed?
Are Vegetation ☐, Soil ☐, or Hydrology ☐ naturally problematic?

Are normal circumstances present? ☐ Yes ☑ No

SUMMARY OF FINDINGS

Hydrophytic Vegetation Present?	☑ Yes ☐ No	Hydric Soils Present?	☑ Yes ☐ No
Wetland Hydrology Present?	☑ Yes ☐ No	Is This Sampling Point Within A Wetland?	☑ **Yes** ☐ **No**

Remarks: Statewide drought

HYDROLOGY

Wetland Hydrology Indicators (Check here if indicators are not present ☐)

Primary:
- ☐ A1 - Surface Water
- ☐ A2 - High Water Table
- ☑ A3 - Saturation
- ☐ B1 - Water Marks
- ☐ B2 - Sediment Deposits
- ☐ B3 - Drift Deposits
- ☐ B4 - Algal Mat or Crust
- ☐ B5 - Iron Deposits
- ☐ B7 - Inundation Visible on Aerial Imagery
- ☐ B8 - Sparsely Vegetated Concave Surface
- ☐ B9 - Water-Stained Leaves
- ☐ B13 - Aquatic Fauna
- ☐ B15 - Marl Deposits
- ☐ C1 - Hydrogen Sulfide Odor
- ☐ C3 - Oxidized Rhizospheres on Living Roots
- ☐ C4 - Presence of Reduced Iron
- ☐ C6 - Recent Iron Reduction in Tilled Soils
- ☐ C7 - Thin Muck Surface
- ☐ Other (Explain in Remarks)

Secondary:
- ☐ B6 - Surface Soil Cracks
- ☐ B10 - Drainage Patterns
- ☐ B16 - Moss Trim Lines
- ☐ C2 - Dry-Season Water Table
- ☐ C8 - Crayfish Burrows
- ☐ C9 - Saturation Visible on Aerial Imagery
- ☐ D1 - Stunted or Stressed Plants
- ☐ D2 - Geomorphic Position
- ☐ D3 - Shallow Aquitard
- ☐ D4 - Microtopographic Relief
- ☐ D5 - FAC-Neutral Test

Field Observations:

Surface Water Present?	☐ Yes ☑ No	Depth:		(in.)
Water Table Present?	☐ Yes ☑ No	Depth:		(in.)
Saturation Present?	☑ Yes ☐ No	Depth:	4	(in.)

Wetland Hydrology Present? ☑ Yes ☐ No

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available: N/A

Remarks: Statewide drought

SOILS

Map Unit Name: Chesuncook-Elliottsville-Telos association, 3 to 15% Series Drainage Class: moderately well drained

Taxonomy (Subgroup): Coarse-loamy, isotic, frigid Aquic Haplorthods

Profile Description (Describe to the depth needed to document the indicator or confirm the absence of indicators.) (Type: C=Concentration, D=Depletion, RM=Reduced Matrix, CS=Covered/Coated Sand Grains; Location: PL=Pore Lining, M=Matrix)

Top Depth	Bottom Depth	Horizon	Matrix Color (Moist)		Matrix %	Mottles Color (Moist)		Mottles %	Mottles Type	Mottles Location	Texture (e.g. clay, sand, loam)
0	4	--	10YR	2/1	100	--	--	--	--	--	VFSL HIGH ORGANIC
4	12	--	10YR	5/1	75	10YR	7/8	25	C	M	ERY FINE SANDY LOA
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--

NRCS Hydric Soil Field Indicators (check here if indicators are not present ☐):
- ☐ A1- Histosol
- ☐ A2 - Histic Epipedon
- ☐ A3 - Black Histic
- ☐ A4 - Hydrogen Sulfide
- ☐ A5 - Stratified Layers
- ☐ A11 - Depleted Below Dark Surface
- ☐ A12 - Thick Dark Surface
- ☐ S1 - Sandy Muck Mineral
- ☐ S4 - Sandy Gleyed Matrix
- ☐ S5 - Sandy Redox
- ☐ S6 - Stripped Matrix
- ☐ S7 - Dark Surface (LRR R, MLRA 149B)
- ☐ S8 - Polyvalue Below Surface (LRR R, MLRA 149B)
- ☐ S9 - Thin Dark Surface (LRR R, MLRA 149B)
- ☐ F1 - Loamy Mucky Mineral (LRR K, L)
- ☐ F2 - Loamy Gleyed Matrix
- ☑ F3 - Depleted Matrix
- ☐ F6 - Redox Dark Surface
- ☐ F7 - Depleted Dark Surface
- ☐ F8 - Redox Depressions

Indicators for Problematic Soils [1]
- ☐ A10 - 2 cm Muck (LRR K, L, MLRA 149B)
- ☐ A16 - Coast Prairie Redox (LRR K, L, R)
- ☐ S3 - 5cm Mucky Peat of Peat (**LRR K, L, R**)
- ☐ S7 - Dark Surface (LRR K, L, M)
- ☐ S8 - Polyvalue Below Surface (**LRR K, L**)
- ☐ S9 - Thin Dark Surface (**LRR K, L**)
- ☐ F12 - Iron-Manganese Masses (**LRR K, L, R**)
- ☐ F19 - Piedmont Floodplain Soils (**MLRA 149B**)
- ☐ TA6 - Mesic Spodic (**MLRA 144A, 145, 149B**)
- ☐ TF2 - Red Parent Material
- ☐ TF12 - Very Shallow Dark Surface
- ☐ Other (Explain in Remarks)

[1] Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (If Observed) Type: LEDGE Depth: 12

Hydric Soil Present? ☑ Yes ☐ No

Remarks:

TETRA TECH

WETLAND DETERMINATION DATA FORM

Northeast and Northcentral Region

Project/Site: Western Maine Renewable Energy Project Wetland ID: W37EI Sample Point **Wetland**

VEGETATION (Species identified in all uppercase are non-native species.)

Tree Stratum (Plot size: 10 meter radius)

	Species Name	% Cover	Dominant	Ind.Status
1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	0		

Sapling/Shrub Stratum (Plot size: 5 meter radius)

1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	0		

Herb Stratum (Plot size: 2 meter radius)

1.	*Carex crinita*	50	Y	OBL
2.	*Carex intumescens*	25	Y	FACW
3.	*Onoclea sensibilis*	5	N	FACW
4.	--	--	--	--
5.	--	--	--	--
6	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
11.	--	--	--	--
12.	--	--	--	--
13.	--	--	--	--
14.	--	--	--	--
15.	--	--	--	--
	Total Cover =	80		

Woody Vine Stratum (Plot size: 10 meter radius)

1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
	Total Cover =	0		

Remarks:

Dominance Test Worksheet

Number of Dominant Species that are OBL, FACW, or FAC: 2 (A)

Total Number of Dominant Species Across All Strata: 2 (B)

Percent of Dominant Species That Are OBL, FACW, or FAC: ***100.0%*** (A/B)

Prevalence Index Worksheet

Total % Cover of:		Multiply by:	
OBL spp.	50	x 1 =	50
FACW spp.	30	x 2 =	60
FAC spp.	0	x 3 =	0
FACU spp.	0	x 4 =	0
UPL spp.	0	x 5 =	0
Total	80 (A)		110 (B)

Prevalence Index = B/A = ***1.375***

Hydrophytic Vegetation Indicators:

- ☑ Yes ☐ No Rapid Test for Hydrophytic Vegetation
- ☑ Yes ☐ No Dominance Test is > 50%
- ☑ Yes ☐ No Prevalence Index is ≤ 3.0 *
- ☐ Yes ☑ No Morphological Adaptations (Explain) *
- ☐ Yes ☑ No Problem Hydrophytic Vegetation (Explain) *

* Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic.

Definitions of Vegetation Strata:

Tree - Woody plants 3 in. (7.6cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/Shrub - Woody plants less than 3 in. DBH and greater than 3.28 ft. tall.

Herb - All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft. tall.

Woody Vines - All woody vines greater than 3.28 ft. in height.

Hydrophytic Vegetation Present ☑ Yes ☐ No

Additional Remarks:

TETRA TECH

WETLAND DETERMINATION DATA FORM
Northeast and Northcentral Region

Project/Site:	Western Maine Renewable Energy Project	Project #: 194-7130	Date: 09/09/20
Applicant:	Western Maine Renewables, LLC		County: Somerset
Investigator #1:	Emmy Irvin	Investigator #2:	State: ME
Soil Unit:	Chesuncook-Elliottsville-Telos association, 3 to 15%	NWI/WWI Classification: Upland	Wetland ID: W38EI
Landform:	Terrace	Local Relief: Linear	Sample Point: **Upland**
Slope (%):	See topo map	Latitude: 45.142746° Longitude: -69.866973° Datum: NAD 83	

Are climatic/hydrologic conditions on the site typical for this time of year? (If no, explain in remarks) ☐ Yes ☑ No

Are Vegetation ☐, Soil ☐, or Hydrology ☐ significantly disturbed?
Are Vegetation ☐, Soil ☐, or Hydrology ☐ naturally problematic?

Are normal circumstances present? ☐ Yes ☑ No

SUMMARY OF FINDINGS

Hydrophytic Vegetation Present?	☐ Yes ☑ No	Hydric Soils Present?	☐ Yes ☑ No
Wetland Hydrology Present?	☐ Yes ☑ No	Is This Sampling Point Within A Wetland?	☐ **Yes** ☑ **No**

Remarks: Statewide drought

HYDROLOGY

Wetland Hydrology Indicators (Check here if indicators are not present ☑)

Primary:
- ☐ A1 - Surface Water
- ☐ A2 - High Water Table
- ☐ A3 - Saturation
- ☐ B1 - Water Marks
- ☐ B2 - Sediment Deposits
- ☐ B3 - Drift Deposits
- ☐ B4 - Algal Mat or Crust
- ☐ B5 - Iron Deposits
- ☐ B7 - Inundation Visible on Aerial Imagery
- ☐ B8 - Sparsely Vegetated Concave Surface
- ☐ B9 - Water-Stained Leaves
- ☐ B13 - Aquatic Fauna
- ☐ B15 - Marl Deposits
- ☐ C1 - Hydrogen Sulfide Odor
- ☐ C3 - Oxidized Rhizospheres on Living Roots
- ☐ C4 - Presence of Reduced Iron
- ☐ C6 - Recent Iron Reduction in Tilled Soils
- ☐ C7 - Thin Muck Surface
- ☐ Other (Explain in Remarks)

Secondary:
- ☐ B6 - Surface Soil Cracks
- ☐ B10 - Drainage Patterns
- ☐ B16 - Moss Trim Lines
- ☐ C2 - Dry-Season Water Table
- ☐ C8 - Crayfish Burrows
- ☐ C9 - Saturation Visible on Aerial Imagery
- ☐ D1 - Stunted or Stressed Plants
- ☐ D2 - Geomorphic Position
- ☐ D3 - Shallow Aquitard
- ☐ D4 - Microtopographic Relief
- ☐ D5 - FAC-Neutral Test

Field Observations:

Surface Water Present?	☐ Yes ☑ No	Depth:	(in.)
Water Table Present?	☐ Yes ☑ No	Depth:	(in.)
Saturation Present?	☐ Yes ☑ No	Depth:	(in.)

Wetland Hydrology Present? ☐ Yes ☑ No

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available: N/A

Remarks: Statewide drought

SOILS

Map Unit Name: Chesuncook-Elliottsville-Telos association, 3 to 15% Series Drainage Class: moderately well drained

Taxonomy (Subgroup): Coarse-loamy, isotic, frigid Aquic Haplorthods

Profile Description (Describe to the depth needed to document the indicator or confirm the absence of indicators.) (Type: C=Concentration, D=Depletion, RM=Reduced Matrix, CS=Covered/Coated Sand Grains; Location: PL=Pore Lining, M=Matrix)

Top Depth	Bottom Depth	Horizon	Matrix Color (Moist)		Matrix %	Mottles Color (Moist)		Mottles %	Mottles Type	Mottles Location	Texture (e.g. clay, sand, loam)
2	6	--	10YR	3/2	100	--	--	--	--	--	fine sandy loam
6	12	--	10YR	5/3	100	--	--	--	--	--	fine sandy loam
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--

NRCS Hydric Soil Field Indicators (check here if indicators are not present ☑):
- ☐ A1- Histosol
- ☐ A2 - Histic Epipedon
- ☐ A3 - Black Histic
- ☐ A4 - Hydrogen Sulfide
- ☐ A5 - Stratified Layers
- ☐ A11 - Depleted Below Dark Surface
- ☐ A12 - Thick Dark Surface
- ☐ S1 - Sandy Muck Mineral
- ☐ S4 - Sandy Gleyed Matrix
- ☐ S5 - Sandy Redox
- ☐ S6 - Stripped Matrix
- ☐ S7 - Dark Surface (LRR R, MLRA 149B)
- ☐ S8 - Polyvalue Below Surface (LRR R, MLRA 149B)
- ☐ S9 - Thin Dark Surface (LRR R, MLRA 149B)
- ☐ F1 - Loamy Mucky Mineral (LRR K, L)
- ☐ F2 - Loamy Gleyed Matrix
- ☐ F3 - Depleted Matrix
- ☐ F6 - Redox Dark Surface
- ☐ F7 - Depleted Dark Surface
- ☐ F8 - Redox Depressions

Indicators for Problematic Soils [1]
- ☐ A10 - 2 cm Muck (LRR K, L, MLRA 149B)
- ☐ A16 - Coast Prairie Redox (LRR K, L, R)
- ☐ S3 - 5cm Mucky Peat of Peat (**LRR K, L, R**)
- ☐ S7 - Dark Surface (LRR K, L, M)
- ☐ S8 - Polyvalue Below Surface (**LRR K, L**)
- ☐ S9 - Thin Dark Surface (**LRR K, L**)
- ☐ F12 - Iron-Manganese Masses (**LRR K, L, R**)
- ☐ F19 - Piedmont Floodplain Soils (**MLRA 149B**)
- ☐ TA6 - Mesic Spodic (**MLRA 144A, 145, 149B**)
- ☐ TF2 - Red Parent Material
- ☐ TF12 - Very Shallow Dark Surface
- ☐ Other (Explain in Remarks)

[1] Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (If Observed) Type: LEDGE Depth: 12

Hydric Soil Present? ☐ Yes ☑ No

Remarks:

TETRA TECH

WETLAND DETERMINATION DATA FORM

Northeast and Northcentral Region

Project/Site: Western Maine Renewable Energy Project | Wetland ID: W38EI | Sample Point **Upland**

VEGETATION (Species identified in all uppercase are non-native species.)

Tree Stratum (Plot size: 10 meter radius)

	Species Name	% Cover	Dominant	Ind.Status
1.	*Acer rubrum*	15	Y	FAC
2.	*Picea rubens*	25	Y	FACU
3.	*Betula alleghaniensis*	20	Y	FAC
4.	*Acer pensylvanicum*	10	Y	FACU
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	70		

Sapling/Shrub Stratum (Plot size: 5 meter radius)

1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	0		

Herb Stratum (Plot size: 2 meter radius)

1.	*Osmunda claytoniana*	1	N	FAC
2.	*Coptis trifolia*	2	N	FACW
3.	*Athyrium angustum*	5	N	FAC
4.	*Maianthemum canadense*	15	Y	FACU
5.	*Medeola virginiana*	10	Y	FACU
6	*Viola palmata*	15	Y	FACU
7.	*Nabalus albus*	5	N	FACU
8.	*Dryopteris campyloptera*	10	Y	FACU
9.	--	--	--	--
10.	--	--	--	--
11.	--	--	--	--
12.	--	--	--	--
13.	--	--	--	--
14.	--	--	--	--
15.	--	--	--	--
	Total Cover =	63		

Woody Vine Stratum (Plot size: 10 meter radius)

1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
	Total Cover =	0		

Remarks:

Dominance Test Worksheet

Number of Dominant Species that are OBL, FACW, or FAC: 2 (A)

Total Number of Dominant Species Across All Strata: 8 (B)

Percent of Dominant Species That Are OBL, FACW, or FAC: ***25.0%*** (A/B)

Prevalence Index Worksheet

Total % Cover of:		Multiply by:	
OBL spp.	0	x 1 =	0
FACW spp.	2	x 2 =	4
FAC spp.	41	x 3 =	123
FACU spp.	90	x 4 =	360
UPL spp.	0	x 5 =	0
Total	133 (A)		487 (B)

Prevalence Index = B/A = ***3.662***

Hydrophytic Vegetation Indicators:

- ☐ Yes ☐ No Rapid Test for Hydrophytic Vegetation
- ☐ Yes ☐ No Dominance Test is > 50%
- ☐ Yes ☐ No Prevalence Index is ≤ 3.0 *
- ☐ Yes ☐ No Morphological Adaptations (Explain) *
- ☐ Yes ☐ No Problem Hydrophytic Vegetation (Explain) *

* Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic.

Definitions of Vegetation Strata:

Tree - Woody plants 3 in. (7.6cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/Shrub - Woody plants less than 3 in. DBH and greater than 3.28 ft. tall.

Herb - All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft. tall.

Woody Vines - All woody vines greater than 3.28 ft. in height.

Hydrophytic Vegetation Present ☐ Yes ☑ No

Additional Remarks:

TETRA TECH

WETLAND DETERMINATION DATA FORM
Northeast and Northcentral Region

Project/Site:	Western Maine Renewable Energy Project	Project #: 194-7130	Date: 09/09/20
Applicant:	Western Maine Renewables, LLC		County: Somerset
Investigator #1:	Emmy Irvin	Investigator #2:	State: ME
Soil Unit:	Chesuncook-Elliottsville-Telos association, 3 to 15%	NWI/WWI Classification: PFO	Wetland ID: W38EI
Landform:	Terrace	Local Relief: Linear	Sample Point: **Wetland**
Slope (%):	See topo map	Latitude: 45.142722° Longitude: -69.866879° Datum: NAD 83	

Are climatic/hydrologic conditions on the site typical for this time of year? (If no, explain in remarks) ☐ Yes ☑ No

Are Vegetation ☐, Soil ☐, or Hydrology ☐ significantly disturbed?
Are Vegetation ☐, Soil ☐, or Hydrology ☐ naturally problematic?

Are normal circumstances present? ☐ Yes ☑ No

SUMMARY OF FINDINGS

Hydrophytic Vegetation Present?	☑ Yes ☐ No	Hydric Soils Present?	☑ Yes ☐ No
Wetland Hydrology Present?	☑ Yes ☐ No	Is This Sampling Point Within A Wetland?	☑ **Yes** ☐ **No**

Remarks: Statewide drought

HYDROLOGY

Wetland Hydrology Indicators (Check here if indicators are not present ☐)

Primary:
- ☐ A1 - Surface Water
- ☐ A2 - High Water Table
- ☑ A3 - Saturation
- ☐ B1 - Water Marks
- ☐ B2 - Sediment Deposits
- ☐ B3 - Drift Deposits
- ☐ B4 - Algal Mat or Crust
- ☐ B5 - Iron Deposits
- ☐ B7 - Inundation Visible on Aerial Imagery
- ☐ B8 - Sparsely Vegetated Concave Surface
- ☐ B9 - Water-Stained Leaves
- ☐ B13 - Aquatic Fauna
- ☐ B15 - Marl Deposits
- ☐ C1 - Hydrogen Sulfide Odor
- ☐ C3 - Oxidized Rhizospheres on Living Roots
- ☐ C4 - Presence of Reduced Iron
- ☐ C6 - Recent Iron Reduction in Tilled Soils
- ☐ C7 - Thin Muck Surface
- ☐ Other (Explain in Remarks)

Secondary:
- ☐ B6 - Surface Soil Cracks
- ☐ B10 - Drainage Patterns
- ☐ B16 - Moss Trim Lines
- ☐ C2 - Dry-Season Water Table
- ☐ C8 - Crayfish Burrows
- ☐ C9 - Saturation Visible on Aerial Imagery
- ☐ D1 - Stunted or Stressed Plants
- ☐ D2 - Geomorphic Position
- ☐ D3 - Shallow Aquitard
- ☐ D4 - Microtopographic Relief
- ☐ D5 - FAC-Neutral Test

Field Observations:

Surface Water Present?	☐ Yes	☑ No	Depth:	(in.)
Water Table Present?	☐ Yes	☑ No	Depth:	(in.)
Saturation Present?	☑ Yes	☐ No	Depth: 0	(in.)

Wetland Hydrology Present? ☑ Yes ☐ No

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available: N/A

Remarks: Statewide drought

SOILS

Map Unit Name: Chesuncook-Elliottsville-Telos association, 3 to 15% Series Drainage Class: moderately well drained

Taxonomy (Subgroup): Coarse-loamy, isotic, frigid Aquic Haplorthods

Profile Description (Describe to the depth needed to document the indicator or confirm the absence of indicators.) (Type: C=Concentration, D=Depletion, RM=Reduced Matrix, CS=Covered/Coated Sand Grains; Location: PL=Pore Lining, M=Matrix)

Top Depth	Bottom Depth	Horizon	Matrix Color (Moist)		Matrix %	Mottles Color (Moist)		Mottles %	Mottles Type	Mottles Location	Texture (e.g. clay, sand, loam)
0	4	--	10YR	2/1	100	--	--	--	--	--	VFSL HIGH ORGANIC
4	12	--	10YR	5/1	75	10YR	7/8	25	C	M	ERY FINE SANDY LOA
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--

NRCS Hydric Soil Field Indicators (check here if indicators are not present ☐):
- ☐ A1- Histosol
- ☐ A2 - Histic Epipedon
- ☐ A3 - Black Histic
- ☐ A4 - Hydrogen Sulfide
- ☐ A5 - Stratified Layers
- ☐ A11 - Depleted Below Dark Surface
- ☐ A12 - Thick Dark Surface
- ☐ S1 - Sandy Muck Mineral
- ☐ S4 - Sandy Gleyed Matrix
- ☐ S5 - Sandy Redox
- ☐ S6 - Stripped Matrix
- ☐ S7 - Dark Surface (LRR R, MLRA 149B)
- ☐ S8 - Polyvalue Below Surface (LRR R, MLRA 149B)
- ☐ S9 - Thin Dark Surface (LRR R, MLRA 149B)
- ☐ F1 - Loamy Mucky Mineral (LRR K, L)
- ☐ F2 - Loamy Gleyed Matrix
- ☑ F3 - Depleted Matrix
- ☐ F6 - Redox Dark Surface
- ☐ F7 - Depleted Dark Surface
- ☐ F8 - Redox Depressions

Indicators for Problematic Soils [1]
- ☐ A10 - 2 cm Muck (LRR K, L, MLRA 149B)
- ☐ A16 - Coast Prairie Redox (LRR K, L, R)
- ☐ S3 - 5cm Mucky Peat of Peat (**LRR K, L, R**)
- ☐ S7 - Dark Surface (LRR K, L, M)
- ☐ S8 - Polyvalue Below Surface (**LRR K, L**)
- ☐ S9 - Thin Dark Surface (**LRR K, L**)
- ☐ F12 - Iron-Manganese Masses (**LRR K, L, R**)
- ☐ F19 - Piedmont Floodplain Soils (**MLRA 149B**)
- ☐ TA6 - Mesic Spodic (**MLRA 144A, 145, 149B**)
- ☐ TF2 - Red Parent Material
- ☐ TF12 - Very Shallow Dark Surface
- ☐ Other (Explain in Remarks)

[1] Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (If Observed) Type: LEDGE Depth: 12

Hydric Soil Present? ☑ Yes ☐ No

Remarks:

TETRA TECH

WETLAND DETERMINATION DATA FORM

Northeast and Northcentral Region

Project/Site: Western Maine Renewable Energy Project Wetland ID: W38EI Sample Point **Wetland**

VEGETATION (Species identified in all uppercase are non-native species.)

Tree Stratum (Plot size: 10 meter radius)

	Species Name	% Cover	Dominant	Ind.Status
1.	*Picea mariana*	20	Y	FACW
2.	*Acer rubrum*	5	N	FAC
3.	*Fagus grandifolia*	5	N	FACU
4.	*Picea rubens*	5	N	FACU
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	35		

Sapling/Shrub Stratum (Plot size: 5 meter radius)

1.	*Alnus incana*	10	Y	FACW
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	10		

Herb Stratum (Plot size: 2 meter radius)

1.	*Carex stricta*	10	N	OBL
2.	*Scirpus cyperinus*	25	Y	OBL
3.	*Onoclea sensibilis*	5	N	FACW
4.	*Eutrochium maculatum*	10	N	OBL
5.	--	--	--	--
6	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
11.	--	--	--	--
12.	--	--	--	--
13.	--	--	--	--
14.	--	--	--	--
15.	--	--	--	--
	Total Cover =	50		

Woody Vine Stratum (Plot size: 10 meter radius)

1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
	Total Cover =	0		

Dominance Test Worksheet

Number of Dominant Species that are OBL, FACW, or FAC: 3 (A)

Total Number of Dominant Species Across All Strata: 3 (B)

Percent of Dominant Species That Are OBL, FACW, or FAC: ***100.0%*** (A/B)

Prevalence Index Worksheet

Total % Cover of:		Multiply by:	
OBL spp.	45	x 1 =	45
FACW spp.	35	x 2 =	70
FAC spp.	5	x 3 =	15
FACU spp.	10	x 4 =	40
UPL spp.	0	x 5 =	0
Total	95 (A)		170 (B)

Prevalence Index = B/A = ***1.789***

Hydrophytic Vegetation Indicators:

- ☑ Yes ☐ No Rapid Test for Hydrophytic Vegetation
- ☑ Yes ☐ No Dominance Test is > 50%
- ☑ Yes ☐ No Prevalence Index is ≤ 3.0 *
- ☐ Yes ☑ No Morphological Adaptations (Explain) *
- ☐ Yes ☑ No Problem Hydrophytic Vegetation (Explain) *

* Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic.

Definitions of Vegetation Strata:

Tree - Woody plants 3 in. (7.6cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/Shrub - Woody plants less than 3 in. DBH and greater than 3.28 ft. tall.

Herb - All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft. tall.

Woody Vines - All woody vines greater than 3.28 ft. in height.

Hydrophytic Vegetation Present ☑ Yes ☐ No

Remarks:

Additional Remarks:

TETRA TECH

WETLAND DETERMINATION DATA FORM
Northeast and Northcentral Region

Project/Site:	Western Maine Renewable Energy Project	Project #: 194-7130	Date: 09/09/20
Applicant:	Western Maine Renewables, LLC		County: Somerset
Investigator #1:	Emmy Irvin	Investigator #2:	State: ME
Soil Unit:	Chesuncook-Elliottsville-Telos association, 3 to 15%	NWI/WWI Classification: Upland	Wetland ID: W43EI
Landform:	Terrace	Local Relief: Linear	Sample Point: **Upland**
Slope (%):	See topo map	Latitude: 45.140627 Longitude: -69.8696469 Datum: NAD 83	

Are climatic/hydrologic conditions on the site typical for this time of year? (If no, explain in remarks) ☐ Yes ☑ No

Are Vegetation ☐, Soil ☐, or Hydrology ☐ significantly disturbed?
Are Vegetation ☐, Soil ☐, or Hydrology ☐ naturally problematic?

Are normal circumstances present? ☐ Yes ☑ No

SUMMARY OF FINDINGS

Hydrophytic Vegetation Present?	☐ Yes ☑ No	Hydric Soils Present?	☐ Yes ☑ No
Wetland Hydrology Present?	☐ Yes ☑ No	Is This Sampling Point Within A Wetland?	☐ **Yes** ☑ **No**

Remarks: Statewide drought

HYDROLOGY

Wetland Hydrology Indicators (Check here if indicators are not present ☑)

Primary:
- ☐ A1 - Surface Water
- ☐ A2 - High Water Table
- ☐ A3 - Saturation
- ☐ B1 - Water Marks
- ☐ B2 - Sediment Deposits
- ☐ B3 - Drift Deposits
- ☐ B4 - Algal Mat or Crust
- ☐ B5 - Iron Deposits
- ☐ B7 - Inundation Visible on Aerial Imagery
- ☐ B8 - Sparsely Vegetated Concave Surface
- ☐ B9 - Water-Stained Leaves
- ☐ B13 - Aquatic Fauna
- ☐ B15 - Marl Deposits
- ☐ C1 - Hydrogen Sulfide Odor
- ☐ C3 - Oxidized Rhizospheres on Living Roots
- ☐ C4 - Presence of Reduced Iron
- ☐ C6 - Recent Iron Reduction in Tilled Soils
- ☐ C7 - Thin Muck Surface
- ☐ Other (Explain in Remarks)

Secondary:
- ☐ B6 - Surface Soil Cracks
- ☐ B10 - Drainage Patterns
- ☐ B16 - Moss Trim Lines
- ☐ C2 - Dry-Season Water Table
- ☐ C8 - Crayfish Burrows
- ☐ C9 - Saturation Visible on Aerial Imagery
- ☐ D1 - Stunted or Stressed Plants
- ☐ D2 - Geomorphic Position
- ☐ D3 - Shallow Aquitard
- ☐ D4 - Microtopographic Relief
- ☐ D5 - FAC-Neutral Test

Field Observations:

Surface Water Present?	☐ Yes ☑ No	Depth:	(in.)
Water Table Present?	☐ Yes ☑ No	Depth:	(in.)
Saturation Present?	☐ Yes ☑ No	Depth:	(in.)

Wetland Hydrology Present? ☐ Yes ☑ No

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available: N/A

Remarks: Statewide drought

SOILS

Map Unit Name: Chesuncook-Elliottsville-Telos association, 3 to 15% Series Drainage Class: moderately well drained

Taxonomy (Subgroup): Coarse-loamy, isotic, frigid Aquic Haplorthods

Profile Description (Describe to the depth needed to document the indicator or confirm the absence of indicators.) (Type: C=Concentration, D=Depletion, RM=Reduced Matrix, CS=Covered/Coated Sand Grains; Location: PL=Pore Lining, M=Matrix)

Top Depth	Bottom Depth	Horizon	Matrix Color (Moist)		Matrix %	Mottles Color (Moist)		Mottles %	Mottles Type	Mottles Location	Texture (e.g. clay, sand, loam)
0	12	--	10YR	5/3	100	--	--	--	--	--	fine sandy loam
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--

NRCS Hydric Soil Field Indicators (check here if indicators are not present ☑):
- ☐ A1- Histosol
- ☐ A2 - Histic Epipedon
- ☐ A3 - Black Histic
- ☐ A4 - Hydrogen Sulfide
- ☐ A5 - Stratified Layers
- ☐ A11 - Depleted Below Dark Surface
- ☐ A12 - Thick Dark Surface
- ☐ S1 - Sandy Muck Mineral
- ☐ S4 - Sandy Gleyed Matrix
- ☐ S5 - Sandy Redox
- ☐ S6 - Stripped Matrix
- ☐ S7 - Dark Surface (LRR R, MLRA 149B)
- ☐ S8 - Polyvalue Below Surface (LRR R, MLRA 149B)
- ☐ S9 - Thin Dark Surface (LRR R, MLRA 149B)
- ☐ F1 - Loamy Mucky Mineral (LRR K, L)
- ☐ F2 - Loamy Gleyed Matrix
- ☐ F3 - Depleted Matrix
- ☐ F6 - Redox Dark Surface
- ☐ F7 - Depleted Dark Surface
- ☐ F8 - Redox Depressions

Indicators for Problematic Soils [1]
- ☐ A10 - 2 cm Muck (LRR K, L, MLRA 149B)
- ☐ A16 - Coast Prairie Redox (LRR K, L, R)
- ☐ S3 - 5cm Mucky Peat of Peat (**LRR K, L, R**)
- ☐ S7 - Dark Surface (LRR K, L, M)
- ☐ S8 - Polyvalue Below Surface (**LRR K, L**)
- ☐ S9 - Thin Dark Surface (**LRR K, L**)
- ☐ F12 - Iron-Manganese Masses (**LRR K, L, R**)
- ☐ F19 - Piedmont Floodplain Soils (**MLRA 149B**)
- ☐ TA6 - Mesic Spodic (**MLRA 144A, 145, 149B**)
- ☐ TF2 - Red Parent Material
- ☐ TF12 - Very Shallow Dark Surface
- ☐ Other (Explain in Remarks)

[1] Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (If Observed) Type: NR Depth: 12

Hydric Soil Present? ☐ Yes ☑ No

Remarks:

TETRA TECH

WETLAND DETERMINATION DATA FORM

Northeast and Northcentral Region

Project/Site: Western Maine Renewable Energy Project | Wetland ID: W43EI | Sample Point **Upland**

VEGETATION (Species identified in all uppercase are non-native species.)

Tree Stratum (Plot size: 10 meter radius)

	Species Name	% Cover	Dominant	Ind.Status
1.	*Betula lenta*	75	Y	FACU
2.	*Acer rubrum*	20	Y	FAC
3.	*Fraxinus nigra*	5	N	FACW
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	100		

Sapling/Shrub Stratum (Plot size: 5 meter radius)

1.	*Acer pensylvanicum*	5	N	FACU
2.	*Betula lenta*	20	Y	FACU
3.	*Acer rubrum*	10	N	FAC
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	35		

Herb Stratum (Plot size: 2 meter radius)

1.	*Medeola virginiana*	5	N	FACU
2.	*Polystichum acrostichoides*	20	Y	FACU
3.	*Phegopteris hexagonoptera*	5	N	FACU
4.	*Athyrium angustum*	5	N	FAC
5.	--	--	--	--
6	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
11.	--	--	--	--
12.	--	--	--	--
13.	--	--	--	--
14.	--	--	--	--
15.	--	--	--	--
	Total Cover =	35		

Woody Vine Stratum (Plot size: 10 meter radius)

1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
	Total Cover =	0		

Remarks:

Dominance Test Worksheet

Number of Dominant Species that are OBL, FACW, or FAC: 1 (A)

Total Number of Dominant Species Across All Strata: 4 (B)

Percent of Dominant Species That Are OBL, FACW, or FAC: ***25.0%*** (A/B)

Prevalence Index Worksheet

Total % Cover of:		Multiply by:	
OBL spp.	0	x 1 =	0
FACW spp.	5	x 2 =	10
FAC spp.	35	x 3 =	105
FACU spp.	130	x 4 =	520
UPL spp.	0	x 5 =	0
Total	170 (A)		635 (B)

Prevalence Index = B/A = ***3.735***

Hydrophytic Vegetation Indicators:

- ☐ Yes ☑ No Rapid Test for Hydrophytic Vegetation
- ☐ Yes ☑ No Dominance Test is > 50%
- ☐ Yes ☑ No Prevalence Index is ≤ 3.0 *
- ☐ Yes ☑ No Morphological Adaptations (Explain) *
- ☐ Yes ☑ No Problem Hydrophytic Vegetation (Explain) *

* Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic.

Definitions of Vegetation Strata:

Tree - Woody plants 3 in. (7.6cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/Shrub - Woody plants less than 3 in. DBH and greater than 3.28 ft. tall.

Herb - All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft. tall.

Woody Vines - All woody vines greater than 3.28 ft. in height.

Hydrophytic Vegetation Present ☐ Yes ☑ No

Additional Remarks:

TETRA TECH

WETLAND DETERMINATION DATA FORM
Northeast and Northcentral Region

Project/Site:	Western Maine Renewable Energy Project	Project #: 194-7130	Date: 09/09/20
Applicant:	Western Maine Renewables, LLC		County: Somerset
Investigator #1:	Emmy Irvin	Investigator #2:	State: ME
Soil Unit:	Chesuncook-Elliottsville-Telos association, 3 to 15%	NWI/WWI Classification: PFO	Wetland ID: W43EI
Landform:	Terrace	Local Relief: Linear	Sample Point: **Wetland**
Slope (%):	See topo map	Latitude: 45.142152 Longitude: -69.867685 Datum: NAD 83	

Are climatic/hydrologic conditions on the site typical for this time of year? (If no, explain in remarks) ☐ Yes ☑ No

Are Vegetation ☐, Soil ☐, or Hydrology ☐ significantly disturbed?
Are Vegetation ☐, Soil ☐, or Hydrology ☐ naturally problematic?

Are normal circumstances present? ☐ Yes ☑ No

SUMMARY OF FINDINGS

Hydrophytic Vegetation Present?	☑ Yes ☐ No	Hydric Soils Present?	☑ Yes ☐ No
Wetland Hydrology Present?	☑ Yes ☐ No	Is This Sampling Point Within A Wetland?	☑ **Yes** ☐ **No**

Remarks: Statewide drought

HYDROLOGY

Wetland Hydrology Indicators (Check here if indicators are not present ☐)

Primary:
- ☐ A1 - Surface Water
- ☐ A2 - High Water Table
- ☑ A3 - Saturation
- ☐ B1 - Water Marks
- ☐ B2 - Sediment Deposits
- ☐ B3 - Drift Deposits
- ☐ B4 - Algal Mat or Crust
- ☐ B5 - Iron Deposits
- ☐ B7 - Inundation Visible on Aerial Imagery
- ☐ B8 - Sparsely Vegetated Concave Surface
- ☐ B9 - Water-Stained Leaves
- ☐ B13 - Aquatic Fauna
- ☐ B15 - Marl Deposits
- ☐ C1 - Hydrogen Sulfide Odor
- ☐ C3 - Oxidized Rhizospheres on Living Roots
- ☐ C4 - Presence of Reduced Iron
- ☐ C6 - Recent Iron Reduction in Tilled Soils
- ☐ C7 - Thin Muck Surface
- ☐ Other (Explain in Remarks)

Secondary:
- ☐ B6 - Surface Soil Cracks
- ☐ B10 - Drainage Patterns
- ☐ B16 - Moss Trim Lines
- ☐ C2 - Dry-Season Water Table
- ☐ C8 - Crayfish Burrows
- ☐ C9 - Saturation Visible on Aerial Imagery
- ☐ D1 - Stunted or Stressed Plants
- ☐ D2 - Geomorphic Position
- ☐ D3 - Shallow Aquitard
- ☐ D4 - Microtopographic Relief
- ☐ D5 - FAC-Neutral Test

Field Observations:

Surface Water Present?	☐ Yes	☑ No	Depth:	(in.)
Water Table Present?	☐ Yes	☑ No	Depth:	(in.)
Saturation Present?	☑ Yes	☐ No	Depth: 6	(in.)

Wetland Hydrology Present? ☑ Yes ☐ No

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available: N/A

Remarks: Statewide drought

SOILS

Map Unit Name: Chesuncook-Elliottsville-Telos association, 3 to 15% Series Drainage Class: moderately well drained

Taxonomy (Subgroup): Coarse-loamy, isotic, frigid Aquic Haplorthods

Profile Description (Describe to the depth needed to document the indicator or confirm the absence of indicators.) (Type: C=Concentration, D=Depletion, RM=Reduced Matrix, CS=Covered/Coated Sand Grains; Location: PL=Pore Lining, M=Matrix)

Top Depth	Bottom Depth	Horizon	Matrix Color (Moist)		Matrix %	Mottles Color (Moist)		Mottles %	Mottles Type	Mottles Location	Texture (e.g. clay, sand, loam)
0	6	--	7.5YR	2.5/1	100	--	--	--	--	--	mucky sandy loam
6	13	--	5Y	5/1	70	7.5YR	5/8	20	C	M	loamy sand
--	--	--	--	--	--	5Y	7/1	10	D	M	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--

NRCS Hydric Soil Field Indicators (check here if indicators are not present ☐):
- ☐ A1- Histosol
- ☐ A2 - Histic Epipedon
- ☐ A3 - Black Histic
- ☐ A4 - Hydrogen Sulfide
- ☐ A5 - Stratified Layers
- ☐ A11 - Depleted Below Dark Surface
- ☑ A12 - Thick Dark Surface
- ☐ S1 - Sandy Muck Mineral
- ☐ S4 - Sandy Gleyed Matrix
- ☐ S5 - Sandy Redox
- ☐ S6 - Stripped Matrix
- ☐ S7 - Dark Surface (LRR R, MLRA 149B)
- ☐ S8 - Polyvalue Below Surface (LRR R, MLRA 149B)
- ☐ S9 - Thin Dark Surface (LRR R, MLRA 149B)
- ☐ F1 - Loamy Mucky Mineral (LRR K, L)
- ☐ F2 - Loamy Gleyed Matrix
- ☐ F3 - Depleted Matrix
- ☐ F6 - Redox Dark Surface
- ☐ F7 - Depleted Dark Surface
- ☐ F8 - Redox Depressions

Indicators for Problematic Soils [1]
- ☐ A10 - 2 cm Muck (LRR K, L, MLRA 149B)
- ☐ A16 - Coast Prairie Redox (LRR K, L, R)
- ☐ S3 - 5cm Mucky Peat of Peat (**LRR K, L, R**)
- ☐ S7 - Dark Surface (LRR K, L, M)
- ☐ S8 - Polyvalue Below Surface (**LRR K, L**)
- ☐ S9 - Thin Dark Surface (**LRR K, L**)
- ☐ F12 - Iron-Manganese Masses (**LRR K, L, R**)
- ☐ F19 - Piedmont Floodplain Soils (**MLRA 149B**)
- ☐ TA6 - Mesic Spodic (**MLRA 144A, 145, 149B**)
- ☐ TF2 - Red Parent Material
- ☐ TF12 - Very Shallow Dark Surface
- ☐ Other (Explain in Remarks)

[1] Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (If Observed) Type: ledge Depth: 13

Hydric Soil Present? ☑ Yes ☐ No

Remarks:

TETRA TECH

WETLAND DETERMINATION DATA FORM

Northeast and Northcentral Region

Project/Site: Western Maine Renewable Energy Project Wetland ID: W43EI Sample Point **Wetland**

VEGETATION (Species identified in all uppercase are non-native species.)

Tree Stratum (Plot size: 10 meter radius)

	Species Name	% Cover	Dominant	Ind.Status
1.	*Fraxinus nigra*	10	Y	FACW
2.	*Betula papyrifera*	20	Y	FACU
3.	*Betula alleghaniensis*	20	Y	FAC
4.	*Picea mariana*	5	N	FACW
5.	*Acer rubrum*	10	Y	FAC
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	65		

Sapling/Shrub Stratum (Plot size: 5 meter radius)

1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	0		

Herb Stratum (Plot size: 2 meter radius)

1.	*Onoclea sensibilis*	10	Y	FACW
2.	--	5	N	FAVW
3.	--	10	Y	FACU
4.	--	5	N	FACU
5.	--	10	Y	FACU
6	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
11.	--	--	--	--
12.	--	--	--	--
13.	--	--	--	--
14.	--	--	--	--
15.	--	--	--	--
	Total Cover =	40		

Woody Vine Stratum (Plot size: 10 meter radius)

1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
	Total Cover =	0		

Remarks:

Dominance Test Worksheet

Number of Dominant Species that are OBL, FACW, or FAC: 4 (A)

Total Number of Dominant Species Across All Strata: 7 (B)

Percent of Dominant Species That Are OBL, FACW, or FAC: ***57.1%*** (A/B)

Prevalence Index Worksheet

Total % Cover of:		Multiply by:	
OBL spp.	0	x 1 =	0
FACW spp.	25	x 2 =	50
FAC spp.	30	x 3 =	90
FACU spp.	45	x 4 =	180
UPL spp.	0	x 5 =	0
Total	100 (A)		320 (B)

Prevalence Index = B/A = ***3.200***

Hydrophytic Vegetation Indicators:

- ☐ Yes ☑ No Rapid Test for Hydrophytic Vegetation
- ☑ Yes ☐ No Dominance Test is > 50%
- ☐ Yes ☑ No Prevalence Index is ≤ 3.0 *
- ☐ Yes ☑ No Morphological Adaptations (Explain) *
- ☐ Yes ☑ No Problem Hydrophytic Vegetation (Explain) *

* Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic.

Definitions of Vegetation Strata:

Tree - Woody plants 3 in. (7.6cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/Shrub - Woody plants less than 3 in. DBH and greater than 3.28 ft. tall.

Herb - All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft. tall.

Woody Vines - All woody vines greater than 3.28 ft. in height.

Hydrophytic Vegetation Present ☑ Yes ☐ No

Additional Remarks:

TETRA TECH

WETLAND DETERMINATION DATA FORM
Northeast and Northcentral Region

Project/Site:	Western Maine Renewable Energy Project	Project #: 194-7130	Date: 09/09/20
Applicant:	Western Maine Renewables, LLC		County: Somerset
Investigator #1:	Emmy Irvin	Investigator #2:	State: ME
Soil Unit:	Chesuncook-Elliottsville-Telos association, 3 to 15%	NWI/WWI Classification: Upland	Wetland ID: W47EI
Landform:	Terrace	Local Relief: Linear	Sample Point: **Upland**
Slope (%):	See topo map	Latitude: 45.140627 Longitude: -69.8696469 Datum: NAD 83	

Are climatic/hydrologic conditions on the site typical for this time of year? (If no, explain in remarks) ☐ Yes ☑ No

Are Vegetation ☐, Soil ☐, or Hydrology ☐ significantly disturbed?
Are Vegetation ☐, Soil ☐, or Hydrology ☐ naturally problematic?

Are normal circumstances present? ☐ Yes ☑ No

SUMMARY OF FINDINGS

Hydrophytic Vegetation Present?	☐ Yes ☑ No	Hydric Soils Present?	☐ Yes ☑ No
Wetland Hydrology Present?	☐ Yes ☑ No	Is This Sampling Point Within A Wetland?	☐ **Yes** ☑ **No**

Remarks: Statewide drought

HYDROLOGY

Wetland Hydrology Indicators (Check here if indicators are not present ☑)

Primary:
- ☐ A1 - Surface Water
- ☐ A2 - High Water Table
- ☐ A3 - Saturation
- ☐ B1 - Water Marks
- ☐ B2 - Sediment Deposits
- ☐ B3 - Drift Deposits
- ☐ B4 - Algal Mat or Crust
- ☐ B5 - Iron Deposits
- ☐ B7 - Inundation Visible on Aerial Imagery
- ☐ B8 - Sparsely Vegetated Concave Surface
- ☐ B9 - Water-Stained Leaves
- ☐ B13 - Aquatic Fauna
- ☐ B15 - Marl Deposits
- ☐ C1 - Hydrogen Sulfide Odor
- ☐ C3 - Oxidized Rhizospheres on Living Roots
- ☐ C4 - Presence of Reduced Iron
- ☐ C6 - Recent Iron Reduction in Tilled Soils
- ☐ C7 - Thin Muck Surface
- ☐ Other (Explain in Remarks)

Secondary:
- ☐ B6 - Surface Soil Cracks
- ☐ B10 - Drainage Patterns
- ☐ B16 - Moss Trim Lines
- ☐ C2 - Dry-Season Water Table
- ☐ C8 - Crayfish Burrows
- ☐ C9 - Saturation Visible on Aerial Imagery
- ☐ D1 - Stunted or Stressed Plants
- ☐ D2 - Geomorphic Position
- ☐ D3 - Shallow Aquitard
- ☐ D4 - Microtopographic Relief
- ☐ D5 - FAC-Neutral Test

Field Observations:

Surface Water Present?	☐ Yes ☑ No	Depth:	(in.)
Water Table Present?	☐ Yes ☑ No	Depth:	(in.)
Saturation Present?	☐ Yes ☑ No	Depth:	(in.)

Wetland Hydrology Present? ☐ Yes ☑ No

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available: N/A

Remarks: Statewide drought

SOILS

Map Unit Name: Chesuncook-Elliottsville-Telos association, 3 to 15% Series Drainage Class: moderately well drained

Taxonomy (Subgroup): Coarse-loamy, isotic, frigid Aquic Haplorthods

Profile Description (Describe to the depth needed to document the indicator or confirm the absence of indicators.) (Type: C=Concentration, D=Depletion, RM=Reduced Matrix, CS=Covered/Coated Sand Grains; Location: PL=Pore Lining, M=Matrix)

Top Depth	Bottom Depth	Horizon	Matrix Color (Moist)		Matrix %	Mottles Color (Moist)		Mottles %	Mottles Type	Mottles Location	Texture (e.g. clay, sand, loam)
0	12	--	10YR	5/3	100	--	--	--	--	--	fine sandy loam
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--

NRCS Hydric Soil Field Indicators (check here if indicators are not present ☑):
- ☐ A1- Histosol
- ☐ A2 - Histic Epipedon
- ☐ A3 - Black Histic
- ☐ A4 - Hydrogen Sulfide
- ☐ A5 - Stratified Layers
- ☐ A11 - Depleted Below Dark Surface
- ☐ A12 - Thick Dark Surface
- ☐ S1 - Sandy Muck Mineral
- ☐ S4 - Sandy Gleyed Matrix
- ☐ S5 - Sandy Redox
- ☐ S6 - Stripped Matrix
- ☐ S7 - Dark Surface (LRR R, MLRA 149B)
- ☐ S8 - Polyvalue Below Surface (LRR R, MLRA 149B)
- ☐ S9 - Thin Dark Surface (LRR R, MLRA 149B)
- ☐ F1 - Loamy Mucky Mineral (LRR K, L)
- ☐ F2 - Loamy Gleyed Matrix
- ☐ F3 - Depleted Matrix
- ☐ F6 - Redox Dark Surface
- ☐ F7 - Depleted Dark Surface
- ☐ F8 - Redox Depressions

Indicators for Problematic Soils [1]
- ☐ A10 - 2 cm Muck (LRR K, L, MLRA 149B)
- ☐ A16 - Coast Prairie Redox (LRR K, L, R)
- ☐ S3 - 5cm Mucky Peat of Peat (**LRR K, L, R**)
- ☐ S7 - Dark Surface (LRR K, L, M)
- ☐ S8 - Polyvalue Below Surface (**LRR K, L**)
- ☐ S9 - Thin Dark Surface (**LRR K, L**)
- ☐ F12 - Iron-Manganese Masses (**LRR K, L, R**)
- ☐ F19 - Piedmont Floodplain Soils (**MLRA 149B**)
- ☐ TA6 - Mesic Spodic (**MLRA 144A, 145, 149B**)
- ☐ TF2 - Red Parent Material
- ☐ TF12 - Very Shallow Dark Surface
- ☐ Other (Explain in Remarks)

[1] Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (If Observed) Type: NR Depth: 12

Hydric Soil Present? ☐ Yes ☑ No

Remarks:

TETRA TECH

WETLAND DETERMINATION DATA FORM

Northeast and Northcentral Region

Project/Site: Western Maine Renewable Energy Project | Wetland ID: W47EI | Sample Point **Upland**

VEGETATION (Species identified in all uppercase are non-native species.)

Tree Stratum (Plot size: 10 meter radius)

	Species Name	% Cover	Dominant	Ind.Status
1.	*Betula lenta*	75	Y	FACU
2.	*Acer rubrum*	20	Y	FAC
3.	*Fraxinus nigra*	5	N	FACW
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	100		

Sapling/Shrub Stratum (Plot size: 5 meter radius)

1.	*Acer pensylvanicum*	5	N	FACU
2.	*Betula lenta*	20	Y	FACU
3.	*Acer rubrum*	10	N	FAC
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	35		

Herb Stratum (Plot size: 2 meter radius)

1.	*Medeola virginiana*	5	N	FACU
2.	*Polystichum acrostichoides*	20	Y	FACU
3.	*Phegopteris hexagonoptera*	5	N	FACU
4.	*Athyrium angustum*	5	N	FAC
5.	--	--	--	--
6	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
11.	--	--	--	--
12.	--	--	--	--
13.	--	--	--	--
14.	--	--	--	--
15.	--	--	--	--
	Total Cover =	35		

Woody Vine Stratum (Plot size: 10 meter radius)

1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
	Total Cover =	0		

Remarks:

Dominance Test Worksheet

Number of Dominant Species that are OBL, FACW, or FAC: 1 (A)

Total Number of Dominant Species Across All Strata: 4 (B)

Percent of Dominant Species That Are OBL, FACW, or FAC: ***25.0%*** (A/B)

Prevalence Index Worksheet

Total % Cover of:		Multiply by:	
OBL spp.	0	x 1 =	0
FACW spp.	5	x 2 =	10
FAC spp.	35	x 3 =	105
FACU spp.	130	x 4 =	520
UPL spp.	0	x 5 =	0
Total	170 (A)		635 (B)

Prevalence Index = B/A = ***3.735***

Hydrophytic Vegetation Indicators:

- ☐ Yes ☑ No Rapid Test for Hydrophytic Vegetation
- ☐ Yes ☑ No Dominance Test is > 50%
- ☐ Yes ☑ No Prevalence Index is ≤ 3.0 *
- ☐ Yes ☑ No Morphological Adaptations (Explain) *
- ☐ Yes ☑ No Problem Hydrophytic Vegetation (Explain) *

* Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic.

Definitions of Vegetation Strata:

Tree - Woody plants 3 in. (7.6cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/Shrub - Woody plants less than 3 in. DBH and greater than 3.28 ft. tall.

Herb - All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft. tall.

Woody Vines - All woody vines greater than 3.28 ft. in height.

Hydrophytic Vegetation Present ☐ Yes ☑ No

Additional Remarks:

TETRA TECH

WETLAND DETERMINATION DATA FORM
Northeast and Northcentral Region

Project/Site:	Western Maine Renewable Energy Project	Project #: 194-7130	Date: 09/09/20
Applicant:	Western Maine Renewables, LLC		County: Somerset
Investigator #1:	Emmy Irvin	Investigator #2:	State: ME
Soil Unit:	Chesuncook-Elliottsville-Telos association, 3 to 15%	NWI/WWI Classification: PFO	Wetland ID: W47EI
Landform:	Terrace	Local Relief: Linear	Sample Point: **Wetland**
Slope (%):	See topo map	Latitude: 45.140674 Longitude: -69.869728 Datum: NAD 83	

Are climatic/hydrologic conditions on the site typical for this time of year? (If no, explain in remarks) ☐ Yes ☑ No

Are Vegetation ☐, Soil ☐, or Hydrology ☐ significantly disturbed?
Are Vegetation ☐, Soil ☐, or Hydrology ☐ naturally problematic?

Are normal circumstances present? ☐ Yes ☑ No

SUMMARY OF FINDINGS

Hydrophytic Vegetation Present?	☑ Yes ☐ No	Hydric Soils Present?	☑ Yes ☐ No
Wetland Hydrology Present?	☑ Yes ☐ No	Is This Sampling Point Within A Wetland?	☑ **Yes** ☐ **No**

Remarks: Statewide drought

HYDROLOGY

Wetland Hydrology Indicators (Check here if indicators are not present ☐)

Primary:
- ☐ A1 - Surface Water
- ☐ A2 - High Water Table
- ☐ A3 - Saturation
- ☐ B1 - Water Marks
- ☐ B2 - Sediment Deposits
- ☐ B3 - Drift Deposits
- ☐ B4 - Algal Mat or Crust
- ☐ B5 - Iron Deposits
- ☐ B7 - Inundation Visible on Aerial Imagery
- ☐ B8 - Sparsely Vegetated Concave Surface
- ☐ B9 - Water-Stained Leaves
- ☐ B13 - Aquatic Fauna
- ☐ B15 - Marl Deposits
- ☐ C1 - Hydrogen Sulfide Odor
- ☑ C3 - Oxidized Rhizospheres on Living Roots
- ☐ C4 - Presence of Reduced Iron
- ☐ C6 - Recent Iron Reduction in Tilled Soils
- ☐ C7 - Thin Muck Surface
- ☐ Other (Explain in Remarks)

Secondary:
- ☐ B6 - Surface Soil Cracks
- ☐ B10 - Drainage Patterns
- ☐ B16 - Moss Trim Lines
- ☐ C2 - Dry-Season Water Table
- ☐ C8 - Crayfish Burrows
- ☐ C9 - Saturation Visible on Aerial Imagery
- ☐ D1 - Stunted or Stressed Plants
- ☐ D2 - Geomorphic Position
- ☐ D3 - Shallow Aquitard
- ☐ D4 - Microtopographic Relief
- ☐ D5 - FAC-Neutral Test

Field Observations:

Surface Water Present?	☐ Yes ☑ No	Depth:	(in.)
Water Table Present?	☐ Yes ☑ No	Depth:	(in.)
Saturation Present?	☐ Yes ☑ No	Depth:	(in.)

Wetland Hydrology Present? ☑ Yes ☐ No

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available: N/A

Remarks: Statewide drought

SOILS

Map Unit Name: Chesuncook-Elliottsville-Telos association, 3 to 15% Series Drainage Class: moderately well drained

Taxonomy (Subgroup): Coarse-loamy, isotic, frigid Aquic Haplorthods

Profile Description (Describe to the depth needed to document the indicator or confirm the absence of indicators.) (Type: C=Concentration, D=Depletion, RM=Reduced Matrix, CS=Covered/Coated Sand Grains; Location: PL=Pore Lining, M=Matrix)

Top Depth	Bottom Depth	Horizon	Matrix Color (Moist)		Matrix %	Mottles Color (Moist)		Mottles %	Mottles Type	Mottles Location	Texture (e.g. clay, sand, loam)
0	14	--	10YR	4/1	80	10YR	2/1	10	--	--	fine sandy loam
--	--	--	--	--	--	10YR	5/6	10	C	M	fine sandy loam
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--

NRCS Hydric Soil Field Indicators (check here if indicators are not present ☐):
- ☐ A1- Histosol
- ☐ A2 - Histic Epipedon
- ☐ A3 - Black Histic
- ☐ A4 - Hydrogen Sulfide
- ☐ A5 - Stratified Layers
- ☐ A11 - Depleted Below Dark Surface
- ☐ A12 - Thick Dark Surface
- ☐ S1 - Sandy Muck Mineral
- ☐ S4 - Sandy Gleyed Matrix
- ☐ S5 - Sandy Redox
- ☐ S6 - Stripped Matrix
- ☐ S7 - Dark Surface (LRR R, MLRA 149B)
- ☐ S8 - Polyvalue Below Surface (LRR R, MLRA 149B)
- ☐ S9 - Thin Dark Surface (LRR R, MLRA 149B)
- ☐ F1 - Loamy Mucky Mineral (LRR K, L)
- ☐ F2 - Loamy Gleyed Matrix
- ☑ F3 - Depleted Matrix
- ☐ F6 - Redox Dark Surface
- ☐ F7 - Depleted Dark Surface
- ☐ F8 - Redox Depressions

Indicators for Problematic Soils [1]
- ☐ A10 - 2 cm Muck (LRR K, L, MLRA 149B)
- ☐ A16 - Coast Prairie Redox (LRR K, L, R)
- ☐ S3 - 5cm Mucky Peat of Peat (**LRR K, L, R**)
- ☐ S7 - Dark Surface (LRR K, L, M)
- ☐ S8 - Polyvalue Below Surface (**LRR K, L**)
- ☐ S9 - Thin Dark Surface (**LRR K, L**)
- ☐ F12 - Iron-Manganese Masses (**LRR K, L, R**)
- ☐ F19 - Piedmont Floodplain Soils (**MLRA 149B**)
- ☐ TA6 - Mesic Spodic (**MLRA 144A, 145, 149B**)
- ☐ TF2 - Red Parent Material
- ☐ TF12 - Very Shallow Dark Surface
- ☐ Other (Explain in Remarks)

[1] Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (If Observed) Type: LEDGE Depth: 14

Hydric Soil Present? ☑ Yes ☐ No

Remarks:

TETRA TECH

WETLAND DETERMINATION DATA FORM

Northeast and Northcentral Region

Project/Site: Western Maine Renewable Energy Project Wetland ID: W47EI Sample Point **Wetland**

VEGETATION (Species identified in all uppercase are non-native species.)

Tree Stratum (Plot size: 10 meter radius)

	Species Name	% Cover	Dominant	Ind.Status
1.	*Larix laricina*	30	Y	FACW
2.	*Acer rubrum*	50	Y	FAC
3.	*Fraxinus nigra*	20	N	FACW
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	100		

Sapling/Shrub Stratum (Plot size: 5 meter radius)

1.	*Picea mariana*	5	N	FACW
2.	*Acer rubrum*	5	N	FAC
3.	*Fraxinus nigra*	5	N	FACW
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	15		

Herb Stratum (Plot size: 2 meter radius)

1.	*Onoclea sensibilis*	10	N	FACW
2.	*Parathelypteris noveboracensis*	10	N	FAC
3.	*Calamagrostis canadensis*	50	Y	OBL
4.	*Fragaria vesca*	30	Y	UPL
5.	--	--	--	--
6	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
11.	--	--	--	--
12.	--	--	--	--
13.	--	--	--	--
14.	--	--	--	--
15.	--	--	--	--
	Total Cover =	100		

Woody Vine Stratum (Plot size: 10 meter radius)

1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
	Total Cover =	0		

Remarks:

Dominance Test Worksheet

Number of Dominant Species that are OBL, FACW, or FAC: 3 (A)

Total Number of Dominant Species Across All Strata: 4 (B)

Percent of Dominant Species That Are OBL, FACW, or FAC: ***75.0%*** (A/B)

Prevalence Index Worksheet

Total % Cover of:		Multiply by:	
OBL spp.	50	x 1 =	50
FACW spp.	70	x 2 =	140
FAC spp.	65	x 3 =	195
FACU spp.	0	x 4 =	0
UPL spp.	30	x 5 =	150
Total	215 (A)		535 (B)

Prevalence Index = B/A = ***2.488***

Hydrophytic Vegetation Indicators:

- ☐ Yes ☑ No Rapid Test for Hydrophytic Vegetation
- ☑ Yes ☐ No Dominance Test is > 50%
- ☑ Yes ☐ No Prevalence Index is ≤ 3.0 *
- ☐ Yes ☑ No Morphological Adaptations (Explain) *
- ☐ Yes ☑ No Problem Hydrophytic Vegetation (Explain) *

* Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic.

Definitions of Vegetation Strata:

Tree - Woody plants 3 in. (7.6cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/Shrub - Woody plants less than 3 in. DBH and greater than 3.28 ft. tall.

Herb - All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft. tall.

Woody Vines - All woody vines greater than 3.28 ft. in height.

Hydrophytic Vegetation Present ☑ Yes ☐ No

Additional Remarks:

TETRA TECH

WETLAND DETERMINATION DATA FORM
Northeast and Northcentral Region

Project/Site:	Western Maine Renewable Energy Project	Project #: 194-7130	Date: 09/09/20
Applicant:	Western Maine Renewables, LLC		County: Somerset
Investigator #1:	Emmy Irvin	Investigator #2:	State: ME
Soil Unit:	Chesuncook-Elliottsville-Telos association, 3 to 15%	NWI/WWI Classification: Upland	Wetland ID: W48EI
Landform:	Terrace	Local Relief: Linear	Sample Point: **Upland**
Slope (%):	See topo map	Latitude: 45.140627 Longitude: -69.8696469 Datum: NAD 83	

Are climatic/hydrologic conditions on the site typical for this time of year? (If no, explain in remarks) ☐ Yes ☑ No

Are Vegetation ☐, Soil ☐, or Hydrology ☐ significantly disturbed?
Are Vegetation ☐, Soil ☐, or Hydrology ☐ naturally problematic?

Are normal circumstances present? ☐ Yes ☑ No

SUMMARY OF FINDINGS

Hydrophytic Vegetation Present?	☐ Yes ☑ No	Hydric Soils Present?	☐ Yes ☑ No
Wetland Hydrology Present?	☐ Yes ☑ No	Is This Sampling Point Within A Wetland?	☐ **Yes** ☑ **No**

Remarks: Statewide drought

HYDROLOGY

Wetland Hydrology Indicators (Check here if indicators are not present ☑)

Primary:
- ☐ A1 - Surface Water
- ☐ A2 - High Water Table
- ☐ A3 - Saturation
- ☐ B1 - Water Marks
- ☐ B2 - Sediment Deposits
- ☐ B3 - Drift Deposits
- ☐ B4 - Algal Mat or Crust
- ☐ B5 - Iron Deposits
- ☐ B7 - Inundation Visible on Aerial Imagery
- ☐ B8 - Sparsely Vegetated Concave Surface
- ☐ B9 - Water-Stained Leaves
- ☐ B13 - Aquatic Fauna
- ☐ B15 - Marl Deposits
- ☐ C1 - Hydrogen Sulfide Odor
- ☐ C3 - Oxidized Rhizospheres on Living Roots
- ☐ C4 - Presence of Reduced Iron
- ☐ C6 - Recent Iron Reduction in Tilled Soils
- ☐ C7 - Thin Muck Surface
- ☐ Other (Explain in Remarks)

Secondary:
- ☐ B6 - Surface Soil Cracks
- ☐ B10 - Drainage Patterns
- ☐ B16 - Moss Trim Lines
- ☐ C2 - Dry-Season Water Table
- ☐ C8 - Crayfish Burrows
- ☐ C9 - Saturation Visible on Aerial Imagery
- ☐ D1 - Stunted or Stressed Plants
- ☐ D2 - Geomorphic Position
- ☐ D3 - Shallow Aquitard
- ☐ D4 - Microtopographic Relief
- ☐ D5 - FAC-Neutral Test

Field Observations:

Surface Water Present?	☐ Yes ☑ No	Depth:	(in.)
Water Table Present?	☐ Yes ☑ No	Depth:	(in.)
Saturation Present?	☐ Yes ☑ No	Depth:	(in.)

Wetland Hydrology Present? ☐ Yes ☑ No

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available: N/A

Remarks: Statewide drought

SOILS

Map Unit Name: Chesuncook-Elliottsville-Telos association, 3 to 15% Series Drainage Class: moderately well drained

Taxonomy (Subgroup): Coarse-loamy, isotic, frigid Aquic Haplorthods

Profile Description (Describe to the depth needed to document the indicator or confirm the absence of indicators.) (Type: C=Concentration, D=Depletion, RM=Reduced Matrix, CS=Covered/Coated Sand Grains; Location: PL=Pore Lining, M=Matrix)

Top Depth	Bottom Depth	Horizon	Matrix Color (Moist)		Matrix %	Mottles Color (Moist)		Mottles %	Mottles Type	Mottles Location	Texture (e.g. clay, sand, loam)
0	12	--	10YR	5/3	100	--	--	--	--	--	fine sandy loam
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--

NRCS Hydric Soil Field Indicators (check here if indicators are not present ☑):
- ☐ A1- Histosol
- ☐ A2 - Histic Epipedon
- ☐ A3 - Black Histic
- ☐ A4 - Hydrogen Sulfide
- ☐ A5 - Stratified Layers
- ☐ A11 - Depleted Below Dark Surface
- ☐ A12 - Thick Dark Surface
- ☐ S1 - Sandy Muck Mineral
- ☐ S4 - Sandy Gleyed Matrix
- ☐ S5 - Sandy Redox
- ☐ S6 - Stripped Matrix
- ☐ S7 - Dark Surface (LRR R, MLRA 149B)
- ☐ S8 - Polyvalue Below Surface (LRR R, MLRA 149B)
- ☐ S9 - Thin Dark Surface (LRR R, MLRA 149B)
- ☐ F1 - Loamy Mucky Mineral (LRR K, L)
- ☐ F2 - Loamy Gleyed Matrix
- ☐ F3 - Depleted Matrix
- ☐ F6 - Redox Dark Surface
- ☐ F7 - Depleted Dark Surface
- ☐ F8 - Redox Depressions

Indicators for Problematic Soils [1]
- ☐ A10 - 2 cm Muck (LRR K, L, MLRA 149B)
- ☐ A16 - Coast Prairie Redox (LRR K, L, R)
- ☐ S3 - 5cm Mucky Peat of Peat (**LRR K, L, R**)
- ☐ S7 - Dark Surface (LRR K, L, M)
- ☐ S8 - Polyvalue Below Surface (**LRR K, L**)
- ☐ S9 - Thin Dark Surface (**LRR K, L**)
- ☐ F12 - Iron-Manganese Masses (**LRR K, L, R**)
- ☐ F19 - Piedmont Floodplain Soils (**MLRA 149B**)
- ☐ TA6 - Mesic Spodic (**MLRA 144A, 145, 149B**)
- ☐ TF2 - Red Parent Material
- ☐ TF12 - Very Shallow Dark Surface
- ☐ Other (Explain in Remarks)

[1] Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (If Observed) Type: NR Depth: 12

Hydric Soil Present? ☐ Yes ☑ No

Remarks:

TETRA TECH

WETLAND DETERMINATION DATA FORM

Northeast and Northcentral Region

Project/Site: Western Maine Renewable Energy Project | Wetland ID: W48EI | Sample Point **Upland**

VEGETATION (Species identified in all uppercase are non-native species.)

Tree Stratum (Plot size: 10 meter radius)

	Species Name	% Cover	Dominant	Ind.Status
1.	*Betula lenta*	75	Y	FACU
2.	*Acer rubrum*	20	Y	FAC
3.	*Fraxinus nigra*	5	N	FACW
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	100		

Sapling/Shrub Stratum (Plot size: 5 meter radius)

1.	*Acer pensylvanicum*	5	N	FACU
2.	*Betula lenta*	20	Y	FACU
3.	*Acer rubrum*	10	N	FAC
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	35		

Herb Stratum (Plot size: 2 meter radius)

1.	*Medeola virginiana*	5	N	FACU
2.	*Polystichum acrostichoides*	20	Y	FACU
3.	*Phegopteris hexagonoptera*	5	N	FACU
4.	*Athyrium angustum*	5	N	FAC
5.	--	--	--	--
6	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
11.	--	--	--	--
12.	--	--	--	--
13.	--	--	--	--
14.	--	--	--	--
15.	--	--	--	--
	Total Cover =	35		

Woody Vine Stratum (Plot size: 10 meter radius)

1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
	Total Cover =	0		

Remarks:

Dominance Test Worksheet

Number of Dominant Species that are OBL, FACW, or FAC: 1 (A)

Total Number of Dominant Species Across All Strata: 4 (B)

Percent of Dominant Species That Are OBL, FACW, or FAC: ***25.0%*** (A/B)

Prevalence Index Worksheet

Total % Cover of:		Multiply by:	
OBL spp.	0	x 1 =	0
FACW spp.	5	x 2 =	10
FAC spp.	35	x 3 =	105
FACU spp.	130	x 4 =	520
UPL spp.	0	x 5 =	0
Total	170 (A)		635 (B)

Prevalence Index = B/A = ***3.735***

Hydrophytic Vegetation Indicators:

- ☐ Yes ☑ No Rapid Test for Hydrophytic Vegetation
- ☐ Yes ☑ No Dominance Test is > 50%
- ☐ Yes ☑ No Prevalence Index is ≤ 3.0 *
- ☐ Yes ☑ No Morphological Adaptations (Explain) *
- ☐ Yes ☑ No Problem Hydrophytic Vegetation (Explain) *

* Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic.

Definitions of Vegetation Strata:

Tree - Woody plants 3 in. (7.6cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/Shrub - Woody plants less than 3 in. DBH and greater than 3.28 ft. tall.

Herb - All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft. tall.

Woody Vines - All woody vines greater than 3.28 ft. in height.

Hydrophytic Vegetation Present ☐ Yes ☑ No

Additional Remarks:

TETRA TECH

WETLAND DETERMINATION DATA FORM
Northeast and Northcentral Region

Project/Site:	Western Maine Renewable Energy Project	Project #: 194-7130	Date: 09/09/20
Applicant:	Western Maine Renewables, LLC		County: Somerset
Investigator #1:	Emmy Irvin	Investigator #2:	State: ME
Soil Unit:	Chesuncook-Elliottsville-Telos association, 3 to 15%	NWI/WWI Classification: PFO	Wetland ID: W48EI
Landform:	Terrace	Local Relief: Linear	Sample Point: **Wetland**
Slope (%):	See topo map	Latitude: 45.140674 Longitude: -69.869728 Datum: NAD 83	

Are climatic/hydrologic conditions on the site typical for this time of year? (If no, explain in remarks) ☐ Yes ☑ No

Are Vegetation ☐, Soil ☐, or Hydrology ☐ significantly disturbed?
Are Vegetation ☐, Soil ☐, or Hydrology ☐ naturally problematic?

Are normal circumstances present? ☐ Yes ☑ No

SUMMARY OF FINDINGS

Hydrophytic Vegetation Present?	☑ Yes ☐ No	Hydric Soils Present?	☑ Yes ☐ No
Wetland Hydrology Present?	☑ Yes ☐ No	Is This Sampling Point Within A Wetland?	☑ **Yes** ☐ **No**

Remarks: Statewide drought

HYDROLOGY

Wetland Hydrology Indicators (Check here if indicators are not present ☐)

Primary:
- ☐ A1 - Surface Water
- ☐ A2 - High Water Table
- ☐ A3 - Saturation
- ☐ B1 - Water Marks
- ☐ B2 - Sediment Deposits
- ☐ B3 - Drift Deposits
- ☐ B4 - Algal Mat or Crust
- ☐ B5 - Iron Deposits
- ☐ B7 - Inundation Visible on Aerial Imagery
- ☐ B8 - Sparsely Vegetated Concave Surface
- ☐ B9 - Water-Stained Leaves
- ☐ B13 - Aquatic Fauna
- ☐ B15 - Marl Deposits
- ☐ C1 - Hydrogen Sulfide Odor
- ☑ C3 - Oxidized Rhizospheres on Living Roots
- ☐ C4 - Presence of Reduced Iron
- ☐ C6 - Recent Iron Reduction in Tilled Soils
- ☐ C7 - Thin Muck Surface
- ☐ Other (Explain in Remarks)

Secondary:
- ☐ B6 - Surface Soil Cracks
- ☐ B10 - Drainage Patterns
- ☐ B16 - Moss Trim Lines
- ☐ C2 - Dry-Season Water Table
- ☐ C8 - Crayfish Burrows
- ☐ C9 - Saturation Visible on Aerial Imagery
- ☐ D1 - Stunted or Stressed Plants
- ☐ D2 - Geomorphic Position
- ☐ D3 - Shallow Aquitard
- ☐ D4 - Microtopographic Relief
- ☐ D5 - FAC-Neutral Test

Field Observations:

Surface Water Present?	☐ Yes ☑ No	Depth:	(in.)
Water Table Present?	☐ Yes ☑ No	Depth:	(in.)
Saturation Present?	☐ Yes ☑ No	Depth:	(in.)

Wetland Hydrology Present? ☑ Yes ☐ No

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available: N/A

Remarks: Statewide drought

SOILS

Map Unit Name: Chesuncook-Elliottsville-Telos association, 3 to 15% Series Drainage Class: moderately well drained

Taxonomy (Subgroup): Coarse-loamy, isotic, frigid Aquic Haplorthods

Profile Description (Describe to the depth needed to document the indicator or confirm the absence of indicators.) (Type: C=Concentration, D=Depletion, RM=Reduced Matrix, CS=Covered/Coated Sand Grains; Location: PL=Pore Lining, M=Matrix)

Top Depth	Bottom Depth	Horizon	Matrix Color (Moist)		Matrix %	Mottles Color (Moist)		Mottles %	Mottles Type	Mottles Location	Texture (e.g. clay, sand, loam)
0	14	--	10YR	4/1	80	10YR	2/1	10	--	--	fine sandy loam
--	--	--	--	--	--	10YR	5/6	10	C	M	fine sandy loam
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--

NRCS Hydric Soil Field Indicators (check here if indicators are not present ☐):
- ☐ A1- Histosol
- ☐ A2 - Histic Epipedon
- ☐ A3 - Black Histic
- ☐ A4 - Hydrogen Sulfide
- ☐ A5 - Stratified Layers
- ☐ A11 - Depleted Below Dark Surface
- ☐ A12 - Thick Dark Surface
- ☐ S1 - Sandy Muck Mineral
- ☐ S4 - Sandy Gleyed Matrix
- ☐ S5 - Sandy Redox
- ☐ S6 - Stripped Matrix
- ☐ S7 - Dark Surface (LRR R, MLRA 149B)
- ☐ S8 - Polyvalue Below Surface (LRR R, MLRA 149B)
- ☐ S9 - Thin Dark Surface (LRR R, MLRA 149B)
- ☐ F1 - Loamy Mucky Mineral (LRR K, L)
- ☐ F2 - Loamy Gleyed Matrix
- ☑ F3 - Depleted Matrix
- ☐ F6 - Redox Dark Surface
- ☐ F7 - Depleted Dark Surface
- ☐ F8 - Redox Depressions

Indicators for Problematic Soils [1]
- ☐ A10 - 2 cm Muck (LRR K, L, MLRA 149B)
- ☐ A16 - Coast Prairie Redox (LRR K, L, R)
- ☐ S3 - 5cm Mucky Peat of Peat (**LRR K, L, R**)
- ☐ S7 - Dark Surface (LRR K, L, M)
- ☐ S8 - Polyvalue Below Surface (**LRR K, L**)
- ☐ S9 - Thin Dark Surface (**LRR K, L**)
- ☐ F12 - Iron-Manganese Masses (**LRR K, L, R**)
- ☐ F19 - Piedmont Floodplain Soils (**MLRA 149B**)
- ☐ TA6 - Mesic Spodic (**MLRA 144A, 145, 149B**)
- ☐ TF2 - Red Parent Material
- ☐ TF12 - Very Shallow Dark Surface
- ☐ Other (Explain in Remarks)

[1] Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (If Observed) Type: LEDGE Depth: 14

Hydric Soil Present? ☑ Yes ☐ No

Remarks:

TETRA TECH

WETLAND DETERMINATION DATA FORM

Northeast and Northcentral Region

Project/Site: Western Maine Renewable Energy Project Wetland ID: W48EI Sample Point **Wetland**

VEGETATION (Species identified in all uppercase are non-native species.)

Tree Stratum (Plot size: 10 meter radius)

	Species Name	% Cover	Dominant	Ind.Status
1.	*Larix laricina*	30	Y	FACW
2.	*Acer rubrum*	50	Y	FAC
3.	*Fraxinus nigra*	20	N	FACW
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	100		

Sapling/Shrub Stratum (Plot size: 5 meter radius)

1.	*Picea mariana*	5	N	FACW
2.	*Acer rubrum*	5	N	FAC
3.	*Fraxinus nigra*	5	N	FACW
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	15		

Herb Stratum (Plot size: 2 meter radius)

1.	*Onoclea sensibilis*	10	N	FACW
2.	*Parathelypteris noveboracensis*	10	N	FAC
3.	*Calamagrostis canadensis*	50	Y	OBL
4.	*Fragaria vesca*	30	Y	UPL
5.	--	--	--	--
6	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
11.	--	--	--	--
12.	--	--	--	--
13.	--	--	--	--
14.	--	--	--	--
15.	--	--	--	--
	Total Cover =	100		

Woody Vine Stratum (Plot size: 10 meter radius)

1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
	Total Cover =	0		

Remarks:

Dominance Test Worksheet

Number of Dominant Species that are OBL, FACW, or FAC: 3 (A)

Total Number of Dominant Species Across All Strata: 4 (B)

Percent of Dominant Species That Are OBL, FACW, or FAC: ***75.0%*** (A/B)

Prevalence Index Worksheet

Total % Cover of:		Multiply by:	
OBL spp.	50	x 1 =	50
FACW spp.	70	x 2 =	140
FAC spp.	65	x 3 =	195
FACU spp.	0	x 4 =	0
UPL spp.	30	x 5 =	150
Total	215 (A)		535 (B)

Prevalence Index = B/A = ***2.488***

Hydrophytic Vegetation Indicators:

- ☐ Yes ☑ No Rapid Test for Hydrophytic Vegetation
- ☑ Yes ☐ No Dominance Test is > 50%
- ☑ Yes ☐ No Prevalence Index is ≤ 3.0 *
- ☐ Yes ☑ No Morphological Adaptations (Explain) *
- ☐ Yes ☑ No Problem Hydrophytic Vegetation (Explain) *

* Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic.

Definitions of Vegetation Strata:

Tree - Woody plants 3 in. (7.6cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/Shrub - Woody plants less than 3 in. DBH and greater than 3.28 ft. tall.

Herb - All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft. tall.

Woody Vines - All woody vines greater than 3.28 ft. in height.

Hydrophytic Vegetation Present ☑ Yes ☐ No

Additional Remarks:

TETRA TECH

WETLAND DETERMINATION DATA FORM
Northeast and Northcentral Region

Project/Site:	Western Maine Renewable Energy Project	Project #: 194-7130	Date: 09/09/20
Applicant:	Western Maine Renewables, LLC		County: Somerset
Investigator #1:	Emmy Irvin	Investigator #2:	State: ME
Soil Unit:	Chesuncook-Elliottsville-Telos association, 3 to 15 percent slopes, very stony	NWI/WWI Classification: Upland	Wetland ID: W51EI
Landform:	Terrace	Local Relief: Linear	Sample Point: **Upland**
Slope (%):	See topo map	Latitude: 45.138110 Longitude: -69.873539 Datum: NAD 83	

Are climatic/hydrologic conditions on the site typical for this time of year? (If no, explain in remarks) ☐ Yes ☑ No

Are Vegetation ☐, Soil ☐, or Hydrology ☐ significantly disturbed?
Are Vegetation ☐, Soil ☐, or Hydrology ☐ naturally problematic?

Are normal circumstances present? ☐ Yes ☑ No

SUMMARY OF FINDINGS

Hydrophytic Vegetation Present?	☐ Yes ☑ No	Hydric Soils Present?	☐ Yes ☑ No
Wetland Hydrology Present?	☐ Yes ☑ No	Is This Sampling Point Within A Wetland?	☐ **Yes** ☑ **No**

Remarks: Statewide drought

HYDROLOGY

Wetland Hydrology Indicators (Check here if indicators are not present ☑)

Primary:
- ☐ A1 - Surface Water
- ☐ A2 - High Water Table
- ☐ A3 - Saturation
- ☐ B1 - Water Marks
- ☐ B2 - Sediment Deposits
- ☐ B3 - Drift Deposits
- ☐ B4 - Algal Mat or Crust
- ☐ B5 - Iron Deposits
- ☐ B7 - Inundation Visible on Aerial Imagery
- ☐ B8 - Sparsely Vegetated Concave Surface
- ☐ B9 - Water-Stained Leaves
- ☐ B13 - Aquatic Fauna
- ☐ B15 - Marl Deposits
- ☐ C1 - Hydrogen Sulfide Odor
- ☐ C3 - Oxidized Rhizospheres on Living Roots
- ☐ C4 - Presence of Reduced Iron
- ☐ C6 - Recent Iron Reduction in Tilled Soils
- ☐ C7 - Thin Muck Surface
- ☐ Other (Explain in Remarks)

Secondary:
- ☐ B6 - Surface Soil Cracks
- ☐ B10 - Drainage Patterns
- ☐ B16 - Moss Trim Lines
- ☐ C2 - Dry-Season Water Table
- ☐ C8 - Crayfish Burrows
- ☐ C9 - Saturation Visible on Aerial Imagery
- ☑ D1 - Stunted or Stressed Plants
- ☐ D2 - Geomorphic Position
- ☐ D3 - Shallow Aquitard
- ☐ D4 - Microtopographic Relief
- ☐ D5 - FAC-Neutral Test

Field Observations:

Surface Water Present?	☐ Yes ☑ No	Depth:	(in.)
Water Table Present?	☐ Yes ☑ No	Depth:	(in.)
Saturation Present?	☐ Yes ☑ No	Depth:	(in.)

Wetland Hydrology Present? ☐ Yes ☑ No

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available: N/A

Remarks: Statewide drought

SOILS

Map Unit Name: Chesuncook-Elliottsville-Telos association, 3 to 15 percent slopes, very stony — Series Drainage Class: Somewhat poorly drained

Taxonomy (Subgroup): Loamy, isotic, frigid, shallow Aquic Haplorthods

Profile Description (Describe to the depth needed to document the indicator or confirm the absence of indicators.) (Type: C=Concentration, D=Depletion, RM=Reduced Matrix, CS=Covered/Coated Sand Grains; Location: PL=Pore Lining, M=Matrix)

Top Depth	Bottom Depth	Horizon	Matrix Color (Moist)		Matrix %	Mottles Color (Moist)		Mottles %	Mottles Type	Mottles Location	Texture (e.g. clay, sand, loam)
0	1	--	2.5YR	3/1	100	--	--	--	--	--	fine sandy loam
1	2	E	7.5YR	7/1	100	--	--	--	--	--	fine sandy loam
2	15	--	7.5YR	4/3	100	--	--	--	--	--	fine sandy loam
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--

NRCS Hydric Soil Field Indicators (check here if indicators are not present ☑):
- ☐ A1- Histosol
- ☐ A2 - Histic Epipedon
- ☐ A3 - Black Histic
- ☐ A4 - Hydrogen Sulfide
- ☐ A5 - Stratified Layers
- ☐ A11 - Depleted Below Dark Surface
- ☐ A12 - Thick Dark Surface
- ☐ S1 - Sandy Muck Mineral
- ☐ S4 - Sandy Gleyed Matrix
- ☐ S5 - Sandy Redox
- ☐ S6 - Stripped Matrix
- ☐ S7 - Dark Surface (LRR R, MLRA 149B)
- ☐ S8 - Polyvalue Below Surface (LRR R, MLRA 149B)
- ☐ S9 - Thin Dark Surface (LRR R, MLRA 149B)
- ☐ F1 - Loamy Mucky Mineral (LRR K, L)
- ☐ F2 - Loamy Gleyed Matrix
- ☐ F3 - Depleted Matrix
- ☐ F6 - Redox Dark Surface
- ☐ F7 - Depleted Dark Surface
- ☐ F8 - Redox Depressions

Indicators for Problematic Soils [1]
- ☐ A10 - 2 cm Muck (LRR K, L, MLRA 149B)
- ☐ A16 - Coast Prairie Redox (LRR K, L, R)
- ☐ S3 - 5cm Mucky Peat of Peat (**LRR K, L, R**)
- ☐ S7 - Dark Surface (LRR K, L, M)
- ☐ S8 - Polyvalue Below Surface (**LRR K, L**)
- ☐ S9 - Thin Dark Surface (**LRR K, L**)
- ☐ F12 - Iron-Manganese Masses (**LRR K, L, R**)
- ☐ F19 - Piedmont Floodplain Soils (**MLRA 149B**)
- ☐ TA6 - Mesic Spodic (**MLRA 144A, 145, 149B**)
- ☐ TF2 - Red Parent Material
- ☐ TF12 - Very Shallow Dark Surface
- ☐ Other (Explain in Remarks)

[1] Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (If Observed) Type: ledge Depth: 11

Hydric Soil Present? ☐ Yes ☑ No

Remarks:

TETRA TECH

WETLAND DETERMINATION DATA FORM

Northeast and Northcentral Region

Project/Site: Western Maine Renewable Energy Project | Wetland ID: W51EI | Sample Point **Upland**

VEGETATION (Species identified in all uppercase are non-native species.)

Tree Stratum (Plot size: 10 meter radius)

	Species Name	% Cover	Dominant	Ind.Status
1.	*Picea rubens*	20	Y	FACU
2.	*Acer rubrum*	20	Y	FAC
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	40		

Sapling/Shrub Stratum (Plot size: 5 meter radius)

1.	*Viburnum lantanoides*	5	Y	FACU
2.	*Picea rubens*	1	N	FACU
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	6		

Herb Stratum (Plot size: 2 meter radius)

1.	*Aralia nudicaulis*	5	Y	FACU
2.	*Acer rubrum*	5	N	FAC
3.	--		--	--
4.	--		--	--
5.	--		--	--
6	--		--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
11.	--	--	--	--
12.	--	--	--	--
13.	--	--	--	--
14.	--	--	--	--
15.	--	--	--	--
	Total Cover =	10		

Woody Vine Stratum (Plot size: 10 meter radius)

1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
	Total Cover =	0		

Dominance Test Worksheet

Number of Dominant Species that are OBL, FACW, or FAC: 1 (A)

Total Number of Dominant Species Across All Strata: 4 (B)

Percent of Dominant Species That Are OBL, FACW, or FAC: ***25.0%*** (A/B)

Prevalence Index Worksheet

Total % Cover of:		Multiply by:	
OBL spp.	0	x 1 =	0
FACW spp.	0	x 2 =	0
FAC spp.	25	x 3 =	75
FACU spp.	31	x 4 =	124
UPL spp.	0	x 5 =	0
Total	56 (A)		199 (B)

Prevalence Index = B/A = ***3.554***

Hydrophytic Vegetation Indicators:

- ☐ Yes ☑ No Rapid Test for Hydrophytic Vegetation
- ☐ Yes ☑ No Dominance Test is > 50%
- ☐ Yes ☑ No Prevalence Index is ≤ 3.0 *
- ☐ Yes ☑ No Morphological Adaptations (Explain) *
- ☐ Yes ☑ No Problem Hydrophytic Vegetation (Explain) *

* Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic.

Definitions of Vegetation Strata:

Tree - Woody plants 3 in. (7.6cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/Shrub - Woody plants less than 3 in. DBH and greater than 3.28 ft. tall.

Herb - All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft. tall.

Woody Vines - All woody vines greater than 3.28 ft. in height.

Hydrophytic Vegetation Present ☐ Yes ☑ No

Remarks:

Additional Remarks:

TETRA TECH

WETLAND DETERMINATION DATA FORM
Northeast and Northcentral Region

Project/Site:	Western Maine Renewable Energy Project	Project #: 194-7130	Date: 09/09/20
Applicant:	Western Maine Renewables, LLC		County: Somerset
Investigator #1:	Emmy Irvin	Investigator #2:	State: ME
Soil Unit:	Chesuncook-Elliottsville-Telos association, 3 to 15%	NWI/WWI Classification: PEM/PSS	Wetland ID: W51EI
Landform:	Terrace	Local Relief: Linear	Sample Point: **Wetland**
Slope (%):	See topo map	Latitude: 45.138704 Longitude: -69.8733048 Datum: NAD 83	

Are climatic/hydrologic conditions on the site typical for this time of year? (If no, explain in remarks) ☐ Yes ☐ No

Are Vegetation ☐, Soil ☐, or Hydrology ☐ significantly disturbed?
Are Vegetation ☐, Soil ☐, or Hydrology ☐ naturally problematic?

Are normal circumstances present? ☐ Yes ☑ No

SUMMARY OF FINDINGS

Hydrophytic Vegetation Present?	☑ Yes ☐ No	Hydric Soils Present?	☑ Yes ☐ No
Wetland Hydrology Present?	☑ Yes ☐ No	Is This Sampling Point Within A Wetland?	☑ **Yes** ☐ **No**

Remarks: Statewide drought

HYDROLOGY

Wetland Hydrology Indicators (Check here if indicators are not present ☐)

Primary:
- ☐ A1 - Surface Water
- ☐ A2 - High Water Table
- ☑ A3 - Saturation
- ☐ B1 - Water Marks
- ☐ B2 - Sediment Deposits
- ☐ B3 - Drift Deposits
- ☐ B4 - Algal Mat or Crust
- ☐ B5 - Iron Deposits
- ☐ B7 - Inundation Visible on Aerial Imagery
- ☐ B8 - Sparsely Vegetated Concave Surface
- ☐ B9 - Water-Stained Leaves
- ☐ B13 - Aquatic Fauna
- ☐ B15 - Marl Deposits
- ☐ C1 - Hydrogen Sulfide Odor
- ☐ C3 - Oxidized Rhizospheres on Living Roots
- ☐ C4 - Presence of Reduced Iron
- ☐ C6 - Recent Iron Reduction in Tilled Soils
- ☐ C7 - Thin Muck Surface
- ☐ Other (Explain in Remarks)

Secondary:
- ☐ B6 - Surface Soil Cracks
- ☑ B10 - Drainage Patterns
- ☐ B16 - Moss Trim Lines
- ☐ C2 - Dry-Season Water Table
- ☐ C8 - Crayfish Burrows
- ☐ C9 - Saturation Visible on Aerial Imagery
- ☐ D1 - Stunted or Stressed Plants
- ☐ D2 - Geomorphic Position
- ☐ D3 - Shallow Aquitard
- ☐ D4 - Microtopographic Relief
- ☑ D5 - FAC-Neutral Test

Field Observations:

Surface Water Present?	☐ Yes ☑ No	Depth:	(in.)
Water Table Present?	☐ Yes ☑ No	Depth:	(in.)
Saturation Present?	☐ Yes ☑ No	Depth:	(in.)

Wetland Hydrology Present? ☑ Yes ☐ No

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available: N/A

Remarks: Statewide drought

SOILS

Map Unit Name: Chesuncook-Elliottsville-Telos association, 3 to 15% Series Drainage Class: Somewhat poorly drained

Taxonomy (Subgroup): Loamy, isotic, frigid, shallow Aquic Haplorthods

Profile Description (Describe to the depth needed to document the indicator or confirm the absence of indicators.) (Type: C=Concentration, D=Depletion, RM=Reduced Matrix, CS=Covered/Coated Sand Grains; Location: PL=Pore Lining, M=Matrix)

Top Depth	Bottom Depth	Horizon	Matrix Color (Moist)		Matrix %	Mottles Color (Moist)		Mottles %	Mottles Type	Mottles Location	Texture (e.g. clay, sand, loam)
0	1	--	7.5YR	3/2	100	--	--	--	--	--	fine sandy loam
1	3	--	2.5Y	3/1	100	--	--	--	--	--	fine sandy loam
3	11	--	5Y	4/2	100	10YR	8/6	2	C	PL	sandy loam
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--

NRCS Hydric Soil Field Indicators (check here if indicators are not present ☐):
- ☐ A1- Histosol
- ☐ A2 - Histic Epipedon
- ☐ A3 - Black Histic
- ☐ A4 - Hydrogen Sulfide
- ☐ A5 - Stratified Layers
- ☐ A11 - Depleted Below Dark Surface
- ☐ A12 - Thick Dark Surface
- ☐ S1 - Sandy Muck Mineral
- ☐ S4 - Sandy Gleyed Matrix
- ☐ S5 - Sandy Redox
- ☐ S6 - Stripped Matrix
- ☐ S7 - Dark Surface (LRR R, MLRA 149B)
- ☐ S8 - Polyvalue Below Surface (LRR R, MLRA 149B)
- ☐ S9 - Thin Dark Surface (LRR R, MLRA 149B)
- ☐ F1 - Loamy Mucky Mineral (LRR K, L)
- ☐ F2 - Loamy Gleyed Matrix
- ☑ F3 - Depleted Matrix
- ☐ F6 - Redox Dark Surface
- ☐ F7 - Depleted Dark Surface
- ☐ F8 - Redox Depressions

Indicators for Problematic Soils [1]
- ☐ A10 - 2 cm Muck (LRR K, L, MLRA 149B)
- ☐ A16 - Coast Prairie Redox (LRR K, L, R)
- ☐ S3 - 5cm Mucky Peat of Peat (**LRR K, L, R**)
- ☐ S7 - Dark Surface (LRR K, L, M)
- ☐ S8 - Polyvalue Below Surface (**LRR K, L**)
- ☐ S9 - Thin Dark Surface (**LRR K, L**)
- ☐ F12 - Iron-Manganese Masses (**LRR K, L, R**)
- ☐ F19 - Piedmont Floodplain Soils (**MLRA 149B**)
- ☐ TA6 - Mesic Spodic (**MLRA 144A, 145, 149B**)
- ☐ TF2 - Red Parent Material
- ☐ TF12 - Very Shallow Dark Surface
- ☐ Other (Explain in Remarks)

[1] Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (If Observed) Type: ledge Depth: 11

Hydric Soil Present? ☑ Yes ☐ No

Remarks:

TETRA TECH

WETLAND DETERMINATION DATA FORM
Northeast and Northcentral Region

Project/Site: Western Maine Renewable Energy Project Wetland ID: W51EI Sample Point **Wetland**

VEGETATION (Species identified in all uppercase are non-native species.)

Tree Stratum (Plot size: 10 meter radius)

	Species Name	% Cover	Dominant	Ind.Status
1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	0		

Sapling/Shrub Stratum (Plot size: 5 meter radius)

1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	0		

Herb Stratum (Plot size: 2 meter radius)

1.	*Calamagrostis canadensis*	50	Y	OBL
2.	*Symphyotrichum laeve*	20	Y	FACU
3.	*Osmunda claytoniana*	10	N	FAC
4.	*Onoclea sensibilis*	2	N	FACW
5.	*Spiraea alba*	5	N	FACW
6	*Rubus allegheniensis*	5	N	FACU
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
11.	--	--	--	--
12.	--	--	--	--
13.	--	--	--	--
14.	--	--	--	--
15.	--	--	--	--
	Total Cover =	92		

Woody Vine Stratum (Plot size: 10 meter radius)

1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
	Total Cover =	0		

Remarks:

Dominance Test Worksheet

Number of Dominant Species that are OBL, FACW, or FAC: 1 (A)

Total Number of Dominant Species Across All Strata: 2 (B)

Percent of Dominant Species That Are OBL, FACW, or FAC: ***50.0%*** (A/B)

Prevalence Index Worksheet

Total % Cover of:		Multiply by:	
OBL spp.	50	x 1 =	50
FACW spp.	7	x 2 =	14
FAC spp.	10	x 3 =	30
FACU spp.	25	x 4 =	100
UPL spp.	0	x 5 =	0
Total	92 (A)		194 (B)

Prevalence Index = B/A = ***2.109***

Hydrophytic Vegetation Indicators:

- ☐ Yes ☐ No Rapid Test for Hydrophytic Vegetation
- ☐ Yes ☐ No Dominance Test is > 50%
- ☐ Yes ☐ No Prevalence Index is ≤ 3.0 *
- ☐ Yes ☐ No Morphological Adaptations (Explain) *
- ☐ Yes ☐ No Problem Hydrophytic Vegetation (Explain) *

* Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic.

Definitions of Vegetation Strata:

Tree - Woody plants 3 in. (7.6cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/Shrub - Woody plants less than 3 in. DBH and greater than 3.28 ft. tall.

Herb - All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft. tall.

Woody Vines - All woody vines greater than 3.28 ft. in height.

Hydrophytic Vegetation Present ☑ Yes ☐ No

Additional Remarks:

TETRA TECH

WETLAND DETERMINATION DATA FORM
Northeast and Northcentral Region

Project/Site:	Western Maine Renewable Energy Project	Project #: 194-7130	Date: 09/09/20
Applicant:	Western Maine Renewables, LLC		County: Somerset
Investigator #1:	Emmy Irvin	Investigator #2:	State: ME
Soil Unit:	Chesuncook-Elliottsville-Telos association, 3 to 15 percent slopes, very stony	NWI/WWI Classification: Upland	Wetland ID: W52EI
Landform:	Terrace	Local Relief: Linear	Sample Point: **Upland**
Slope (%):	See topo map	Latitude: 45.138110 Longitude: -69.873539 Datum: NAD 83	
Are climatic/hydrologic conditions on the site typical for this time of year? (If no, explain in remarks)		☐ Yes ☑ No	
Are Vegetation ☐, Soil ☐, or Hydrology ☐ significantly disturbed? Are Vegetation ☐, Soil ☐, or Hydrology ☐ naturally problematic?		Are normal circumstances present? ☐ Yes ☑ No	

SUMMARY OF FINDINGS

Hydrophytic Vegetation Present?	☐ Yes ☑ No	Hydric Soils Present?	☐ Yes ☑ No
Wetland Hydrology Present?	☐ Yes ☑ No	Is This Sampling Point Within A Wetland?	☐ **Yes** ☑ **No**

Remarks: Statewide drought

HYDROLOGY

Wetland Hydrology Indicators (Check here if indicators are not present): ☑

Primary:
- ☐ A1 - Surface Water
- ☐ A2 - High Water Table
- ☐ A3 - Saturation
- ☐ B1 - Water Marks
- ☐ B2 - Sediment Deposits
- ☐ B3 - Drift Deposits
- ☐ B4 - Algal Mat or Crust
- ☐ B5 - Iron Deposits
- ☐ B7 - Inundation Visible on Aerial Imagery
- ☐ B8 - Sparsely Vegetated Concave Surface
- ☐ B9 - Water-Stained Leaves
- ☐ B13 - Aquatic Fauna
- ☐ B15 - Marl Deposits
- ☐ C1 - Hydrogen Sulfide Odor
- ☐ C3 - Oxidized Rhizospheres on Living Roots
- ☐ C4 - Presence of Reduced Iron
- ☐ C6 - Recent Iron Reduction in Tilled Soils
- ☐ C7 - Thin Muck Surface
- ☐ Other (Explain in Remarks)

Secondary:
- ☐ B6 - Surface Soil Cracks
- ☐ B10 - Drainage Patterns
- ☐ B16 - Moss Trim Lines
- ☐ C2 - Dry-Season Water Table
- ☐ C8 - Crayfish Burrows
- ☐ C9 - Saturation Visible on Aerial Imagery
- ☑ D1 - Stunted or Stressed Plants
- ☐ D2 - Geomorphic Position
- ☐ D3 - Shallow Aquitard
- ☐ D4 - Microtopographic Relief
- ☐ D5 - FAC-Neutral Test

Field Observations:

Surface Water Present?	☐ Yes ☑ No	Depth:	(in.)
Water Table Present?	☐ Yes ☑ No	Depth:	(in.)
Saturation Present?	☐ Yes ☑ No	Depth:	(in.)

Wetland Hydrology Present? ☐ Yes ☑ No

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available: N/A

Remarks: Statewide drought

SOILS

Map Unit Name: Chesuncook-Elliottsville-Telos association, 3 to 15 percent slopes, very stony — Series Drainage Class: Somewhat poorly drained

Taxonomy (Subgroup): Loamy, isotic, frigid, shallow Aquic Haplorthods

Profile Description (Describe to the depth needed to document the indicator or confirm the absence of indicators.) (Type: C=Concentration, D=Depletion, RM=Reduced Matrix, CS=Covered/Coated Sand Grains; Location: PL=Pore Lining, M=Matrix)

Top Depth	Bottom Depth	Horizon	Matrix Color (Moist)		Matrix %	Mottles Color (Moist)		Mottles %	Mottles Type	Mottles Location	Texture (e.g. clay, sand, loam)
0	1	--	2.5YR	3/1	100	--	--	--	--	--	fine sandy loam
1	2	E	7.5YR	7/1	100	--	--	--	--	--	fine sandy loam
2	15	--	7.5YR	4/3	100	--	--	--	--	--	fine sandy loam
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--

NRCS Hydric Soil Field Indicators (check here if indicators are not present): ☑
- ☐ A1- Histosol
- ☐ A2 - Histic Epipedon
- ☐ A3 - Black Histic
- ☐ A4 - Hydrogen Sulfide
- ☐ A5 - Stratified Layers
- ☐ A11 - Depleted Below Dark Surface
- ☐ A12 - Thick Dark Surface
- ☐ S1 - Sandy Muck Mineral
- ☐ S4 - Sandy Gleyed Matrix
- ☐ S5 - Sandy Redox
- ☐ S6 - Stripped Matrix
- ☐ S7 - Dark Surface (LRR R, MLRA 149B)
- ☐ S8 - Polyvalue Below Surface (LRR R, MLRA 149B)
- ☐ S9 - Thin Dark Surface (LRR R, MLRA 149B)
- ☐ F1 - Loamy Mucky Mineral (LRR K, L)
- ☐ F2 - Loamy Gleyed Matrix
- ☐ F3 - Depleted Matrix
- ☐ F6 - Redox Dark Surface
- ☐ F7 - Depleted Dark Surface
- ☐ F8 - Redox Depressions

Indicators for Problematic Soils [1]
- ☐ A10 - 2 cm Muck (LRR K, L, MLRA 149B)
- ☐ A16 - Coast Prairie Redox (LRR K, L, R)
- ☐ S3 - 5cm Mucky Peat of Peat (**LRR K, L, R**)
- ☐ S7 - Dark Surface (LRR K, L, M)
- ☐ S8 - Polyvalue Below Surface (**LRR K, L**)
- ☐ S9 - Thin Dark Surface (**LRR K, L**)
- ☐ F12 - Iron-Manganese Masses (**LRR K, L, R**)
- ☐ F19 - Piedmont Floodplain Soils (**MLRA 149B**)
- ☐ TA6 - Mesic Spodic (**MLRA 144A, 145, 149B**)
- ☐ TF2 - Red Parent Material
- ☐ TF12 - Very Shallow Dark Surface
- ☐ Other (Explain in Remarks)

[1] Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (If Observed) Type: ledge Depth: 11

Hydric Soil Present? ☐ Yes ☑ No

Remarks:

TETRA TECH

WETLAND DETERMINATION DATA FORM

Northeast and Northcentral Region

Project/Site: Western Maine Renewable Energy Project | Wetland ID: W52EI | Sample Point **Upland**

VEGETATION (Species identified in all uppercase are non-native species.)

Tree Stratum (Plot size: 10 meter radius)

	Species Name	% Cover	Dominant	Ind.Status
1.	*Picea rubens*	20	Y	FACU
2.	*Acer rubrum*	20	Y	FAC
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	40		

Sapling/Shrub Stratum (Plot size: 5 meter radius)

1.	*Viburnum lantanoides*	5	Y	FACU
2.	*Picea rubens*	1	N	FACU
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	6		

Herb Stratum (Plot size: 2 meter radius)

1.	*Aralia nudicaulis*	5	Y	FACU
2.	*Acer rubrum*	5	N	FAC
3.	--		--	--
4.	--		--	--
5.	--		--	--
6	--		--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
11.	--	--	--	--
12.	--	--	--	--
13.	--	--	--	--
14.	--	--	--	--
15.	--	--	--	--
	Total Cover =	10		

Woody Vine Stratum (Plot size: 10 meter radius)

1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
	Total Cover =	0		

Remarks:

Dominance Test Worksheet

Number of Dominant Species that are OBL, FACW, or FAC: 1 (A)

Total Number of Dominant Species Across All Strata: 4 (B)

Percent of Dominant Species That Are OBL, FACW, or FAC: ***25.0%*** (A/B)

Prevalence Index Worksheet

Total % Cover of:		Multiply by:	
OBL spp.	0	x 1 =	0
FACW spp.	0	x 2 =	0
FAC spp.	25	x 3 =	75
FACU spp.	31	x 4 =	124
UPL spp.	0	x 5 =	0
Total	56 (A)		199 (B)

Prevalence Index = B/A = ***3.554***

Hydrophytic Vegetation Indicators:

- ☐ Yes ☑ No Rapid Test for Hydrophytic Vegetation
- ☐ Yes ☑ No Dominance Test is > 50%
- ☐ Yes ☑ No Prevalence Index is ≤ 3.0 *
- ☐ Yes ☑ No Morphological Adaptations (Explain) *
- ☐ Yes ☑ No Problem Hydrophytic Vegetation (Explain) *

* Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic.

Definitions of Vegetation Strata:

Tree - Woody plants 3 in. (7.6cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/Shrub - Woody plants less than 3 in. DBH and greater than 3.28 ft. tall.

Herb - All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft. tall.

Woody Vines - All woody vines greater than 3.28 ft. in height.

Hydrophytic Vegetation Present ☐ Yes ☑ No

Additional Remarks:

TETRA TECH

WETLAND DETERMINATION DATA FORM
Northeast and Northcentral Region

Project/Site:	Western Maine Renewable Energy Project	Project #: 194-7130	Date: 09/09/20
Applicant:	Western Maine Renewables, LLC		County: Somerset
Investigator #1:	Emmy Irvin	Investigator #2:	State: ME
Soil Unit:	Chesuncook-Elliottsville-Telos association, 3 to 15%	NWI/WWI Classification: PEM/PSS	Wetland ID: W52EI
Landform:	Terrace	Local Relief: Linear	Sample Point: **Wetland**
Slope (%):	See topo map	Latitude: 45.138704 Longitude: -69.8733048 Datum: NAD 83	

Are climatic/hydrologic conditions on the site typical for this time of year? (If no, explain in remarks) ☐ Yes ☐ No

Are Vegetation ☐, Soil ☐, or Hydrology ☐ significantly disturbed? Are normal circumstances present? ☐ Yes ☑ No

Are Vegetation ☐, Soil ☐, or Hydrology ☐ naturally problematic?

SUMMARY OF FINDINGS

Hydrophytic Vegetation Present? ☑ Yes ☐ No

Wetland Hydrology Present? ☑ Yes ☐ No

Hydric Soils Present? ☑ Yes ☐ No

Is This Sampling Point Within A Wetland? ☑ **Yes** ☐ **No**

Remarks: Statewide drought

HYDROLOGY

Wetland Hydrology Indicators (Check here if indicators are not present): ☐

Primary:

- ☐ A1 - Surface Water
- ☐ A2 - High Water Table
- ☑ A3 - Saturation
- ☐ B1 - Water Marks
- ☐ B2 - Sediment Deposits
- ☐ B3 - Drift Deposits
- ☐ B4 - Algal Mat or Crust
- ☐ B5 - Iron Deposits
- ☐ B7 - Inundation Visible on Aerial Imagery
- ☐ B8 - Sparsely Vegetated Concave Surface
- ☐ B9 - Water-Stained Leaves
- ☐ B13 - Aquatic Fauna
- ☐ B15 - Marl Deposits
- ☐ C1 - Hydrogen Sulfide Odor
- ☐ C3 - Oxidized Rhizospheres on Living Roots
- ☐ C4 - Presence of Reduced Iron
- ☐ C6 - Recent Iron Reduction in Tilled Soils
- ☐ C7 - Thin Muck Surface
- ☐ Other (Explain in Remarks)

Secondary:

- ☐ B6 - Surface Soil Cracks
- ☑ B10 - Drainage Patterns
- ☐ B16 - Moss Trim Lines
- ☐ C2 - Dry-Season Water Table
- ☐ C8 - Crayfish Burrows
- ☐ C9 - Saturation Visible on Aerial Imagery
- ☐ D1 - Stunted or Stressed Plants
- ☐ D2 - Geomorphic Position
- ☐ D3 - Shallow Aquitard
- ☐ D4 - Microtopographic Relief
- ☑ D5 - FAC-Neutral Test

Field Observations:

Surface Water Present? ☐ Yes ☑ No Depth: (in.)

Water Table Present? ☐ Yes ☑ No Depth: (in.)

Saturation Present? ☐ Yes ☑ No Depth: (in.)

Wetland Hydrology Present? ☑ Yes ☐ No

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available: N/A

Remarks: Statewide drought

SOILS

Map Unit Name: Chesuncook-Elliottsville-Telos association, 3 to 15% Series Drainage Class: Somewhat poorly drained

Taxonomy (Subgroup): Loamy, isotic, frigid, shallow Aquic Haplorthods

Profile Description (Describe to the depth needed to document the indicator or confirm the absence of indicators.) (Type: C=Concentration, D=Depletion, RM=Reduced Matrix, CS=Covered/Coated Sand Grains; Location: PL=Pore Lining, M=Matrix)

Top Depth	Bottom Depth	Horizon	Matrix Color (Moist)		Matrix %	Mottles Color (Moist)		Mottles %	Mottles Type	Mottles Location	Texture (e.g. clay, sand, loam)
0	1	--	7.5YR	3/2	100	--	--	--	--	--	fine sandy loam
1	3	--	2.5Y	3/1	100	--	--	--	--	--	fine sandy loam
3	11	--	5Y	4/2	100	10YR	8/6	2	C	PL	sandy loam
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--

NRCS Hydric Soil Field Indicators (check here if indicators are not present): ☐

- ☐ A1- Histosol
- ☐ A2 - Histic Epipedon
- ☐ A3 - Black Histic
- ☐ A4 - Hydrogen Sulfide
- ☐ A5 - Stratified Layers
- ☐ A11 - Depleted Below Dark Surface
- ☐ A12 - Thick Dark Surface
- ☐ S1 - Sandy Muck Mineral
- ☐ S4 - Sandy Gleyed Matrix
- ☐ S5 - Sandy Redox
- ☐ S6 - Stripped Matrix
- ☐ S7 - Dark Surface (LRR R, MLRA 149B)
- ☐ S8 - Polyvalue Below Surface (LRR R, MLRA 149B)
- ☐ S9 - Thin Dark Surface (LRR R, MLRA 149B)
- ☐ F1 - Loamy Mucky Mineral (LRR K, L)
- ☐ F2 - Loamy Gleyed Matrix
- ☑ F3 - Depleted Matrix
- ☐ F6 - Redox Dark Surface
- ☐ F7 - Depleted Dark Surface
- ☐ F8 - Redox Depressions

Indicators for Problematic Soils [1]

- ☐ A10 - 2 cm Muck (LRR K, L, MLRA 149B)
- ☐ A16 - Coast Prairie Redox (LRR K, L, R)
- ☐ S3 - 5cm Mucky Peat of Peat (**LRR K, L, R**)
- ☐ S7 - Dark Surface (LRR K, L, M)
- ☐ S8 - Polyvalue Below Surface (**LRR K, L**)
- ☐ S9 - Thin Dark Surface (**LRR K, L**)
- ☐ F12 - Iron-Manganese Masses (**LRR K, L, R**)
- ☐ F19 - Piedmont Floodplain Soils (**MLRA 149B**)
- ☐ TA6 - Mesic Spodic (**MLRA 144A, 145, 149B**)
- ☐ TF2 - Red Parent Material
- ☐ TF12 - Very Shallow Dark Surface
- ☐ Other (Explain in Remarks)

[1] Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (If Observed) Type: ledge Depth: 11

Hydric Soil Present? ☑ Yes ☐ No

Remarks:

TETRA TECH

WETLAND DETERMINATION DATA FORM

Northeast and Northcentral Region

Project/Site: Western Maine Renewable Energy Project | Wetland ID: W52EI | Sample Point **Wetland**

VEGETATION (Species identified in all uppercase are non-native species.)

Tree Stratum (Plot size: 10 meter radius)

	Species Name	% Cover	Dominant	Ind.Status
1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	0		

Sapling/Shrub Stratum (Plot size: 5 meter radius)

1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	0		

Herb Stratum (Plot size: 2 meter radius)

1.	*Calamagrostis canadensis*	50	Y	OBL
2.	*Symphyotrichum laeve*	20	Y	FACU
3.	*Osmunda claytoniana*	10	N	FAC
4.	*Onoclea sensibilis*	2	N	FACW
5.	*Spiraea alba*	5	N	FACW
6	*Rubus allegheniensis*	5	N	FACU
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
11.	--	--	--	--
12.	--	--	--	--
13.	--	--	--	--
14.	--	--	--	--
15.	--	--	--	--
	Total Cover =	92		

Woody Vine Stratum (Plot size: 10 meter radius)

1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
	Total Cover =	0		

Remarks:

Dominance Test Worksheet

Number of Dominant Species that are OBL, FACW, or FAC: 1 (A)

Total Number of Dominant Species Across All Strata: 2 (B)

Percent of Dominant Species That Are OBL, FACW, or FAC: ***50.0%*** (A/B)

Prevalence Index Worksheet

Total % Cover of:		Multiply by:	
OBL spp.	50	x 1 =	50
FACW spp.	7	x 2 =	14
FAC spp.	10	x 3 =	30
FACU spp.	25	x 4 =	100
UPL spp.	0	x 5 =	0
Total	92 (A)		194 (B)

Prevalence Index = B/A = ***2.109***

Hydrophytic Vegetation Indicators:

- ☐ Yes ☐ No Rapid Test for Hydrophytic Vegetation
- ☐ Yes ☐ No Dominance Test is > 50%
- ☐ Yes ☐ No Prevalence Index is ≤ 3.0 *
- ☐ Yes ☐ No Morphological Adaptations (Explain) *
- ☐ Yes ☐ No Problem Hydrophytic Vegetation (Explain) *

* Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic.

Definitions of Vegetation Strata:

Tree - Woody plants 3 in. (7.6cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/Shrub - Woody plants less than 3 in. DBH and greater than 3.28 ft. tall.

Herb - All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft. tall.

Woody Vines - All woody vines greater than 3.28 ft. in height.

Hydrophytic Vegetation Present ☑ Yes ☐ No

Additional Remarks:

TETRA TECH

WETLAND DETERMINATION DATA FORM
Northeast and Northcentral Region

Project/Site:	Western Maine Renewable Energy Project	Project #:	194-7130
Applicant:	Western Maine Renewables, LLC		
Investigator #1:	Emmy Irvin	Investigator #2:	
Soil Unit:	Telos-Chesuncook association, 3 to 15% slopes	NWI/WWI Classification:	Upland
Landform:	Terrace	Local Relief:	Linear
Slope (%):	See topo map	Latitude: 45.148614	Longitude: -69.853279 Datum: NAD 83

Are climatic/hydrologic conditions on the site typical for this time of year? (If no, explain in remarks) ☐ Yes ☑ No

Are Vegetation ☐, Soil ☐, or Hydrology ☐ significantly disturbed?
Are Vegetation ☐, Soil ☐, or Hydrology ☐ naturally problematic?

Are normal circumstances present? ☐ Yes ☑ No

Date:	09/09/20
County:	Somerset
State:	ME
Wetland ID:	W61EI
Sample Point:	**Upland**

SUMMARY OF FINDINGS

Hydrophytic Vegetation Present?	☐ Yes ☑ No	Hydric Soils Present?	☐ Yes ☑ No
Wetland Hydrology Present?	☐ Yes ☑ No	Is This Sampling Point Within A Wetland?	☐ **Yes** ☑ **No**

Remarks: Statewide drought

HYDROLOGY

Wetland Hydrology Indicators (Check here if indicators are not present ☑)

Primary:
- ☐ A1 - Surface Water
- ☐ A2 - High Water Table
- ☐ A3 - Saturation
- ☐ B1 - Water Marks
- ☐ B2 - Sediment Deposits
- ☐ B3 - Drift Deposits
- ☐ B4 - Algal Mat or Crust
- ☐ B5 - Iron Deposits
- ☐ B7 - Inundation Visible on Aerial Imagery
- ☐ B8 - Sparsely Vegetated Concave Surface
- ☐ B9 - Water-Stained Leaves
- ☐ B13 - Aquatic Fauna
- ☐ B15 - Marl Deposits
- ☐ C1 - Hydrogen Sulfide Odor
- ☐ C3 - Oxidized Rhizospheres on Living Roots
- ☐ C4 - Presence of Reduced Iron
- ☐ C6 - Recent Iron Reduction in Tilled Soils
- ☐ C7 - Thin Muck Surface
- ☐ Other (Explain in Remarks)

Secondary:
- ☐ B6 - Surface Soil Cracks
- ☐ B10 - Drainage Patterns
- ☐ B16 - Moss Trim Lines
- ☐ C2 - Dry-Season Water Table
- ☐ C8 - Crayfish Burrows
- ☐ C9 - Saturation Visible on Aerial Imagery
- ☐ D1 - Stunted or Stressed Plants
- ☐ D2 - Geomorphic Position
- ☐ D3 - Shallow Aquitard
- ☐ D4 - Microtopographic Relief
- ☐ D5 - FAC-Neutral Test

Field Observations:

Surface Water Present?	☐ Yes ☑ No	Depth:	(in.)
Water Table Present?	☐ Yes ☑ No	Depth:	(in.)
Saturation Present?	☐ Yes ☑ No	Depth:	(in.)

Wetland Hydrology Present? ☐ Yes ☑ No

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available: N/A

Remarks: Statewide drought

SOILS

Map Unit Name: Telos-Chesuncook association, 3 to 15% slopes Series Drainage Class: Well Drained

Taxonomy (Subgroup): Loamy, isotic, frigid Lithic Haplohumods

Profile Description (Describe to the depth needed to document the indicator or confirm the absence of indicators.) (Type: C=Concentration, D=Depletion, RM=Reduced Matrix, CS=Covered/Coated Sand Grains; Location: PL=Pore Lining, M=Matrix)

Top Depth	Bottom Depth	Horizon	Matrix Color (Moist)		Matrix %	Mottles Color (Moist)		Mottles %	Mottles Type	Mottles Location	Texture (e.g. clay, sand, loam)
0	14	A	10YR	3/2	100	--	--	--	--	--	fine sandy loam
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--

NRCS Hydric Soil Field Indicators (check here if indicators are not present ☑):
- ☐ A1- Histosol
- ☐ A2 - Histic Epipedon
- ☐ A3 - Black Histic
- ☐ A4 - Hydrogen Sulfide
- ☐ A5 - Stratified Layers
- ☐ A11 - Depleted Below Dark Surface
- ☐ A12 - Thick Dark Surface
- ☐ S1 - Sandy Muck Mineral
- ☐ S4 - Sandy Gleyed Matrix
- ☐ S5 - Sandy Redox
- ☐ S6 - Stripped Matrix
- ☐ S7 - Dark Surface (LRR R, MLRA 149B)
- ☐ S8 - Polyvalue Below Surface (LRR R, MLRA 149B)
- ☐ S9 - Thin Dark Surface (LRR R, MLRA 149B)
- ☐ F1 - Loamy Mucky Mineral (LRR K, L)
- ☐ F2 - Loamy Gleyed Matrix
- ☐ F3 - Depleted Matrix
- ☐ F6 - Redox Dark Surface
- ☐ F7 - Depleted Dark Surface
- ☐ F8 - Redox Depressions

Indicators for Problematic Soils [1]
- ☐ A10 - 2 cm Muck (LRR K, L, MLRA 149B)
- ☐ A16 - Coast Prairie Redox (LRR K, L, R)
- ☐ S3 - 5cm Mucky Peat of Peat (**LRR K, L, R**)
- ☐ S7 - Dark Surface (LRR K, L, M)
- ☐ S8 - Polyvalue Below Surface (**LRR K, L**)
- ☐ S9 - Thin Dark Surface (**LRR K, L**)
- ☐ F12 - Iron-Manganese Masses (**LRR K, L, R**)
- ☐ F19 - Piedmont Floodplain Soils (**MLRA 149B**)
- ☐ TA6 - Mesic Spodic (**MLRA 144A, 145, 149B**)
- ☐ TF2 - Red Parent Material
- ☐ TF12 - Very Shallow Dark Surface
- ☐ Other (Explain in Remarks)

[1] Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (If Observed) Type: LEDGE Depth: 18

Hydric Soil Present? ☐ Yes ☑ No

Remarks:

TETRA TECH

WETLAND DETERMINATION DATA FORM

Northeast and Northcentral Region

Project/Site: Western Maine Renewable Energy Project | Wetland ID: W61EI | Sample Point **Upland**

VEGETATION (Species identified in all uppercase are non-native species.)

Tree Stratum (Plot size: 10 meter radius)

	Species Name	% Cover	Dominant	Ind.Status
1.	*Acer rubrum*	10	Y	FAC
2.	*Fagus grandifolia*	5	Y	FACU
3.	*Betula papyrifera*	1	N	FACU
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	16		

Sapling/Shrub Stratum (Plot size: 5 meter radius)

1.	*Viburnum lantanoides*	5	--	FACU
2.	*Acer rubrum*	1	--	FAC
3.	*Acer pensylvanicum*	1	--	FACU
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	7		

Herb Stratum (Plot size: 2 meter radius)

1.	*Acer rubrum*	5	N	FAC
2.	*Maianthemum canadense*	5	N	FACU
3.	*Uvularia sessilifolia*	10	Y	FACU
4.	--	--	--	--
5.	--	--	--	--
6	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
11.	--	--	--	--
12.	--	--	--	--
13.	--	--	--	--
14.	--	--	--	--
15.	--	--	--	--
	Total Cover =	20		

Woody Vine Stratum (Plot size: 10 meter radius)

1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
	Total Cover =	0		

Remarks:

Dominance Test Worksheet

Number of Dominant Species that are OBL, FACW, or FAC: 1 (A)

Total Number of Dominant Species Across All Strata: 3 (B)

Percent of Dominant Species That Are OBL, FACW, or FAC: ***33.3%*** (A/B)

Prevalence Index Worksheet

Total % Cover of:		Multiply by:	
OBL spp.	0	x 1 =	0
FACW spp.	0	x 2 =	0
FAC spp.	16	x 3 =	48
FACU spp.	27	x 4 =	108
UPL spp.	0	x 5 =	0
Total	43 (A)		156 (B)

Prevalence Index = B/A = ***3.628***

Hydrophytic Vegetation Indicators:

- ☐ Yes ☑ No Rapid Test for Hydrophytic Vegetation
- ☐ Yes ☑ No Dominance Test is > 50%
- ☐ Yes ☑ No Prevalence Index is ≤ 3.0 *
- ☐ Yes ☑ No Morphological Adaptations (Explain) *
- ☐ Yes ☑ No Problem Hydrophytic Vegetation (Explain) *

* Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic.

Definitions of Vegetation Strata:

Tree - Woody plants 3 in. (7.6cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/Shrub - Woody plants less than 3 in. DBH and greater than 3.28 ft. tall.

Herb - All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft. tall.

Woody Vines - All woody vines greater than 3.28 ft. in height.

Hydrophytic Vegetation Present ☐ Yes ☑ No

Additional Remarks:

TETRA TECH

WETLAND DETERMINATION DATA FORM
Northeast and Northcentral Region

Project/Site:	Western Maine Renewable Energy Project	Project #:	194-7130
Applicant:	Western Maine Renewables, LLC		
Investigator #1:	Emmy Irvin	Investigator #2:	
Soil Unit:	Telos-Chesuncook association, 3 to 15% slopes	NWI/WWI Classification:	PEM
Landform:	Terrace	Local Relief:	Linear
Slope (%):	See topo map	Latitude: 45.148321°	Longitude: -69.853153° Datum: NAD 83

Are climatic/hydrologic conditions on the site typical for this time of year? (If no, explain in remarks) ☐ Yes ☑ No

Are Vegetation ☐, Soil ☐, or Hydrology ☐ significantly disturbed?
Are Vegetation ☐, Soil ☐, or Hydrology ☐ naturally problematic?

Are normal circumstances present? ☐ Yes ☑ No

Date:	09/09/20
County:	Somerset
State:	ME
Wetland ID:	W61EI
Sample Point:	**Wetland**

SUMMARY OF FINDINGS

Hydrophytic Vegetation Present?	☑ Yes ☐ No	Hydric Soils Present?	☑ Yes ☐ No
Wetland Hydrology Present?	☑ Yes ☐ No	Is This Sampling Point Within A Wetland?	☑ **Yes** ☐ **No**

Remarks: Statewide drought

HYDROLOGY

Wetland Hydrology Indicators (Check here if indicators are not present ☐)

Primary:
- ☐ A1 - Surface Water
- ☐ A2 - High Water Table
- ☑ A3 - Saturation
- ☑ B1 - Water Marks
- ☐ B2 - Sediment Deposits
- ☐ B3 - Drift Deposits
- ☐ B4 - Algal Mat or Crust
- ☐ B5 - Iron Deposits
- ☐ B7 - Inundation Visible on Aerial Imagery
- ☐ B8 - Sparsely Vegetated Concave Surface
- ☐ B9 - Water-Stained Leaves
- ☐ B13 - Aquatic Fauna
- ☐ B15 - Marl Deposits
- ☐ C1 - Hydrogen Sulfide Odor
- ☐ C3 - Oxidized Rhizospheres on Living Roots
- ☐ C4 - Presence of Reduced Iron
- ☐ C6 - Recent Iron Reduction in Tilled Soils
- ☐ C7 - Thin Muck Surface
- ☐ Other (Explain in Remarks)

Secondary:
- ☐ B6 - Surface Soil Cracks
- ☐ B10 - Drainage Patterns
- ☐ B16 - Moss Trim Lines
- ☐ C2 - Dry-Season Water Table
- ☐ C8 - Crayfish Burrows
- ☐ C9 - Saturation Visible on Aerial Imagery
- ☐ D1 - Stunted or Stressed Plants
- ☐ D2 - Geomorphic Position
- ☐ D3 - Shallow Aquitard
- ☐ D4 - Microtopographic Relief
- ☐ D5 - FAC-Neutral Test

Field Observations:

Surface Water Present?	☐ Yes ☐ No	Depth:		(in.)
Water Table Present?	☐ Yes ☐ No	Depth:		(in.)
Saturation Present?	☑ Yes ☐ No	Depth:	8	(in.)

Wetland Hydrology Present? ☑ Yes ☐ No

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available: N/A

Remarks: Statewide drought

SOILS

Map Unit Name: Telos-Chesuncook association, 3 to 15% slopes Series Drainage Class: somewhat poorly drained

Taxonomy (Subgroup): Loamy, isotic, frigid, shallow Aquic Haplorthods

Profile Description (Describe to the depth needed to document the indicator or confirm the absence of indicators.) (Type: C=Concentration, D=Depletion, RM=Reduced Matrix, CS=Covered/Coated Sand Grains; Location: PL=Pore Lining, M=Matrix)

Top Depth	Bottom Depth	Horizon	Matrix Color (Moist)		Matrix %	Mottles Color (Moist)		Mottles %	Mottles Type	Mottles Location	Texture (e.g. clay, sand, loam)
0	15	--	10YR	3/1	100	--	--	--	--	--	fine sandy loam
15	18	--	10YR	4/1	100	--	--	--	--	--	fine sandy loam
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--

NRCS Hydric Soil Field Indicators (check here if indicators are not present ☐):
- ☐ A1- Histosol
- ☐ A2 - Histic Epipedon
- ☐ A3 - Black Histic
- ☐ A4 - Hydrogen Sulfide
- ☐ A5 - Stratified Layers
- ☐ A11 - Depleted Below Dark Surface
- ☑ A12 - Thick Dark Surface
- ☐ S1 - Sandy Muck Mineral
- ☐ S4 - Sandy Gleyed Matrix
- ☐ S5 - Sandy Redox
- ☐ S6 - Stripped Matrix
- ☐ S7 - Dark Surface (LRR R, MLRA 149B)
- ☐ S8 - Polyvalue Below Surface (LRR R, MLRA 149B)
- ☐ S9 - Thin Dark Surface (LRR R, MLRA 149B)
- ☐ F1 - Loamy Mucky Mineral (LRR K, L)
- ☐ F2 - Loamy Gleyed Matrix
- ☐ F3 - Depleted Matrix
- ☐ F6 - Redox Dark Surface
- ☐ F7 - Depleted Dark Surface
- ☐ F8 - Redox Depressions

Indicators for Problematic Soils [1]
- ☐ A10 - 2 cm Muck (LRR K, L, MLRA 149B)
- ☐ A16 - Coast Prairie Redox (LRR K, L, R)
- ☐ S3 - 5cm Mucky Peat of Peat (**LRR K, L, R**)
- ☐ S7 - Dark Surface (LRR K, L, M)
- ☐ S8 - Polyvalue Below Surface (**LRR K, L**)
- ☐ S9 - Thin Dark Surface (**LRR K, L**)
- ☐ F12 - Iron-Manganese Masses (**LRR K, L, R**)
- ☐ F19 - Piedmont Floodplain Soils (**MLRA 149B**)
- ☐ TA6 - Mesic Spodic (**MLRA 144A, 145, 149B**)
- ☐ TF2 - Red Parent Material
- ☐ TF12 - Very Shallow Dark Surface
- ☐ Other (Explain in Remarks)

[1] Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (If Observed) Type: ledge Depth: 18

Hydric Soil Present? ☑ Yes ☐ No

Remarks:

TETRA TECH

WETLAND DETERMINATION DATA FORM
Northeast and Northcentral Region

Project/Site: Western Maine Renewable Energy Project Wetland ID: W61EI Sample Point **Wetland**

VEGETATION (Species identified in all uppercase are non-native species.)

Tree Stratum (Plot size: 10 meter radius)

	Species Name	% Cover	Dominant	Ind.Status
1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	0		

Sapling/Shrub Stratum (Plot size: 5 meter radius)

1.	*Alnus incana*	5	N	FACW
2.	*Acer rubrum*	5	N	FAC
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	10		

Herb Stratum (Plot size: 2 meter radius)

1.	*Onoclea sensibilis*	5	N	FACW
2.	*Osmunda claytoniana*	10	N	FAC
3.	*Calamagrostis canadensis*	30	Y	OBL
4.	*Carex stricta*	25	Y	OBL
5.	*Spiraea alba*	10	N	FACW
6	*Typha angustifolia*	10	N	OBL
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
11.	--	--	--	--
12.	--	--	--	--
13.	--	--	--	--
14.	--	--	--	--
15.	--	--	--	--
	Total Cover =	90		

Woody Vine Stratum (Plot size: 10 meter radius)

1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
	Total Cover =	0		

Remarks:

Dominance Test Worksheet

Number of Dominant Species that are OBL, FACW, or FAC: 2 (A)

Total Number of Dominant Species Across All Strata: 2 (B)

Percent of Dominant Species That Are OBL, FACW, or FAC: ***100.0%*** (A/B)

Prevalence Index Worksheet

Total % Cover of:		Multiply by:	
OBL spp.	65	x 1 =	65
FACW spp.	20	x 2 =	40
FAC spp.	15	x 3 =	45
FACU spp.	0	x 4 =	0
UPL spp.	0	x 5 =	0
Total	100 (A)		150 (B)

Prevalence Index = B/A = ***1.500***

Hydrophytic Vegetation Indicators:

- ☐ Yes ☑ No Rapid Test for Hydrophytic Vegetation
- ☑ Yes ☐ No Dominance Test is > 50%
- ☑ Yes ☐ No Prevalence Index is ≤ 3.0 *
- ☐ Yes ☑ No Morphological Adaptations (Explain) *
- ☐ Yes ☑ No Problem Hydrophytic Vegetation (Explain) *

* Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic.

Definitions of Vegetation Strata:

Tree - Woody plants 3 in. (7.6cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/Shrub - Woody plants less than 3 in. DBH and greater than 3.28 ft. tall.

Herb - All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft. tall.

Woody Vines - All woody vines greater than 3.28 ft. in height.

Hydrophytic Vegetation Present ☑ Yes ☐ No

Additional Remarks:

TETRA TECH

WETLAND DETERMINATION DATA FORM
Northeast and Northcentral Region

Project/Site:	Western Maine Renewable Energy Project		Project #: 194-7130	Date:	09/09/20
Applicant:	Western Maine Renewables, LLC			County:	Somerset
Investigator #1:	Emmy Irvin	Investigator #2:		State:	ME
Soil Unit:	Telos-Chesuncook association, 3 to 15% slopes		NWI/WWI Classification: Upland	Wetland ID:	W63EI
Landform:	Terrace	Local Relief: Linear		Sample Point:	**Upland**
Slope (%):	See topo map	Latitude: 45.147121	Longitude: -69.85223412	Datum: NAD 83	

Are climatic/hydrologic conditions on the site typical for this time of year? (If no, explain in remarks) ☐ Yes ☑ No

Are Vegetation ☐, Soil ☐, or Hydrology ☐ significantly disturbed?
Are Vegetation ☐, Soil ☐, or Hydrology ☐ naturally problematic?

Are normal circumstances present? ☐ Yes ☑ No

SUMMARY OF FINDINGS

Hydrophytic Vegetation Present?	☐ Yes ☑ No	Hydric Soils Present?	☐ Yes ☑ No
Wetland Hydrology Present?	☐ Yes ☑ No	Is This Sampling Point Within A Wetland?	☐ **Yes** ☑ **No**

Remarks: Statewide drought

HYDROLOGY

Wetland Hydrology Indicators (Check here if indicators are not present ☑)

Primary:
- ☐ A1 - Surface Water
- ☐ A2 - High Water Table
- ☐ A3 - Saturation
- ☐ B1 - Water Marks
- ☐ B2 - Sediment Deposits
- ☐ B3 - Drift Deposits
- ☐ B4 - Algal Mat or Crust
- ☐ B5 - Iron Deposits
- ☐ B7 - Inundation Visible on Aerial Imagery
- ☐ B8 - Sparsely Vegetated Concave Surface
- ☐ B9 - Water-Stained Leaves
- ☐ B13 - Aquatic Fauna
- ☐ B15 - Marl Deposits
- ☐ C1 - Hydrogen Sulfide Odor
- ☐ C3 - Oxidized Rhizospheres on Living Roots
- ☐ C4 - Presence of Reduced Iron
- ☐ C6 - Recent Iron Reduction in Tilled Soils
- ☐ C7 - Thin Muck Surface
- ☐ Other (Explain in Remarks)

Secondary:
- ☐ B6 - Surface Soil Cracks
- ☐ B10 - Drainage Patterns
- ☐ B16 - Moss Trim Lines
- ☐ C2 - Dry-Season Water Table
- ☐ C8 - Crayfish Burrows
- ☐ C9 - Saturation Visible on Aerial Imagery
- ☐ D1 - Stunted or Stressed Plants
- ☐ D2 - Geomorphic Position
- ☐ D3 - Shallow Aquitard
- ☐ D4 - Microtopographic Relief
- ☐ D5 - FAC-Neutral Test

Field Observations:

Surface Water Present?	☐ Yes ☑ No	Depth:	(in.)
Water Table Present?	☐ Yes ☑ No	Depth:	(in.)
Saturation Present?	☐ Yes ☑ No	Depth:	(in.)

Wetland Hydrology Present? ☐ Yes ☑ No

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available: N/A

Remarks: Statewide drought

SOILS

Map Unit Name: Telos-Chesuncook association, 3 to 15% slopes — Series Drainage Class: Well Drained

Taxonomy (Subgroup): Loamy, isotic, frigid Lithic Haplohumods

Profile Description (Describe to the depth needed to document the indicator or confirm the absence of indicators.) (Type: C=Concentration, D=Depletion, RM=Reduced Matrix, CS=Covered/Coated Sand Grains; Location: PL=Pore Lining, M=Matrix)

Top Depth	Bottom Depth	Horizon	Matrix Color (Moist)		Matrix %	Mottles Color (Moist)		Mottles %	Mottles Type	Mottles Location	Texture (e.g. clay, sand, loam)
0	15	a	10YR	3/3	100	--	--	--	--	--	fine sandy loam
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--

NRCS Hydric Soil Field Indicators (check here if indicators are not present ☑):
- ☐ A1- Histosol
- ☐ A2 - Histic Epipedon
- ☐ A3 - Black Histic
- ☐ A4 - Hydrogen Sulfide
- ☐ A5 - Stratified Layers
- ☐ A11 - Depleted Below Dark Surface
- ☐ A12 - Thick Dark Surface
- ☐ S1 - Sandy Muck Mineral
- ☐ S4 - Sandy Gleyed Matrix
- ☐ S5 - Sandy Redox
- ☐ S6 - Stripped Matrix
- ☐ S7 - Dark Surface (LRR R, MLRA 149B)
- ☐ S8 - Polyvalue Below Surface (LRR R, MLRA 149B)
- ☐ S9 - Thin Dark Surface (LRR R, MLRA 149B)
- ☐ F1 - Loamy Mucky Mineral (LRR K, L)
- ☐ F2 - Loamy Gleyed Matrix
- ☐ F3 - Depleted Matrix
- ☐ F6 - Redox Dark Surface
- ☐ F7 - Depleted Dark Surface
- ☐ F8 - Redox Depressions

Indicators for Problematic Soils [1]
- ☐ A10 - 2 cm Muck (LRR K, L, MLRA 149B)
- ☐ A16 - Coast Prairie Redox (LRR K, L, R)
- ☐ S3 - 5cm Mucky Peat of Peat (**LRR K, L, R**)
- ☐ S7 - Dark Surface (LRR K, L, M)
- ☐ S8 - Polyvalue Below Surface (**LRR K, L**)
- ☐ S9 - Thin Dark Surface (**LRR K, L**)
- ☐ F12 - Iron-Manganese Masses (**LRR K, L, R**)
- ☐ F19 - Piedmont Floodplain Soils (**MLRA 149B**)
- ☐ TA6 - Mesic Spodic (**MLRA 144A, 145, 149B**)
- ☐ TF2 - Red Parent Material
- ☐ TF12 - Very Shallow Dark Surface
- ☐ Other (Explain in Remarks)

[1] Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (If Observed) Type: LEDGE Depth: 15

Hydric Soil Present? ☐ Yes ☑ No

Remarks:

TETRA TECH

WETLAND DETERMINATION DATA FORM

Northeast and Northcentral Region

Project/Site: Western Maine Renewable Energy Project | Wetland ID: W63EI | Sample Point **Upland**

VEGETATION (Species identified in all uppercase are non-native species.)

Tree Stratum (Plot size: 10 meter radius)

	Species Name	% Cover	Dominant	Ind.Status
1.	*Acer rubrum*	5	N	FAC
2.	*Betula alleghaniensis*	5	N	FAC
3.	*Betula papyrifera*	5	N	FACU
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	15		

Sapling/Shrub Stratum (Plot size: 5 meter radius)

1.	*Alnus incana*	1	N	FACW
2.	*Acer rubrum*	1	N	FAC
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	2		

Herb Stratum (Plot size: 2 meter radius)

1.	*Viola palmata*	5	N	FACU
2.	*Maianthemum canadense*	10	Y	FACU
3.	*Uvularia sessilifolia*	10	Y	FACU
4.	*Symphyotrichum laeve*	5	N	FACU
5.	--	--	--	--
6	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
11.	--	--	--	--
12.	--	--	--	--
13.	--	--	--	--
14.	--	--	--	--
15.	--	--	--	--
	Total Cover =	30		

Woody Vine Stratum (Plot size: 10 meter radius)

1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
	Total Cover =	0		

Remarks:

Dominance Test Worksheet

Number of Dominant Species that are OBL, FACW, or FAC: 0 (A)

Total Number of Dominant Species Across All Strata: 2 (B)

Percent of Dominant Species That Are OBL, FACW, or FAC: ***0.0%*** (A/B)

Prevalence Index Worksheet

Total % Cover of:		Multiply by:	
OBL spp.	0	x 1 =	0
FACW spp.	1	x 2 =	2
FAC spp.	11	x 3 =	33
FACU spp.	35	x 4 =	140
UPL spp.	0	x 5 =	0
Total	47 (A)		175 (B)

Prevalence Index = B/A = ***3.723***

Hydrophytic Vegetation Indicators:

- ☐ Yes ☑ No Rapid Test for Hydrophytic Vegetation
- ☐ Yes ☑ No Dominance Test is > 50%
- ☐ Yes ☑ No Prevalence Index is ≤ 3.0 *
- ☐ Yes ☑ No Morphological Adaptations (Explain) *
- ☐ Yes ☑ No Problem Hydrophytic Vegetation (Explain) *

* Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic.

Definitions of Vegetation Strata:

Tree - Woody plants 3 in. (7.6cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/Shrub - Woody plants less than 3 in. DBH and greater than 3.28 ft. tall.

Herb - All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft. tall.

Woody Vines - All woody vines greater than 3.28 ft. in height.

Hydrophytic Vegetation Present ☐ Yes ☑ No

Additional Remarks:

TETRA TECH

WETLAND DETERMINATION DATA FORM
Northeast and Northcentral Region

Project/Site:	Western Maine Renewable Energy Project	Project #: 194-7130	Date: 09/09/20
Applicant:	Western Maine Renewables, LLC		County: Somerset
Investigator #1:	Emmy Irvin	Investigator #2:	State: ME
Soil Unit:	Telos-Chesuncook association, 3 to 15 percent	NWI/WWI Classification: PEM	Wetland ID: W63EI
Landform:	Terrace	Local Relief: Linear	Sample Point: **Wetland**
Slope (%):	See topo map	Latitude: 45.147085 Longitude: -69.8522341 Datum: NAD 83	

Are climatic/hydrologic conditions on the site typical for this time of year? (If no, explain in remarks) ☐ Yes ☑ No

Are Vegetation ☐, Soil ☐, or Hydrology ☐ significantly disturbed?
Are Vegetation ☐, Soil ☐, or Hydrology ☐ naturally problematic?

Are normal circumstances present? ☐ Yes ☑ No

SUMMARY OF FINDINGS

Hydrophytic Vegetation Present?	☑ Yes ☐ No	Hydric Soils Present?	☑ Yes ☐ No
Wetland Hydrology Present?	☑ Yes ☐ No	Is This Sampling Point Within A Wetland?	☑ **Yes** ☐ **No**

Remarks: Statewide drought

HYDROLOGY

Wetland Hydrology Indicators (Check here if indicators are not present ☐)

Primary:
- ☑ A1 - Surface Water
- ☐ A2 - High Water Table
- ☐ A3 - Saturation
- ☐ B1 - Water Marks
- ☐ B2 - Sediment Deposits
- ☐ B3 - Drift Deposits
- ☐ B4 - Algal Mat or Crust
- ☐ B5 - Iron Deposits
- ☐ B7 - Inundation Visible on Aerial Imagery
- ☐ B8 - Sparsely Vegetated Concave Surface
- ☐ B9 - Water-Stained Leaves
- ☐ B13 - Aquatic Fauna
- ☐ B15 - Marl Deposits
- ☐ C1 - Hydrogen Sulfide Odor
- ☐ C3 - Oxidized Rhizospheres on Living Roots
- ☐ C4 - Presence of Reduced Iron
- ☐ C6 - Recent Iron Reduction in Tilled Soils
- ☐ C7 - Thin Muck Surface
- ☐ Other (Explain in Remarks)

Secondary:
- ☐ B6 - Surface Soil Cracks
- ☑ B10 - Drainage Patterns
- ☐ B16 - Moss Trim Lines
- ☐ C2 - Dry-Season Water Table
- ☐ C8 - Crayfish Burrows
- ☐ C9 - Saturation Visible on Aerial Imagery
- ☐ D1 - Stunted or Stressed Plants
- ☐ D2 - Geomorphic Position
- ☐ D3 - Shallow Aquitard
- ☐ D4 - Microtopographic Relief
- ☐ D5 - FAC-Neutral Test

Field Observations:

Surface Water Present?	☑ Yes ☐ No	Depth:	(in.)
Water Table Present?	☐ Yes ☑ No	Depth:	(in.)
Saturation Present?	☐ Yes ☑ No	Depth:	(in.)

Wetland Hydrology Present? ☑ Yes ☐ No

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available: N/A

Remarks: Statewide drought.

SOILS

Map Unit Name: Telos-Chesuncook association, 3 to 15 percent Series Drainage Class: somewhat poorly drained

Taxonomy (Subgroup): Loamy, isotic, frigid, shallow Aquic Haplorthods

Profile Description (Describe to the depth needed to document the indicator or confirm the absence of indicators.) (Type: C=Concentration, D=Depletion, RM=Reduced Matrix, CS=Covered/Coated Sand Grains; Location: PL=Pore Lining, M=Matrix)

Top Depth	Bottom Depth	Horizon	Matrix Color (Moist)		Matrix %	Mottles Color (Moist)		Mottles %	Mottles Type	Mottles Location	Texture (e.g. clay, sand, loam)
0	10	--	10YR	3/1	60	10YR	6/8	5	C	PL	silt loam
--	--	--	--	--	--	5Y	5/1	35	D	M	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--

NRCS Hydric Soil Field Indicators (check here if indicators are not present ☐):
- ☐ A1- Histosol
- ☐ A2 - Histic Epipedon
- ☐ A3 - Black Histic
- ☐ A4 - Hydrogen Sulfide
- ☐ A5 - Stratified Layers
- ☐ A11 - Depleted Below Dark Surface
- ☐ A12 - Thick Dark Surface
- ☐ S1 - Sandy Muck Mineral
- ☐ S4 - Sandy Gleyed Matrix
- ☐ S5 - Sandy Redox
- ☐ S6 - Stripped Matrix
- ☐ S7 - Dark Surface (LRR R, MLRA 149B)
- ☐ S8 - Polyvalue Below Surface (LRR R, MLRA 149B)
- ☐ S9 - Thin Dark Surface (LRR R, MLRA 149B)
- ☐ F1 - Loamy Mucky Mineral (LRR K, L)
- ☐ F2 - Loamy Gleyed Matrix
- ☐ F3 - Depleted Matrix
- ☑ F6 - Redox Dark Surface
- ☐ F7 - Depleted Dark Surface
- ☐ F8 - Redox Depressions

Indicators for Problematic Soils [1]
- ☐ A10 - 2 cm Muck (LRR K, L, MLRA 149B)
- ☐ A16 - Coast Prairie Redox (LRR K, L, R)
- ☐ S3 - 5cm Mucky Peat of Peat (**LRR K, L, R**)
- ☐ S7 - Dark Surface (LRR K, L, M)
- ☐ S8 - Polyvalue Below Surface (**LRR K, L**)
- ☐ S9 - Thin Dark Surface (**LRR K, L**)
- ☐ F12 - Iron-Manganese Masses (**LRR K, L, R**)
- ☐ F19 - Piedmont Floodplain Soils (**MLRA 149B**)
- ☐ TA6 - Mesic Spodic (**MLRA 144A, 145, 149B**)
- ☐ TF2 - Red Parent Material
- ☐ TF12 - Very Shallow Dark Surface
- ☐ Other (Explain in Remarks)

[1] Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (If Observed) Type: LEDGE Depth: 10

Hydric Soil Present? ☑ Yes ☐ No

Remarks:

TETRA TECH

WETLAND DETERMINATION DATA FORM

Northeast and Northcentral Region

Project/Site: Western Maine Renewable Energy Project | Wetland ID: W63EI | Sample Point **Wetland**

VEGETATION (Species identified in all uppercase are non-native species.)

Tree Stratum (Plot size: 10 meter radius)

	Species Name	% Cover	Dominant	Ind.Status
1.	*Fraxinus nigra*	10	Y	FACW
2.	*Acer rubrum*	5	Y	FAC
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	15		

Sapling/Shrub Stratum (Plot size: 5 meter radius)

1.	*Alnus incana*	5	Y	FACW
2.	*Acer rubrum*	5	Y	FAC
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	10		

Herb Stratum (Plot size: 2 meter radius)

1.	*Calamagrostis canadensis*	30	Y	OBL
2.	*Phalaris arundinacea*	80	Y	FACW
3.	*Scirpus cyperinus*	5	N	OBL
4.	*Spiraea alba*	10	N	FACW
5.	*Onoclea sensibilis*	2	N	FACW
6	*Symphyotrichum novae-angliae*	5	N	FACW
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
11.	--	--	--	--
12.	--	--	--	--
13.	--	--	--	--
14.	--	--	--	--
15.	--	--	--	--
	Total Cover =	132		

Woody Vine Stratum (Plot size: 10 meter radius)

1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
	Total Cover =	0		

Remarks:

Dominance Test Worksheet

Number of Dominant Species that are OBL, FACW, or FAC: 6 (A)

Total Number of Dominant Species Across All Strata: 6 (B)

Percent of Dominant Species That Are OBL, FACW, or FAC: ***100.0%*** (A/B)

Prevalence Index Worksheet

Total % Cover of:		Multiply by:	
OBL spp.	35	x 1 =	35
FACW spp.	112	x 2 =	224
FAC spp.	10	x 3 =	30
FACU spp.	0	x 4 =	0
UPL spp.	0	x 5 =	0
Total	157 (A)		289 (B)

Prevalence Index = B/A = ***1.841***

Hydrophytic Vegetation Indicators:

- ☐ Yes ☑ No Rapid Test for Hydrophytic Vegetation
- ☑ Yes ☐ No Dominance Test is > 50%
- ☑ Yes ☐ No Prevalence Index is ≤ 3.0 *
- ☐ Yes ☑ No Morphological Adaptations (Explain) *
- ☐ Yes ☑ No Problem Hydrophytic Vegetation (Explain) *

* Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic.

Definitions of Vegetation Strata:

Tree - Woody plants 3 in. (7.6cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/Shrub - Woody plants less than 3 in. DBH and greater than 3.28 ft. tall.

Herb - All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft. tall.

Woody Vines - All woody vines greater than 3.28 ft. in height.

Hydrophytic Vegetation Present ☑ Yes ☐ No

Additional Remarks:

TETRA TECH

WETLAND DETERMINATION DATA FORM
Northeast and Northcentral Region

Project/Site:	Western Maine Renewable Energy Project		Project #: 194-7130	Date:	09/09/20
Applicant:	Western Maine Renewables, LLC			County:	Somerset
Investigator #1:	Emmy Irvin	Investigator #2:		State:	ME
Soil Unit:	Telos-Chesuncook association, 3 to 15% slopes		NWI/WWI Classification: Upland	Wetland ID:	W67EI
Landform:	Terrace		Local Relief: Linear	Sample Point:	**Upland**
Slope (%):	See topo map	Latitude: 45.145100	Longitude: -69.853	Datum: NAD 83	

Are climatic/hydrologic conditions on the site typical for this time of year? (If no, explain in remarks) ☐ Yes ☑ No

Are Vegetation ☐, Soil ☐, or Hydrology ☐ significantly disturbed?
Are Vegetation ☐, Soil ☐, or Hydrology ☐ naturally problematic?

Are normal circumstances present? ☐ Yes ☑ No

SUMMARY OF FINDINGS

Hydrophytic Vegetation Present?	☐ Yes ☑ No	Hydric Soils Present?	☐ Yes ☑ No
Wetland Hydrology Present?	☐ Yes ☑ No	Is This Sampling Point Within A Wetland?	☐ **Yes** ☑ **No**

Remarks: Statewide drought

HYDROLOGY

Wetland Hydrology Indicators (Check here if indicators are not present): ☑

Primary:
- ☐ A1 - Surface Water
- ☐ A2 - High Water Table
- ☐ A3 - Saturation
- ☐ B1 - Water Marks
- ☐ B2 - Sediment Deposits
- ☐ B3 - Drift Deposits
- ☐ B4 - Algal Mat or Crust
- ☐ B5 - Iron Deposits
- ☐ B7 - Inundation Visible on Aerial Imagery
- ☐ B8 - Sparsely Vegetated Concave Surface
- ☐ B9 - Water-Stained Leaves
- ☐ B13 - Aquatic Fauna
- ☐ B15 - Marl Deposits
- ☐ C1 - Hydrogen Sulfide Odor
- ☐ C3 - Oxidized Rhizospheres on Living Roots
- ☐ C4 - Presence of Reduced Iron
- ☐ C6 - Recent Iron Reduction in Tilled Soils
- ☐ C7 - Thin Muck Surface
- ☐ Other (Explain in Remarks)

Secondary:
- ☐ B6 - Surface Soil Cracks
- ☐ B10 - Drainage Patterns
- ☐ B16 - Moss Trim Lines
- ☐ C2 - Dry-Season Water Table
- ☐ C8 - Crayfish Burrows
- ☐ C9 - Saturation Visible on Aerial Imagery
- ☐ D1 - Stunted or Stressed Plants
- ☐ D2 - Geomorphic Position
- ☐ D3 - Shallow Aquitard
- ☐ D4 - Microtopographic Relief
- ☐ D5 - FAC-Neutral Test

Field Observations:

Surface Water Present?	☐ Yes ☑ No	Depth:	(in.)
Water Table Present?	☐ Yes ☑ No	Depth:	(in.)
Saturation Present?	☐ Yes ☑ No	Depth:	(in.)

Wetland Hydrology Present? ☐ Yes ☑ No

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available: N/A

Remarks: Statewide drought

SOILS

Map Unit Name: Telos-Chesuncook association, 3 to 15% slopes — Series Drainage Class: Well Drained

Taxonomy (Subgroup): Loamy, isotic, frigid Lithic Haplohumods

Profile Description (Describe to the depth needed to document the indicator or confirm the absence of indicators.) (Type: C=Concentration, D=Depletion, RM=Reduced Matrix, CS=Covered/Coated Sand Grains; Location: PL=Pore Lining, M=Matrix)

Top Depth	Bottom Depth	Horizon	Matrix Color (Moist)		Matrix %	Mottles Color (Moist)		Mottles %	Mottles Type	Mottles Location	Texture (e.g. clay, sand, loam)
0	6	1	10YR	5/3	100	--	--	--	--	--	fine sandy loam
6	12	2	10YR	5/2	100	--	--	--	--	--	fine sandy loam
12	18	3	2.5Y	5/2	100	--	--	--	--	--	fine sandy loam
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--

NRCS Hydric Soil Field Indicators (check here if indicators are not present): ☑

- ☐ A1- Histosol
- ☐ A2 - Histic Epipedon
- ☐ A3 - Black Histic
- ☐ A4 - Hydrogen Sulfide
- ☐ A5 - Stratified Layers
- ☐ A11 - Depleted Below Dark Surface
- ☐ A12 - Thick Dark Surface
- ☐ S1 - Sandy Muck Mineral
- ☐ S4 - Sandy Gleyed Matrix
- ☐ S5 - Sandy Redox
- ☐ S6 - Stripped Matrix
- ☐ S7 - Dark Surface (LRR R, MLRA 149B)
- ☐ S8 - Polyvalue Below Surface (LRR R, MLRA 149B)
- ☐ S9 - Thin Dark Surface (LRR R, MLRA 149B)
- ☐ F1 - Loamy Mucky Mineral (LRR K, L)
- ☐ F2 - Loamy Gleyed Matrix
- ☐ F3 - Depleted Matrix
- ☐ F6 - Redox Dark Surface
- ☐ F7 - Depleted Dark Surface
- ☐ F8 - Redox Depressions

Indicators for Problematic Soils [1]
- ☐ A10 - 2 cm Muck (LRR K, L, MLRA 149B)
- ☐ A16 - Coast Prairie Redox (LRR K, L, R)
- ☐ S3 - 5cm Mucky Peat of Peat (**LRR K, L, R**)
- ☐ S7 - Dark Surface (LRR K, L, M)
- ☐ S8 - Polyvalue Below Surface (**LRR K, L**)
- ☐ S9 - Thin Dark Surface (**LRR K, L**)
- ☐ F12 - Iron-Manganese Masses (**LRR K, L, R**)
- ☐ F19 - Piedmont Floodplain Soils (**MLRA 149B**)
- ☐ TA6 - Mesic Spodic (**MLRA 144A, 145, 149B**)
- ☐ TF2 - Red Parent Material
- ☐ TF12 - Very Shallow Dark Surface
- ☐ Other (Explain in Remarks)

[1] Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (If Observed) Type: LEDGE Depth: 18

Hydric Soil Present? ☐ Yes ☑ No

Remarks:

TETRA TECH

WETLAND DETERMINATION DATA FORM

Northeast and Northcentral Region

Project/Site: Western Maine Renewable Energy Project | Wetland ID: W67EI | Sample Point **Upland**

VEGETATION (Species identified in all uppercase are non-native species.)

Tree Stratum (Plot size: 10 meter radius)

	Species Name	% Cover	Dominant	Ind.Status
1.	*Acer rubrum*	5	N	FAC
2.	*Betula alleghaniensis*	5	N	FAC
3.	*Abies balsamea*	5	N	FAC
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	15		

Sapling/Shrub Stratum (Plot size: 5 meter radius)

1.	*Rubus idaeus*	10	Y	FACU
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	10		

Herb Stratum (Plot size: 2 meter radius)

1.	*Solidago canadensis*	20	Y	FACU
2.	*Rubus idaeus*	10	Y	FACU
3.	*Calamagrostis canadensis*	5	N	OBL
4.	*Symphyotrichum laeve*	5	N	FACU
5.	*Maianthemum canadense*	2	N	FACU
6	*Aralia nudicaulis*	5	N	FACU
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
11.	--	--	--	--
12.	--	--	--	--
13.	--	--	--	--
14.	--	--	--	--
15.	--	--	--	--
	Total Cover =	47		

Woody Vine Stratum (Plot size: 10 meter radius)

1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
	Total Cover =	0		

Remarks:

Dominance Test Worksheet

Number of Dominant Species that are OBL, FACW, or FAC: 0 (A)

Total Number of Dominant Species Across All Strata: 3 (B)

Percent of Dominant Species That Are OBL, FACW, or FAC: ***0.0%*** (A/B)

Prevalence Index Worksheet

Total % Cover of:		Multiply by:	
OBL spp.	5	x 1 =	5
FACW spp.	0	x 2 =	0
FAC spp.	15	x 3 =	45
FACU spp.	52	x 4 =	208
UPL spp.	0	x 5 =	0
Total	72 (A)		258 (B)

Prevalence Index = B/A = ***3.583***

Hydrophytic Vegetation Indicators:

- ☐ Yes ☑ No Rapid Test for Hydrophytic Vegetation
- ☐ Yes ☑ No Dominance Test is > 50%
- ☐ Yes ☑ No Prevalence Index is ≤ 3.0 *
- ☐ Yes ☑ No Morphological Adaptations (Explain) *
- ☐ Yes ☑ No Problem Hydrophytic Vegetation (Explain) *

* Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic.

Definitions of Vegetation Strata:

Tree - Woody plants 3 in. (7.6cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/Shrub - Woody plants less than 3 in. DBH and greater than 3.28 ft. tall.

Herb - All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft. tall.

Woody Vines - All woody vines greater than 3.28 ft. in height.

Hydrophytic Vegetation Present ☐ Yes ☑ No

Additional Remarks:

TETRA TECH

WETLAND DETERMINATION DATA FORM
Northeast and Northcentral Region

Project/Site:	Western Maine Renewable Energy Project	Project #: 194-7130	Date: 09/09/20
Applicant:	Western Maine Renewables, LLC		County: Somerset
Investigator #1:	Emmy Irvin	Investigator #2:	State: ME
Soil Unit:	Telos-Chesuncook association, 3 to 15 percent slopes	NWI/WWI Classification: PEM	Wetland ID: W67EI
Landform:	Terrace	Local Relief: Linear	Sample Point: **Wetland**
Slope (%):	See topo map	Latitude: 45.143541° Longitude: -69.850896° Datum: NAD 83	

Are climatic/hydrologic conditions on the site typical for this time of year? (If no, explain in remarks) ☐ Yes ☑ No

Are Vegetation ☐, Soil ☐, or Hydrology ☐ significantly disturbed?
Are Vegetation ☐, Soil ☐, or Hydrology ☐ naturally problematic?

Are normal circumstances present? ☐ Yes ☑ No

SUMMARY OF FINDINGS

Hydrophytic Vegetation Present?	☑ Yes ☐ No	Hydric Soils Present?	☑ Yes ☐ No
Wetland Hydrology Present?	☑ Yes ☐ No	Is This Sampling Point Within A Wetland?	☑ **Yes** ☐ **No**

Remarks: Statewide drought

HYDROLOGY

Wetland Hydrology Indicators (Check here if indicators are not present ☐)

Primary:
- ☐ A1 - Surface Water
- ☐ A2 - High Water Table
- ☑ A3 - Saturation
- ☑ B1 - Water Marks
- ☐ B2 - Sediment Deposits
- ☐ B3 - Drift Deposits
- ☐ B4 - Algal Mat or Crust
- ☐ B5 - Iron Deposits
- ☐ B7 - Inundation Visible on Aerial Imagery
- ☐ B8 - Sparsely Vegetated Concave Surface
- ☐ B9 - Water-Stained Leaves
- ☐ B13 - Aquatic Fauna
- ☐ B15 - Marl Deposits
- ☐ C1 - Hydrogen Sulfide Odor
- ☐ C3 - Oxidized Rhizospheres on Living Roots
- ☐ C4 - Presence of Reduced Iron
- ☐ C6 - Recent Iron Reduction in Tilled Soils
- ☐ C7 - Thin Muck Surface
- ☐ Other (Explain in Remarks)

Secondary:
- ☐ B6 - Surface Soil Cracks
- ☐ B10 - Drainage Patterns
- ☐ B16 - Moss Trim Lines
- ☐ C2 - Dry-Season Water Table
- ☐ C8 - Crayfish Burrows
- ☐ C9 - Saturation Visible on Aerial Imagery
- ☐ D1 - Stunted or Stressed Plants
- ☐ D2 - Geomorphic Position
- ☐ D3 - Shallow Aquitard
- ☐ D4 - Microtopographic Relief
- ☐ D5 - FAC-Neutral Test

Field Observations:

Surface Water Present?	☐ Yes	☑ No	Depth:	(in.)
Water Table Present?	☐ Yes	☑ No	Depth:	(in.)
Saturation Present?	☑ Yes	☐ No	Depth: 8	(in.)

Wetland Hydrology Present? ☑ Yes ☐ No

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available: N/A

Remarks: Statewide drought

SOILS

Map Unit Name: Telos-Chesuncook association, 3 to 15 percent slopes Series Drainage Class: somewhat poorly drained

Taxonomy (Subgroup): Loamy, isotic, frigid, shallow Aquic Haplorthods

Profile Description (Describe to the depth needed to document the indicator or confirm the absence of indicators.) (Type: C=Concentration, D=Depletion, RM=Reduced Matrix, CS=Covered/Coated Sand Grains; Location: PL=Pore Lining, M=Matrix)

Top Depth	Bottom Depth	Horizon	Matrix Color (Moist)		Matrix %	Mottles Color (Moist)		Mottles %	Mottles Type	Mottles Location	Texture (e.g. clay, sand, loam)
0	18	--	10YR	2/1	100	--	--	--	--	--	muck
		--				--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--

NRCS Hydric Soil Field Indicators (check here if indicators are not present ☑):
- ☑ A1- Histosol
- ☐ A2 - Histic Epipedon
- ☐ A3 - Black Histic
- ☐ A4 - Hydrogen Sulfide
- ☐ A5 - Stratified Layers
- ☐ A11 - Depleted Below Dark Surface
- ☐ A12 - Thick Dark Surface
- ☐ S1 - Sandy Muck Mineral
- ☐ S4 - Sandy Gleyed Matrix
- ☐ S5 - Sandy Redox
- ☐ S6 - Stripped Matrix
- ☐ S7 - Dark Surface (LRR R, MLRA 149B)
- ☐ S8 - Polyvalue Below Surface (LRR R, MLRA 149B)
- ☐ S9 - Thin Dark Surface (LRR R, MLRA 149B)
- ☐ F1 - Loamy Mucky Mineral (LRR K, L)
- ☐ F2 - Loamy Gleyed Matrix
- ☐ F3 - Depleted Matrix
- ☐ F6 - Redox Dark Surface
- ☐ F7 - Depleted Dark Surface
- ☐ F8 - Redox Depressions

Indicators for Problematic Soils [1]
- ☐ A10 - 2 cm Muck (LRR K, L, MLRA 149B)
- ☐ A16 - Coast Prairie Redox (LRR K, L, R)
- ☐ S3 - 5cm Mucky Peat of Peat (**LRR K, L, R**)
- ☐ S7 - Dark Surface (LRR K, L, M)
- ☐ S8 - Polyvalue Below Surface (**LRR K, L**)
- ☐ S9 - Thin Dark Surface (**LRR K, L**)
- ☐ F12 - Iron-Manganese Masses (**LRR K, L, R**)
- ☐ F19 - Piedmont Floodplain Soils (**MLRA 149B**)
- ☐ TA6 - Mesic Spodic (**MLRA 144A, 145, 149B**)
- ☐ TF2 - Red Parent Material
- ☐ TF12 - Very Shallow Dark Surface
- ☐ Other (Explain in Remarks)

[1] Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (If Observed) Type: NR Depth: 18

Hydric Soil Present? ☑ Yes ☐ No

Remarks:

TETRA TECH

WETLAND DETERMINATION DATA FORM

Northeast and Northcentral Region

Project/Site: Western Maine Renewable Energy Project Wetland ID: W67EI Sample Point **Wetland**

VEGETATION (Species identified in all uppercase are non-native species.)

Tree Stratum (Plot size: 10 meter radius)

	Species Name	% Cover	Dominant	Ind.Status
1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	0		

Sapling/Shrub Stratum (Plot size: 5 meter radius)

1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	0		

Herb Stratum (Plot size: 2 meter radius)

1.	*Phragmites australis*	5	N	FACW
2.	*Calamagrostis canadensis*	20	Y	OBL
3.	*Carex stricta*	15	Y	OBL
4.	*Equisetum arvense*	10	N	FAC
5.	*Onoclea sensibilis*	5	N	FACW
6	*Phalaris arundinacea*	15	Y	FACW
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
11.	--	--	--	--
12.	--	--	--	--
13.	--	--	--	--
14.	--	--	--	--
15.	--	--	--	--
	Total Cover =	70		

Woody Vine Stratum (Plot size: 10 meter radius)

1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
	Total Cover =	0		

Remarks:

Dominance Test Worksheet

Number of Dominant Species that are OBL, FACW, or FAC: 3 (A)

Total Number of Dominant Species Across All Strata: 3 (B)

Percent of Dominant Species That Are OBL, FACW, or FAC: ***100.0%*** (A/B)

Prevalence Index Worksheet

Total % Cover of:		Multiply by:	
OBL spp.	35	x 1 =	35
FACW spp.	25	x 2 =	50
FAC spp.	10	x 3 =	30
FACU spp.	0	x 4 =	0
UPL spp.	0	x 5 =	0
Total	70 (A)		115 (B)

Prevalence Index = B/A = ***1.643***

Hydrophytic Vegetation Indicators:

- ☑ Yes ☐ No Rapid Test for Hydrophytic Vegetation
- ☑ Yes ☐ No Dominance Test is > 50%
- ☑ Yes ☐ No Prevalence Index is ≤ 3.0 *
- ☐ Yes ☑ No Morphological Adaptations (Explain) *
- ☐ Yes ☑ No Problem Hydrophytic Vegetation (Explain) *

* Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic.

Definitions of Vegetation Strata:

Tree - Woody plants 3 in. (7.6cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/Shrub - Woody plants less than 3 in. DBH and greater than 3.28 ft. tall.

Herb - All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft. tall.

Woody Vines - All woody vines greater than 3.28 ft. in height.

Hydrophytic Vegetation Present ☑ Yes ☐ No

Additional Remarks:

TETRA TECH

WETLAND DETERMINATION DATA FORM
Northeast and Northcentral Region

Project/Site:	Western Maine Renewable Energy Project	Project #: 194-7130	Date: 09/09/20
Applicant:	Western Maine Renewables, LLC		County: Somerset
Investigator #1:	Emmy Irvin	Investigator #2:	State: ME
Soil Unit:	Telos-Chesuncook association, 3 to 15% slopes	NWI/WWI Classification: Upland	Wetland ID: W68EI
Landform:	Terrace	Local Relief: Linear	Sample Point: **Upland**
Slope (%):	See topo map	Latitude: 45.145100 Longitude: -69.853 Datum: NAD 83	

Are climatic/hydrologic conditions on the site typical for this time of year? (If no, explain in remarks) ☐ Yes ☑ No

Are Vegetation ☐ , Soil ☐ , or Hydrology ☐ significantly disturbed? Are normal circumstances present? ☐ Yes ☑ No

Are Vegetation ☐ , Soil ☐ , or Hydrology ☐ naturally problematic?

SUMMARY OF FINDINGS

Hydrophytic Vegetation Present?	☐ Yes ☑ No	Hydric Soils Present?	☐ Yes ☑ No
Wetland Hydrology Present?	☐ Yes ☑ No	Is This Sampling Point Within A Wetland?	☐ **Yes** ☑ **No**

Remarks: Statewide drought

HYDROLOGY

Wetland Hydrology Indicators (Check here if indicators are not present): ☑

Primary:
- ☐ A1 - Surface Water
- ☐ A2 - High Water Table
- ☐ A3 - Saturation
- ☐ B1 - Water Marks
- ☐ B2 - Sediment Deposits
- ☐ B3 - Drift Deposits
- ☐ B4 - Algal Mat or Crust
- ☐ B5 - Iron Deposits
- ☐ B7 - Inundation Visible on Aerial Imagery
- ☐ B8 - Sparsely Vegetated Concave Surface
- ☐ B9 - Water-Stained Leaves
- ☐ B13 - Aquatic Fauna
- ☐ B15 - Marl Deposits
- ☐ C1 - Hydrogen Sulfide Odor
- ☐ C3 - Oxidized Rhizospheres on Living Roots
- ☐ C4 - Presence of Reduced Iron
- ☐ C6 - Recent Iron Reduction in Tilled Soils
- ☐ C7 - Thin Muck Surface
- ☐ Other (Explain in Remarks)

Secondary:
- ☐ B6 - Surface Soil Cracks
- ☐ B10 - Drainage Patterns
- ☐ B16 - Moss Trim Lines
- ☐ C2 - Dry-Season Water Table
- ☐ C8 - Crayfish Burrows
- ☐ C9 - Saturation Visible on Aerial Imagery
- ☐ D1 - Stunted or Stressed Plants
- ☐ D2 - Geomorphic Position
- ☐ D3 - Shallow Aquitard
- ☐ D4 - Microtopographic Relief
- ☐ D5 - FAC-Neutral Test

Field Observations:

Surface Water Present?	☐ Yes ☑ No	Depth:	(in.)
Water Table Present?	☐ Yes ☑ No	Depth:	(in.)
Saturation Present?	☐ Yes ☑ No	Depth:	(in.)

Wetland Hydrology Present? ☐ Yes ☑ No

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available: N/A

Remarks: Statewide drought

SOILS

Map Unit Name: Telos-Chesuncook association, 3 to 15% slopes Series Drainage Class: Well Drained

Taxonomy (Subgroup): Loamy, isotic, frigid Lithic Haplohumods

Profile Description (Describe to the depth needed to document the indicator or confirm the absence of indicators.) (Type: C=Concentration, D=Depletion, RM=Reduced Matrix, CS=Covered/Coated Sand Grains; Location: PL=Pore Lining, M=Matrix)

Top Depth	Bottom Depth	Horizon	Matrix Color (Moist)		Matrix %	Mottles Color (Moist)		Mottles %	Mottles Type	Mottles Location	Texture (e.g. clay, sand, loam)
0	16	--	10YR	5/3	100	--	--	--	--	--	fine sandy loam
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--

NRCS Hydric Soil Field Indicators (check here if indicators are not present): ☑
- ☐ A1- Histosol
- ☐ A2 - Histic Epipedon
- ☐ A3 - Black Histic
- ☐ A4 - Hydrogen Sulfide
- ☐ A5 - Stratified Layers
- ☐ A11 - Depleted Below Dark Surface
- ☐ A12 - Thick Dark Surface
- ☐ S1 - Sandy Muck Mineral
- ☐ S4 - Sandy Gleyed Matrix
- ☐ S5 - Sandy Redox
- ☐ S6 - Stripped Matrix
- ☐ S7 - Dark Surface (LRR R, MLRA 149B)
- ☐ S8 - Polyvalue Below Surface (LRR R, MLRA 149B)
- ☐ S9 - Thin Dark Surface (LRR R, MLRA 149B)
- ☐ F1 - Loamy Mucky Mineral (LRR K, L)
- ☐ F2 - Loamy Gleyed Matrix
- ☐ F3 - Depleted Matrix
- ☐ F6 - Redox Dark Surface
- ☐ F7 - Depleted Dark Surface
- ☐ F8 - Redox Depressions

Indicators for Problematic Soils [1]
- ☐ A10 - 2 cm Muck (LRR K, L, MLRA 149B)
- ☐ A16 - Coast Prairie Redox (LRR K, L, R)
- ☐ S3 - 5cm Mucky Peat of Peat (**LRR K, L, R**)
- ☐ S7 - Dark Surface (LRR K, L, M)
- ☐ S8 - Polyvalue Below Surface (**LRR K, L**)
- ☐ S9 - Thin Dark Surface (**LRR K, L**)
- ☐ F12 - Iron-Manganese Masses (**LRR K, L, R**)
- ☐ F19 - Piedmont Floodplain Soils (**MLRA 149B**)
- ☐ TA6 - Mesic Spodic (**MLRA 144A, 145, 149B**)
- ☐ TF2 - Red Parent Material
- ☐ TF12 - Very Shallow Dark Surface
- ☐ Other (Explain in Remarks)

[1] Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (If Observed) Type: LEDGE Depth: 16

Hydric Soil Present? ☐ Yes ☑ No

Remarks:

TETRA TECH

WETLAND DETERMINATION DATA FORM

Northeast and Northcentral Region

Project/Site: Western Maine Renewable Energy Project | Wetland ID: W68EI | Sample Point **Upland**

VEGETATION (Species identified in all uppercase are non-native species.)

Tree Stratum (Plot size: 10 meter radius)

	Species Name	% Cover	Dominant	Ind.Status
1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	0		

Sapling/Shrub Stratum (Plot size: 5 meter radius)

1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	0		

Herb Stratum (Plot size: 2 meter radius)

1.	*Solidago canadensis*	20	Y	FACU
2.	*Rubus idaeus*	10	Y	FACU
3.	*Calamagrostis canadensis*	5	N	OBL
4.	*Symphyotrichum laeve*	5	N	FACU
5.	*Maianthemum canadense*	2	N	FACU
6	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
11.	--	--	--	--
12.	--	--	--	--
13.	--	--	--	--
14.	--	--	--	--
15.	--	--	--	--
	Total Cover =	42		

Woody Vine Stratum (Plot size: 10 meter radius)

1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
	Total Cover =	0		

Remarks:

Dominance Test Worksheet

Number of Dominant Species that are OBL, FACW, or FAC: 0 (A)

Total Number of Dominant Species Across All Strata: 2 (B)

Percent of Dominant Species That Are OBL, FACW, or FAC: ***0.0%*** (A/B)

Prevalence Index Worksheet

Total % Cover of:		Multiply by:	
OBL spp.	5	x 1 =	5
FACW spp.	0	x 2 =	0
FAC spp.	0	x 3 =	0
FACU spp.	37	x 4 =	148
UPL spp.	0	x 5 =	0
Total	42 (A)		153 (B)

Prevalence Index = B/A = ***3.643***

Hydrophytic Vegetation Indicators:

- ☐ Yes ☑ No Rapid Test for Hydrophytic Vegetation
- ☐ Yes ☑ No Dominance Test is > 50%
- ☐ Yes ☑ No Prevalence Index is ≤ 3.0 *
- ☐ Yes ☑ No Morphological Adaptations (Explain) *
- ☐ Yes ☑ No Problem Hydrophytic Vegetation (Explain) *

* Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic.

Definitions of Vegetation Strata:

Tree - Woody plants 3 in. (7.6cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/Shrub - Woody plants less than 3 in. DBH and greater than 3.28 ft. tall.

Herb - All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft. tall.

Woody Vines - All woody vines greater than 3.28 ft. in height.

Hydrophytic Vegetation Present ☐ Yes ☑ No

Additional Remarks:

TETRA TECH

WETLAND DETERMINATION DATA FORM
Northeast and Northcentral Region

Project/Site:	Western Maine Renewable Energy Project	Project #: 194-7130	Date: 09/09/20
Applicant:	Western Maine Renewables, LLC		County: Somerset
Investigator #1:	Emmy Irvin	Investigator #2:	State: ME
Soil Unit:	Telos-Chesuncook association, 3 to 15 percent slopes	NWI/WWI Classification: PEM	Wetland ID: W68EI
Landform:	Terrace	Local Relief: Linear	Sample Point: **Wetland**
Slope (%):	See topo map	Latitude: 45.142780 Longitude: -69.8507348 Datum: NAD 83	

Are climatic/hydrologic conditions on the site typical for this time of year? (If no, explain in remarks) ☐ Yes ☑ No

Are Vegetation ☐, Soil ☐, or Hydrology ☐ significantly disturbed? Are normal circumstances present? ☐ Yes ☑ No

Are Vegetation ☐, Soil ☐, or Hydrology ☐ naturally problematic?

SUMMARY OF FINDINGS

Hydrophytic Vegetation Present? ☑ Yes ☐ No

Wetland Hydrology Present? ☑ Yes ☐ No

Hydric Soils Present? ☑ Yes ☐ No

Is This Sampling Point Within A Wetland? ☑ **Yes** ☐ **No**

Remarks: Statewide drought

HYDROLOGY

Wetland Hydrology Indicators (Check here if indicators are not present): ☐

Primary:

- ☐ A1 - Surface Water
- ☐ A2 - High Water Table
- ☑ A3 - Saturation
- ☑ B1 - Water Marks
- ☐ B2 - Sediment Deposits
- ☐ B3 - Drift Deposits
- ☐ B4 - Algal Mat or Crust
- ☐ B5 - Iron Deposits
- ☐ B7 - Inundation Visible on Aerial Imagery
- ☐ B8 - Sparsely Vegetated Concave Surface
- ☐ B9 - Water-Stained Leaves
- ☐ B13 - Aquatic Fauna
- ☐ B15 - Marl Deposits
- ☐ C1 - Hydrogen Sulfide Odor
- ☐ C3 - Oxidized Rhizospheres on Living Roots
- ☐ C4 - Presence of Reduced Iron
- ☐ C6 - Recent Iron Reduction in Tilled Soils
- ☐ C7 - Thin Muck Surface
- ☐ Other (Explain in Remarks)

Secondary:

- ☐ B6 - Surface Soil Cracks
- ☐ B10 - Drainage Patterns
- ☐ B16 - Moss Trim Lines
- ☐ C2 - Dry-Season Water Table
- ☐ C8 - Crayfish Burrows
- ☐ C9 - Saturation Visible on Aerial Imagery
- ☐ D1 - Stunted or Stressed Plants
- ☐ D2 - Geomorphic Position
- ☐ D3 - Shallow Aquitard
- ☐ D4 - Microtopographic Relief
- ☐ D5 - FAC-Neutral Test

Field Observations:

Surface Water Present?	☐ Yes	☑ No	Depth:	(in.)
Water Table Present?	☐ Yes	☑ No	Depth:	(in.)
Saturation Present?	☑ Yes	☐ No	Depth: 8	(in.)

Wetland Hydrology Present? ☑ Yes ☐ No

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available: N/A

Remarks: Statewide drought

SOILS

Map Unit Name: Telos-Chesuncook association, 3 to 15 percent slopes — Series Drainage Class: somewhat poorly drained

Taxonomy (Subgroup): Loamy, isotic, frigid, shallow Aquic Haplorthods

Profile Description (Describe to the depth needed to document the indicator or confirm the absence of indicators.) (Type: C=Concentration, D=Depletion, RM=Reduced Matrix, CS=Covered/Coated Sand Grains; Location: PL=Pore Lining, M=Matrix)

Top Depth	Bottom Depth	Horizon	Matrix Color (Moist)	Matrix %	Mottles Color (Moist)	Mottles %	Mottles Type	Mottles Location	Texture (e.g. clay, sand, loam)
0	16	--	10YR 2/1	100	--	--	--	--	muck
		--			--	--	--	--	--
--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--

NRCS Hydric Soil Field Indicators (check here if indicators are not present ☑)

- ☑ A1- Histosol
- ☐ A2 - Histic Epipedon
- ☐ A3 - Black Histic
- ☐ A4 - Hydrogen Sulfide
- ☐ A5 - Stratified Layers
- ☐ A11 - Depleted Below Dark Surface
- ☐ A12 - Thick Dark Surface
- ☐ S1 - Sandy Muck Mineral
- ☐ S4 - Sandy Gleyed Matrix
- ☐ S5 - Sandy Redox
- ☐ S6 - Stripped Matrix
- ☐ S7 - Dark Surface (LRR R, MLRA 149B)
- ☐ S8 - Polyvalue Below Surface (LRR R, MLRA 149B)
- ☐ S9 - Thin Dark Surface (LRR R, MLRA 149B)
- ☐ F1 - Loamy Mucky Mineral (LRR K, L)
- ☐ F2 - Loamy Gleyed Matrix
- ☐ F3 - Depleted Matrix
- ☐ F6 - Redox Dark Surface
- ☐ F7 - Depleted Dark Surface
- ☐ F8 - Redox Depressions

Indicators for Problematic Soils [1]

- ☐ A10 - 2 cm Muck (LRR K, L, MLRA 149B)
- ☐ A16 - Coast Prairie Redox (LRR K, L, R)
- ☐ S3 - 5cm Mucky Peat of Peat (**LRR K, L, R**)
- ☐ S7 - Dark Surface (LRR K, L, M)
- ☐ S8 - Polyvalue Below Surface (**LRR K, L**)
- ☐ S9 - Thin Dark Surface (**LRR K, L**)
- ☐ F12 - Iron-Manganese Masses (**LRR K, L, R**)
- ☐ F19 - Piedmont Floodplain Soils (**MLRA 149B**)
- ☐ TA6 - Mesic Spodic (**MLRA 144A, 145, 149B**)
- ☐ TF2 - Red Parent Material
- ☐ TF12 - Very Shallow Dark Surface
- ☐ Other (Explain in Remarks)

[1] Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (If Observed) Type: ledge Depth: 16

Hydric Soil Present? ☑ Yes ☐ No

Remarks:

TETRA TECH

WETLAND DETERMINATION DATA FORM

Northeast and Northcentral Region

Project/Site: Western Maine Renewable Energy Project | Wetland ID: W68EI | Sample Point **Wetland**

VEGETATION (Species identified in all uppercase are non-native species.)

Tree Stratum (Plot size: 10 meter radius)

	Species Name	% Cover	Dominant	Ind.Status
1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	0		

Sapling/Shrub Stratum (Plot size: 5 meter radius)

1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	0		

Herb Stratum (Plot size: 2 meter radius)

1.	*Typha angustifolia*	10	Y	OBL
2.	*Calamagrostis canadensis*	20	Y	OBL
3.	*Carex stricta*	10	Y	OBL
4.	*Equisetum arvense*	5	N	FAC
5.	*Onoclea sensibilis*	5	N	FACW
6	*Phalaris arundinacea*	10	Y	FACW
7.	*Iris versicolor*	2	N	OBL
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
11.	--	--	--	--
12.	--	--	--	--
13.	--	--	--	--
14.	--	--	--	--
15.	--	--	--	--
	Total Cover =	62		

Woody Vine Stratum (Plot size: 10 meter radius)

1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
	Total Cover =	0		

Remarks:

Dominance Test Worksheet

Number of Dominant Species that are OBL, FACW, or FAC: 4 (A)

Total Number of Dominant Species Across All Strata: 4 (B)

Percent of Dominant Species That Are OBL, FACW, or FAC: ***100.0%*** (A/B)

Prevalence Index Worksheet

Total % Cover of:		Multiply by:	
OBL spp.	42	x 1 =	42
FACW spp.	15	x 2 =	30
FAC spp.	5	x 3 =	15
FACU spp.	0	x 4 =	0
UPL spp.	0	x 5 =	0
Total	62 (A)		87 (B)

Prevalence Index = B/A = ***1.403***

Hydrophytic Vegetation Indicators:

- ☐ Yes ☑ No Rapid Test for Hydrophytic Vegetation
- ☑ Yes ☐ No Dominance Test is > 50%
- ☑ Yes ☐ No Prevalence Index is ≤ 3.0 *
- ☐ Yes ☑ No Morphological Adaptations (Explain) *
- ☐ Yes ☑ No Problem Hydrophytic Vegetation (Explain) *

* Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic.

Definitions of Vegetation Strata:

Tree - Woody plants 3 in. (7.6cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/Shrub - Woody plants less than 3 in. DBH and greater than 3.28 ft. tall.

Herb - All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft. tall.

Woody Vines - All woody vines greater than 3.28 ft. in height.

Hydrophytic Vegetation Present ☑ Yes ☐ No

Additional Remarks:

TETRA TECH

WETLAND DETERMINATION DATA FORM
Northeast and Northcentral Region

Project/Site:	Western Maine Renewable Energy Project	Project #: 194-7130	Date: 09/09/20
Applicant:	Western Maine Renewables, LLC		County: Somerset
Investigator #1:	Emmy Irvin	Investigator #2:	State: ME
Soil Unit:	Telos-Chesuncook association, 3 to 15% slopes	NWI/WWI Classification: Upland	Wetland ID: W71EI
Landform:	Terrace	Local Relief: Linear	Sample Point: **Upland**
Slope (%):	See topo map	Latitude: 45.145100 Longitude: -69.853 Datum: NAD 83	

Are climatic/hydrologic conditions on the site typical for this time of year? (If no, explain in remarks) ☐ Yes ☑ No

Are Vegetation ☐ , Soil ☐ , or Hydrology ☐ significantly disturbed? Are normal circumstances present? ☐ Yes ☑ No

Are Vegetation ☐ , Soil ☐ , or Hydrology ☐ naturally problematic?

SUMMARY OF FINDINGS

Hydrophytic Vegetation Present?	☐ Yes ☑ No	Hydric Soils Present?	☐ Yes ☑ No
Wetland Hydrology Present?	☐ Yes ☑ No	Is This Sampling Point Within A Wetland?	☐ **Yes** ☑ **No**

Remarks: Statewide drought

HYDROLOGY

Wetland Hydrology Indicators (Check here if indicators are not present): ☑

Primary:
- ☐ A1 - Surface Water
- ☐ A2 - High Water Table
- ☐ A3 - Saturation
- ☐ B1 - Water Marks
- ☐ B2 - Sediment Deposits
- ☐ B3 - Drift Deposits
- ☐ B4 - Algal Mat or Crust
- ☐ B5 - Iron Deposits
- ☐ B7 - Inundation Visible on Aerial Imagery
- ☐ B8 - Sparsely Vegetated Concave Surface
- ☐ B9 - Water-Stained Leaves
- ☐ B13 - Aquatic Fauna
- ☐ B15 - Marl Deposits
- ☐ C1 - Hydrogen Sulfide Odor
- ☐ C3 - Oxidized Rhizospheres on Living Roots
- ☐ C4 - Presence of Reduced Iron
- ☐ C6 - Recent Iron Reduction in Tilled Soils
- ☐ C7 - Thin Muck Surface
- ☐ Other (Explain in Remarks)

Secondary:
- ☐ B6 - Surface Soil Cracks
- ☐ B10 - Drainage Patterns
- ☐ B16 - Moss Trim Lines
- ☐ C2 - Dry-Season Water Table
- ☐ C8 - Crayfish Burrows
- ☐ C9 - Saturation Visible on Aerial Imagery
- ☐ D1 - Stunted or Stressed Plants
- ☐ D2 - Geomorphic Position
- ☐ D3 - Shallow Aquitard
- ☐ D4 - Microtopographic Relief
- ☐ D5 - FAC-Neutral Test

Field Observations:

Surface Water Present?	☐ Yes ☑ No	Depth:	(in.)
Water Table Present?	☐ Yes ☑ No	Depth:	(in.)
Saturation Present?	☐ Yes ☑ No	Depth:	(in.)

Wetland Hydrology Present? ☐ Yes ☑ No

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available: N/A

Remarks: Statewide drought

SOILS

Map Unit Name: Telos-Chesuncook association, 3 to 15% slopes Series Drainage Class: Well Drained

Taxonomy (Subgroup): Loamy, isotic, frigid Lithic Haplohumods

Profile Description (Describe to the depth needed to document the indicator or confirm the absence of indicators.) (Type: C=Concentration, D=Depletion, RM=Reduced Matrix, CS=Covered/Coated Sand Grains; Location: PL=Pore Lining, M=Matrix)

Top Depth	Bottom Depth	Horizon	Matrix Color (Moist)		Matrix %	Mottles Color (Moist)		Mottles %	Mottles Type	Mottles Location	Texture (e.g. clay, sand, loam)
0	6	--	10YR	5/3	100	--	--	--	--	--	fine sandy loam
6	12	--	10YR	5/2	100	--	--	--	--	--	fine sandy loam
12	18	--	2.5Y	5/2	100	--	--	--	--	--	fine sandy loam
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--

NRCS Hydric Soil Field Indicators (check here if indicators are not present): ☑
- ☐ A1- Histosol
- ☐ A2 - Histic Epipedon
- ☐ A3 - Black Histic
- ☐ A4 - Hydrogen Sulfide
- ☐ A5 - Stratified Layers
- ☐ A11 - Depleted Below Dark Surface
- ☐ A12 - Thick Dark Surface
- ☐ S1 - Sandy Muck Mineral
- ☐ S4 - Sandy Gleyed Matrix
- ☐ S5 - Sandy Redox
- ☐ S6 - Stripped Matrix
- ☐ S7 - Dark Surface (LRR R, MLRA 149B)
- ☐ S8 - Polyvalue Below Surface (LRR R, MLRA 149B)
- ☐ S9 - Thin Dark Surface (LRR R, MLRA 149B)
- ☐ F1 - Loamy Mucky Mineral (LRR K, L)
- ☐ F2 - Loamy Gleyed Matrix
- ☐ F3 - Depleted Matrix
- ☐ F6 - Redox Dark Surface
- ☐ F7 - Depleted Dark Surface
- ☐ F8 - Redox Depressions

Indicators for Problematic Soils [1]
- ☐ A10 - 2 cm Muck (LRR K, L, MLRA 149B)
- ☐ A16 - Coast Prairie Redox (LRR K, L, R)
- ☐ S3 - 5cm Mucky Peat of Peat (**LRR K, L, R**)
- ☐ S7 - Dark Surface (LRR K, L, M)
- ☐ S8 - Polyvalue Below Surface (**LRR K, L**)
- ☐ S9 - Thin Dark Surface (**LRR K, L**)
- ☐ F12 - Iron-Manganese Masses (**LRR K, L, R**)
- ☐ F19 - Piedmont Floodplain Soils (**MLRA 149B**)
- ☐ TA6 - Mesic Spodic (**MLRA 144A, 145, 149B**)
- ☐ TF2 - Red Parent Material
- ☐ TF12 - Very Shallow Dark Surface
- ☐ Other (Explain in Remarks)

[1] Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (If Observed) Type: LEDGE Depth: 18

Hydric Soil Present? ☐ Yes ☑ No

Remarks:

TETRA TECH

WETLAND DETERMINATION DATA FORM

Northeast and Northcentral Region

Project/Site: Western Maine Renewable Energy Project | Wetland ID: W71EI | Sample Point **Upland**

VEGETATION (Species identified in all uppercase are non-native species.)

Tree Stratum (Plot size: 10 meter radius)

	Species Name	% Cover	Dominant	Ind.Status
1.	*Acer rubrum*	5	N	FAC
2.	*Betula alleghaniensis*	5	N	FAC
3.	*Abies balsamea*	5	N	FAC
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	15		

Sapling/Shrub Stratum (Plot size: 5 meter radius)

1.	*Rubus idaeus*	10	Y	FACU
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	10		

Herb Stratum (Plot size: 2 meter radius)

1.	*Solidago canadensis*	20	Y	FACU
2.	*Rubus idaeus*	10	Y	FACU
3.	*Calamagrostis canadensis*	5	N	OBL
4.	*Symphyotrichum laeve*	5	N	FACU
5.	*Maianthemum canadense*	2	N	FACU
6	*Aralia nudicaulis*	5	N	FACU
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
11.	--	--	--	--
12.	--	--	--	--
13.	--	--	--	--
14.	--	--	--	--
15.	--	--	--	--
	Total Cover =	47		

Woody Vine Stratum (Plot size: 10 meter radius)

1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
	Total Cover =	0		

Remarks:

Dominance Test Worksheet

Number of Dominant Species that are OBL, FACW, or FAC: 0 (A)

Total Number of Dominant Species Across All Strata: 3 (B)

Percent of Dominant Species That Are OBL, FACW, or FAC: ***0.0%*** (A/B)

Prevalence Index Worksheet

Total % Cover of:		Multiply by:	
OBL spp.	5	x 1 =	5
FACW spp.	0	x 2 =	0
FAC spp.	15	x 3 =	45
FACU spp.	52	x 4 =	208
UPL spp.	0	x 5 =	0
Total	72 (A)		258 (B)

Prevalence Index = B/A = ***3.583***

Hydrophytic Vegetation Indicators:

- ☐ Yes ☑ No Rapid Test for Hydrophytic Vegetation
- ☐ Yes ☑ No Dominance Test is > 50%
- ☐ Yes ☑ No Prevalence Index is ≤ 3.0 *
- ☐ Yes ☑ No Morphological Adaptations (Explain) *
- ☐ Yes ☑ No Problem Hydrophytic Vegetation (Explain) *

* Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic.

Definitions of Vegetation Strata:

Tree - Woody plants 3 in. (7.6cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/Shrub - Woody plants less than 3 in. DBH and greater than 3.28 ft. tall.

Herb - All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft. tall.

Woody Vines - All woody vines greater than 3.28 ft. in height.

Hydrophytic Vegetation Present ☐ Yes ☑ No

Additional Remarks:

TETRA TECH

WETLAND DETERMINATION DATA FORM
Northeast and Northcentral Region

Project/Site:	Western Maine Renewable Energy Project	Project #: 194-7130	Date: 09/09/20
Applicant:	Western Maine Renewables, LLC		County: Somerset
Investigator #1:	Emmy Irvin	Investigator #2:	State: ME
Soil Unit:	Telos-Chesuncook association, 3 to 15 percent slopes	NWI/WWI Classification: PEM	Wetland ID: W71EI
Landform:	Terrace	Local Relief: Linear	Sample Point: **Wetland**
Slope (%):	See topo map	Latitude: 45.143541° Longitude: -69.850896° Datum: NAD 83	

Are climatic/hydrologic conditions on the site typical for this time of year? (If no, explain in remarks) ☐ Yes ☑ No

Are Vegetation ☐, Soil ☐, or Hydrology ☐ significantly disturbed? Are normal circumstances present? ☐ Yes ☑ No

Are Vegetation ☐, Soil ☐, or Hydrology ☐ naturally problematic?

SUMMARY OF FINDINGS

Hydrophytic Vegetation Present? ☑ Yes ☐ No

Wetland Hydrology Present? ☑ Yes ☐ No

Hydric Soils Present? ☑ Yes ☐ No

Is This Sampling Point Within A Wetland? ☑ **Yes** ☐ **No**

Remarks: Statewide drought

HYDROLOGY

Wetland Hydrology Indicators (Check here if indicators are not present): ☐

Primary:

- ☐ A1 - Surface Water
- ☐ A2 - High Water Table
- ☑ A3 - Saturation
- ☑ B1 - Water Marks
- ☐ B2 - Sediment Deposits
- ☐ B3 - Drift Deposits
- ☐ B4 - Algal Mat or Crust
- ☐ B5 - Iron Deposits
- ☐ B7 - Inundation Visible on Aerial Imagery
- ☐ B8 - Sparsely Vegetated Concave Surface
- ☐ B9 - Water-Stained Leaves
- ☐ B13 - Aquatic Fauna
- ☐ B15 - Marl Deposits
- ☐ C1 - Hydrogen Sulfide Odor
- ☐ C3 - Oxidized Rhizospheres on Living Roots
- ☐ C4 - Presence of Reduced Iron
- ☐ C6 - Recent Iron Reduction in Tilled Soils
- ☐ C7 - Thin Muck Surface
- ☐ Other (Explain in Remarks)

Secondary:

- ☐ B6 - Surface Soil Cracks
- ☐ B10 - Drainage Patterns
- ☐ B16 - Moss Trim Lines
- ☐ C2 - Dry-Season Water Table
- ☐ C8 - Crayfish Burrows
- ☐ C9 - Saturation Visible on Aerial Imagery
- ☐ D1 - Stunted or Stressed Plants
- ☐ D2 - Geomorphic Position
- ☐ D3 - Shallow Aquitard
- ☐ D4 - Microtopographic Relief
- ☐ D5 - FAC-Neutral Test

Field Observations:

Surface Water Present?	☐ Yes	☑ No	Depth:	(in.)
Water Table Present?	☐ Yes	☑ No	Depth:	(in.)
Saturation Present?	☑ Yes	☐ No	Depth: 8	(in.)

Wetland Hydrology Present? ☑ Yes ☐ No

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available: N/A

Remarks: Statewide drought

SOILS

Map Unit Name: Telos-Chesuncook association, 3 to 15 percent slopes Series Drainage Class: somewhat poorly drained

Taxonomy (Subgroup): Loamy, isotic, frigid, shallow Aquic Haplorthods

Profile Description (Describe to the depth needed to document the indicator or confirm the absence of indicators.) (Type: C=Concentration, D=Depletion, RM=Reduced Matrix, CS=Covered/Coated Sand Grains; Location: PL=Pore Lining, M=Matrix)

Top Depth	Bottom Depth	Horizon	Matrix Color (Moist)	Matrix %	Mottles Color (Moist)	Mottles %	Mottles Type	Mottles Location	Texture (e.g. clay, sand, loam)
0	18	--	10YR 2/1	100	--	--	--	--	muck
		--			--	--	--	--	--
--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--

NRCS Hydric Soil Field Indicators (check here if indicators are not present ☑)

- ☑ A1- Histosol
- ☐ A2 - Histic Epipedon
- ☐ A3 - Black Histic
- ☐ A4 - Hydrogen Sulfide
- ☐ A5 - Stratified Layers
- ☐ A11 - Depleted Below Dark Surface
- ☐ A12 - Thick Dark Surface
- ☐ S1 - Sandy Muck Mineral
- ☐ S4 - Sandy Gleyed Matrix
- ☐ S5 - Sandy Redox
- ☐ S6 - Stripped Matrix
- ☐ S7 - Dark Surface (LRR R, MLRA 149B)
- ☐ S8 - Polyvalue Below Surface (LRR R, MLRA 149B)
- ☐ S9 - Thin Dark Surface (LRR R, MLRA 149B)
- ☐ F1 - Loamy Mucky Mineral (LRR K, L)
- ☐ F2 - Loamy Gleyed Matrix
- ☐ F3 - Depleted Matrix
- ☐ F6 - Redox Dark Surface
- ☐ F7 - Depleted Dark Surface
- ☐ F8 - Redox Depressions

Indicators for Problematic Soils [1]

- ☐ A10 - 2 cm Muck (LRR K, L, MLRA 149B)
- ☐ A16 - Coast Prairie Redox (LRR K, L, R)
- ☐ S3 - 5cm Mucky Peat of Peat (**LRR K, L, R**)
- ☐ S7 - Dark Surface (LRR K, L, M)
- ☐ S8 - Polyvalue Below Surface (**LRR K, L**)
- ☐ S9 - Thin Dark Surface (**LRR K, L**)
- ☐ F12 - Iron-Manganese Masses (**LRR K, L, R**)
- ☐ F19 - Piedmont Floodplain Soils (**MLRA 149B**)
- ☐ TA6 - Mesic Spodic (**MLRA 144A, 145, 149B**)
- ☐ TF2 - Red Parent Material
- ☐ TF12 - Very Shallow Dark Surface
- ☐ Other (Explain in Remarks)

[1] Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (If Observed) Type: Depth: 18

Hydric Soil Present? ☑ Yes ☐ No

Remarks:

TETRA TECH

WETLAND DETERMINATION DATA FORM

Northeast and Northcentral Region

Project/Site: Western Maine Renewable Energy Project | Wetland ID: W71EI | Sample Point **Wetland**

VEGETATION (Species identified in all uppercase are non-native species.)

Tree Stratum (Plot size: 10 meter radius)

	Species Name	% Cover	Dominant	Ind.Status
1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	0		

Sapling/Shrub Stratum (Plot size: 5 meter radius)

1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	0		

Herb Stratum (Plot size: 2 meter radius)

1.	*Phragmites australis*	5	N	FACW
2.	*Calamagrostis canadensis*	20	Y	OBL
3.	*Carex stricta*	15	Y	OBL
4.	*Equisetum arvense*	10	Y	FAC
5.	*Onoclea sensibilis*	5	N	FACW
6	*Phalaris arundinacea*	15	Y	FACW
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
11.	--	--	--	--
12.	--	--	--	--
13.	--	--	--	--
14.	--	--	--	--
15.	--	--	--	--
	Total Cover =	70		

Woody Vine Stratum (Plot size: 10 meter radius)

1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
	Total Cover =	0		

Remarks:

Dominance Test Worksheet

Number of Dominant Species that are OBL, FACW, or FAC: 4 (A)

Total Number of Dominant Species Across All Strata: 4 (B)

Percent of Dominant Species That Are OBL, FACW, or FAC: ***100.0%*** (A/B)

Prevalence Index Worksheet

Total % Cover of:		Multiply by:	
OBL spp.	35	x 1 =	35
FACW spp.	25	x 2 =	50
FAC spp.	10	x 3 =	30
FACU spp.	0	x 4 =	0
UPL spp.	0	x 5 =	0
Total	70 (A)		115 (B)

Prevalence Index = B/A = ***1.643***

Hydrophytic Vegetation Indicators:

- ☑ Yes ☐ No Rapid Test for Hydrophytic Vegetation
- ☑ Yes ☐ No Dominance Test is > 50%
- ☑ Yes ☐ No Prevalence Index is ≤ 3.0 *
- ☐ Yes ☑ No Morphological Adaptations (Explain) *
- ☐ Yes ☑ No Problem Hydrophytic Vegetation (Explain) *

* Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic.

Definitions of Vegetation Strata:

Tree - Woody plants 3 in. (7.6cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/Shrub - Woody plants less than 3 in. DBH and greater than 3.28 ft. tall.

Herb - All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft. tall.

Woody Vines - All woody vines greater than 3.28 ft. in height.

Hydrophytic Vegetation Present ☑ Yes ☐ No

Additional Remarks:

TETRA TECH

WETLAND DETERMINATION DATA FORM
Northeast and Northcentral Region

Project/Site:	Western Maine Renewable Energy Project	Project #:	194-7130
Applicant:	Western Maine Renewables, LLC		
Investigator #1:	Emmy Irvin	Investigator #2:	
Soil Unit:	Telos-Chesuncook-Elliottsville association, 3 to 15 percent slopes	NWI/WWI Classification:	Upland
Landform:	Terrace	Local Relief:	Linear
Slope (%):	See topo map	Latitude: 45.14626951800	Longitude: -69.865158585 Datum: NAD 83

Are climatic/hydrologic conditions on the site typical for this time of year? (If no, explain in remarks) ☐ Yes ☑ No

Are Vegetation ☐, Soil ☐, or Hydrology ☐significantly disturbed?
Are Vegetation ☐, Soil ☐, or Hydrology ☐naturally problematic?

Are normal circumstances present? ☐ Yes ☑ No

Date:	09/09/20
County:	Somerset
State:	ME
Wetland ID:	W81EI
Sample Point:	**Upland**

SUMMARY OF FINDINGS

Hydrophytic Vegetation Present?	☐ Yes ☑ No	Hydric Soils Present?	☐ Yes ☑ No
Wetland Hydrology Present?	☐ Yes ☑ No	Is This Sampling Point Within A Wetland?	☐ **Yes** ☑ **No**

Remarks: Statewide drought

HYDROLOGY

Wetland Hydrology Indicators (Check here if indicators are not present): ☑

Primary:
- ☐ A1 - Surface Water
- ☐ A2 - High Water Table
- ☐ A3 - Saturation
- ☐ B1 - Water Marks
- ☐ B2 - Sediment Deposits
- ☐ B3 - Drift Deposits
- ☐ B4 - Algal Mat or Crust
- ☐ B5 - Iron Deposits
- ☐ B7 - Inundation Visible on Aerial Imagery
- ☐ B8 - Sparsely Vegetated Concave Surface
- ☐ B9 - Water-Stained Leaves
- ☐ B13 - Aquatic Fauna
- ☐ B15 - Marl Deposits
- ☐ C1 - Hydrogen Sulfide Odor
- ☐ C3 - Oxidized Rhizospheres on Living Roots
- ☐ C4 - Presence of Reduced Iron
- ☐ C6 - Recent Iron Reduction in Tilled Soils
- ☐ C7 - Thin Muck Surface
- ☐ Other (Explain in Remarks)

Secondary:
- ☐ B6 - Surface Soil Cracks
- ☐ B10 - Drainage Patterns
- ☐ B16 - Moss Trim Lines
- ☐ C2 - Dry-Season Water Table
- ☐ C8 - Crayfish Burrows
- ☐ C9 - Saturation Visible on Aerial Imagery
- ☐ D1 - Stunted or Stressed Plants
- ☐ D2 - Geomorphic Position
- ☐ D3 - Shallow Aquitard
- ☐ D4 - Microtopographic Relief
- ☐ D5 - FAC-Neutral Test

Field Observations:

Surface Water Present?	☐ Yes ☑ No	Depth:	(in.)
Water Table Present?	☐ Yes ☑ No	Depth:	(in.)
Saturation Present?	☐ Yes ☑ No	Depth:	(in.)

Wetland Hydrology Present? ☐ Yes ☑ No

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available: N/A

Remarks: Statewide drought

SOILS

Map Unit Name: Telos-Chesuncook-Elliottsville association, 3 to 15 percent slopes, very stony — Series Drainage Class: Well Drained

Taxonomy (Subgroup): Loamy, isotic, frigid Lithic Haplohumods

Profile Description (Describe to the depth needed to document the indicator or confirm the absence of indicators.) (Type: C=Concentration, D=Depletion, RM=Reduced Matrix, CS=Covered/Coated Sand Grains; Location: PL=Pore Lining, M=Matrix)

Top Depth	Bottom Depth	Horizon	Matrix Color (Moist)		Matrix %	Mottles Color (Moist)		Mottles %	Mottles Type	Mottles Location	Texture (e.g. clay, sand, loam)
0	3	1	10YR	3/2	100	--	--	--	--	--	fine sandy loam
3	8	2	7.5YR	3/2	100	--	--	--	--	--	fine sandy loam
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--

NRCS Hydric Soil Field Indicators (check here if indicators are not present): ☑

- ☐ A1- Histosol
- ☐ A2 - Histic Epipedon
- ☐ A3 - Black Histic
- ☐ A4 - Hydrogen Sulfide
- ☐ A5 - Stratified Layers
- ☐ A11 - Depleted Below Dark Surface
- ☐ A12 - Thick Dark Surface
- ☐ S1 - Sandy Muck Mineral
- ☐ S4 - Sandy Gleyed Matrix
- ☐ S5 - Sandy Redox
- ☐ S6 - Stripped Matrix
- ☐ S7 - Dark Surface (LRR R, MLRA 149B)
- ☐ S8 - Polyvalue Below Surface (LRR R, MLRA 149B)
- ☐ S9 - Thin Dark Surface (LRR R, MLRA 149B)
- ☐ F1 - Loamy Mucky Mineral (LRR K, L)
- ☐ F2 - Loamy Gleyed Matrix
- ☐ F3 - Depleted Matrix
- ☐ F6 - Redox Dark Surface
- ☐ F7 - Depleted Dark Surface
- ☐ F8 - Redox Depressions

Indicators for Problematic Soils [1]
- ☐ A10 - 2 cm Muck (LRR K, L, MLRA 149B)
- ☐ A16 - Coast Prairie Redox (LRR K, L, R)
- ☐ S3 - 5cm Mucky Peat of Peat (**LRR K, L, R**)
- ☐ S7 - Dark Surface (LRR K, L, M)
- ☐ S8 - Polyvalue Below Surface (**LRR K, L**)
- ☐ S9 - Thin Dark Surface (**LRR K, L**)
- ☐ F12 - Iron-Manganese Masses (**LRR K, L, R**)
- ☐ F19 - Piedmont Floodplain Soils (**MLRA 149B**)
- ☐ TA6 - Mesic Spodic (**MLRA 144A, 145, 149B**)
- ☐ TF2 - Red Parent Material
- ☐ TF12 - Very Shallow Dark Surface
- ☐ Other (Explain in Remarks)

[1] Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (If Observed) Type: LEDGE Depth: 8

Hydric Soil Present? ☐ Yes ☑ No

Remarks:

TETRA TECH

WETLAND DETERMINATION DATA FORM

Northeast and Northcentral Region

Project/Site: Western Maine Renewable Energy Project | Wetland ID: W81EI | Sample Point **Upland**

VEGETATION (Species identified in all uppercase are non-native species.)

Tree Stratum (Plot size: 10 meter radius)

	Species Name	% Cover	Dominant	Ind.Status
1.	*Acer rubrum*	15	Y	FAC
2.	*Larix laricina*	5	N	FACW
3.	*Picea rubens*	5	N	FACU
4.	*Fraxinus pennsylvanica*	5	N	FACW
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	30		

Sapling/Shrub Stratum (Plot size: 5 meter radius)

1.	*Acer rubrum*	10	N	FAC
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	10		

Herb Stratum (Plot size: 2 meter radius)

1.	*Aralia nudicaulis*	10	Y	FACU
2.	*Phegopteris hexagonoptera*	2	N	FACU
3.	*Tsuga canadensis*	1	N	FACU
4.	--	--	--	--
5.	--	--	--	--
6	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
11.	--	--	--	--
12.	--	--	--	--
13.	--	--	--	--
14.	--	--	--	--
15.	--	--	--	--
	Total Cover =	13		

Woody Vine Stratum (Plot size: 10 meter radius)

1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
	Total Cover =	0		

Remarks:

Dominance Test Worksheet

Number of Dominant Species that are OBL, FACW, or FAC: 1 (A)

Total Number of Dominant Species Across All Strata: 2 (B)

Percent of Dominant Species That Are OBL, FACW, or FAC: ***50.0%*** (A/B)

Prevalence Index Worksheet

Total % Cover of:		Multiply by:	
OBL spp.	0	x 1 =	0
FACW spp.	10	x 2 =	20
FAC spp.	25	x 3 =	75
FACU spp.	18	x 4 =	72
UPL spp.	0	x 5 =	0
Total	53 (A)		167 (B)

Prevalence Index = B/A = ***3.151***

Hydrophytic Vegetation Indicators:

- ☐ Yes ☑ No Rapid Test for Hydrophytic Vegetation
- ☐ Yes ☑ No Dominance Test is > 50%
- ☐ Yes ☑ No Prevalence Index is ≤ 3.0 *
- ☐ Yes ☑ No Morphological Adaptations (Explain) *
- ☐ Yes ☑ No Problem Hydrophytic Vegetation (Explain) *

* Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic.

Definitions of Vegetation Strata:

Tree - Woody plants 3 in. (7.6cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/Shrub - Woody plants less than 3 in. DBH and greater than 3.28 ft. tall.

Herb - All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft. tall.

Woody Vines - All woody vines greater than 3.28 ft. in height.

Hydrophytic Vegetation Present ☐ Yes ☑ No

Additional Remarks:

TETRA TECH

WETLAND DETERMINATION DATA FORM
Northeast and Northcentral Region

Project/Site:	Western Maine Renewable Energy Project	Project #: 194-7130	Date: 09/09/20
Applicant:	Western Maine Renewables, LLC		County: Somerset
Investigator #1:	Emmy Irvin	Investigator #2:	State: ME
Soil Unit:	Telos-Chesuncook association, 3 to 15 percent slopes	NWI/WWI Classification: PFO	Wetland ID: W81EI
Landform:	Terrace	Local Relief: Linear	Sample Point: **Wetland**
Slope (%):	See topo map	Latitude: 45.148580 Longitude: -69.8618612 Datum: NAD 83	

Are climatic/hydrologic conditions on the site typical for this time of year? (If no, explain in remarks) ☐ Yes ☑ No

Are Vegetation ☐, Soil ☐, or Hydrology ☐ significantly disturbed?
Are Vegetation ☐, Soil ☐, or Hydrology ☐ naturally problematic?

Are normal circumstances present? ☐ Yes ☑ No

SUMMARY OF FINDINGS

Hydrophytic Vegetation Present?	☑ Yes ☐ No	Hydric Soils Present?	☑ Yes ☐ No
Wetland Hydrology Present?	☑ Yes ☐ No	Is This Sampling Point Within A Wetland?	☑ **Yes** ☐ **No**

Remarks: Statewide drought

HYDROLOGY

Wetland Hydrology Indicators (Check here if indicators are not present ☐)

Primary:
- ☐ A1 - Surface Water
- ☐ A2 - High Water Table
- ☐ A3 - Saturation
- ☐ B1 - Water Marks
- ☐ B2 - Sediment Deposits
- ☐ B3 - Drift Deposits
- ☐ B4 - Algal Mat or Crust
- ☐ B5 - Iron Deposits
- ☐ B7 - Inundation Visible on Aerial Imagery
- ☐ B8 - Sparsely Vegetated Concave Surface
- ☑ B9 - Water-Stained Leaves
- ☐ B13 - Aquatic Fauna
- ☐ B15 - Marl Deposits
- ☐ C1 - Hydrogen Sulfide Odor
- ☐ C3 - Oxidized Rhizospheres on Living Roots
- ☐ C4 - Presence of Reduced Iron
- ☐ C6 - Recent Iron Reduction in Tilled Soils
- ☐ C7 - Thin Muck Surface
- ☐ Other (Explain in Remarks)

Secondary:
- ☐ B6 - Surface Soil Cracks
- ☑ B10 - Drainage Patterns
- ☐ B16 - Moss Trim Lines
- ☐ C2 - Dry-Season Water Table
- ☐ C8 - Crayfish Burrows
- ☐ C9 - Saturation Visible on Aerial Imagery
- ☐ D1 - Stunted or Stressed Plants
- ☐ D2 - Geomorphic Position
- ☐ D3 - Shallow Aquitard
- ☐ D4 - Microtopographic Relief
- ☐ D5 - FAC-Neutral Test

Field Observations:

Surface Water Present?	☐ Yes ☑ No	Depth:	(in.)
Water Table Present?	☐ Yes ☑ No	Depth:	(in.)
Saturation Present?	☐ Yes ☑ No	Depth:	(in.)

Wetland Hydrology Present? ☑ Yes ☐ No

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available: N/A

Remarks: Statewide drought

SOILS

Map Unit Name: Telos-Chesuncook association, 3 to 15 percent slopes Series Drainage Class: Somewhat poorly drained

Taxonomy (Subgroup): Loamy, isotic, frigid, shallow Aquic Haplorthods

Profile Description (Describe to the depth needed to document the indicator or confirm the absence of indicators.) (Type: C=Concentration, D=Depletion, RM=Reduced Matrix, CS=Covered/Coated Sand Grains; Location: PL=Pore Lining, M=Matrix)

Top Depth	Bottom Depth	Horizon	Matrix Color (Moist)		Matrix %	Mottles Color (Moist)		Mottles %	Mottles Type	Mottles Location	Texture (e.g. clay, sand, loam)
0	8	--	10YR	2/1	100	--	--	--	--	--	fine sandy loam
8	14	--	10YR	2/1	40	7.5YR	4/6	15	C	M	fine sandy loam
--	--	--	--	--	--	10YR	4/1	45	D	M	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--

NRCS Hydric Soil Field Indicators (check here if indicators are not present ☐):
- ☐ A1- Histosol
- ☐ A2 - Histic Epipedon
- ☐ A3 - Black Histic
- ☐ A4 - Hydrogen Sulfide
- ☐ A5 - Stratified Layers
- ☐ A11 - Depleted Below Dark Surface
- ☐ A12 - Thick Dark Surface
- ☐ S1 - Sandy Muck Mineral
- ☐ S4 - Sandy Gleyed Matrix
- ☐ S5 - Sandy Redox
- ☐ S6 - Stripped Matrix
- ☐ S7 - Dark Surface (LRR R, MLRA 149B)
- ☐ S8 - Polyvalue Below Surface (LRR R, MLRA 149B)
- ☐ S9 - Thin Dark Surface (LRR R, MLRA 149B)
- ☐ F1 - Loamy Mucky Mineral (LRR K, L)
- ☐ F2 - Loamy Gleyed Matrix
- ☐ F3 - Depleted Matrix
- ☑ F6 - Redox Dark Surface
- ☐ F7 - Depleted Dark Surface
- ☐ F8 - Redox Depressions

Indicators for Problematic Soils [1]
- ☐ A10 - 2 cm Muck (LRR K, L, MLRA 149B)
- ☐ A16 - Coast Prairie Redox (LRR K, L, R)
- ☐ S3 - 5cm Mucky Peat of Peat (**LRR K, L, R**)
- ☐ S7 - Dark Surface (LRR K, L, M)
- ☐ S8 - Polyvalue Below Surface (**LRR K, L**)
- ☐ S9 - Thin Dark Surface (**LRR K, L**)
- ☐ F12 - Iron-Manganese Masses (**LRR K, L, R**)
- ☐ F19 - Piedmont Floodplain Soils (**MLRA 149B**)
- ☐ TA6 - Mesic Spodic (**MLRA 144A, 145, 149B**)
- ☐ TF2 - Red Parent Material
- ☐ TF12 - Very Shallow Dark Surface
- ☐ Other (Explain in Remarks)

[1] Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (If Observed) Type: LEDGE Depth: 14

Hydric Soil Present? ☑ Yes ☐ No

Remarks:

TETRA TECH

WETLAND DETERMINATION DATA FORM

Northeast and Northcentral Region

Project/Site: Western Maine Renewable Energy Project Wetland ID: W81EI Sample Point **Wetland**

VEGETATION (Species identified in all uppercase are non-native species.)

Tree Stratum (Plot size: 10 meter radius)

	Species Name	% Cover	Dominant	Ind.Status
1.	*Acer rubrum*	20	Y	FAC
2.	*Picea mariana*	20	Y	FACW
3.	*Picea rubens*	10	N	FACU
4.	*Betula alleghaniensis*	20	Y	FAC
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	70		

Sapling/Shrub Stratum (Plot size: 5 meter radius)

1.	*Acer rubrum*	5	N	FAC
2.	*Thuja occidentalis*	5	N	FACW
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	10		

Herb Stratum (Plot size: 2 meter radius)

1.	*Phegopteris hexagonoptera*	2	n	FACU
2.	*Tiarella cordifolia*	10	Y	FACU
3.	*Osmundastrum cinnamomeum*	15	Y	FACW
4.	*Onoclea sensibilis*	5	n	FACW
5.	*Osmunda spectabilis*	5	n	OBL
6	*Calamagrostis canadensis*	1	n	OBL
7.	*Cornus canadensis*	1	n	FAC
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
11.	--	--	--	--
12.	--	--	--	--
13.	--	--	--	--
14.	--	--	--	--
15.	--	--	--	--
	Total Cover =	39		

Woody Vine Stratum (Plot size: 10 meter radius)

1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
	Total Cover =	0		

Remarks:

Dominance Test Worksheet

Number of Dominant Species that are OBL, FACW, or FAC: 4 (A)

Total Number of Dominant Species Across All Strata: 5 (B)

Percent of Dominant Species That Are OBL, FACW, or FAC: ***80.0%*** (A/B)

Prevalence Index Worksheet

Total % Cover of:		Multiply by:	
OBL spp.	6	x 1 =	6
FACW spp.	45	x 2 =	90
FAC spp.	46	x 3 =	138
FACU spp.	22	x 4 =	88
UPL spp.	0	x 5 =	0
Total	119 (A)		322 (B)

Prevalence Index = B/A = ***2.706***

Hydrophytic Vegetation Indicators:

- ☐ Yes ☑ No Rapid Test for Hydrophytic Vegetation
- ☑ Yes ☐ No Dominance Test is > 50%
- ☑ Yes ☐ No Prevalence Index is ≤ 3.0 *
- ☐ Yes ☑ No Morphological Adaptations (Explain) *
- ☐ Yes ☑ No Problem Hydrophytic Vegetation (Explain) *

* Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic.

Definitions of Vegetation Strata:

Tree - Woody plants 3 in. (7.6cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/Shrub - Woody plants less than 3 in. DBH and greater than 3.28 ft. tall.

Herb - All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft. tall.

Woody Vines - All woody vines greater than 3.28 ft. in height.

Hydrophytic Vegetation Present ☑ Yes ☐ No

Additional Remarks:

TETRA TECH

WETLAND DETERMINATION DATA FORM
Northeast and Northcentral Region

Project/Site:	Western Maine Renewable Energy Project	Project #: 194-7130	Date: 09/09/20
Applicant:	Western Maine Renewables, LLC		County: Somerset
Investigator #1:	Emmy Irvin	Investigator #2:	State: ME
Soil Unit:	Monarda-Telos complex, 0 to 8 percent slopes, very stony	NWI/WWI Classification: Upland	Wetland ID: W92EI
Landform:	Terrace	Local Relief: Linear	Sample Point: **Upland**
Slope (%):	See topo map	Latitude: 45.15494990000 Longitude: -69.852701855 Datum: NAD 83	

Are climatic/hydrologic conditions on the site typical for this time of year? (If no, explain in remarks) ☐ Yes ☑ No

Are Vegetation ☑, Soil ☐, or Hydrology ☐ significantly disturbed?
Are Vegetation ☐, Soil ☐, or Hydrology ☐ naturally problematic?

Are normal circumstances present? ☐ Yes ☑ No

SUMMARY OF FINDINGS

Hydrophytic Vegetation Present?	☐ Yes ☑ No	Hydric Soils Present?	☐ Yes ☑ No
Wetland Hydrology Present?	☐ Yes ☑ No	Is This Sampling Point Within A Wetland?	☐ **Yes** ☑ **No**

Remarks: Statewide drought; wetland occurs within USAF Radar Station field

HYDROLOGY

Wetland Hydrology Indicators (Check here if indicators are not present): ☑

Primary:
- ☐ A1 - Surface Water
- ☐ A2 - High Water Table
- ☐ A3 - Saturation
- ☐ B1 - Water Marks
- ☐ B2 - Sediment Deposits
- ☐ B3 - Drift Deposits
- ☐ B4 - Algal Mat or Crust
- ☐ B5 - Iron Deposits
- ☐ B7 - Inundation Visible on Aerial Imagery
- ☐ B8 - Sparsely Vegetated Concave Surface
- ☐ B9 - Water-Stained Leaves
- ☐ B13 - Aquatic Fauna
- ☐ B15 - Marl Deposits
- ☐ C1 - Hydrogen Sulfide Odor
- ☐ C3 - Oxidized Rhizospheres on Living Roots
- ☐ C4 - Presence of Reduced Iron
- ☐ C6 - Recent Iron Reduction in Tilled Soils
- ☐ C7 - Thin Muck Surface
- ☐ Other (Explain in Remarks)

Secondary:
- ☐ B6 - Surface Soil Cracks
- ☐ B10 - Drainage Patterns
- ☐ B16 - Moss Trim Lines
- ☐ C2 - Dry-Season Water Table
- ☐ C8 - Crayfish Burrows
- ☐ C9 - Saturation Visible on Aerial Imagery
- ☐ D1 - Stunted or Stressed Plants
- ☐ D2 - Geomorphic Position
- ☐ D3 - Shallow Aquitard
- ☐ D4 - Microtopographic Relief
- ☐ D5 - FAC-Neutral Test

Field Observations:

Surface Water Present?	☐ Yes ☑ No	Depth:	(in.)
Water Table Present?	☐ Yes ☑ No	Depth:	(in.)
Saturation Present?	☐ Yes ☑ No	Depth:	(in.)

Wetland Hydrology Present? ☐ Yes ☑ No

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available: N/A

Remarks: Statewide drought

SOILS

Map Unit Name: Monarda-Telos complex, 0 to 8 percent slopes, very stony Series Drainage Class: Well Drained

Taxonomy (Subgroup): Loamy, isotic, frigid Lithic Haplohumods

Profile Description (Describe to the depth needed to document the indicator or confirm the absence of indicators.) (Type: C=Concentration, D=Depletion, RM=Reduced Matrix, CS=Covered/Coated Sand Grains; Location: PL=Pore Lining, M=Matrix)

Top Depth	Bottom Depth	Horizon	Matrix Color (Moist)		Matrix %	Mottles Color (Moist)		Mottles %	Mottles Type	Mottles Location	Texture (e.g. clay, sand, loam)
0	2	A	10YR	2/1	100	--	--	--	--	--	fine sandy loam
2	3	E	10YR	6/1	100	--	--	--	--	--	fine sandy loam
3	12	B	10YR	2/1	100	--	--	--	--	--	fine sandy loam
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--

NRCS Hydric Soil Field Indicators (check here if indicators are not present): ☑

- ☐ A1- Histosol
- ☐ A2 - Histic Epipedon
- ☐ A3 - Black Histic
- ☐ A4 - Hydrogen Sulfide
- ☐ A5 - Stratified Layers
- ☐ A11 - Depleted Below Dark Surface
- ☐ A12 - Thick Dark Surface
- ☐ S1 - Sandy Muck Mineral
- ☐ S4 - Sandy Gleyed Matrix
- ☐ S5 - Sandy Redox
- ☐ S6 - Stripped Matrix
- ☐ S7 - Dark Surface (LRR R, MLRA 149B)
- ☐ S8 - Polyvalue Below Surface (LRR R, MLRA 149B)
- ☐ S9 - Thin Dark Surface (LRR R, MLRA 149B)
- ☐ F1 - Loamy Mucky Mineral (LRR K, L)
- ☐ F2 - Loamy Gleyed Matrix
- ☐ F3 - Depleted Matrix
- ☐ F6 - Redox Dark Surface
- ☐ F7 - Depleted Dark Surface
- ☐ F8 - Redox Depressions

Indicators for Problematic Soils [1]
- ☐ A10 - 2 cm Muck (LRR K, L, MLRA 149B)
- ☐ A16 - Coast Prairie Redox (LRR K, L, R)
- ☐ S3 - 5cm Mucky Peat of Peat (**LRR K, L, R**)
- ☐ S7 - Dark Surface (LRR K, L, M)
- ☐ S8 - Polyvalue Below Surface (**LRR K, L**)
- ☐ S9 - Thin Dark Surface (**LRR K, L**)
- ☐ F12 - Iron-Manganese Masses (**LRR K, L, R**)
- ☐ F19 - Piedmont Floodplain Soils (**MLRA 149B**)
- ☐ TA6 - Mesic Spodic (**MLRA 144A, 145, 149B**)
- ☐ TF2 - Red Parent Material
- ☐ TF12 - Very Shallow Dark Surface
- ☐ Other (Explain in Remarks)

[1] Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (If Observed) Type: LEDGE Depth: 12

Hydric Soil Present? ☐ Yes ☑ No

Remarks:

TETRA TECH

WETLAND DETERMINATION DATA FORM

Northeast and Northcentral Region

Project/Site: Western Maine Renewable Energy Project | Wetland ID: W92EI | Sample Point **Upland**

VEGETATION (Species identified in all uppercase are non-native species.)

Tree Stratum (Plot size: 10 meter radius)

	Species Name	% Cover	Dominant	Ind.Status
1.	*Tsuga canadensis*	10	Y	FACU
2.	*Thuja occidentalis*	5	N	FACW
3.	*Betula papyrifera*	10	Y	FACU
4.	*Acer rubrum*	5	N	FAC
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	30		

Sapling/Shrub Stratum (Plot size: 5 meter radius)

1.	*Thuja occidentalis*	15	Y	FACW
2.	*Betula papyrifera*	20	Y	FACU
3.	*Ilex verticillata*	5	N	FACW
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	40		

Herb Stratum (Plot size: 2 meter radius)

1.	*Clintonia borealis*	10	Y	FAC
2.	*Cornus canadensis*	10	Y	FAC
3.	*Symphyotrichum ericoides*	10	Y	FACU
4.	*Medeola virginiana*	10	Y	FACU
5.	*Maianthemum canadense*	5	N	FACU
6	*Osmunda claytoniana*	10	Y	FAC
7.	*Symphoricarpos albus*	5	N	FACU
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
11.	--	--	--	--
12.	--	--	--	--
13.	--	--	--	--
14.	--	--	--	--
15.	--	--	--	--
	Total Cover =	60		

Woody Vine Stratum (Plot size: 10 meter radius)

1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
	Total Cover =	0		

Remarks:

Dominance Test Worksheet

Number of Dominant Species that are OBL, FACW, or FAC: 4 (A)

Total Number of Dominant Species Across All Strata: 9 (B)

Percent of Dominant Species That Are OBL, FACW, or FAC: ***44.4%*** (A/B)

Prevalence Index Worksheet

Total % Cover of:		Multiply by:	
OBL spp.	0	x 1 =	0
FACW spp.	25	x 2 =	50
FAC spp.	35	x 3 =	105
FACU spp.	70	x 4 =	280
UPL spp.	0	x 5 =	0
Total	130 (A)		435 (B)

Prevalence Index = B/A = ***3.346***

Hydrophytic Vegetation Indicators:

- ☐ Yes ☑ No Rapid Test for Hydrophytic Vegetation
- ☐ Yes ☑ No Dominance Test is > 50%
- ☐ Yes ☑ No Prevalence Index is ≤ 3.0 *
- ☐ Yes ☑ No Morphological Adaptations (Explain) *
- ☐ Yes ☑ No Problem Hydrophytic Vegetation (Explain) *

* Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic.

Definitions of Vegetation Strata:

Tree - Woody plants 3 in. (7.6cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/Shrub - Woody plants less than 3 in. DBH and greater than 3.28 ft. tall.

Herb - All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft. tall.

Woody Vines - All woody vines greater than 3.28 ft. in height.

Hydrophytic Vegetation Present ☐ Yes ☑ No

Additional Remarks:

TETRA TECH

WETLAND DETERMINATION DATA FORM
Northeast and Northcentral Region

Project/Site:	Western Maine Renewable Energy Project	Project #: 194-7130	Date: 09/09/20
Applicant:	Western Maine Renewables, LLC		County: Somerset
Investigator #1:	Emmy Irvin	Investigator #2:	State: ME
Soil Unit:	Monarda-Telos complex, 0 to 8 percent slopes, very stony	NWI/WWI Classification: PFO	Wetland ID: W92EI
Landform:	Terrace	Local Relief: Linear	Sample Point: **Wetland**
Slope (%):	See topo map	Latitude: 45.155391° Longitude: -69.852149° Datum: NAD 83	

Are climatic/hydrologic conditions on the site typical for this time of year? (If no, explain in remarks) ☐ Yes ☑ No

Are Vegetation ☑, Soil ☐, or Hydrology ☐ significantly disturbed? Are normal circumstances present? ☐ Yes ☑ No

Are Vegetation ☐, Soil ☐, or Hydrology ☐ naturally problematic?

SUMMARY OF FINDINGS

Hydrophytic Vegetation Present?	☑ Yes ☐ No	Hydric Soils Present?	☑ Yes ☐ No
Wetland Hydrology Present?	☑ Yes ☐ No	Is This Sampling Point Within A Wetland?	☑ **Yes** ☐ **No**

Remarks: Statewide drought; wetland occurs within USAF Radar Station field

HYDROLOGY

Wetland Hydrology Indicators (Check here if indicators are not present): ☐

Primary:

- ☐ A1 - Surface Water
- ☐ A2 - High Water Table
- ☐ A3 - Saturation
- ☐ B1 - Water Marks
- ☐ B2 - Sediment Deposits
- ☐ B3 - Drift Deposits
- ☐ B4 - Algal Mat or Crust
- ☐ B5 - Iron Deposits
- ☐ B7 - Inundation Visible on Aerial Imagery
- ☐ B8 - Sparsely Vegetated Concave Surface
- ☑ B9 - Water-Stained Leaves
- ☐ B13 - Aquatic Fauna
- ☐ B15 - Marl Deposits
- ☐ C1 - Hydrogen Sulfide Odor
- ☐ C3 - Oxidized Rhizospheres on Living Roots
- ☐ C4 - Presence of Reduced Iron
- ☐ C6 - Recent Iron Reduction in Tilled Soils
- ☐ C7 - Thin Muck Surface
- ☐ Other (Explain in Remarks)

Secondary:

- ☐ B6 - Surface Soil Cracks
- ☐ B10 - Drainage Patterns
- ☐ B16 - Moss Trim Lines
- ☐ C2 - Dry-Season Water Table
- ☐ C8 - Crayfish Burrows
- ☐ C9 - Saturation Visible on Aerial Imagery
- ☐ D1 - Stunted or Stressed Plants
- ☐ D2 - Geomorphic Position
- ☐ D3 - Shallow Aquitard
- ☐ D4 - Microtopographic Relief
- ☐ D5 - FAC-Neutral Test

Field Observations:

Surface Water Present?	☐ Yes ☑ No	Depth:	(in.)
Water Table Present?	☐ Yes ☑ No	Depth:	(in.)
Saturation Present?	☐ Yes ☑ No	Depth:	(in.)

Wetland Hydrology Present? ☑ Yes ☐ No

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available: N/A

Remarks: Statewide drought

SOILS

Map Unit Name: Monarda-Telos complex, 0 to 8 percent slopes, very stony Series Drainage Class: Well Drained

Taxonomy (Subgroup): Loamy, isotic, frigid Lithic Haplohumods

Profile Description (Describe to the depth needed to document the indicator or confirm the absence of indicators.) (Type: C=Concentration, D=Depletion, RM=Reduced Matrix, CS=Covered/Coated Sand Grains; Location: PL=Pore Lining, M=Matrix)

Top Depth	Bottom Depth	Horizon	Matrix Color (Moist)		Matrix %	Mottles Color (Moist)		Mottles %	Mottles Type	Mottles Location	Texture (e.g. clay, sand, loam)
0	8	1	10YR	4/1	80	10YR	3/6	20	C	M	fine sandy loam
8	18	2	2.5Y	5/2	75	10YR	3/6	25	C	M	fine sandy loam
--	--	--	--	--	--	--	--	--	--	--	--
--		--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--

NRCS Hydric Soil Field Indicators (check here if indicators are not present): ☐

- ☐ A1- Histosol
- ☐ A2 - Histic Epipedon
- ☐ A3 - Black Histic
- ☐ A4 - Hydrogen Sulfide
- ☐ A5 - Stratified Layers
- ☐ A11 - Depleted Below Dark Surface
- ☐ A12 - Thick Dark Surface
- ☐ S1 - Sandy Muck Mineral
- ☐ S4 - Sandy Gleyed Matrix
- ☐ S5 - Sandy Redox
- ☐ S6 - Stripped Matrix
- ☐ S7 - Dark Surface (LRR R, MLRA 149B)
- ☐ S8 - Polyvalue Below Surface (LRR R, MLRA 149B)
- ☐ S9 - Thin Dark Surface (LRR R, MLRA 149B)
- ☐ F1 - Loamy Mucky Mineral (LRR K, L)
- ☐ F2 - Loamy Gleyed Matrix
- ☑ F3 - Depleted Matrix
- ☐ F6 - Redox Dark Surface
- ☐ F7 - Depleted Dark Surface
- ☐ F8 - Redox Depressions

Indicators for Problematic Soils [1]

- ☐ A10 - 2 cm Muck (LRR K, L, MLRA 149B)
- ☐ A16 - Coast Prairie Redox (LRR K, L, R)
- ☐ S3 - 5cm Mucky Peat of Peat (**LRR K, L, R**)
- ☐ S7 - Dark Surface (LRR K, L, M)
- ☐ S8 - Polyvalue Below Surface (**LRR K, L**)
- ☐ S9 - Thin Dark Surface (**LRR K, L**)
- ☐ F12 - Iron-Manganese Masses (**LRR K, L, R**)
- ☐ F19 - Piedmont Floodplain Soils (**MLRA 149B**)
- ☐ TA6 - Mesic Spodic (**MLRA 144A, 145, 149B**)
- ☐ TF2 - Red Parent Material
- ☐ TF12 - Very Shallow Dark Surface
- ☐ Other (Explain in Remarks)

[1] Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (If Observed) Type: NR Depth:

Hydric Soil Present? ☑ Yes ☐ No

Remarks:

TETRA TECH

WETLAND DETERMINATION DATA FORM

Northeast and Northcentral Region

Project/Site: Western Maine Renewable Energy Project Wetland ID: W92EI Sample Point **Wetland**

VEGETATION (Species identified in all uppercase are non-native species.)

Tree Stratum (Plot size: 10 meter radius)

	Species Name	% Cover	Dominant	Ind.Status
1.	*Thuja occidentalis*	20	Y	FACW
2.	*Betula alleghaniensis*	15	Y	FAC
3.	*Picea mariana*	10	Y	FACW
4.	*Pinus strobus*	2	N	FACU
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	47		

Sapling/Shrub Stratum (Plot size: 5 meter radius)

1.	*Spiraea alba*	10	Y	FACW
2.	*Thuja occidentalis*	15	Y	FACW
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	25		

Herb Stratum (Plot size: 2 meter radius)

1.	*Scirpus cyperinus*	10	Y	OBL
2.	*Eutrochium fistulosum*	5	N	FACW
3.	*Achillea millefolium*	10	Y	FACU
4.	*Onoclea sensibilis*	20	Y	FACW
5.	*Carex stricta*	5	N	OBL
6	*Anaphalis margaritacea*	5	N	FACU
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
11.	--	--	--	--
12.	--	--	--	--
13.	--	--	--	--
14.	--	--	--	--
15.	--	--	--	--
	Total Cover =	55		

Woody Vine Stratum (Plot size: 10 meter radius)

1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
	Total Cover =	0		

Dominance Test Worksheet

Number of Dominant Species that are OBL, FACW, or FAC: 7 (A)

Total Number of Dominant Species Across All Strata: 8 (B)

Percent of Dominant Species That Are OBL, FACW, or FAC: ***87.5%*** (A/B)

Prevalence Index Worksheet

Total % Cover of:		Multiply by:	
OBL spp.	15	x 1 =	15
FACW spp.	80	x 2 =	160
FAC spp.	15	x 3 =	45
FACU spp.	17	x 4 =	68
UPL spp.	0	x 5 =	0
Total	127 (A)		288 (B)

Prevalence Index = B/A = ***2.268***

Hydrophytic Vegetation Indicators:

- ☐ Yes ☑ No Rapid Test for Hydrophytic Vegetation
- ☑ Yes ☐ No Dominance Test is > 50%
- ☑ Yes ☐ No Prevalence Index is ≤ 3.0 *
- ☐ Yes ☑ No Morphological Adaptations (Explain) *
- ☐ Yes ☑ No Problem Hydrophytic Vegetation (Explain) *

* Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic.

Definitions of Vegetation Strata:

Tree - Woody plants 3 in. (7.6cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/Shrub - Woody plants less than 3 in. DBH and greater than 3.28 ft. tall.

Herb - All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft. tall.

Woody Vines - All woody vines greater than 3.28 ft. in height.

Hydrophytic Vegetation Present ☑ Yes ☐ No

Remarks:

Additional Remarks:

TETRA TECH

WETLAND DETERMINATION DATA FORM
Northeast and Northcentral Region

Project/Site:	Western Maine Renewable Energy Project	Project #: 194-7130	Date: 09/09/20
Applicant:	Western Maine Renewables, LLC		County: Somerset
Investigator #1:	Emmy Irvin	Investigator #2:	State: ME
Soil Unit:	Monarda-Burnham complex, 0 to 3 percent slopes, very stony	NWI/WWI Classification: Upland	Wetland ID: W98EI
Landform:	Terrace	Local Relief: Linear	Sample Point: **Upland**
Slope (%):	See topo map	Latitude: 45.15602402400 Longitude: -69.852326 Datum: NAD 83	

Are climatic/hydrologic conditions on the site typical for this time of year? (If no, explain in remarks) ☐ Yes ☑ No

Are Vegetation ☑, Soil ☐, or Hydrology ☐significantly disturbed? Are normal circumstances present? ☐ Yes ☑ No

Are Vegetation ☐, Soil ☐, or Hydrology ☐naturally problematic?

SUMMARY OF FINDINGS

Hydrophytic Vegetation Present?	☑ Yes ☐ No	Hydric Soils Present?	☐ Yes ☑ No
Wetland Hydrology Present?	☐ Yes ☑ No	Is This Sampling Point Within A Wetland?	☐ **Yes** ☑ **No**

Remarks: Statewide drought; occurs in USAF Radar Station field

HYDROLOGY

Wetland Hydrology Indicators (Check here if indicators are not present): ☑

Primary:
- ☐ A1 - Surface Water
- ☐ A2 - High Water Table
- ☐ A3 - Saturation
- ☐ B1 - Water Marks
- ☐ B2 - Sediment Deposits
- ☐ B3 - Drift Deposits
- ☐ B4 - Algal Mat or Crust
- ☐ B5 - Iron Deposits
- ☐ B7 - Inundation Visible on Aerial Imagery
- ☐ B8 - Sparsely Vegetated Concave Surface
- ☐ B9 - Water-Stained Leaves
- ☐ B13 - Aquatic Fauna
- ☐ B15 - Marl Deposits
- ☐ C1 - Hydrogen Sulfide Odor
- ☐ C3 - Oxidized Rhizospheres on Living Roots
- ☐ C4 - Presence of Reduced Iron
- ☐ C6 - Recent Iron Reduction in Tilled Soils
- ☐ C7 - Thin Muck Surface
- ☐ Other (Explain in Remarks)

Secondary:
- ☐ B6 - Surface Soil Cracks
- ☐ B10 - Drainage Patterns
- ☐ B16 - Moss Trim Lines
- ☐ C2 - Dry-Season Water Table
- ☐ C8 - Crayfish Burrows
- ☐ C9 - Saturation Visible on Aerial Imagery
- ☐ D1 - Stunted or Stressed Plants
- ☐ D2 - Geomorphic Position
- ☐ D3 - Shallow Aquitard
- ☐ D4 - Microtopographic Relief
- ☐ D5 - FAC-Neutral Test

Field Observations:

Surface Water Present?	☐ Yes ☑ No	Depth:	(in.)
Water Table Present?	☐ Yes ☑ No	Depth:	(in.)
Saturation Present?	☐ Yes ☑ No	Depth:	(in.)

Wetland Hydrology Present? ☐ Yes ☑ No

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available: N/A

Remarks: Statewide drought

SOILS

Map Unit Name: Monarda-Burnham complex, 0 to 3 percent slopes, very stony Series Drainage Class: Well Drained

Taxonomy (Subgroup): Loamy, isotic, frigid Lithic Haplohumods

Profile Description (Describe to the depth needed to document the indicator or confirm the absence of indicators.) (Type: C=Concentration, D=Depletion, RM=Reduced Matrix, CS=Covered/Coated Sand Grains; Location: PL=Pore Lining, M=Matrix)

Top Depth	Bottom Depth	Horizon	Matrix Color (Moist)		Matrix %	Mottles Color (Moist)		Mottles %	Mottles Type	Mottles Location	Texture (e.g. clay, sand, loam)
0	8	1	10YR	3/1	100	--	--	--	--	--	fine sandy loam
8	11	2	2.5Y	5/2	100	--	--	--	--	--	fine sandy loam
--	--	--	--	--	--	--	--	--	--	--	
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--

NRCS Hydric Soil Field Indicators (check here if indicators are not present): ☑
- ☐ A1- Histosol
- ☐ A2 - Histic Epipedon
- ☐ A3 - Black Histic
- ☐ A4 - Hydrogen Sulfide
- ☐ A5 - Stratified Layers
- ☐ A11 - Depleted Below Dark Surface
- ☐ A12 - Thick Dark Surface
- ☐ S1 - Sandy Muck Mineral
- ☐ S4 - Sandy Gleyed Matrix
- ☐ S5 - Sandy Redox
- ☐ S6 - Stripped Matrix
- ☐ S7 - Dark Surface (LRR R, MLRA 149B)
- ☐ S8 - Polyvalue Below Surface (LRR R, MLRA 149B)
- ☐ S9 - Thin Dark Surface (LRR R, MLRA 149B)
- ☐ F1 - Loamy Mucky Mineral (LRR K, L)
- ☐ F2 - Loamy Gleyed Matrix
- ☐ F3 - Depleted Matrix
- ☐ F6 - Redox Dark Surface
- ☐ F7 - Depleted Dark Surface
- ☐ F8 - Redox Depressions

Indicators for Problematic Soils [1]
- ☐ A10 - 2 cm Muck (LRR K, L, MLRA 149B)
- ☐ A16 - Coast Prairie Redox (LRR K, L, R)
- ☐ S3 - 5cm Mucky Peat of Peat (**LRR K, L, R**)
- ☐ S7 - Dark Surface (LRR K, L, M)
- ☐ S8 - Polyvalue Below Surface (**LRR K, L**)
- ☐ S9 - Thin Dark Surface (**LRR K, L**)
- ☐ F12 - Iron-Manganese Masses (**LRR K, L, R**)
- ☐ F19 - Piedmont Floodplain Soils (**MLRA 149B**)
- ☐ TA6 - Mesic Spodic (**MLRA 144A, 145, 149B**)
- ☐ TF2 - Red Parent Material
- ☐ TF12 - Very Shallow Dark Surface
- ☐ Other (Explain in Remarks)

[1] Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (If Observed) Type: LEDGE Depth: 9

Hydric Soil Present? ☐ Yes ☑ No

Remarks:

TETRA TECH

WETLAND DETERMINATION DATA FORM

Northeast and Northcentral Region

Project/Site: Western Maine Renewable Energy Project | Wetland ID: W98EI | Sample Point **Upland**

VEGETATION (Species identified in all uppercase are non-native species.)

Tree Stratum (Plot size: 10 meter radius)

	Species Name	% Cover	Dominant	Ind.Status
1.	*Acer rubrum*	15	Y	FAC
2.	*Thuja occidentalis*	5	N	FACW
3.	*Betula papyrifera*	15	Y	FACU
4.	*Tsuga canadensis*	15	Y	FACU
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	50		

Sapling/Shrub Stratum (Plot size: 5 meter radius)

1.	*Acer rubrum*	5	N	FAC
2.	*Ilex verticillata*	5	N	FACW
3.	*Tsuga canadensis*	5	N	FACU
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	15		

Herb Stratum (Plot size: 2 meter radius)

1.	*Cornus canadensis*	80	Y	FAC
2.	*Scirpus cyperinus*	10	N	OBL
3.	*Symphyotrichum ericoides*	15	N	FACU
4.	*Gaultheria hispidula*	20	Y	FACW
5.	--	--	--	--
6	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
11.	--	--	--	--
12.	--	--	--	--
13.	--	--	--	--
14.	--	--	--	--
15.	--	--	--	--
	Total Cover =	125		

Woody Vine Stratum (Plot size: 10 meter radius)

1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
	Total Cover =	0		

Remarks:

Dominance Test Worksheet

Number of Dominant Species that are OBL, FACW, or FAC: 3 (A)

Total Number of Dominant Species Across All Strata: 5 (B)

Percent of Dominant Species That Are OBL, FACW, or FAC: ***60.0%*** (A/B)

Prevalence Index Worksheet

Total % Cover of:		Multiply by:	
OBL spp.	10	x 1 =	10
FACW spp.	30	x 2 =	60
FAC spp.	100	x 3 =	300
FACU spp.	50	x 4 =	200
UPL spp.	0	x 5 =	0
Total	190 (A)		570 (B)

Prevalence Index = B/A = ***3.000***

Hydrophytic Vegetation Indicators:

- ☐ Yes ☑ No Rapid Test for Hydrophytic Vegetation
- ☑ Yes ☐ No Dominance Test is > 50%
- ☑ Yes ☐ No Prevalence Index is ≤ 3.0 *
- ☐ Yes ☑ No Morphological Adaptations (Explain) *
- ☐ Yes ☑ No Problem Hydrophytic Vegetation (Explain) *

* Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic.

Definitions of Vegetation Strata:

Tree - Woody plants 3 in. (7.6cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/Shrub - Woody plants less than 3 in. DBH and greater than 3.28 ft. tall.

Herb - All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft. tall.

Woody Vines - All woody vines greater than 3.28 ft. in height.

Hydrophytic Vegetation Present ☑ Yes ☐ No

Additional Remarks:

TETRA TECH

WETLAND DETERMINATION DATA FORM
Northeast and Northcentral Region

Project/Site:	Western Maine Renewable Energy Project	Project #: 194-7130	Date: 09/09/20
Applicant:	Western Maine Renewables, LLC		County: Somerset
Investigator #1:	Emmy Irvin	Investigator #2:	State: ME
Soil Unit:	Monarda-Telos complex, 0 to 8 percent slopes, very stony	NWI/WWI Classification: PEM/PSS	Wetland ID: W98EI
Landform:	Terrace	Local Relief: Linear	Sample Point: **Wetland**
Slope (%):	See topo map	Latitude: 45.156135° Longitude: -69.852196° Datum: NAD 83	

Are climatic/hydrologic conditions on the site typical for this time of year? (If no, explain in remarks) ☐ Yes ☑ No

Are Vegetation ☑, Soil ☐, or Hydrology ☐significantly disturbed? Are normal circumstances present? ☐ Yes ☑ No

Are Vegetation ☐, Soil ☐, or Hydrology ☐naturally problematic?

SUMMARY OF FINDINGS

Hydrophytic Vegetation Present?	☑ Yes ☐ No	Hydric Soils Present?	☑ Yes ☐ No
Wetland Hydrology Present?	☑ Yes ☐ No	Is This Sampling Point Within A Wetland?	☑ **Yes** ☐ **No**

Remarks: Statewide drought; occurs in USAF Radar Station field

HYDROLOGY

Wetland Hydrology Indicators (Check here if indicators are not present): ☑

Primary:
- ☐ A1 - Surface Water
- ☐ A2 - High Water Table
- ☑ A3 - Saturation
- ☐ B1 - Water Marks
- ☐ B2 - Sediment Deposits
- ☐ B3 - Drift Deposits
- ☐ B4 - Algal Mat or Crust
- ☐ B5 - Iron Deposits
- ☐ B7 - Inundation Visible on Aerial Imagery
- ☐ B8 - Sparsely Vegetated Concave Surface
- ☐ B9 - Water-Stained Leaves
- ☐ B13 - Aquatic Fauna
- ☐ B15 - Marl Deposits
- ☐ C1 - Hydrogen Sulfide Odor
- ☐ C3 - Oxidized Rhizospheres on Living Roots
- ☐ C4 - Presence of Reduced Iron
- ☐ C6 - Recent Iron Reduction in Tilled Soils
- ☐ C7 - Thin Muck Surface
- ☐ Other (Explain in Remarks)

Secondary:
- ☐ B6 - Surface Soil Cracks
- ☐ B10 - Drainage Patterns
- ☐ B16 - Moss Trim Lines
- ☐ C2 - Dry-Season Water Table
- ☐ C8 - Crayfish Burrows
- ☐ C9 - Saturation Visible on Aerial Imagery
- ☐ D1 - Stunted or Stressed Plants
- ☐ D2 - Geomorphic Position
- ☐ D3 - Shallow Aquitard
- ☑ D4 - Microtopographic Relief
- ☐ D5 - FAC-Neutral Test

Field Observations:

Surface Water Present?	☐ Yes	☑ No	Depth:	(in.)
Water Table Present?	☐ Yes	☑ No	Depth:	(in.)
Saturation Present?	☑ Yes	☐ No	Depth: 10	(in.)

Wetland Hydrology Present? ☑ Yes ☐ No

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available: N/A

Remarks: Statewide drought

SOILS

Map Unit Name: Monarda-Telos complex, 0 to 8 percent slopes, very stony Series Drainage Class: Poorly drained

Taxonomy (Subgroup): Loamy, mixed, active, acid, frigid, shallow Aeric Endoaquepts

Profile Description (Describe to the depth needed to document the indicator or confirm the absence of indicators.) (Type: C=Concentration, D=Depletion, RM=Reduced Matrix, CS=Covered/Coated Sand Grains; Location: PL=Pore Lining, M=Matrix)

Top Depth	Bottom Depth	Horizon	Matrix Color (Moist)		Matrix %	Mottles Color (Moist)		Mottles %	Mottles Type	Mottles Location	Texture (e.g. clay, sand, loam)
0	14	1	--	black	organic	--	--	--	--	--	muck
14	19	2	10YR	5/1	100	--	--	--	--	--	fine sandy loam
--	--	--	--	--	--	--	--	--	--	--	
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--

NRCS Hydric Soil Field Indicators (check here if indicators are not present): ☐

- ☐ A1- Histosol
- ☑ A2 - Histic Epipedon
- ☐ A3 - Black Histic
- ☐ A4 - Hydrogen Sulfide
- ☐ A5 - Stratified Layers
- ☐ A11 - Depleted Below Dark Surface
- ☐ A12 - Thick Dark Surface
- ☐ S1 - Sandy Muck Mineral
- ☐ S4 - Sandy Gleyed Matrix
- ☐ S5 - Sandy Redox
- ☐ S6 - Stripped Matrix
- ☐ S7 - Dark Surface (LRR R, MLRA 149B)
- ☐ S8 - Polyvalue Below Surface (LRR R, MLRA 149B)
- ☐ S9 - Thin Dark Surface (LRR R, MLRA 149B)
- ☐ F1 - Loamy Mucky Mineral (LRR K, L)
- ☐ F2 - Loamy Gleyed Matrix
- ☐ F3 - Depleted Matrix
- ☐ F6 - Redox Dark Surface
- ☐ F7 - Depleted Dark Surface
- ☐ F8 - Redox Depressions

Indicators for Problematic Soils [1]
- ☐ A10 - 2 cm Muck (LRR K, L, MLRA 149B)
- ☐ A16 - Coast Prairie Redox (LRR K, L, R)
- ☐ S3 - 5cm Mucky Peat of Peat (**LRR K, L, R**)
- ☐ S7 - Dark Surface (LRR K, L, M)
- ☐ S8 - Polyvalue Below Surface (**LRR K, L**)
- ☐ S9 - Thin Dark Surface (**LRR K, L**)
- ☐ F12 - Iron-Manganese Masses (**LRR K, L, R**)
- ☐ F19 - Piedmont Floodplain Soils (**MLRA 149B**)
- ☐ TA6 - Mesic Spodic (**MLRA 144A, 145, 149B**)
- ☐ TF2 - Red Parent Material
- ☐ TF12 - Very Shallow Dark Surface
- ☐ Other (Explain in Remarks)

[1] Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (If Observed) Type: NR Depth:

Hydric Soil Present? ☑ Yes ☐ No

Remarks:

TETRA TECH

WETLAND DETERMINATION DATA FORM

Northeast and Northcentral Region

Project/Site: Western Maine Renewable Energy Project Wetland ID: W98EI Sample Point **Wetland**

VEGETATION (Species identified in all uppercase are non-native species.)

Tree Stratum (Plot size: 10 meter radius)

	Species Name	% Cover	Dominant	Ind.Status
1.	*Salix bebbiana*	10	Y	FACW
2.	*Thuja occidentalis*	10	N	FACW
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	20		

Sapling/Shrub Stratum (Plot size: 5 meter radius)

1.	*Thuja occidentalis*	10	Y	FACW
2.	*Salix bebbiana*	5	N	FACW
3.	*Ilex verticillata*	5	N	FACW
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	20		

Herb Stratum (Plot size: 2 meter radius)

1.	*Equisetum arvense*	5	N	FAC
2.	*Scirpus cyperinus*	80	Y	OBL
3.	*Symphyotrichum novae-angliae*	5	N	FACW
4.	*Spiraea alba*	20	Y	FACW
5.	--	--	--	--
6	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
11.	--	--	--	--
12.	--	--	--	--
13.	--	--	--	--
14.	--	--	--	--
15.	--	--	--	--
	Total Cover =	110		

Woody Vine Stratum (Plot size: 10 meter radius)

1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
	Total Cover =	0		

Remarks:

Dominance Test Worksheet

Number of Dominant Species that are OBL, FACW, or FAC: 4 (A)

Total Number of Dominant Species Across All Strata: 4 (B)

Percent of Dominant Species That Are OBL, FACW, or FAC: ***100.0%*** (A/B)

Prevalence Index Worksheet

Total % Cover of:		Multiply by:	
OBL spp.	80	x 1 =	80
FACW spp.	65	x 2 =	130
FAC spp.	5	x 3 =	15
FACU spp.	0	x 4 =	0
UPL spp.	0	x 5 =	0
Total	150 (A)		225 (B)

Prevalence Index = B/A = ***1.500***

Hydrophytic Vegetation Indicators:

- ☐ Yes ☑ No Rapid Test for Hydrophytic Vegetation
- ☑ Yes ☐ No Dominance Test is > 50%
- ☑ Yes ☐ No Prevalence Index is ≤ 3.0 *
- ☐ Yes ☑ No Morphological Adaptations (Explain) *
- ☐ Yes ☑ No Problem Hydrophytic Vegetation (Explain) *

* Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic.

Definitions of Vegetation Strata:

Tree - Woody plants 3 in. (7.6cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/Shrub - Woody plants less than 3 in. DBH and greater than 3.28 ft. tall.

Herb - All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft. tall.

Woody Vines - All woody vines greater than 3.28 ft. in height.

Hydrophytic Vegetation Present ☑ Yes ☐ No

Additional Remarks:

TETRA TECH

WETLAND DETERMINATION DATA FORM
Northeast and Northcentral Region

Project/Site:	Western Maine Renewable Energy Project	Project #: 194-7130	Date: 09/09/20
Applicant:	Western Maine Renewables, LLC		County: Somerset
Investigator #1:	Emmy Irvin	Investigator #2:	State: ME
Soil Unit:	Monarda-Burnham complex, 0 to 3 percent slopes, very stony	NWI/WWI Classification: Upland	Wetland ID: W99EI
Landform:	Terrace	Local Relief: Linear	Sample Point: **Upland**
Slope (%):	See topo map	Latitude: 45.15602402400 Longitude: -69.852326 Datum: NAD 83	

Are climatic/hydrologic conditions on the site typical for this time of year? (If no, explain in remarks) ☐ Yes ☑ No

Are Vegetation ☐, Soil ☐, or Hydrology ☐significantly disturbed? Are normal circumstances present? ☐ Yes ☑ No

Are Vegetation ☐, Soil ☐, or Hydrology ☐naturally problematic?

SUMMARY OF FINDINGS

Hydrophytic Vegetation Present?	☐ Yes ☑ No	Hydric Soils Present?	☐ Yes ☑ No
Wetland Hydrology Present?	☐ Yes ☑ No	Is This Sampling Point Within A Wetland?	☐ **Yes** ☑ **No**

Remarks: Statewide drought

HYDROLOGY

Wetland Hydrology Indicators (Check here if indicators are not present): ☑

Primary:

- ☐ A1 - Surface Water
- ☐ A2 - High Water Table
- ☐ A3 - Saturation
- ☐ B1 - Water Marks
- ☐ B2 - Sediment Deposits
- ☐ B3 - Drift Deposits
- ☐ B4 - Algal Mat or Crust
- ☐ B5 - Iron Deposits
- ☐ B7 - Inundation Visible on Aerial Imagery
- ☐ B8 - Sparsely Vegetated Concave Surface
- ☐ B9 - Water-Stained Leaves
- ☐ B13 - Aquatic Fauna
- ☐ B15 - Marl Deposits
- ☐ C1 - Hydrogen Sulfide Odor
- ☐ C3 - Oxidized Rhizospheres on Living Roots
- ☐ C4 - Presence of Reduced Iron
- ☐ C6 - Recent Iron Reduction in Tilled Soils
- ☐ C7 - Thin Muck Surface
- ☐ Other (Explain in Remarks)

Secondary:

- ☐ B6 - Surface Soil Cracks
- ☐ B10 - Drainage Patterns
- ☐ B16 - Moss Trim Lines
- ☐ C2 - Dry-Season Water Table
- ☐ C8 - Crayfish Burrows
- ☐ C9 - Saturation Visible on Aerial Imagery
- ☐ D1 - Stunted or Stressed Plants
- ☐ D2 - Geomorphic Position
- ☐ D3 - Shallow Aquitard
- ☐ D4 - Microtopographic Relief
- ☐ D5 - FAC-Neutral Test

Field Observations:

Surface Water Present?	☐ Yes ☑ No	Depth:	(in.)
Water Table Present?	☐ Yes ☑ No	Depth:	(in.)
Saturation Present?	☐ Yes ☑ No	Depth:	(in.)

Wetland Hydrology Present? ☐ Yes ☑ No

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available: N/A

Remarks: Statewide drought

SOILS

Map Unit Name: Monarda-Burnham complex, 0 to 3 percent slopes, very stony Series Drainage Class: Well Drained

Taxonomy (Subgroup): Loamy, isotic, frigid Lithic Haplohumods

Profile Description (Describe to the depth needed to document the indicator or confirm the absence of indicators.) (Type: C=Concentration, D=Depletion, RM=Reduced Matrix, CS=Covered/Coated Sand Grains; Location: PL=Pore Lining, M=Matrix)

Top Depth	Bottom Depth	Horizon	Matrix Color (Moist)		Matrix %	Mottles Color (Moist)		Mottles %	Mottles Type	Mottles Location	Texture (e.g. clay, sand, loam)
0	8	--	10YR	3/1	100	--	--	--	--	--	fine sandy loam
8	12	--	10YR	3/3	100	--	--	--	--	--	fine sandy loam
--	--	--	--	--	--	--	--	--	--	--	
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--

NRCS Hydric Soil Field Indicators (check here if indicators are not present): ☑

- ☐ A1- Histosol
- ☐ A2 - Histic Epipedon
- ☐ A3 - Black Histic
- ☐ A4 - Hydrogen Sulfide
- ☐ A5 - Stratified Layers
- ☐ A11 - Depleted Below Dark Surface
- ☐ A12 - Thick Dark Surface
- ☐ S1 - Sandy Muck Mineral
- ☐ S4 - Sandy Gleyed Matrix
- ☐ S5 - Sandy Redox
- ☐ S6 - Stripped Matrix
- ☐ S7 - Dark Surface (LRR R, MLRA 149B)
- ☐ S8 - Polyvalue Below Surface (LRR R, MLRA 149B)
- ☐ S9 - Thin Dark Surface (LRR R, MLRA 149B)
- ☐ F1 - Loamy Mucky Mineral (LRR K, L)
- ☐ F2 - Loamy Gleyed Matrix
- ☐ F3 - Depleted Matrix
- ☐ F6 - Redox Dark Surface
- ☐ F7 - Depleted Dark Surface
- ☐ F8 - Redox Depressions

Indicators for Problematic Soils [1]

- ☐ A10 - 2 cm Muck (LRR K, L, MLRA 149B)
- ☐ A16 - Coast Prairie Redox (LRR K, L, R)
- ☐ S3 - 5cm Mucky Peat of Peat (**LRR K, L, R**)
- ☐ S7 - Dark Surface (LRR K, L, M)
- ☐ S8 - Polyvalue Below Surface (**LRR K, L**)
- ☐ S9 - Thin Dark Surface (**LRR K, L**)
- ☐ F12 - Iron-Manganese Masses (**LRR K, L, R**)
- ☐ F19 - Piedmont Floodplain Soils (**MLRA 149B**)
- ☐ TA6 - Mesic Spodic (**MLRA 144A, 145, 149B**)
- ☐ TF2 - Red Parent Material
- ☐ TF12 - Very Shallow Dark Surface
- ☐ Other (Explain in Remarks)

[1] Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (If Observed) Type: LEDGE Depth: 12

Hydric Soil Present? ☐ Yes ☑ No

Remarks:

TETRA TECH

WETLAND DETERMINATION DATA FORM

Northeast and Northcentral Region

Project/Site: Western Maine Renewable Energy Project | Wetland ID: W99EI | Sample Point **Upland**

VEGETATION (Species identified in all uppercase are non-native species.)

Tree Stratum (Plot size: 10 meter radius)

	Species Name	% Cover	Dominant	Ind.Status
1.	*Picea rubens*	5	N	FACU
2.	*Picea mariana*	5	N	FACW
3.	*Acer rubrum*	5	N	FAC
4.	*Tsuga canadensis*	1	N	FACU
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	16		

Sapling/Shrub Stratum (Plot size: 5 meter radius)

1.	*Betula papyrifera*	25	Y	FACU
2.	*Salix alba*	5	N	FACW
3.	*Tsuga canadensis*	1	N	FACU
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	31		

Herb Stratum (Plot size: 2 meter radius)

1.	*Anaphalis margaritacea*	20	N	FACU
2.	*Vicia americana*	5	N	FACU
3.	*Solidago canadensis*	20	N	FACU
4.	*Galium aparine*	50	Y	FACU
5.	*Trifolium pratense*	30	Y	FACU
6	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
11.	--	--	--	--
12.	--	--	--	--
13.	--	--	--	--
14.	--	--	--	--
15.	--	--	--	--
	Total Cover =	125		

Woody Vine Stratum (Plot size: 10 meter radius)

1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
	Total Cover =	0		

Remarks:

Dominance Test Worksheet

Number of Dominant Species that are OBL, FACW, or FAC: 0 (A)

Total Number of Dominant Species Across All Strata: 3 (B)

Percent of Dominant Species That Are OBL, FACW, or FAC: ***0.0%*** (A/B)

Prevalence Index Worksheet

Total % Cover of:		Multiply by:	
OBL spp.	0	x 1 =	0
FACW spp.	10	x 2 =	20
FAC spp.	5	x 3 =	15
FACU spp.	157	x 4 =	628
UPL spp.	0	x 5 =	0
Total	172 (A)		663 (B)

Prevalence Index = B/A = ***3.855***

Hydrophytic Vegetation Indicators:

- ☐ Yes ☑ No Rapid Test for Hydrophytic Vegetation
- ☐ Yes ☑ No Dominance Test is > 50%
- ☐ Yes ☑ No Prevalence Index is ≤ 3.0 *
- ☐ Yes ☑ No Morphological Adaptations (Explain) *
- ☐ Yes ☑ No Problem Hydrophytic Vegetation (Explain) *

* Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic.

Definitions of Vegetation Strata:

Tree - Woody plants 3 in. (7.6cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/Shrub - Woody plants less than 3 in. DBH and greater than 3.28 ft. tall.

Herb - All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft. tall.

Woody Vines - All woody vines greater than 3.28 ft. in height.

Hydrophytic Vegetation Present ☐ Yes ☑ No

Additional Remarks:

TETRA TECH

WETLAND DETERMINATION DATA FORM
Northeast and Northcentral Region

Project/Site:	Western Maine Renewable Energy Project	Project #: 194-7130	Date: 09/09/20
Applicant:	Western Maine Renewables, LLC		County: Somerset
Investigator #1:	Emmy Irvin	Investigator #2:	State: ME
Soil Unit:	Telos-Chesuncook association, 3 to 15 percent slopes	NWI/WWI Classification: PEM/PSS	Wetland ID: W99EI
Landform:	Terrace	Local Relief: Linear	Sample Point: **Wetland**
Slope (%):	See topo map	Latitude: 45.140609 Longitude: -69.8499599 Datum: NAD 83	

Are climatic/hydrologic conditions on the site typical for this time of year? (If no, explain in remarks) ☐ Yes ☑ No

Are Vegetation ☑, Soil ☐, or Hydrology ☐ significantly disturbed?
Are Vegetation ☐, Soil ☐, or Hydrology ☐ naturally problematic?

Are normal circumstances present? ☐ Yes ☑ No

SUMMARY OF FINDINGS

Hydrophytic Vegetation Present?	☑ Yes ☐ No	Hydric Soils Present?	☑ Yes ☐ No
Wetland Hydrology Present?	☑ Yes ☐ No	Is This Sampling Point Within A Wetland?	☑ **Yes** ☐ **No**

Remarks: Statewide drought; occurs in USAF Radar Station field

HYDROLOGY

Wetland Hydrology Indicators (Check here if indicators are not present ☐)

Primary:
- ☐ A1 - Surface Water
- ☐ A2 - High Water Table
- ☐ A3 - Saturation
- ☐ B1 - Water Marks
- ☐ B2 - Sediment Deposits
- ☐ B3 - Drift Deposits
- ☐ B4 - Algal Mat or Crust
- ☐ B5 - Iron Deposits
- ☐ B7 - Inundation Visible on Aerial Imagery
- ☐ B8 - Sparsely Vegetated Concave Surface
- ☐ B9 - Water-Stained Leaves
- ☐ B13 - Aquatic Fauna
- ☐ B15 - Marl Deposits
- ☐ C1 - Hydrogen Sulfide Odor
- ☐ C3 - Oxidized Rhizospheres on Living Roots
- ☐ C4 - Presence of Reduced Iron
- ☐ C6 - Recent Iron Reduction in Tilled Soils
- ☐ C7 - Thin Muck Surface
- ☐ Other (Explain in Remarks)

Secondary:
- ☐ B6 - Surface Soil Cracks
- ☐ B10 - Drainage Patterns
- ☐ B16 - Moss Trim Lines
- ☐ C2 - Dry-Season Water Table
- ☐ C8 - Crayfish Burrows
- ☐ C9 - Saturation Visible on Aerial Imagery
- ☑ D1 - Stunted or Stressed Plants
- ☐ D2 - Geomorphic Position
- ☐ D3 - Shallow Aquitard
- ☐ D4 - Microtopographic Relief
- ☑ D5 - FAC-Neutral Test

Field Observations:

Surface Water Present?	☐ Yes ☑ No	Depth:	(in.)
Water Table Present?	☐ Yes ☑ No	Depth:	(in.)
Saturation Present?	☐ Yes ☑ No	Depth:	(in.)

Wetland Hydrology Present? ☑ Yes ☐ No

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available: N/A

Remarks: Statewide drought

SOILS

Map Unit Name: Telos-Chesuncook association, 3 to 15 percent slopes — Series Drainage Class: somewhat poorly drained

Taxonomy (Subgroup): Loamy, isotic, frigid, shallow Aquic Haplorthods

Profile Description (Describe to the depth needed to document the indicator or confirm the absence of indicators.) (Type: C=Concentration, D=Depletion, RM=Reduced Matrix, CS=Covered/Coated Sand Grains; Location: PL=Pore Lining, M=Matrix)

Top Depth	Bottom Depth	Horizon	Matrix Color (Moist)		Matrix %	Mottles Color (Moist)		Mottles %	Mottles Type	Mottles Location	Texture (e.g. clay, sand, loam)
0	10	--	2.5Y	4/1	100	10YR	4/6	5	c	m	fine sandy loam
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--

NRCS Hydric Soil Field Indicators (check here if indicators are not present ☑):
- ☐ A1- Histosol
- ☐ A2 - Histic Epipedon
- ☐ A3 - Black Histic
- ☐ A4 - Hydrogen Sulfide
- ☐ A5 - Stratified Layers
- ☐ A11 - Depleted Below Dark Surface
- ☐ A12 - Thick Dark Surface
- ☐ S1 - Sandy Muck Mineral
- ☐ S4 - Sandy Gleyed Matrix
- ☐ S5 - Sandy Redox
- ☐ S6 - Stripped Matrix
- ☐ S7 - Dark Surface (LRR R, MLRA 149B)
- ☐ S8 - Polyvalue Below Surface (LRR R, MLRA 149B)
- ☐ S9 - Thin Dark Surface (LRR R, MLRA 149B)
- ☐ F1 - Loamy Mucky Mineral (LRR K, L)
- ☐ F2 - Loamy Gleyed Matrix
- ☑ F3 - Depleted Matrix
- ☐ F6 - Redox Dark Surface
- ☐ F7 - Depleted Dark Surface
- ☐ F8 - Redox Depressions

Indicators for Problematic Soils [1]
- ☐ A10 - 2 cm Muck (LRR K, L, MLRA 149B)
- ☐ A16 - Coast Prairie Redox (LRR K, L, R)
- ☐ S3 - 5cm Mucky Peat of Peat (**LRR K, L, R**)
- ☐ S7 - Dark Surface (LRR K, L, M)
- ☐ S8 - Polyvalue Below Surface (**LRR K, L**)
- ☐ S9 - Thin Dark Surface (**LRR K, L**)
- ☐ F12 - Iron-Manganese Masses (**LRR K, L, R**)
- ☐ F19 - Piedmont Floodplain Soils (**MLRA 149B**)
- ☐ TA6 - Mesic Spodic (**MLRA 144A, 145, 149B**)
- ☐ TF2 - Red Parent Material
- ☐ TF12 - Very Shallow Dark Surface
- ☐ Other (Explain in Remarks)

[1] Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (If Observed) Type: ledge Depth: 10

Hydric Soil Present? ☑ Yes ☐ No

Remarks:

TETRA TECH

WETLAND DETERMINATION DATA FORM

Northeast and Northcentral Region

Project/Site: Western Maine Renewable Energy Project Wetland ID: W99EI Sample Point **Wetland**

VEGETATION (Species identified in all uppercase are non-native species.)

Tree Stratum (Plot size: 10 meter radius)

	Species Name	% Cover	Dominant	Ind.Status
1.	*Larix laricina*	10	N	FACW
2.	*Betula alleghaniensis*	10	N	FAC
3.	*Picea mariana*	15	Y	FACW
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	35		

Sapling/Shrub Stratum (Plot size: 5 meter radius)

1.	*Salix bebbiana*	20	Y	FACW
2.	*Spiraea alba*	25	Y	FACW
3.	*Populus tremuloides*	10	N	FACU
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	55		

Herb Stratum (Plot size: 2 meter radius)

1.	*Symphyotrichum novae-angliae*	15	N	FACW
2.	*Phalaris arundinacea*	50	Y	FACW
3.	*Osmunda claytoniana*	30	Y	FAC
4.	--	--	--	--
5.	--	--	--	--
6	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
11.	--	--	--	--
12.	--	--	--	--
13.	--	--	--	--
14.	--	--	--	--
15.	--	--	--	--
	Total Cover =	95		

Woody Vine Stratum (Plot size: 10 meter radius)

1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
	Total Cover =	0		

Remarks:

Dominance Test Worksheet

Number of Dominant Species that are OBL, FACW, or FAC: 5 (A)

Total Number of Dominant Species Across All Strata: 5 (B)

Percent of Dominant Species That Are OBL, FACW, or FAC: ***100.0%*** (A/B)

Prevalence Index Worksheet

Total % Cover of:		Multiply by:	
OBL spp.	0	x 1 =	0
FACW spp.	135	x 2 =	270
FAC spp.	40	x 3 =	120
FACU spp.	10	x 4 =	40
UPL spp.	0	x 5 =	0
Total	185 (A)		430 (B)

Prevalence Index = B/A = ***2.324***

Hydrophytic Vegetation Indicators:

- ☐ Yes ☑ No Rapid Test for Hydrophytic Vegetation
- ☑ Yes ☐ No Dominance Test is > 50%
- ☑ Yes ☐ No Prevalence Index is ≤ 3.0 *
- ☐ Yes ☑ No Morphological Adaptations (Explain) *
- ☐ Yes ☑ No Problem Hydrophytic Vegetation (Explain) *

* Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic.

Definitions of Vegetation Strata:

Tree - Woody plants 3 in. (7.6cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/Shrub - Woody plants less than 3 in. DBH and greater than 3.28 ft. tall.

Herb - All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft. tall.

Woody Vines - All woody vines greater than 3.28 ft. in height.

Hydrophytic Vegetation Present ☑ Yes ☐ No

Additional Remarks:

TETRA TECH

WETLAND DETERMINATION DATA FORM
Northeast and Northcentral Region

Project/Site:	Moscow Renewable Energy Project		Project #: 194-7130	Date:	09/09/20
Applicant:	Patriot Renewables			County:	Somerset
Investigator #1:	Nicc Johnson	Investigator #2:	Emmy Irvin	State:	ME
Soil Unit:	Monarda-Telos complex, 0 to 8 percent slopes, very stony		NWI/WWI Classification: Upland	Wetland ID:	W08NJ
Landform:	Terrace	Local Relief:	Linear	Sample Point:	**Upland**
Slope (%):	See topo map	Latitude: 45.136905	Longitude: -69.8302848	Datum:	NAD 83

Are climatic/hydrologic conditions on the site typical for this time of year? (If no, explain in remarks) ☐ Yes ☐ No

Are Vegetation ☐, Soil ☐, or Hydrology ☐ significantly disturbed?
Are Vegetation ☐, Soil ☐, or Hydrology ☐ naturally problematic?

Are normal circumstances present? ☐ Yes ☑ No

SUMMARY OF FINDINGS

Hydrophytic Vegetation Present?	☐ Yes ☑ No	Hydric Soils Present?	☐ Yes ☑ No
Wetland Hydrology Present?	☐ Yes ☑ No	Is This Sampling Point Within A Wetland?	☐ **Yes** ☑ **No**

Remarks: Statewide drought

HYDROLOGY

Wetland Hydrology Indicators (Check here if indicators are not present ☑)

Primary:
- ☐ A1 - Surface Water
- ☐ A2 - High Water Table
- ☐ A3 - Saturation
- ☐ B1 - Water Marks
- ☐ B2 - Sediment Deposits
- ☐ B3 - Drift Deposits
- ☐ B4 - Algal Mat or Crust
- ☐ B5 - Iron Deposits
- ☐ B7 - Inundation Visible on Aerial Imagery
- ☐ B8 - Sparsely Vegetated Concave Surface
- ☐ B9 - Water-Stained Leaves
- ☐ B13 - Aquatic Fauna
- ☐ B15 - Marl Deposits
- ☐ C1 - Hydrogen Sulfide Odor
- ☐ C3 - Oxidized Rhizospheres on Living Roots
- ☐ C4 - Presence of Reduced Iron
- ☐ C6 - Recent Iron Reduction in Tilled Soils
- ☐ C7 - Thin Muck Surface
- ☐ Other (Explain in Remarks)

Secondary:
- ☐ B6 - Surface Soil Cracks
- ☐ B10 - Drainage Patterns
- ☐ B16 - Moss Trim Lines
- ☐ C2 - Dry-Season Water Table
- ☐ C8 - Crayfish Burrows
- ☐ C9 - Saturation Visible on Aerial Imagery
- ☐ D1 - Stunted or Stressed Plants
- ☐ D2 - Geomorphic Position
- ☐ D3 - Shallow Aquitard
- ☐ D4 - Microtopographic Relief
- ☐ D5 - FAC-Neutral Test

Field Observations:

Surface Water Present?	☐ Yes ☑ No	Depth:	(in.)
Water Table Present?	☐ Yes ☑ No	Depth:	(in.)
Saturation Present?	☐ Yes ☑ No	Depth:	(in.)

Wetland Hydrology Present? ☐ Yes ☑ No

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available: N/A

Remarks: Statewide drought

SOILS

Map Unit Name: Monarda-Telos complex, 0 to 8 percent slopes, very stony — Series Drainage Class: Somewhat poorly drained

Taxonomy (Subgroup): Loamy, mixed, active, acid, frigid, shallow Aeric Endoaquepts

Profile Description (Describe to the depth needed to document the indicator or confirm the absence of indicators.) (Type: C=Concentration, D=Depletion, RM=Reduced Matrix, CS=Covered/Coated Sand Grains; Location: PL=Pore Lining, M=Matrix)

Top Depth	Bottom Depth	Horizon	Matrix Color (Moist)		Matrix %	Mottles Color (Moist)		Mottles %	Mottles Type	Mottles Location	Texture (e.g. clay, sand, loam)
0	12	--	10YR	4/3	100	--	--	--	--	--	FINE SANDY LOAM
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--

NRCS Hydric Soil Field Indicators (check here if indicators are not present ☑):
- ☐ A1- Histosol
- ☐ A2 - Histic Epipedon
- ☐ A3 - Black Histic
- ☐ A4 - Hydrogen Sulfide
- ☐ A5 - Stratified Layers
- ☐ A11 - Depleted Below Dark Surface
- ☐ A12 - Thick Dark Surface
- ☐ S1 - Sandy Muck Mineral
- ☐ S4 - Sandy Gleyed Matrix
- ☐ S5 - Sandy Redox
- ☐ S6 - Stripped Matrix
- ☐ S7 - Dark Surface (LRR R, MLRA 149B)
- ☐ S8 - Polyvalue Below Surface (LRR R, MLRA 149B)
- ☐ S9 - Thin Dark Surface (LRR R, MLRA 149B)
- ☐ F1 - Loamy Mucky Mineral (LRR K, L)
- ☐ F2 - Loamy Gleyed Matrix
- ☐ F3 - Depleted Matrix
- ☐ F6 - Redox Dark Surface
- ☐ F7 - Depleted Dark Surface
- ☐ F8 - Redox Depressions

Indicators for Problematic Soils [1]
- ☐ A10 - 2 cm Muck (LRR K, L, MLRA 149B)
- ☐ A16 - Coast Prairie Redox (LRR K, L, R)
- ☐ S3 - 5cm Mucky Peat of Peat (**LRR K, L, R**)
- ☐ S7 - Dark Surface (LRR K, L, M)
- ☐ S8 - Polyvalue Below Surface (**LRR K, L**)
- ☐ S9 - Thin Dark Surface (**LRR K, L**)
- ☐ F12 - Iron-Manganese Masses (**LRR K, L, R**)
- ☐ F19 - Piedmont Floodplain Soils (**MLRA 149B**)
- ☐ TA6 - Mesic Spodic (**MLRA 144A, 145, 149B**)
- ☐ TF2 - Red Parent Material
- ☐ TF12 - Very Shallow Dark Surface
- ☐ Other (Explain in Remarks)

[1] Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (If Observed) Type: Ledge Depth: 12

Hydric Soil Present? ☐ Yes ☑ No

Remarks:

TETRA TECH

WETLAND DETERMINATION DATA FORM

Northeast and Northcentral Region

Project/Site: Moscow Renewable Energy Project | Wetland ID: W08NJ | Sample Point **Upland**

VEGETATION (Species identified in all uppercase are non-native species.)

Tree Stratum (Plot size: 10 meter radius)

	Species Name	% Cover	Dominant	Ind.Status
1.	*Betula populifolia*	40	Y	FAC
2.	*Betula papyrifera*	10	N	FACU
3.	*Picea rubens*	10	--	FACU
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	60		

Sapling/Shrub Stratum (Plot size: 5 meter radius)

1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	0		

Herb Stratum (Plot size: 2 meter radius)

1.	*Solidago canadensis*	30	Y	FACU
2.	*Rubus idaeus*	15	Y	FACU
3.	*Anaphalis margaritacea*	5	N	FACU
4.	*Lupinus polyphyllus*	5	N	FACU
5.	--	--	--	--
6	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
11.	--	--	--	--
12.	--	--	--	--
13.	--	--	--	--
14.	--	--	--	--
15.	--	--	--	--
	Total Cover =	55		

Woody Vine Stratum (Plot size: 10 meter radius)

1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
	Total Cover =	0		

Remarks:

Dominance Test Worksheet

Number of Dominant Species that are OBL, FACW, or FAC: 1 (A)

Total Number of Dominant Species Across All Strata: 3 (B)

Percent of Dominant Species That Are OBL, FACW, or FAC: ***33.3%*** (A/B)

Prevalence Index Worksheet

Total % Cover of:		Multiply by:	
OBL spp.	0	x 1 =	0
FACW spp.	0	x 2 =	0
FAC spp.	40	x 3 =	120
FACU spp.	75	x 4 =	300
UPL spp.	0	x 5 =	0
Total	115 (A)		420 (B)

Prevalence Index = B/A = ***3.652***

Hydrophytic Vegetation Indicators:

- ☐ Yes ☑ No Rapid Test for Hydrophytic Vegetation
- ☐ Yes ☑ No Dominance Test is > 50%
- ☐ Yes ☑ No Prevalence Index is ≤ 3.0 *
- ☐ Yes ☑ No Morphological Adaptations (Explain) *
- ☐ Yes ☑ No Problem Hydrophytic Vegetation (Explain) *

* Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic.

Definitions of Vegetation Strata:

Tree - Woody plants 3 in. (7.6cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/Shrub - Woody plants less than 3 in. DBH and greater than 3.28 ft. tall.

Herb - All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft. tall.

Woody Vines - All woody vines greater than 3.28 ft. in height.

Hydrophytic Vegetation Present ☐ Yes ☑ No

Additional Remarks:

TETRA TECH

WETLAND DETERMINATION DATA FORM
Northeast and Northcentral Region

Project/Site:	Moscow Renewable Energy Project		Project #: 194-7130	Date:	09/09/20
Applicant:	Patriot Renewables			County:	Somerset
Investigator #1:	Nicc Johnson	Investigator #2:	Emmy Irvin	State:	ME
Soil Unit:	Monarda-Telos complex, 0 to 8 percent slopes, very stony		NWI/WWI Classification: PEM/PSS/OW	Wetland ID:	W08NJ
Landform:	Terrace	Local Relief:	Linear	Sample Point:	**WET**
Slope (%):	See topo map	Latitude: 45.134615	Longitude: -69.8400239	Datum:	NAD 83

Are climatic/hydrologic conditions on the site typical for this time of year? (If no, explain in remarks) ☐ Yes ☑ No

Are Vegetation ☐, Soil ☐, or Hydrology ☐ significantly disturbed?
Are Vegetation ☐, Soil ☐, or Hydrology ☐ naturally problematic?

Are normal circumstances present? ☐ Yes ☑ No

SUMMARY OF FINDINGS

Hydrophytic Vegetation Present?	☑ Yes ☐ No	Hydric Soils Present?	☑ Yes ☐ No
Wetland Hydrology Present?	☑ Yes ☐ No	Is This Sampling Point Within A Wetland?	☑ **Yes** ☐ **No**

Remarks: Statewide drought

HYDROLOGY

Wetland Hydrology Indicators (Check here if indicators are not present ☐)

Primary:
- ☑ A1 - Surface Water
- ☐ A2 - High Water Table
- ☑ A3 - Saturation
- ☐ B1 - Water Marks
- ☐ B2 - Sediment Deposits
- ☐ B3 - Drift Deposits
- ☐ B4 - Algal Mat or Crust
- ☐ B5 - Iron Deposits
- ☐ B7 - Inundation Visible on Aerial Imagery
- ☐ B8 - Sparsely Vegetated Concave Surface
- ☐ B9 - Water-Stained Leaves
- ☐ B13 - Aquatic Fauna
- ☐ B15 - Marl Deposits
- ☑ C1 - Hydrogen Sulfide Odor
- ☐ C3 - Oxidized Rhizospheres on Living Roots
- ☐ C4 - Presence of Reduced Iron
- ☐ C6 - Recent Iron Reduction in Tilled Soils
- ☐ C7 - Thin Muck Surface
- ☐ Other (Explain in Remarks)

Secondary:
- ☐ B6 - Surface Soil Cracks
- ☐ B10 - Drainage Patterns
- ☐ B16 - Moss Trim Lines
- ☐ C2 - Dry-Season Water Table
- ☐ C8 - Crayfish Burrows
- ☐ C9 - Saturation Visible on Aerial Imagery
- ☐ D1 - Stunted or Stressed Plants
- ☐ D2 - Geomorphic Position
- ☐ D3 - Shallow Aquitard
- ☐ D4 - Microtopographic Relief
- ☐ D5 - FAC-Neutral Test

Field Observations:

Surface Water Present?	☑ Yes ☐ No	Depth:	NR	(in.)
Water Table Present?	☐ Yes ☑ No	Depth:		(in.)
Saturation Present?	☑ Yes ☐ No	Depth:	0	(in.)

Wetland Hydrology Present? ☑ Yes ☐ No

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available: N/A

Remarks: Statewide drought

SOILS

Map Unit Name: Monarda-Telos complex, 0 to 8 percent slopes, very stony — Series Drainage Class: Somewhat poorly drained

Taxonomy (Subgroup): Loamy, mixed, active, acid, frigid, shallow Aeric Endoaquepts

Profile Description (Describe to the depth needed to document the indicator or confirm the absence of indicators.) (Type: C=Concentration, D=Depletion, RM=Reduced Matrix, CS=Covered/Coated Sand Grains; Location: PL=Pore Lining, M=Matrix)

Top Depth	Bottom Depth	Horizon	Matrix Color (Moist)	Matrix %	Mottles Color (Moist)	Mottles %	Mottles Type	Mottles Location	Texture (e.g. clay, sand, loam)
0	12	--	--	--	--	--	--	--	muck
--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--

NRCS Hydric Soil Field Indicators (check here if indicators are not present ☐):
- ☑ A1- Histosol
- ☐ A2 - Histic Epipedon
- ☐ A3 - Black Histic
- ☐ A4 - Hydrogen Sulfide
- ☐ A5 - Stratified Layers
- ☐ A11 - Depleted Below Dark Surface
- ☐ A12 - Thick Dark Surface
- ☐ S1 - Sandy Muck Mineral
- ☐ S4 - Sandy Gleyed Matrix
- ☐ S5 - Sandy Redox
- ☐ S6 - Stripped Matrix
- ☐ S7 - Dark Surface (LRR R, MLRA 149B)
- ☐ S8 - Polyvalue Below Surface (LRR R, MLRA 149B)
- ☐ S9 - Thin Dark Surface (LRR R, MLRA 149B)
- ☐ F1 - Loamy Mucky Mineral (LRR K, L)
- ☐ F2 - Loamy Gleyed Matrix
- ☐ F3 - Depleted Matrix
- ☐ F6 - Redox Dark Surface
- ☐ F7 - Depleted Dark Surface
- ☐ F8 - Redox Depressions

Indicators for Problematic Soils [1]
- ☐ A10 - 2 cm Muck (LRR K, L, MLRA 149B)
- ☐ A16 - Coast Prairie Redox (LRR K, L, R)
- ☐ S3 - 5cm Mucky Peat of Peat (**LRR K, L, R**)
- ☐ S7 - Dark Surface (LRR K, L, M)
- ☐ S8 - Polyvalue Below Surface (**LRR K, L**)
- ☐ S9 - Thin Dark Surface (**LRR K, L**)
- ☐ F12 - Iron-Manganese Masses (**LRR K, L, R**)
- ☐ F19 - Piedmont Floodplain Soils (**MLRA 149B**)
- ☐ TA6 - Mesic Spodic (**MLRA 144A, 145, 149B**)
- ☐ TF2 - Red Parent Material
- ☐ TF12 - Very Shallow Dark Surface
- ☐ Other (Explain in Remarks)

[1] Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (If Observed) Type: LEDGE Depth: 12

Hydric Soil Present? ☑ Yes ☐ No

Remarks:

TETRA TECH

WETLAND DETERMINATION DATA FORM

Northeast and Northcentral Region

Project/Site: Moscow Renewable Energy Project | Wetland ID: W08NJ | Sample Point **WET**

VEGETATION (Species identified in all uppercase are non-native species.)

Tree Stratum (Plot size: 10 meter radius)

	Species Name	% Cover	Dominant	Ind.Status
1.	*Acer rubrum*	5	N	FAC
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	5		

Sapling/Shrub Stratum (Plot size: 5 meter radius)

1.	*Populus tremuloides*	10	N	FACU
2.	*Alnus incana*	5	N	FACW
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	15		

Herb Stratum (Plot size: 2 meter radius)

1.	*Carex stricta*	100	Y	OBL
2.	*Scirpus cyperinus*	50	Y	OBL
3.	*Spiraea alba*	10	N	FACW
4.	*Onoclea sensibilis*	10	N	FACW
5.	*Typha angustifolia*	30	Y	OBL
6	*Symphyotrichum novae-angliae*	5	N	FACW
7.	*Juncus sp.*	--	--	#N/A
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
11.	--	--	--	--
12.	--	--	--	--
13.	--	--	--	--
14.	--	--	--	--
15.	--	--	--	--
	Total Cover =	205		

Woody Vine Stratum (Plot size: 10 meter radius)

1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
	Total Cover =	0		

Remarks:

Dominance Test Worksheet

Number of Dominant Species that are OBL, FACW, or FAC: 3 (A)

Total Number of Dominant Species Across All Strata: 3 (B)

Percent of Dominant Species That Are OBL, FACW, or FAC: ***100.0%*** (A/B)

Prevalence Index Worksheet

Total % Cover of:		Multiply by:	
OBL spp.	180	x 1 =	180
FACW spp.	30	x 2 =	60
FAC spp.	5	x 3 =	15
FACU spp.	10	x 4 =	40
UPL spp.	0	x 5 =	0
Total	225 (A)		295 (B)

Prevalence Index = B/A = ***1.311***

Hydrophytic Vegetation Indicators:

- ☑ Yes ☐ No Rapid Test for Hydrophytic Vegetation
- ☑ Yes ☐ No Dominance Test is > 50%
- ☑ Yes ☐ No Prevalence Index is ≤ 3.0 *
- ☐ Yes ☑ No Morphological Adaptations (Explain) *
- ☐ Yes ☑ No Problem Hydrophytic Vegetation (Explain) *

* Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic.

Definitions of Vegetation Strata:

Tree - Woody plants 3 in. (7.6cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/Shrub - Woody plants less than 3 in. DBH and greater than 3.28 ft. tall.

Herb - All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft. tall.

Woody Vines - All woody vines greater than 3.28 ft. in height.

Hydrophytic Vegetation Present ☑ Yes ☐ No

Additional Remarks:

EXHIBIT 7-6 AQUATIC RESOURCES PHOTOGRAPHIC LOG

Appendix D
Western Maine Renewable Energy Project
Impacted Resources Photographs

Wetlands

Photo: 01 Description: Wetland W12EI is a forested wetland that is adjacent to a gravel road. Date: June 16, 2020 Source: Tetra Tech, Inc.	

Photo: 02 Description: Wetland W17DS, located adjacent to clearing near USAF Radar Station field road berm. Date: June 2, 2020 Source: Tetra Tech, Inc.	

Appendix D
Western Maine Renewable Energy Project
Impacted Resources Photographs

Photo: 03 Description: Wetland W18EI is a forested wetland. Date: June 4, 2020 Source: Tetra Tech, Inc.	

Photo: 04 Description: Wetland W30EI; seepy wetland on hillslope, disturbed from timber harvest activities. Date: June 15, 2020 Source: Tetra Tech, Inc.	

Appendix D
Western Maine Renewable Energy Project
Impacted Resources Photographs

Photo: 05 Description: Wetland W35EI is a forested wetland. Date: June 16, 2020 Source: Tetra Tech, Inc.	

Photo: 06 Description: Wetland W37EI is a forested wetland. Date: June 2, 2020 Source: Tetra Tech, Inc.	

Appendix D
Western Maine Renewable Energy Project
Impacted Resources Photographs

Photo: 07 Description: Wetland W38EI will be impacted by fill and clearing Date: June 4, 2020 Source: Tetra Tech, Inc.	

Photo: 08 Description: Wetland W43EI; forested isolated depression. Date: June 16, 2020 Source: Tetra Tech, Inc.	

Appendix D
Western Maine Renewable Energy Project
Impacted Resources Photographs

Photo: 09 Description: Wetland W47EI is a forested wetland. Date: June 16, 2020 Source: Tetra Tech, Inc.	

Photo: 10 Description: Wetland W48EI is a forested wetland. Date: June 16,2020 Source: Tetra Tech, Inc.	

Appendix D
Western Maine Renewable Energy Project
Impacted Resources Photographs

Photo: 11 Description: Wetland W51EI is an emergent wetland. Date: May 5, 2020 Source: Tetra Tech, Inc.	

Photo: 12 Description: Wetland W52EI is a forested wetland. Date: May 5, 2020 Source: Tetra Tech, Inc.	

Appendix D
Western Maine Renewable Energy Project
Impacted Resources Photographs

Photo: 13 Description: Wetland W61EI; emergent, naturalized, depression adjacent to the road. Date: June 23, 2020 Source: Tetra Tech, Inc.	

Photo: 14 Description: Wetland W63EI is a forested wetland Date: June 16, 2020 Source: Tetra Tech, Inc.	

Appendix D
Western Maine Renewable Energy Project
Impacted Resources Photographs

Photo: 15 Description: Wetland W67EI Date: June 16, 2020 Source: Tetra Tech, Inc.	

Photo: 16 Description: Wetland W68EI Date: June 16, 2020 Source: Tetra Tech, Inc.	

Appendix D
Western Maine Renewable Energy Project
Impacted Resources Photographs

Photo: 17 Description: Wetland W71EI is an emergent wetland with beaver activity. Date: June 22, 2020 Source: Tetra Tech, Inc.	

Photo: 18 Description: Wetland W81EI is a forested wetland. Date: September 22, 2020 Source: Tetra Tech, Inc.	

Appendix D
Western Maine Renewable Energy Project
Impacted Resources Photographs

Photo: 19 Description: Wetland W92EI is a forested wetland. Date: September 22, 2020 Source: Tetra Tech, Inc.	

Photo: 20 Description: Wetland W98EI is a forested wetland. Date: September 22, 2020 Source: Tetra Tech, Inc.	

Appendix D
Western Maine Renewable Energy Project
Impacted Resources Photographs

Photo: 21 Description: Wetland W99EI is a forested wetland. Date: May 5, 2020 Source: Tetra Tech, Inc.	

Photo: 22 Description: Wetland W123NJ is an extension of a wetland that was originally located during the growing season of 2020. Date: April 27, 2021 Source: Tetra Tech, Inc.	

Appendix D
Western Maine Renewable Energy Project
Impacted Resources Photographs

Photo: 23 Description: Wetland W126EI is an extension of a wetland that was originally located during the growing season of 2020. Date: April 24,2021 Source: Tetra Tech, Inc.	

Photo: 24 Description: Wetland WET-68-02 Date: May 19, 2021 Source: Ian Broadwater	

Appendix D
Western Maine Renewable Energy Project
Impacted Resources Photographs

Watercourses

Photo: 25 Description: S21EI Date: July 21, 2020 Source: Tetra Tech, Inc.	

Photo: 26 Description: Ephemeral watercourse S24EI; flows southeast from wetlands W49EI to W48EI. Date: June 17, 2020 Source: Tetra Tech, Inc.	

Appendix D
Western Maine Renewable Energy Project
Impacted Resources Photographs

Photo: 27 Description: Watercourse S26EI flows south through a culvert in a road, towards Chase Pond. Date: June 22, 2020 Source: Tetra Tech, Inc.	

Photo: 28 Description: S28EI Date: June 16, 2020 Source: Tetra Tech, Inc.	

Appendix D
Western Maine Renewable Energy Project
Impacted Resources Photographs

Photo: 29 Description: Intermittent watercourse S32EI; crosses the Study Area. Date: June 22, 2020 Source: Tetra Tech, Inc.	

Photo: 30 Description: Watercourse S51EI (Bassett Brook); Photo of the approximately 7-foot culvert outlet with some damage. Date: September 10 , 2020 Source: Tetra Tech, Inc.	

Appendix D
Western Maine Renewable Energy Project
Impacted Resources Photographs

Photo: 31 Description: Intermittent watercourse S52EI; crosses a road that is proposed for accessing the western turbine locations. Date: September 23, 2020 Source: Tetra Tech, Inc.	

Photo: 32 Description: S53EI Date: September 23, 2020 Source: Tetra Tech, Inc.	

EXHIBIT 7-7 FUNCTIONS AND VALUES ASSESSMENT SUMMARY FORMS

Exhibit 7-7

Wetland Function-Value Evaluation Form – Palustrine Forested -WOSS

Human made? **No** Is wetland part of a wildlife corridor? **No** or a "habitat island"? **No** Wetland ID: **See Table 7-1** Adjacent land use: **Gravel Road, Active Timberland, abandoned radar facility** Distance to nearest roadway or other development? **Some areas are adjacent to roadway, some are 1,500+ feet from roadway** Dominant wetland systems present: **PFO** Contiguous undeveloped buffer zone present: **No** Prepared by: **Emmy Irvin** Is the wetland a separate hydraulic system? **No** If not, where does the wetland lie in the drainage basin: **Generally, ridge line seep wetlands and plateau wetlands** Impact: Type: **Fill** How many tributaries contribute to the wetland? **3** Wildlife & vegetation diversity/abundance: **See Exhibit 7-4 Natural Resources Survey Report, Table 2.**

Wetland Impact: **Type**: Clearing: 791 square feet **Type:** Permanent: 13,566 square feet **Combined Total:** 14,358 square feet

Function/Value	Suitability Y/N	Rational Reference #'s	Principal or Secondary Function	Comments
Groundwater Recharge/Discharge	Y	7, 9, 10	Primary	Some wetlands contain small streams that originate and/or disperse in wetland
Floodflow Alteration	Y	1	secondary	This is a large wetland compared to other wetlands in the area
Fish and Shellfish Habitat	N			Wetlands are not suitable to fish and shellfish habitat
Production Export	N			No exportable products are produced in wetlands
Sediment/Toxicant Retention	Y	1, 10	secondary	Some wetlands contain small streams and flood in the spring
Nutrient Removal	N			Wetlands are not suitable to nutrient removal
Sediment/Shoreline Stabilization	Y	2, 4	secondary	Some wetlands provide bank stabilization to intermittent streams
Wildlife Habitat	Y	5, 7, 8, 20	secondary	Wildlife habitat is abundant in the surrounding area
Educational/Scientific Value	N			Limited potential for educational values
Recreation	N			No potential for recreation associated with wetlands
Uniqueness/Heritage	Y	24		Wetland is, or contains, a WOSS
Visual Quality/Aesthetics	N			Not a visually or aesthetically pleasing wetland
Endangered Species Habitat	N			No listed species habitat is present in wetlands
Other	N			

Wetland Function-Value Evaluation Form – Palustrine Forested – Non-WOSS

Human made? **No** Is wetland part of a wildlife corridor? **No** or a "habitat island"? **No** Wetland ID: **See Table 7-1** Adjacent land use: **Gravel Road, Active Timberland, abandoned radar facility** Distance to nearest roadway or other development? **Some areas are adjacent to roadway, some are 1,500+ feet from roadway** Dominant wetland systems present: **PFO** Contiguous undeveloped buffer zone present: **No** Prepared by: **Emmy Irvin** Is the wetland a separate hydraulic system? **No** If not, where does the wetland lie in the drainage basin: **Generally, ridge line seep wetlands and plateau wetlands** Impact: Type: **Fill** How many tributaries contribute to the wetland? **0** Wildlife & vegetation diversity/abundance: **See Exhibit 7-4 Natural Resources Survey Report, Table 2.**

Wetland Impact: **Type**: Clearing: 1,840 square feet **Type:** Permanent: 17,776 square feet **Combined Total:** 19,616 square feet

Function/Value	Suitability Y/N	Rational Reference #'s	Principal or Secondary Function	Comments
Groundwater Recharge/Discharge	N			Limited potential for groundwater recharge or discharge
Floodflow Alteration	Y	1, 2, 3, 5, 6	Primary	Some wetlands are large compared to other wetlands in the area and are in a relatively flat area that has flood storage potential
Fish and Shellfish Habitat	N			Wetlands are not suitable to fish and shellfish habitat
Production Export	N			No exportable products are produced in wetlands
Sediment/Toxicant Retention	Y	1, 2	secondary	Some wetlands are in previously disturbed area that has potential for erosion
Nutrient Removal	Y	4, 8	secondary	Some wetlands have a dense herbaceous layer in a addition to a think canopy
Sediment/Shoreline Stabilization	Y	3	secondary	Wetland occurs in between roadway and two intermittent or perennial streams
Wildlife Habitat	N	4, 7, 8	secondary	Disturbed wetland in managed forest, other less impacted resources nearby
Educational/Scientific Value	N			Limited potential for educational values
Recreation	N			No potential for recreation associated with wetlands
Uniqueness/Heritage	N			Limited potential for uniqueness or heritage value
Visual Quality/Aesthetics	N			Not a visually or aesthetically pleasing wetland
Endangered Species Habitat	N			No listed species habitat is present in wetlands
Other	N			

Wetland Function-Value Evaluation Form – Palustrine Emergent -Non-WOSS

Human made? **No** Is wetland part of a wildlife corridor? **No** or a "habitat island"? **No** Wetland ID: **See Table 7-1** Adjacent land use: **Gravel Road, Active Timberland, abandoned radar facility** Distance to nearest roadway or other development? **Some areas are adjacent to roadway, some are 1,500+ feet from roadway** Dominant wetland systems present: **PEM** Contiguous undeveloped buffer zone present: **No** Prepared by: **Emmy Irvin** Is the wetland a separate hydraulic system? **No** If not, where does the wetland lie in the drainage basin: **Generally, ridge line seep wetlands and plateau wetlands** Impact: Type: **Fill** How many tributaries contribute to the wetland? **3** Wildlife & vegetation diversity/abundance: **See Exhibit 7-4 Natural Resources Survey Report, Table 2.**

Wetland Impact: **Type**: Clearing: 9,832 square feet **Type:** Permanent: 40,734 square feet **Combined Total:** 50,566 square feet

Function/Value	Suitability Y/N	Rational Reference #'s	Principal or Secondary Function	Comments
Groundwater Recharge/Discharge	N			Limited potential for groundwater recharge or discharge
Floodflow Alteration	Y	1, 6, 7, 13	secondary	Some wetlands are large compared to other wetlands in the area and are in a relatively flat area that has flood storage potential and/or have an associated intermittent stream
Fish and Shellfish Habitat	N			Wetlands are not suitable to fish and shellfish habitat
Production Export	N			No exportable products are produced in wetlands
Sediment/Toxicant Retention	Y	1, 2, 10	secondary	Some wetlands occur in the USAF radar field with historic human made disturbances or within man-made roadside ditches
Nutrient Removal	Y	8	Secondary	Some wetlands have a thick herbaceous layer
Sediment/Shoreline Stabilization	N			Wetland occurs in between roadway and two intermittent or perennial streams
Wildlife Habitat	Y	3, 4, 5, 7, 8, 13,17, 21	Primary	Wildlife habitat is abundant in the surrounding area. some wetlands have beaver activity.
Educational/Scientific Value	N			Limited potential for educational values
Recreation	N			No potential for recreation associated with wetlands
Uniqueness/Heritage	N			Limited potential for uniqueness or heritage value
Visual Quality/Aesthetics	N			Not a visually or aesthetically pleasing wetland
Endangered Species Habitat	N			No listed species habitat is present in wetlands
Other	N			

Wetland Function-Value Evaluation Form – Palustrine Emergent--WOSS

Human made? **No** Is wetland part of a wildlife corridor? **No** or a "habitat island"? **No** Wetland ID: **See Table 7-1** Adjacent land use: **Gravel Road, Active Timberland, abandoned radar facility** Distance to nearest roadway or other development? **Some areas are adjacent to roadway, some are 1,500+ feet from roadway** Dominant wetland systems present: **PEM** Contiguous undeveloped buffer zone present: **No** Prepared by: **Emmy Irvin** Is the wetland a separate hydraulic system? **No** If not, where does the wetland lie in the drainage basin: **Generally, ridge line seep wetlands and plateau wetlands** Impact: Type: **Fill** How many tributaries contribute to the wetland? **2** Wildlife & vegetation diversity/abundance: **See Exhibit 7-4 Natural Resources Survey Report, Table 2.**

Wetland Impact: **Type**: Clearing: 4,088 square feet **Type:** Permanent: 0 square feet **Combined Total:** 4,088 square feet

Function/Value	Suitability Y/N	Rational Reference #'s	Principal or Secondary Function	Comments
Groundwater Recharge/Discharge	N			Limited potential for groundwater recharge or discharge
Floodflow Alteration	N	6, 7, 13	Primary	Wetlands have intermittent watercourses associated with them and are in flat areas with flood storage potential
Fish and Shellfish Habitat	N			Wetlands are not suitable to fish and shellfish habitat
Production Export	N			No exportable products are produced in wetlands
Sediment/Toxicant Retention	Y	1, 2, 10	secondary	Some wetlands occur in the USAF radar field with historic human made disturbances or within man-made roadside ditches
Nutrient Removal	N			Some wetlands have a thick herbaceous layer
Sediment/Shoreline Stabilization	N			Limited potential for sediment or shoreline stabilization
Wildlife Habitat	Y	17	Secondary	Some wetlands have signs of beaver activity
Educational/Scientific Value	N			Limited potential for educational values
Recreation	N			No potential for recreation associated with wetlands
Uniqueness/Heritage	N			Limited potential for uniqueness or heritage value
Visual Quality/Aesthetics	N			Not a visually or aesthetically pleasing wetland
Endangered Species Habitat	N			No listed species habitat is present in wetlands
Other	N			