



Mail Processing Center  
Federal Aviation Administration  
Southwest Regional Office  
Obstruction Evaluation Group  
2601 Meacham Boulevard  
Fort Worth, TX 76137

Aeronautical Study No.  
2012-WTE-5738-OE

Issued Date: 12/21/2012

Josh Bagnato  
Blue Sky West, LLC  
129 Middle Street, 3rd Floor  
Portland, ME 04101

**\*\* DETERMINATION OF NO HAZARD TO AIR NAVIGATION \*\***

The Federal Aviation Administration has conducted an aeronautical study under the provisions of 49 U.S.C., Section 44718 and if applicable Title 14 of the Code of Federal Regulations, part 77, concerning:

|            |   |
|------------|---|
| Structure: | Wind Turbine T-58   |
| Location:  | Bingham, ME   |
| Latitude:  | 45-10-45.80N NAD 83   |
| Longitude: | 69-38-18.56W  |
| Heights:   | 1470 feet site elevation (SE)<br>499 feet above ground level (AGL)<br>1969 feet above mean sea level (AMSL) |

This aeronautical study revealed that the structure does not exceed obstruction standards and would not be a hazard to air navigation provided the following condition(s), if any, is(are) met:

As a condition to this Determination, the structure is marked/lighted in accordance with FAA Advisory circular 70/7460-1 K Change 2, Obstruction Marking and Lighting, white paint/synchronized red lights - Chapters 4,12&13(Turbines).

It is required that FAA Form 7460-2, Notice of Actual Construction or Alteration, be e-filed any time the project is abandoned or:

- At least 10 days prior to start of construction (7460-2, Part I)  
 Within 5 days after the construction reaches its greatest height (7460-2, Part II)

**See attachment for additional condition(s) or information.**

While the structure does not constitute a hazard to air navigation, it would be located within or near a military training area and/or route.

This determination expires on 06/21/2014 unless:

- (a) the construction is started (not necessarily completed) and FAA Form 7460-2, Notice of Actual Construction or Alteration, is received by this office.
- (b) extended, revised, or terminated by the issuing office.

NOTE: REQUEST FOR EXTENSION OF THE EFFECTIVE PERIOD OF THIS DETERMINATION MUST BE E-FILED AT LEAST 15 DAYS PRIOR TO THE EXPIRATION DATE. AFTER RE-EVALUATION OF CURRENT OPERATIONS IN THE AREA OF THE STRUCTURE TO DETERMINE THAT NO SIGNIFICANT AERONAUTICAL CHANGES HAVE OCCURRED, YOUR DETERMINATION MAY BE ELIGIBLE FOR ONE EXTENSION OF THE EFFECTIVE PERIOD.

Additional wind turbines or met towers proposed in the future may cause a cumulative effect on the national airspace system. This determination is based, in part, on the foregoing description which includes specific coordinates and heights . Any changes in coordinates will void this determination. Any future construction or alteration requires separate notice to the FAA.

This determination does include temporary construction equipment such as cranes, derricks, etc., which may be used during actual construction of the structure. However, this equipment shall not exceed the overall heights as indicated above. Equipment which has a height greater than the studied structure requires separate notice to the FAA.

This determination concerns the effect of this structure on the safe and efficient use of navigable airspace by aircraft and does not relieve the sponsor of compliance responsibilities relating to any law, ordinance, or regulation of any Federal, State, or local government body.

Any failure or malfunction that lasts more than thirty (30) minutes and affects a top light or flashing obstruction light, regardless of its position, should be reported immediately to (877) 487-6867 so a Notice to Airmen (NOTAM) can be issued. As soon as the normal operation is restored, notify the same number.

If we can be of further assistance, please contact our office at (404) 305-7081. On any future correspondence concerning this matter, please refer to Aeronautical Study Number 2012-WTE-5738-OE.

**Signature Control No: 174584607-179586445**

( DNE -WT )

Michael Blaich  
Specialist

Attachment(s)  
Additional Information  
Frequency Data

## **Additional information for ASN 2012-WTE-5738-OE**

This structure may present an operational impact to the Department of Defense (DoD) in conducting low altitude tactical and surface-to-air counter-tactics training and/or Research, Development, Testing, and Evaluation that is outside the scope of Title 14, Code of Federal Regulations Part 77. As such, the DoD requests that the developer coordinate with the Executive Director, Department of Defense Siting Clearinghouse by e-mail at [DoDSitingClearinghouse@osd.mil](mailto:DoDSitingClearinghouse@osd.mil) or 571-372-6745 to discuss potential mitigation options.

Frequency Data for ASN 2012-WTE-5738-OE

| <b>LOW<br/>FREQUENCY</b> | <b>HIGH<br/>FREQUENCY</b> | <b>FREQUENCY<br/>UNIT</b> | <b>ERP</b> | <b>ERP<br/>UNIT</b> |
|--------------------------|---------------------------|---------------------------|------------|---------------------|
| 824                      | 849                       | MHz                       | 500        | W                   |