



## **Appendix B** **Required Supporting Documentation**

Applicants must submit external reports and opinions from certified professionals such as consultants, architects, engineers, and asbestos management planners and designers to substantiate and define the extent of the problem, propose solutions, and develop budgets.

Indoor Air Quality (IAQ)

Written reports that substantiate the exact cause of any indoor air problems, the severity and extent of the problem, the air sampling conducted to quantify the problem, and the parameters and criteria by which the professional determined the magnitude and scope of the problem.

Asbestos Abatement

Written reports that substantiate the health hazard of the asbestos to building occupants. The asbestos must be presenting an airborne risk to building occupants according to currently adopted asbestos standards or be scheduled to be removed because of another Priority One health, safety, and compliance renovation project.

Roof Renovations

Written reports that detail structural upgrades necessary to comply with currently applicable building codes or that detail how the current roof is a Priority One health and safety issue. The applicant should cite the current roof code(s) for the building and how the current roof situation is not in compliance with the relevant code(s). Re-roofing projects are considered to be the responsibility of the school administrative unit under their capital renewal program.

ADA Compliance

Written reports that demonstrate that the project will correct ADA deficiencies of higher priority such as access to a building from sidewalks, parking, or public transportation, access to various school programs, and access to a restroom. School administrative units must have a long-range ADA compliance strategy to bring their facilities into compliance.

Other (please list and explain):

Written reports that demonstrate a need in terms of immediate health, safety, and compliance concerns in a school building. Examples of immediate concerns that may qualify under this category include the lack of fire safety warning devices and contaminated well water.