

STATE OF MAINE DEPARTMENT OF TRANSPORTATION 16 STATE HOUSE STATION AUGUSTA, MAINE 04333-0016

DAVID A. COLE

COMMISSIONER

August 5, 2008 Subject: **Brewer**

Federal Project No: STP-1487(100)X

Pin No: 014871.00 **Amendment No. 1**

Dear Sir/Ms:

Make the following change to the Bid Document:

In the Bid Book (page 3), "SCHEDULE OF ITEMS", ITEM NO 202.202, REMOVING PAVEMENT SURFACE, **CHANGE** the quantity form 240.000 to **4500.000**. Make this change in pen and ink.

The following questions have been received:

Question: Item 202.202, Removing Pavement Surface, appears to be used in an area of full depth pavement removal from approximately Station 85+25 to 86+25, or is it common excavation? How will pavement removal in the mill & overlay section from Station 86+25 to 94 +50 and South Brewer Drive be paid for?

Response: Station 85+25 to 86+25 should be paid for by Common Excavation. The pavement removal in the mill & overlay section should be paid for under Item 202.202, Removing Pavement Surface.

Question: How is the fine grade for pavement in area 85+25 to 86+25 paid for?

Response: All required fine grade from 85+25 to 86+25 shall be incidental to 203.20, Common Excavation.

Question: How will the 2" wide "Hand Grinding" from station 82+67 to 86+25 be paid for?

Response: We believe this is in reference to the 2' Hand Grinding from Sta. 83+26 to Sta. 86+25 LT. This item should be paid for under Item 202.202, Removing Pavement Surface as referenced on Sheet 21.



Question: Item 411.09 provides for 600CY of "Untreated Aggregate Surface Course" on this project, is this quantity correct? Can you provide detail in regards to where the material will be used?

Response: This item refers to the gravel driveways on the project. The locations for this item:

Driveway @ Sta. 84+33 RT to 85+40 RT (Sheet 6) Driveway @ Sta. 89+40 LT (Sheet 6)

Question: The drainage schedule on Plan Sheet 6 of 33, SD-2 is shown as Type "C" Underdrain. Is SD-2 intended to be Class III RCP or Option III pipe? If so, will the bid quantities be adjusted?

Response: SD-2 was intended to be a Type "C" Underdrain Option III pipe therefore the quantity should not be adjusted.

Question: There is no item for tack on this project, should this item be added?

Response: Tack is considered incidental, refer to Special Provision 403.

Question: Item 202.202 - Is the quantity of 240 SY correct? Seems Light?

Response: No, the quantity of 240 SY is not correct. The correct quantity for this item is 4500 SY as corrected in this amendment.

Consider this information prior to submitting your bid on August 6, 2008.

Sincerely,

Scott Bickford

Contracts & Specifications Engineer