

Hiram

This report shows the 2017-2019 Work Plan entries for Hiram. The costs listed are the total cost of these projects – some of which may extend into neighboring towns. It also shows a listing of maintenance work specifically recorded to Hiram in 2016, as well as any 2016 Local Road Assistance payments. Activities that are managed on a larger scale, such as snow & ice control, and maintenance work done by contract are not listed. The maintenance accomplishments may also extend into neighboring towns, but are listed in the first town where the work was reported. Finally, any capital projects that were completed in 2016 are also listed.

Planned Capital and Maintenance Work 2017-2019

Work Plan Year: 2017

Municipalities(s): Baldwin, Bridgton, Brownfield, Cornish, Hiram, Hollis, Limington, Porter, Sebago, Standish, Waterboro

Asset(s): Route 107, Route 11, Plains Road, Route 114, South Hiram Road, Route 160, Route 117

Description: Baldwin Area 2017 LCP.

ID	Scope of Work	Highway Corridor Priority	Estimated Funding
024001.00	Light Capital Paving	Varies	\$1,265,100

Work Plan Year: 2017

Municipalities(s): Baldwin, Hiram, Sebago

Asset(s): Convene Road, Sebago Road

Description: Tree and brush removal Convene Road Baldwin/Sebago

ID	Scope of Work	Highway Corridor Priority	Estimated Funding
WR 33229	Maintenance	Corridor 5	\$73,575

Work Plan Year: 2017

Municipalities(s): Hiram

Asset(s): South Hiram Road

Description: Bridge Improvements on Wadsworth Bridge (No. 3946)

ID	Scope of Work	Highway Corridor Priority	Estimated Funding
WR 33549	Maintenance	Corridor 5	\$30,000

Work Plan Year: 2017

Municipalities(s): Denmark, Hiram

Asset(s): Route 117

Description: Tree and brush removal on Route 117

ID	Scope of Work	Highway Corridor Priority	Estimated Funding
WR 33180	Maintenance	Corridor 3	\$49,700

Work Plan Year: 2017

Municipalities(s): Hiram

Asset(s): Route 5

Description: Tree and brush removal Route 5 in Hiram

ID	Scope of Work	Highway Corridor Priority	Estimated Funding
WR 33177	Maintenance	Corridor 3	\$11,225

Work Plan Year: 2017

Municipalities(s): Hiram

Asset(s): Route 5

Description: Bridge Improvements Hiram Bridge (No. 2373)

ID	Scope of Work	Highway Corridor Priority	Estimated Funding
WR 33467	Maintenance	Corridor 3	\$75,000

Local Road Assistance – Fiscal Year 2016

\$50,368

Maintenance Accomplishments – 2016

Activities managed on a larger scale, such as snow & ice control, and work done by contract are not listed. *The maintenance accomplishments may extend into neighboring towns, but are listed in the first town where the work was reported.*

12.5 Ton(s) of Cold Patch Applied
 2.0 Bridge(s) Cleaned
 3.0 Bridge(s) Washed
 46,140.0 Linear Feet of Backhoe Ditching
 20.0 Minor Sign(s) Installed or Maintained
 12.5 Mile(s) of Shoulder prepared for LCP
 15.0 Shoulder Miles of Litter and Debris Removal
 29.2 Shoulder Miles of Mowing
 35.7 Miles of Striping Applied
 12.0 Mile(s) of Shoulder Graded
 630.0 Linear Feet of Shoulder Rebuilt
 394.5 Center Lane Mile(s) Patrolling and Inspecting
 26.0 Drainage Structures Cleaned
 1.0 Bridge(s) Sealed
 208.0 Linear Feet of Guardrail or Fence Maintained
 15.0 Drainage Structures Installed or Replaced
 2,000.0 Linear Feet of Brush Removed
 10.0 Linear Feet of Bridge Rail Repaired or Replaced
 231.0 Sq Feet of Pavement Legend Applied
 7,739.2 Ton(s) of Hot Mix Paving
 22,200.0 Linear Feet of Grader Ditching
 12.0 Trees Removed

Completed Capital Projects – 2016

022072.00 HIRAM - FRYEBURG Fog Seal
 018601.00 DENMARK AREA 2016 LCP DENMARK AREA 2016 LCP