

## Kingfield

This report shows the 2017-2019 Work Plan entries for Kingfield. The costs listed are the total cost of these projects – some of which may extend into neighboring towns. It also shows a listing of maintenance work specifically recorded to Kingfield in 2016, as well as any 2016 Local Road Assistance payments. Activities that are managed on a larger scale, such as snow & ice control, and maintenance work done by contract are not listed. The maintenance accomplishments may also extend into neighboring towns, but are listed in the first town where the work was reported. Finally, any capital projects that were completed in 2016 are also listed.

### Planned Capital and Maintenance Work 2017-2019

**Work Plan Year:** 2017

**Municipalities(s):** Kingfield

**Asset(s):** Route 142

**Description:** Beginning at the existing sidewalk on Depot Street and extending 0.65 of a mile to the Kingfield Elementary School.

ID	Scope of Work	Highway Corridor Priority	Estimated Funding
018882.00	Bicycle-Pedestrian - PE Only	Varies	\$62,000

**Work Plan Year:** 2018/19

**Municipalities(s):** Kingfield

**Asset(s):** Route 16

**Description:** Centennial Bridge (No.5852) over the Carrabasset River. Located 0.05 of a mile north of Main Street.

ID	Scope of Work	Highway Corridor Priority	Estimated Funding
023048.00	Bridge Wearing Surface Replacement	2	\$400,000

### Local Road Assistance – Fiscal Year 2016

\$14,408

### Maintenance Accomplishments – 2016

Activities managed on a larger scale, such as snow & ice control, and work done by contract are not listed. *The maintenance accomplishments may extend into neighboring towns, but are listed in the first town where the work was reported.*

- 5.0 Emergency Event Responses
- 33.1 Shoulder Miles of Herbicide Applied
- 149.0 Miles of Striping Applied
- 27.0 Minor Sign(s) Installed or Maintained
- 32.4 Ton(s) of Cold Patch Applied
- 9.3 Shoulder Miles of Sweeping
- 1.0 Bridge(s) Cleaned
- 125.5 Center Lane Mile(s) Patrolling and Inspecting
- 5.0 Bridge(s) Washed
- 2.0 Mile(s) of Shoulder prepared for LCP
- 4.0 Bridge Inspection(s) Performed
- 1,300.0 Ton(s) of Hot Mix Paving
- 3.0 Drainage Structures Repaired
- 2.0 Linear Feet of Bridge Rail Repaired or Replaced

### Completed Capital Projects – 2016

018609.00 STRONG AREA 2016 LCP STRONG AREA 2016 LCP