ADDENDUM NO. 1

March 31, 2023 528138

RE: KINGMAN ELEMENTARY SCHOOL

MECHANICAL SYSTEM UPGRADES

FROM: DuBOIS & KING, INC.

36 Penn Plaza

Bangor, Maine 04401 (207) 573-4130

TO: **Prospective Bidders**

This Addendum forms part of the Contract Documents and modifies the original Bidding Documents issued by the Maine Department of Education for the Kingman School Mechanical System Upgrades project dated March, 2023. Acknowledge receipt of this Addendum in the space provided on the Bid Form. Failure to do so will subject the Bidder to disqualification.

I. Pre-Bid Meeting

A Pre-Bid meeting was held at the Kingman School on March 23, 2023 at 3:00 p.m. Attendees are listed on the attached Pre-Bid Meeting Attendance Log. Matthew Merchant, of DuBois & King, Inc. described key elements of the project. The following addresses questions received at the pre-bid meeting, as well as project document revisions.

II. Contract Documents (Plan) Changes

1. Sheet M3.1 – FIRST FLOOR PLAN MECHANICAL

- A. Refer to attached revised Sheet M3.1 for the following changes:
 - a. Added FTR units in Speech Guidance (16) and Corridor (10).
 - b. Added CUH in Vestibule (6)
 - c. Added tag note 15.

2. Sheet M4.1 – MECHANICAL ENLARGED PLANS

- A. REVISE Tag Note 4 as follows:
 - 4. PROVIDE NEW PROPANE-FIRED BURNER FOR EXISTING BOILER. PROVIDE EITHER CARLIN EZGAS PRO MODEL EZ-1 OR RIELLO R-40 SERIES MODEL F-5 BURNER. PROVIDE BAROMETRIC DAMPER WITH MANUAL RESET SPILL SWITCH IN BOILER FLUE.

3. Sheet M5.1 – MECHANICAL DETAILS

A. Refer to attached revised Sheet M5.1 for revised "Exhaust Hood Curb Detail".



4. Sheet M6.1 – MECHANICAL SCHEDULES

A. ADD the below to project "DESIGN BASIS"

Per owner's request, the deficiencies noted in the "Pre-Engineered Restaurant Fire Suppression Systems Report" authored by Guay Fire Equip Inc and dated 03.15.2023 are to be addressed in this project. The scope of work solely address the deficiencies noted in the report, and the compliance of the rest of the kitchen hood exhaust system to meet NFPA 96 and other applicable codes has not been evaluated.

III. Contract Documents (Specification) Changes

1. Specification 00 11 13 NOTICE TO CONTRACTORS

- A. CHANGE bid due date from APRIL 4, 2023 to APRIL 11, 2023.
- B. CHANGE Final Completion date from 01 September 2023 to 23 August 2024.

2. Specification 01100 – SUMMARY

- A. Section 1.03B Contract Duration: DELETE "Substantial Completion by September 1, 2023 and Final Completion by December 31, 2023." and REPLACE with "Final Completion by August 23, 2024.
- B. <u>Section 1.07A Time Restrictions</u>: DELETE "Limit work to the hours of 7:00 am to 5:30 pm." and REPLACE with "No time restrictions when school is not in session. Work shall be coordinated with Owner when school is in session."

IV. Questions & Answers

1. Who is the current fuel supplier for the Maine department of Education (owner) at Kingman School (regarding propane tank, if required to be sourced from supplier or not)?

Current fuel supplier is Dead River Company.

2. What information is there for the replacement propane burners for the conversion, the burners are not on the materials schedule?

Provide either Carlin EZGas Pro model EZ-1 or Riello R-Series model R-40 burner.

3. What is the age of the existing boilers?

The boilers were replaced 10-12 years ago.

- **4.** What are the dimensions for the breeching pipe on the existing boiler? Existing drawings not available, contractor responsible for verifying existing conditions.
- 5. Can a units list be provided for the new control valves to be installed on existing heating apparatus?



New control valves shall be provided for all heating units as indicated on the drawings.

- 6. Has there been any testing done for asbestos in the work areas? Asbestos report is attached.
- 7. Can a map of the heating zones for the school be provided? See Answer to question 4.
- 8. The louver in the gymnasium is not shown on the existing plans, does this device work, if not, will it be a part of the scope of work?

It is not part of the scope of work, believed to be in working condition.

9. Can a site demolition plan be created?

Provided, Sheet M2.1.

10. Is there a possibility of relocating the proposed Energy Recovery unit to be outside the attic space?

No. Work to be completed as specified by owner on plan set.

11. Roof Detail?

Mount exhaust hood EH-1 on roof curb.

V. Additional Information

1. None

This document constitutes Addendum 1 for this project.






3/23/2023

Kingman School- Mechanical System Upgrades

| Pre-Bid Meeting Sign-in Sheet | |
|-------------------------------|---|
| Matthew Merchant | DuBois . King |
| Peter Naumayer | Mechanical Services |
| Early Penny | DuBois King Mechanical Services Sallivan & Marezitt |
| | <u>\$</u> |
| | |
| | |
| | |
| | |
| | |
| | |
| | |



FIRST FLOOR PLAN - MECHANICAL

SCALE: 1/8" = 1'-0"

KEYED NOTES:

1 PROVIDE NEW WALL-MOUNTED CABINET UNIT HEATER. CONNECT TO EXISTING PIPING RUNOUTS.

PROVIDE NEW MAKE-UP AIR UNIT LOCATED OUTSIDE ON GRADE. PROVIDE CONCRETE PAD FOR UNIT. MOUNT UNIT ON 36" EQUIPMENT CURB TO MAINTAIN BOTTOM OF MAKE-UP AIR INTAKE A MINIMUM OF 36" ABOVE GRADE. REFER TO SHEET M5.1 FOR CONCRETE PAD DETAIL.

PROVIDE NEW ENERGY RECOVERY UNIT IN ATTIC SPACE. SUSPEND ERU FROM ROOF STRUCTURE (ROOF TRUSS CONSTRUCTION) WITH THREADED RODS WITH VIBRATION ISOLATORS. PROVIDE PLYWOOD BOARDS FOR ACCESS ROUTE FROM ATTIC HATCH TO UNIT.

4 ROUTE DUCTWORK THROUGH ROOF TRUSSESS IN ATTIC.

PROVIDE NEW 1,000 GALLON PROPANE STORAGE TANK BURIED UNDERGROUND. REFER TO DETAIL ON SHEET M5.1.

6 ROUTE PROPANE PIPING ALONG EXTERIOR WALL TO MAKE-UP AIR UNIT.

PROVIDE OUTSIDE AIR LOUVER IN EXTERIOR WALL. MOUNT LOUVER AS HIGH AS POSSIBLE ABOVE WINDOW.

8 ROUTE EXHAUST DUCT UP THROUGH ROOF TO EXHAUST HOOD. PATCH EXISTING SHINGLE ROOF TO MAINTAIN ROOF WARRANTY.

9 PROPANE PIPING TO MECHANICAL ROOM. REFER TO SHEET M4.1 FOR CONTINUATION.

PROVIDE NEW 3-WAY HOT WATER HEATING DDC CONTROL VALVE FOR EXISTING EQUIPMENT AND CONNECT TO NEW BMS SYSTEM.

PROVIDE 575 MBH LP REGULATOR ON WALL. REGLATOR SHALL BE LOCATED A MINIMUM OF 5' FROM ALL SOURCES OF IGNITION PER NFPA 58.

 $\langle 12 \rangle$ PROVIDE FLEX DUCT CONNECTION AT ALL DUCT CONNECTIONS TO ERV.

ROUTE DUCTWORK UP EXTERIOR WALL AND PENETRATE BUILDING ABOVE EXISTING LAY-IN CEILING. SEAL PENETRATION.

14 PROVIDE NEW DIFFUSER OR GRILLE IN EXISTING CEILING. PATCH CEILING AS REQUIRED TO MATCH

MODIFY EXHAUST DUCTING TO MEET ALL NFPA 96 CRITERIA INCLUDING SEALING ALL JOINTS AIR TIGHT INCLUDING THE HOOD TO DUCT JOINT. PROVIDE A COMPLETE UL300 COMPLIANT FIRE SUPPRESSION SYSTEM. THIS WORK IS INTENDED TO ADDRESS DEFICIENCIES NOTED IN "PRE-ENGINEERED RESTAURANT FIRE SUPPRESSION SYSTEMS REPORT" AUTHORED BY GUAY FIRE EQUIP INC. DATED 03/15/23. THE COMPLIANCE OF THE REST OF THE HOOD EXHAUST SYSTEM TO MEET NFPA 96 AND ALL OTHER APPLICABLE CODES HAS NOT BEEN EVALUATED.


DuBois EKing Inc.

6 GREEN TREE DRIVE S0. BURLINGTON, VT 05403 TEL: 802.878.7661 www.dubois-king.com

VERMONT NEW HAMPSHIRE MAINE AND NEW YOR

MAINE AND NEW YORK

© Copyright 2023 DuBois & King Inc.



| | | | HCM | λЯ |
|--|--|--|------------------------|-------------|
| | | | 03/31/2023 ADDENDUM #1 | DESCRIPTION |
| | | | 03/31/2023 | DATE |
| | | | 1 | NO. |
| | | | | |
| | | | | |



KINGMAN SCHOOL MECHANICAL SYSTEM UPGRADES

25 PARK ST. KINGMAN, ME 04451

SHEET TITLE

FIRST FLOOR PLAN - MECHANICAL


| DRAWN BY | DATE |
|------------|---------------|
| MJH | 03/10/2023 |
| CHECKED BY | D&K PROJECT # |
| SVD | 528138 |
| PROJ. ENG. | D&K ARCHIVE # |
| SVD | |

M3 1

SHEET NUMBER

SHEET 6 OF 11

ISSUED FOR BID 03/10/2023



2 ENLARGED MECHANICAL ROOM PLAN - MECHANICAL DEMOLITION SCALE: 1/4" = 1'-0"





4 4 4



KEYED NOTES:

- 1 COMPLETELY REMOVE EXISTING FUEL OIL BURNER AND ALL ASSOCIATED MECHANICAL AND CONTROLS CONNECTIONS. EXISTING BOILER SHALL REMAIN. COORDINATE WITH ELECTRICAL
- 2 COMPLETELY REMOVE EXISTING FUEL OIL PIPING AND ALL ASSOCIATED HANGERS AND SUPPORTS.
- $\langle 4 \rangle$ PROVIDE NEW PROPANE-FIRED BURNER FOR EXISTING BOILER. PROVIDE EITHER CARLIN EZGAS MODEL EZ-1 OR RIELLO R-40 SERIES MODEL F-5 BURNER. PROVIDE BAROMETRIC DAMPER WITH MANUAL RESET SPILL SWITCH IN BOILER FLUE. 5 ROUTE PROPANE PIPING TO PROPANE STORAGE TANKS. REFER TO CONTINUATION.
- 6 DDC TEMPERATURE CONTROL PANEL.
- PROVIDE SIDEWALL COMBUSTION AIR FAN. INTERLOCK FAN WITH BOILERS THROUGH BOILER CONTROOLER..
- \langle 8 \rangle PROVIDE EXISTING PUMPS WITH NEW BACNET CONNECTION TO NEW BMS.
- 9 PROVIDE EXISTING BOILERS WITH NEW BOILER CONTROLLER WITH BACNET CONNECTION TO NEW
- COMPLETELY REMOVE EXISTING SUMP PUMP DRAIN PIPING AND ALL ASSOCIATED HANGERS AND SUPPORTS BACK TO POINT INDICATED.
- CONNECT NEW 3" SUMP PUMP DRAIN PIPING TO EXISTING PIPING. ROUTE 3" DRAIN PIPING THROUGH FOUNDATION WALL AND CONNECT TO NEW UNDERDRAIN PIPING. REFER TO SITE PLAN ON SHEET SP101 FOR CONTINUATION.

6 GREEN TREE DRIVE S0. BURLINGTON, VT 05403 TEL: 802.878.7661 www.dubois-king.com

> VERMONT **NEW HAMPSHIRE**

MAINE AND NEW YORK © Copyright 2023 DuBois & King Inc.



| | | | S | $\dot{\circ}$ |
|--|--|--|------------------------|---------------|
| | | | S HUM | ВҮ |
| | | | 03/31/2023 ADDENDUM #1 | DESCRIPTION |
| | | | 03/31/2023 | DATE |
| | | | 1 | NO. |
| | | | | |



KINGMAN SCHOOL MECHANICAL SYSTEM UPGRADES

25 PARK ST. KINGMAN, ME 04451

SHEET TITLE

MECHANICAL **ENLARGED PLANS**


| DRAWN BY | DATE |
|------------|---------------|
| MJH | 03/10/202 |
| CHECKED BY | D&K PROJECT # |
| SVD | 528138 |
| PROJ. ENG. | D&K ARCHIVE # |
| SVD | |
| | |


SHEET NUMBER

SHEET 7 OF 11


ISSUED FOR BID


03/10/2023













9 EXTERIOR EQUIPMENT CONCRETE PAD DETAIL NOT TO SCALE

- 1. CONCRETE SHALL BE STONE CONCRETE HAVING A MINIMUM COMPRESSIVE STRENGTH OF 4,500 PSI AT 28 DAYS.
- 2. COORDINATE SIZES, LOCATIONS AND QUANTITIES WITH MECHANICAL DRAWINGS.



2 GAS SUPPLY CONNECTION DETAIL NOT TO SCALE




NOTES:

ELBOW


LOCKING LUGS INTEGRAL WITH VALVE
 MAXIMUM UNSUPORTED VANE LENGTH 48"
 FRAMES— BOLTED OR RIVETED TO ELBOW
 VANES AND FRAMES— SAME GAUGE AS

| SINGLE VANE SCHEDULE | | | | |
|----------------------|------|--------|----|--|
| | R | SP | GA | |
| SMALL | 2" | 1 ½" | 24 | |
| LARGE | 4 ½" | 3 1/4" | 22 | |
| | | | | |


DOUBLE THICKNESS TURNING VANES FOR SQUARE ELBOWS NOT TO SCALE




8 UNDERGROUND LP GAS STORAGE TANK
NOT TO SCALE



ROUND DUCT BRANCH CONNECTION DETAIL



4 CEILING DIFFUSER INSTALLATION DETAILS NOT TO SCALE



7 LP GAS STORAGE TANK PIPING DETAIL
NOT TO SCALE

ISSUED FOR BID

03/10/2023



6 GREEN TREE DRIVE S0. BURLINGTON, VT 05403 TEL: 802.878.7661 www.dubois-king.com

VERMONT NEW HAMPSHIRE MAINE AND NEW YORK

MAINE AND NEW YORK
© Copyright 2023 DuBois & King Inc



| , | - | 03/31/2023 | 1 03/31/2023 ADDENDUM #1 | MJH SV | S |
|---|----------|------------|--------------------------|--------|---|
| | NO. | NO. DATE | DESCRIPTION | BY CK' | ठ |



KINGMAN SCHOOL MECHANICAL SYSTEM UPGRADES

25 PARK ST. KINGMAN, ME 04451

SHEET TITLE

MECHANICAL DETAILS

 DRAWN BY
 DATE

 MJH
 03/10/2023

 CHECKED BY
 D&K PROJECT #

 SVD
 528138

 PROJ. ENG.
 D&K ARCHIVE #

SHEET NUMBER

M5.1

SHEET 8 OF 11

SURVEILLANCE INSPECTION REPORT

| LEA Education | On the Zenongaresed Secretary |
|----------------------------|---|
| SCHOOL Kingnan | Glenewtory School |
| ADDRESS _ 25 fack S | |
| - Kengnad. | Me 04451 |
| | |
| DATE OF INSPECTION | 8/17: |
| NAME OF INSPECTOR | Georgea Clink |
| THE CONDITION OF ACBM IN T | THE BUILDING NOT LISTED BELOW IS UNCHANGED. |
| LOCATION: | CHANGE NOTED: work complited |
| ang 15,-24, 25 | NorthEast Building Services |
| Montheast Builde | |
| Dervices layed | hencoln, Me 290-3390 |
| new tile an has | Cluxus. Leon Oudletto, Owner. |
| There was 663 sq x | <u>/+</u> |
| of commercial and | de all others areas |
| Qunch tiles afred. | down found to be st. |
| ones the existing a | slestos |
| geoor. | |
| SIGNATURE OF INSPECTOR | Trada lin |



HALEY WARD


ENGINEERING | ENVIRONMENTAL | SURVEYING



LETTER OF TRANSMITTAL

| Date: | November 2, 2021 | JN: | 11045.002 |
|----------------------------|--|--|--|
| To: | Ms. Sandy Moody | Re: | Three-year AHERA Re-inspection |
| | Maine Dept. of Environme Protection | ental | EUT State of Maine |
| | 17 State House Station | | |
| | Augusta, Maine 04333 | | |
| WE ARE | SENDING YOU | | |
| | CHED BY EMAIL | □ UNDER SEPAR | ATE COVER |
| POR BUILD | NAME OF STREET | IN THE RESERVE | |
| COPIES | DATE | | DESCRIPTION |
| 1 | November 1, 2021 | Three-year Al- State of Maine | ERA Re-inspection reports for EUT – |
| THESE AF | RE TRANSMITTED AS CHECKE | D BELOW: | |
| ☐ For Ap ☐ For Yo ☐ As Red | pproval \(\sigma \) Apprount \(\text{ur Use} \) \(\sigma \) Return \(\text{quested} \) | oved as Submitted oved as Noted ned for Corrections is Due20_ | □ ResubmitCopies for Approval □ SubmitCopies for Distribution □ ReturnCorrected Prints □ Prints Returned After Loan |
| Schools i complet | ncluding Connor, Kingman, ar | nd Edmunds. The 21 (respectively). | 2021 AHERA Re-inspection reports for EUT initial AHERA Re-inspection was The original reports were sent to the EUT |
| Copy To: CC: Ms. Si | usan Wilson, Dept of Education – EUT S ohn Bucci – Maine DEP (Electronic cop | State of Maine | d: _Deborah A. Kasik (jok) |





November 1, 2021

Ms. Susan Wilson
Department of Education
Education in Unorganized Territories
136 State House Station
Augusta, Maine 04333-0136

Re: Re-inspection of Kingman Elementary School for the Presence of Asbestos-Containing Materials in Accordance with the Asbestos Hazard Emergency Response Act (AHERA)

Dear Ms. Wilson:

On October 20, 2021, Haley Ward, Inc. (Haley Ward) conducted an Asbestos Reinspection Survey as required by the Asbestos Hazard Emergency Response Act (AHERA), at the Kingman Elementary School located in Kingman, Maine. The purpose of the reinspection was to observe the current conditions of asbestos-containing building materials (ACBM) and identify changes in quantity and condition of these materials since the original AHERA survey was conducted by Balsam Environmental Consultants in 1988. Previous documented three-year re-inspections occurred in 2000 (Eastern Skies Environmental Services); 2003, 2007, 2010 (Summit Environmental Consultants, Inc.); and 2014 (CES, Inc. – now Haley Ward). Ms. Deborah Kasik (Haley Ward), a U.S. Environmental Protection Agency (USEPA) and Maine Department of Environmental Protection (MDEP) accredited Asbestos Inspector and Asbestos Management Planner performed the current re-inspection.

During the re-inspection of the above referenced facility, the Haley Ward representative noted the following observations:





Kingman Elementary School

ACBM identified in the Kingman Elementary School during the original survey included vinyl asbestos floor tile (VAT) located throughout in the following areas:

- Classroom 1 (Library)
- Classroom 2
- Classroom 3
- Janitor's Closet
- Teacher's Room
- Teacher's Restroom
- Laundry (formerly office)
- Storage off Hallway
- Hallway

The VAT present throughout the school was observed to be in good condition. In November 2020, Stone Core Click Engineered Vinyl Plank Flooring was installed over existing VAT in the following areas:

- Classroom 3
- Teacher's Room
- Teacher's Restroom
- Laundry Room (formerly office)

The VAT in the Main Hallway leading to Classroom 1 through Classroom 3 was covered with 12-inch by 12-inch floor tiles in August 2017.

Both floor coverings (plank flooring and 12-inch floor tiles) were observed to be in good condition. The VAT remains beneath these floor coverings.

Changes were observed to the VAT in the following areas:

- Janitor's closet floor tiles are significantly worn with water damage (tiles are not sealed or waxed due to room usage).
- Storage off hallway floor tiles are worn with minor damage (floor tiles do not get sealed or waxed due to room usage).
- Library evidence of water damage noted along exterior wall; however, floor tiles are intact. Loose tiles were covered with cement and sealed.

Based on discussions with school representatives, ACBM has not been removed since the most recent AHERA three-year re-inspection performed in October of 2014.



Records of the Six-Month Asbestos Surveillance Evaluations were reviewed and indicate inspection by the school's Competent Person. Copies of work authorizations and the annual notification were included as part of the Management Plan. Available records indicate that asbestos awareness training had been completed by the school's administrator; however, we recommend that the facility conduct annual asbestos awareness training for the school's custodian in accordance with AHERA. Documentation of training and surveillances should be maintained with copies of your existing AHERA Asbestos Management Plan.

The floor tiles should be maintained under the school's Operations and Maintenance Program. Records of any implemented removals and repairs, including completion date should be noted in the school's AHERA Asbestos Management Plan.

Please provide a copy of this report to the school for filing with the existing AHERA Asbestos Management Plan. A copy should be maintained with the Education in Unorganized Territories' master AHERA records. Contact us immediately if you have any questions related to this project, or if we can be of assistance with any other issues.

Sincerely,

Haley Ward, Inc.

Deborah A. Kasik

Vibral A. Kasik

Project Scientist II

Maine Licensed Asbestos Inspector No. AI-0177

Maine Licensed Asbestos Management Planner No. MP-0178

Dennis B. Kingman Jr. CHMM

Senior Project Manager II

Maine Licensed Asbestos Inspector No. Al-0034

Maine Licensed Asbestos Management Planner No. MP-0092

DAK/DBK/jok Attachment




ASBESTOS HAZARD EMERGENCY RESPONSE ACT

RE-INSPECTION SURVEY

SIGNATURE PAGE

| Name of LEA: | Education in the Unorganized Territories |
|--|---|
| Name of School: | Kingman Elementary School (AHERA ID # 1118) |
| Address of School: | Maple Street |
| | Kingman Township, Maine 04451 |
| Re-inspection Conducted by: | Deborah A. Kasik |
| | (Typed Name of Inspector) |
| | (Signature of Inspector) |
| Inspector: RJ Enterprises, Inc Accreditation Ager | |
| Management Planner: | Dennis B. Kingman, Jr. |
| | (Typed Name of Management Planner) |
| | (Signature of Management Planner) |
| Management Planner: RJ Enterprises, Inc. | AMPR-21-10-14 MP-0092 10/08/21 |

Accreditation Agency Accreditation # MDEP License #



November 1, 2021

Ms. Susan Wilson
Department of Education
Education in Unorganized Territories
136 State House Station
Augusta, Maine 04333-0136

Re: Re-inspection of Connor Consolidated School for the Presence of Asbestos-Containing Materials in Accordance with the Asbestos Hazard Emergency Response Act (AHERA)

Dear Ms. Wilson:

On October 14, 2021, Haley Ward, Inc. (Haley Ward) conducted an Asbestos Reinspection Survey as required by the Asbestos Hazard Emergency Response Act (AHERA) at the Connor Consolidated School located in Connor Township, Maine. The purpose of the re-inspection was to observe the current conditions of asbestos-containing building materials (ACBM) and identify changes in quantity and condition of these materials since the original AHERA survey was conducted by Balsam Environmental Consultants in 1988. Previous documented three-year re-inspections occurred in 2000 (Eastern Skies Environmental Services); 2003, 2007, 2010 (Summit Environmental Consultants, Inc.); and 2014 (CES, Inc. – now Haley Ward). Ms. Deborah Kasik (Haley Ward), a U.S. Environmental Protection Agency (USEPA) and Maine Department of Environmental Protection (MDEP) accredited Asbestos Inspector and Asbestos Management Planner performed the current re-inspection.

During the re-inspection of the above referenced facility, the Haley Ward representative noted the following observations:

Connor Consolidated School

ACBM identified in the Connor Consolidated School during the original survey included vinyl asbestos floor tile (VAT) located throughout the building. The gymnasium was added in 2001 and the original gym was converted to hall and office space.

Ms. Susan Wilson | 11.01.2021 | 11045.002 | Page 1





Suspect ACBM in the new gym area includes 12-inch by 12-inch floor tile and ceiling tiles in the locker rooms, storage room, and office area. If impacted by future renovation, these materials should be sampled for the presence of asbestos or demonstrate with documentation provided by the architect that non-asbestos materials were used during construction of the gymnasium addition.

Based on discussions with school representatives, ACBM has not been removed after the most recent AHERA three-year re-inspection performed in October of 2014.

ACBM identified in the Connor Consolidated School during the original survey included vinyl asbestos floor tile (VAT) located in the following areas of the building:

- Grades 2 and 3
- Hallway near stairwell
- Grades K and 1
- Pre-K
- Art, Health, and Music Classroom
- Library
- Grades 4, 5, and 6
- Office near Teacher's Room
- Hallway and Storage Room off Kitchen

Response actions conducted since the previous three-year re-inspection are as follows:

- Previously identified damage near the entry door in the Storage Corridor adjacent to Kitchen has been sealed.
- Installed 12-inch by 12-inch floor tiles over existing ACM nine-inch floor tiles in the hallway to the gym, custodian storage, conference room, and Mrs. Johnson-Roy's room, as indicated in the previous three-year re-inspection.
- Replaced area of damaged tiles near the exterior door in Grades 2 and 3.
- Minor damage at the entry door to the classroom for Grades 2 and 3 filled with concrete and sealed.
- Replacement floor tiles were used in the Art, Health, & Music Classroom.

The floor tiles should be maintained under the school's Operations and Maintenance Program. Records of any implemented removals and repairs, including completion date should be noted in the school's AHERA Asbestos Management Plan.

Records of the Six-Month Asbestos Surveillance Evaluations were reviewed and indicate inspection by the school's competent person. A copy of the annual notification was included as part of the Management Plan. Available records indicate that asbestos awareness training had been completed by the school's administrator; however, we recommend that the facility conduct annual asbestos awareness training for the



school's custodian in accordance with AHERA. Documentation of training and surveillances should be maintained with copies of your existing AHERA Asbestos Management Plan.

Please provide a copy of this report to the school for filing with the existing AHERA Asbestos Management Plan. A copy should be maintained with the Education in Unorganized Territories' master AHERA records. Contact us immediately if you have any questions related to this project, or if we can be of assistance with any other issues.

Sincerely,

Haley Ward, Inc.

Deborah A. Kasik Project Scientist II

Maine Licensed Asbestos Inspector No. AI-0177

Arrah A. Kasik

Maine Licensed Asbestos Management Planner No. MP-0178

Dennis B. Kingman Wr. CHMM

Senior Project Manager II

Maine Licensed Asbestos Inspector No. Al-0034

Maine Licensed Asbestos Management Planner No. MP-0092

DAK/DBK/jok Attachment



ASBESTOS HAZARD EMERGENCY RESPONSE ACT

RE-INSPECTION SURVEY

SIGNATURE PAGE

| Name of LEA: | Education in the Unorganized Territories | | | | |
|--------------------------------|--|----------|--|--|--|
| Name of School: | Connor Consolidated School (AHERA ID # 1116) | | | | |
| Address of School: | RFD #4 | | | | |
| | Caribou, Maine 04736 | | | | |
| Re-inspection Conducted by: | Deborah A. Kasik | | | | |
| | (Typed Name of Inspector) | | | | |
| | Nebrah A. Karik | | | | |
| | (Signature of Inspector) | | | | |
| Inspector: RJ Enterprises, Inc | | 11/12/20 | | | |
| Accreditation Agen | cy Accreditation # MDEP License # | Date | | | |
| | | | | | |
| Management Planner: | Dennis B. Kingman, Jr. | | | | |
| | (Typed Name of Management Planner) | | | | |
| | antella . | | | | |
| | (Signature of Management Planner) | | | | |
| Management | | | | | |
| Planner: RJ Enterprises, Inc | | 10/08/21 | | | |
| Accreditation Ager | CV Accreditation # MDEP License # | Dato | | | |

State of Maine

Department of Environmental Protection Lead & Asbestos Hazard Prevention Program 17 State House Station, Augusta, ME 04333 TEL (207) 287-2651 FAX (207) 287-6220

AHERA Reinspection Notification Form Z


Date Received by MDEP:

Important Notice

In accordance with Chapter 425 Asbestos Management Regulation 425.4(C)(5)(e), an Asbestos Consultant is required provide an electronic file, or upon request a paper copy, of each three-year AHERA re-inspection and management plan recommendation report to the Local Education Agency (LEA) and the State of Maine Bureau of General Services [BGS] (77 SHS Augusta, ME 04333-0077) within 60 days of completing of each re-inspection. In addition, the Asbestos Consultant is required to notify the Department of dates that the reports were sent to the LEA and BGS; notification to the Department is concurrent with re-inspection report submissions to the LEA and BGS. A completed Form Z must be submitted to the Department for each school reinspected unless multiple schools within the same LEA are reinspected during the same calendar month, then only one completed Form Z for the LEA is required. Do not send the Department a copy of the reinspection report.

| cond the Department a copy of the reinspection report. | | |
|---|---|---------------------------|
| Asbestos Consultant: | | |
| Company Name: HALEY WARD, LOC. Address: I MERCHANT'S PLAZA SUITE | | |
| Address: 1 MERCHANT'S PLAZA SUITE | 701 | |
| City: BANGOR | State: ME | Zip: 04401 |
| Telephone: (207) 989-4824 | | 701 |
| Management Planner: DENNIS B. KINGMAN JRCG | ertification #: MP-0092 | Expiration Date: 10/31/21 |
| Local Education Agency (LEA): | | . , , . |
| Name: EDUCATION IN UNORGANIZED TERR | TORIES | # Schools Reinspected: 3 |
| Address: 136 STATE HOUSE STATION | | _ |
| City: AUCIUSTA State: M | E | zip: 04333 - 0136 |
| City: AUCTUSTA State: M LEA Contact: BARB PINEAU - CONNOR TRUBU AHERA Reinspection: | NEWCOMB Telephon | ie: |
| AHERA Reinspection: | 70 75 | |
| Date of Reinspection: 10/14/21 CONNOR; 10/20/21 KING | MAN; 10/21/21 | DMUNDS |
| Date Reinspection Report sent to LEA: 10/29/21 | , , | |
| Date Reinspection Report sent to BGS: 10/29/21 | | |
| List all schools covered by this notification & indicate whether ACM is present | or is ACM Eroo: | |
| CONNOR CONSOLIDATED SCHOOL- ACM | Doctor | |
| KINGMAN ELEMENTARY SCHOOL - ACI | 415 PRESENT | _ |
| EDMUNDS CONSOLIBATED SCHOOL - A | CMIS PRESENT | T |
| | .,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,, | |

| Submitted by: | |
|------------------------------|---------------|
| Signature Masik | Date 10/29/21 |
| Print Name: DEBORAH A. KASIK | |



November 1, 2021

Ms. Susan Wilson
Department of Education
Education in Unorganized Territories
136 State House Station
Augusta, Maine 04333-0136

Re: Re-inspection of Edmunds Consolidated School for the Presence of Asbestos-Containing Materials in Accordance with the Asbestos Hazard Emergency Response Act (AHERA)

Dear Ms. Wilson:

On October 21, 2021, Haley Ward, Inc. (Haley Ward) conducted an Asbestos Re-inspection Survey as required by the Asbestos Hazard Emergency Response Act (AHERA) at the Edmunds Consolidated School located in Dennysville, Maine. The purpose of the re-inspection was to observe the current conditions of asbestos-containing building materials (ACBM) and identify changes in quantity and condition of these materials since the original AHERA survey was conducted by Balsam Environmental Consultants in 1988. Previous documented three-year re-inspections occurred in 2000 (Eastern Skies Environmental Services); 2003, 2007, 2010 (Summit Environmental Consultants, Inc.); and 2014 (CES, Inc. – now Haley Ward). Ms. Deborah Kasik (Haley Ward), a U.S. Environmental Protection Agency (USEPA) and Maine Department of Environmental Protection (MDEP) accredited Asbestos Inspector and Asbestos Management Planner performed the current re-inspection.

During the re-inspection of the above referenced facility, the Haley Ward representative noted the following observations:

Edmunds Consolidated School

ACBM identified in the Edmunds Consolidated School during the original survey included vinyl asbestos floor tile (VAT) located throughout in the following areas:

- Resource Room
- Classroom 5 and 6
- Classroom 7 and 8
- Hallway
- Custodian's Closet

Ms. Susan Wilson | 11.01.2021 | 11045.002 | Page 1



The identified VAT is present beneath carpeting in all areas except for the VAT present in the Custodian's Closet where it has been covered with a layer of sheet flooring and a layer of 12-inch floor tiles. The floor tile adhesive associated with the VAT was not originally sampled and analyzed for asbestos. This material should be assumed ACBM until analytical testing demonstrates it does not contain asbestos.

Records of the Six-Month Asbestos Surveillance Evaluations were reviewed and indicate inspection by the school's competent person. Copies of work authorizations and the annual notification were included as part of the Management Plan. Available records indicate that asbestos awareness training had been completed by the school's administrator; however, we recommend that the facility conduct annual asbestos awareness training for the school's custodian in accordance with AHERA. Documentation of training and surveillances should be maintained with copies of your existing AHERA Asbestos Management Plan.

The floor tiles should be maintained under the school's Operations and Maintenance Program. Records of any implemented removals and repairs, including the completion date should be noted in the school's AHERA Asbestos Management Plan.

Please provide a copy of this report to the school for filing with the existing AHERA Asbestos Management Plan. A copy should be maintained with the Education in Unorganized Territories' master AHERA records. Contact us immediately if you have any questions related to this project, or if we can be of assistance with any other issues.

Sincerely,

Haley Ward, Inc.

Deborah A. Kasik Project Scientist II

Maine Licensed Asbestos Inspector No. AI-0177

Maine Licensed Asbestos Management Planner No. MP-0178

Dennis B. Kingman Jr. CHMM Senior Project Manager II

Maine Licensed Asbestos Inspector No. AI-0034

Maine Licensed Asbestos Management Planner No. MP-0092

DAK/DBK/jok Attachment



ASBESTOS HAZARD EMERGENCY RESPONSE ACT

RE-INSPECTION SURVEY

SIGNATURE PAGE

| Name of LEA: | Education in the Unorganized Territories | |
|-----------------------------------|--|--|
| Name of School: | Edmunds Consolidated School (AHERA ID # 1117) | |
| Address of School: | Harrison Road | |
| | Dennysville, Maine 04451 | |
| Re-inspection Conducted by: | Deborah A. Kasik | |
| , | (Typed Name of Inspector) | |
| | Debrah a. Karik | |
| | (Signature of Inspector) | |
| | | |
| Inspector: RJ Enterprises, Inc | | |
| Accreditation Agen | cy Accreditation # MDEP License # Date | |
| | | |
| Management Planner: | Dennis B. Kingman, Jr. | |
| | (Typed Name of Management Planner) | |
| | The state of the s | |
| (Signature of Management Planner) | | |
| | | |
| Management | | |
| Planner: RJ Enterprises, Inc | 10/00/21 | |
| Accreditation Agend | cy Accreditation # MDEP License # Date | |

State of Maine

Department of Environmental Protection Lead & Asbestos Hazard Prevention Program 17 State House Station, Augusta, ME 04333 TEL (207) 287-2651 FAX (207) 287-6220

AHERA Reinspection Notification Form Z

Date Received by MDEP:

Important Notice

In accordance with Chapter 425 Asbestos Management Regulation 425.4(C)(5)(e), an Asbestos Consultant is required provide an electronic file, or upon request a paper copy, of each three-year AHERA re-inspection and management plan recommendation report to the Local Education Agency (LEA) and the State of Maine Bureau of General Services [BGS] (77 SHS Augusta, ME 04333-0077) within 60 days of completing of each re-inspection. In addition, the Asbestos Consultant is required to notify the Department of dates that the reports were sent to the LEA and BGS; notification to the Department is concurrent with re-inspection report submissions to the LEA and BGS. A completed Form Z must be submitted to the Department for each school reinspected unless multiple schools within the same LEA are reinspected during the same calendar month, then only one completed Form Z for the LEA is required. Do not send the Department a copy of the reinspection report.

| send the Department a copy of the reinspection report. | | no ZEA is required. Do not |
|--|-----------------------|----------------------------|
| Asbestos Consultant: | | |
| Company Name: HALEY WARD, Soc. Address: 1 MERCHANT'S PLAZA SUITE | | |
| Address: 1 MERCHANT'S PLAZA SUITE | 701 | |
| city:BANGOR | State: ME | Zip: 04401 |
| Telephone: (207) 989-4824 | | |
| Management Planner: DENNIS B. KINGMAN JRCG | ertification #: MP009 | Expiration Date: 10/3// |
| Local Education Agency (LEA): | , /6 | 1-101 |
| Name: EDUCATION IN UNORGANIZED TERR | 17) RIES | # Schools Reinspected: 3 |
| Address: (36 STATE HOUSE STATION) | | |
| City: AuCTUSTA State: M | E | 7in: 0// 7 2 7 |
| City: AUCTUSTA State: M LEA Contact: BETH LONGAN-KINGMAN EDI AHERA Reinspection: | NEWCOMB Telephor | Zip: 04333 - 0136 ne: |
| AHERA Reinspection: | - Mar P3 | |
| Date of Reinspection: 10/14/21 CONNOR; 10/20/21 KING | MAN; 10/21/21 | EDMUNDS |
| Date Reinspection Report sent to LEA: 10/29/21 | , , , | |
| Date Reinspection Report sent to BGS: 10/29/21 | | |
| List all schools covered by this notification & indicate whether ACM is present | or is ACM From: | |
| CONNOR CONSOLIDATED SCHOOL - ACM | IS PASSED 1 | |
| KINGMAN ELEMENTARY SCHOOL - ACA | 415 PRESENT | - |
| EDMUNDS CONSOLIBATED SCHOOL - ACMIS PRESENT | | |
| | . 10 1. (200) | , |

| Submitted by: | |
|------------------------------|---------------|
| Debnah Alasik Signature | Date 10/29/21 |
| Print Name: DEBORAH A. KASIK | , |