## MASONRY REPAIRS AND ASSOCIATED WORK AT THE

# CENTER BUILDING

67 INDEPENDENCE DRIVE AUGUSTA, MAINE 04330

## PREPARED FOR

STATE OF MAINE BUREAU OF GENERAL SERVICES 111 SEWALL STREET, 77 STATE HOUSE STATION AUGUSTA, MAINE 04333

DRAWING NO

A702

**COVER SHEET** G100

G101


MASONRY REPAIR DETAILS

A101 A201 **ELEVATIONS** A202 A203 **ELEVATIONS** 

**ELEVATIONS** A701 MASONRY REPAIR DETAILS

SITE MAP NOT TO SCALE SITE PLAN, GENERAL NOTES, AND ELEVATION NOTES OVERALL ROOF AREA PLAN





LOCATION MAP NOT TO SCALE

GALE


MASONAY KEPAIKS AND ASSOCIATED WORK
67 INDEPENDENCE DRIVE
UGUSTA, IME 04330 OWNER
STATE OF MAINE BUREAU OF GENERAL SERVICES
111 SEWALL STREET, 77 STATE HOUSE STATION
ALIGHSTA ME 04333


NO.	DATE	D	ESCRIPTION	BY		
PROJECT NO.			839100			
CADD FILE			839100 G100			
DESIGNED BY			ACP			
DRAWN BY			MRS			
CHECKED BY			ACP			
DATE			2/29/2024			
DRAWING SCALE			NOT TO SCALE			
GRAPHIC SCALE						


GRAPHIC SCALE


SHEET TITLE

**COVER SHEET** 










\PARTIAL SOUTH ELEVATION A201 SCALE: NOT TO SCALE









PARTIAL NORTH ELEVATION A201 SCALE: NOT TO SCALE



Gale Associates, Inc. Engineers and Planners

5 Moulton Street Portland, ME 04101 207.536.1092 www.gainc.com

Boston Baltimore Orlando Hartford Manchester Portland

This drawing and the design and construction features disclosed are proprietary to Gale Associates, Inc. and shall not be altered or reused in whole or part without the express written permission of Gale Associates, Inc.

Copyright©2022

SS AND ASSOCIATE SENTER BUILDING PENDENCE DRIVE JSTA, ME 04330

MASONR

### REPAIR LEGEND

**ELEVATION NOTES** 

REFER TO GENERAL AND ELEVATION NOTES ON SHEET G101 FOR ADDITIONAL INFORMATION

- ATMOSPHERIC STAINING TO BE CLEANED; # INDICATES SQUARE ALGAE GROWTH TO BE CLEANED;
- # INDICATES SQUARE FEET CRACKED BRICK TO BE REMOVED
- AND REPLACED; # INDICATES UNITS DISPLACED BRICK TO BE REMOVED AND REPLACED;

# INDICATES UNITS

- DETERIORATED MORTAR JOINT TO BE CUT AND REPOINTED, REFER TO DETAIL 4/A701 FOR ADDITIONAL INFORMATION; # INDICATES SQUARE FEET
- CRACKED STONE TO BE REPAIRED, REFER TO DETAIL 7/A702 FOR ADDITIONAL INFORMATION; # INDICATES LINEAR FEET
- SPALLED STONE TO BE REPAIRED; # INDICATES SQUARE FEET DETERIORATED MORTAR JOINT TO
- BE REPOINTED; # INDICATES LINEAR FEET, REFER TO DETAIL 4/A701 FOR ADDITIONAL INFORMATION
- EXISTING ANCHOR / METAL STUB TO BE REMOVED AND INFILLED
- REPOINTED, REFER TO DETAIL 4/A701 FOR ADDITIONAL # INDICATES LÍNEAR FEET

SPALLED BRICK TO BE REMOVED


- AND REPLACED; # INDICATES UNITS FAILED SEALANT TO BE REMOVED
- AND REPLACED; # INDICATES
- EFFLORESCENCE TO BE CLEANED; # INDICATES SQUARE FEET
- RUST STAINING TO BE CLEANED; # INDICATES SQUARE FEET
- BRICK MASONRY TO BE REBUILT;
  # INDICATES APPROXIMATE SQUARE FEET
- APPROXIMATE LOCATION OF NEW THROUGHWALL FLASHING; REFER TO DETAIL
  - APPROXIMATE LOCATION OF NEW THROUGHWALL FLASHING; REFER TO DETAIL
  - APPROXIMATE LOCATION OF **NEW THROUGHWALL** FLASHING; REFER TO DETAIL

#### REPAIR NOTES

THE DEFECTS NOTED INDICATE APPROXIMATE LOCATIONS. THEY ARE NO INTENDED TO DEFINE LIMITS OF WORK. AREAS NOT NOTED ON THESE DRAWINGS EXHIBITING SIMILAR DEFECTS AS THOSE SHOWN SHALL BE REPAIRED IN A SIMILAR MANNER.

NOT ALL DEFECTS INCLUDED IN THE LEGEND MAY BE INCLUDED ON THIS SHEET

- IN THE EVENT THAT ADDITIONAL DEFECTS ARE ENCOUNTERED TO THOSE INCLUDED IN THE CONTRACT DOCUMENTS, CONTRACTOR IS TO REPORT THE ADDITIONAL QUANTITIES TO THE OWNER AND ENGINEER PRIOR TO PERFORMING REPAIRS. COORDINATE WITH SPECIFICATION SECTION 01 22 00 - UNIT PRICES.
- CONTRACTOR TO CLEAN EFFLORESCENCE, ALGAE GROWTH, VEGETATIVE GROWTH, ATMOSPHERIC STAINING, AND RUST STAINING FROM 100% OF BRICK MASONRY ELEVATIONS.
- REMOVE, STORE, AND REINSTALL DOWNSPOUTS AS REQUIRED TO PERFORM THE WORK.



DESCRIPTION PROJECT NO. 839100 CADD FILE 839100 A200s **DESIGNED BY** ACP **DRAWN BY** MRS ACP **CHECKED BY** 

DRAWING SCALE NOT TO SCALE **GRAPHIC SCALE** 

2/29/2024

SHEET TITLE

**ELEVATIONS** 

DRAWING NO.






PARTIAL SOUTH ELEVATION
SCALE: NOT TO SCALE







PARTIAL WEST ELEVATION

SCALE: NOT TO SCALE



Gale Associates, Inc. Engineers and Planners

5 Moulton Street Portland, ME 04101 P 207.536.1092

ASSOCIATE BUILDING ICE DRIVE E 04330

MAS(

www.gainc.com

Boston Baltimore Orlando Hartford

Manchester Portland

This drawing and the design and construction features disclosed are proprietary to Gale Associates, Inc. and shall not be altered or reused in whole or part without the express written permission of Gale Associates, Inc.

Copyright©2022

#### REFER TO GENERAL AND ELEVATION NOTES ON SHEET G101 FOR ADDITIONAL INFORMATION

**ELEVATION NOTES** 

REPAIR LEGEND

ATMOSPHERIC STAINING TO BE CLEANED; # INDICATES SQUARE

ALGAE GROWTH TO BE CLEANED; # INDICATES SQUARE FEET

CRACKED BRICK TO BE REMOVED
AND REPLACED;
# INDICATES UNITS

DISPLACED BRICK TO BE REMOVED AND REPLACED;
# INDICATES UNITS

DETERIORATED MORTAR JOINT TO BE CUT AND REPOINTED, REFER TO DETAIL 4/A701 FOR ADDITIONAL INFORMATION; # INDICATES SQUARE FEET

CS # CRACKED STONE TO BE REPAIRED,
REFER TO DETAIL 7/A702 FOR
ADDITIONAL INFORMATION;
# INDICATES LINEAR FEET

SS SPALLED STONE TO BE REPAIRED; # INDICATES SQUARE FEET

DETERIORATED MORTAR JOINT TO BE REPOINTED; # INDICATES LINEAR FEET, REFER TO DETAIL 4/A701 FOR ADDITIONAL INFORMATION

EXISTING ANCHOR / METAL STUB TO BE REMOVED AND INFILLED

STEP CRACK TO BE CUT AND REPOINTED, REFER TO DETAIL 4/A701 FOR ADDITIONAL INFORMATION;
# INDICATES LINEAR FEET

SPALLED BRICK TO BE REMOVED
AND REPLACED;
# INDICATES UNITS

FS FAILED SEALANT TO BE REMOVED AND REPLACED; # INDICATES LINEAR FEET

EF EFFLORESCENCE TO BE CLEANED;
# INDICATES SQUARE FEET

RS RUST STAINING TO BE CLEANED; # INDICATES SQUARE FEET

BRICK MASONRY TO BE REBUILT;
# INDICATES APPROXIMATE
SQUARE FEET

APPROXIMATE LOCATION OF NEW THROUGHWALL FLASHING; REFER TO DETAIL


APPROXIMATE LOCATION OF NEW THROUGHWALL FLASHING; REFER TO DETAIL

APPROXIMATE LOCATION OF NEW THROUGHWALL FLASHING; REFER TO DETAIL

NOT ALL DEFECTS INCLUDED IN THE LEGEND MAY BE INCLUDED ON THIS SHEET

## REPAIR NOTES

- 1. THE DEFECTS NOTED INDICATE APPROXIMATE LOCATIONS. THEY ARE NO INTENDED TO DEFINE LIMITS OF WORK. AREAS NOT NOTED ON THESE DRAWINGS EXHIBITING SIMILAR DEFECTS AS THOSE SHOWN SHALL BE REPAIRED IN A SIMILAR MANNER.
- 2. IN THE EVENT THAT ADDITIONAL DEFECTS ARE ENCOUNTERED TO THOSE INCLUDED IN THE CONTRACT DOCUMENTS, CONTRACTOR IS TO REPORT THE ADDITIONAL QUANTITIES TO THE OWNER AND ENGINEER PRIOR TO PERFORMING REPAIRS. COORDINATE WITH SPECIFICATION SECTION 01 22 00 UNIT PRICES.
- 3. CONTRACTOR TO CLEAN EFFLORESCENCE, ALGAE GROWTH, VEGETATIVE GROWTH, ATMOSPHERIC STAINING, AND RUST STAINING FROM 100% OF BRICK MASONRY ELEVATIONS.
- 4. REMOVE, STORE, AND REINSTALL DOWNSPOUTS AS REQUIRED TO PERFORM THE WORK.



NO. DATE DESCRIPTION BY
PROJECT NO. 839100
CADD FILE 839100 A200s
DESIGNED BY ACP
DRAWN BY MRS
CHECKED BY ACP
DATE 2/29/2024

DRAWING SCALE


GRAPHIC SCALE


SHEET TITLE

**ELEVATIONS** 

A202


DRAWING NO.






PARTIAL WEST ELEVATION
SCALE: NOT TO SCALE









PARTIAL WEST ELEVATION
SCALE: NOT TO SCALE



Gale Associates, Inc. Engineers and Planners

5 Moulton Street Portland, ME 04101 P 207.536.1092

ASSOCIATE BUILDING ICE DRIVE E 04330

MASONRY

www.gainc.com

Boston Baltimore Orlando Hartford

Manchester Portland

This drawing and the design and construction features disclosed are proprietary to Gale Associates, Inc. and shall not be altered or

reused in whole or part without the express

written permission of Gale Associates, Inc. Copyright©2022

## **ELEVATION NOTES**

1. REFER TO GENERAL AND ELEVATION NOTES ON SHEET G101 FOR ADDITIONAL INFORMATION

## REPAIR LEGEND

- ATMOSPHERIC STAINING TO BE CLEANED; # INDICATES SQUARE FEET
- ALGAE GROWTH TO BE CLEANED; # INDICATES SQUARE FEET
- CRACKED BRICK TO BE REMOVED
  AND REPLACED;
  # INDICATES UNITS
- DISPLACED BRICK TO BE REMOVED AND REPLACED;
  # INDICATES UNITS
- DETERIORATED MORTAR JOINT TO BE CUT AND REPOINTED, REFER TO DETAIL 4/A701 FOR ADDITIONAL INFORMATION; # INDICATES SQUARE FEET
- CS CRACKED STONE TO BE REPAIRED, REFER TO DETAIL 7/A702 FOR ADDITIONAL INFORMATION; # INDICATES LINEAR FEET
- SS # SPALLED STONE TO BE REPAIRED; # INDICATES SQUARE FEET

  DETERIORATED MORTAR JOINT TO BE REPOINTED; # INDICATES

  HERDER STONE TO BE REPAIRED; # INDICATES
- # BE REPOINTED; # INDICATES
  LINEAR FEET, REFER TO DETAIL
  4/A701 FOR ADDITIONAL
  INFORMATION
- × EXISTING ANCHOR / METAL STUB TO BE REMOVED AND INFILLED


STEP CRACK TO BE CUT AND REPOINTED, REFER TO DETAIL 4/A701 FOR ADDITIONAL INFORMATION; # INDICATES LINEAR FEET

- SPALLED BRICK TO BE REMOVED AND REPLACED;
  # INDICATES UNITS
- FS FAILED SEALANT TO BE REMOVED AND REPLACED; # INDICATES LINEAR FEET
- EF EFFLORESCENCE TO BE CLEANED;
  # INDICATES SQUARE FEET
- RS RUST STAINING TO BE CLEANED; # INDICATES SQUARE FEET
- BRICK MASONRY TO BE REBUILT;
  # INDICATES APPROXIMATE
  SQUARE FEET
- APPROXIMATE LOCATION OF NEW THROUGHWALL FLASHING; REFER TO DETAIL 1/A701
- APPROXIMATE LOCATION OF NEW THROUGHWALL FLASHING; REFER TO DETAIL 2/A701
- APPROXIMATE LOCATION OF NEW THROUGHWALL FLASHING; REFER TO DETAIL

NOT ALL DEFECTS INCLUDED IN THE LEGEND MAY BE INCLUDED ON THIS SHEET

## **REPAIR NOTES**

- 1. THE DEFECTS NOTED INDICATE APPROXIMATE LOCATIONS. THEY ARE NO INTENDED TO DEFINE LIMITS OF WORK. AREAS NOT NOTED ON THESE DRAWINGS EXHIBITING SIMILAR DEFECTS AS THOSE SHOWN SHALL BE REPAIRED IN A SIMILAR MANNER.
- 2. IN THE EVENT THAT ADDITIONAL DEFECTS ARE ENCOUNTERED TO THOSE INCLUDED IN THE CONTRACT DOCUMENTS, CONTRACTOR IS TO REPORT THE ADDITIONAL QUANTITIES TO THE OWNER AND ENGINEER PRIOR TO PERFORMING REPAIRS. COORDINATE WITH SPECIFICATION SECTION 01 22 00 UNIT PRICES.
- 3. CONTRACTOR TO CLEAN EFFLORESCENCE, ALGAE GROWTH, VEGETATIVE GROWTH, ATMOSPHERIC STAINING, AND RUST STAINING FROM 100% OF BRICK MASONRY ELEVATIONS.
- 4. REMOVE, STORE, AND REINSTALL DOWNSPOUTS AS REQUIRED TO PERFORM THE WORK.



·				
NO.	DATE	DESCRIPTION		BY
PROJECT NO.			839100	
CADD FILE			839100 A200s	
DESIGNED BY			ACP	
DRAWN BY			MRS	
CHECKED BY			ACP	

DATE 2/29/2024

DRAWING SCALE NOT TO SCALE

GRAPHIC SCALE

SHEET TITLE

**ELEVATIONS** 

A203

DRAWING NO.

