

SERIAL NO.	LOCATION	DATE	ARRIVED	PROBLEM	REPAIR	COMPLETED	CHEMIST
80-005676	Aroostook SO	12/11/2015	12/28/2015	Enter key not responding for calcheck	No problem found, cleaned keyboard	1/6/2016	rm
80-005556	Bar Harbor PD	11/17/2015	11/19/2015	Diagnostic failure	F.S.	12/23/2015	rm
80-005612	Boothbay Harbor PD	12/31/2014	12/31/2014	No power	F.S.	1/21/2015	rm
80-005607	Bridgton PD	5/17/2016	5/18/2016	No power	F.S.	6/16/2016	rm
80-005671	Camden PD	11/6/2014	11/6/2014	No power	F.S.	12/9/2014	rm
80-005564	Carrabassett Valley PD	10/7/2014	10/10/2014	No power	F.S.	12/4/2014	rm
80-005670	Cumberland PD	7/1/2016	7/15/2016	Purge fails on subject tests, no power	F.S.	10/19/2016	rm
DR 2287	Cumberland PD	10/20/2016	10/21/2016	Stops stirring occasionally	F.S.	11/21/2016	rm
80-005705	E. Millinockett PD	9/12/2014	9/18/2014	No power	F.S.	10/10/2014	rm
80-005674	Freeport PD	1/15/2015	1/15/2015	Interferent detected problem?	No problem found, sent to F.S.	2/25/2015	rm
80-005602	Fryeburg PD	4/10/2015	4/15/2015	No power	F.S.	6/1/2015	rm
80-005701	Gardiner PD	7/3/2014	7/3/2014	.09 solution reads low?	F.S.	7/18/2014	rm
80-005701	Gardiner PD	10/9/2015	10/9/2015	.05 & .10 solutions read low, INT too	F.S.	11/13/2015	rm
80-005586	HETL - 2	3/22/2016	3/22/2016	No display. No power	F.S.	5/5/2016	rm
80-005585	HETL - 3	12/15/2015	12/15/2015	No power	F.S.	3/3/2016	rm
80-005623	Knox SO	9/9/2015	9/9/2015	No power	F.S.	10/7/2015	rm
DR-2290	Lisbon PD	9/30/2014	9/30/2014	No display on simulator	F.S.	10/20/2014	rm
80-005668	Oakland PD	9/8/2016	9/13/2016	No power	F.S.	11/30/2016	rm
80-005625	Old Town PD	1/7/2014	1/17/2014	Interferent on subj tests, calchecks	F.S.	2/11/2014	rm
80-005673	Oxford PD	4/11/2016	4/13/2016	No power	F.S.	5/18/2016	rm
80-005622	Oxford SO	1/6/2016	1/21/2016	Interferent on subj tests, calchecks	F.S.	4/21/2016	rm
DR-2317	Richmond PD	8/7/2014	8/7/2014	No display	F.S.	8/28/2014	rm
80-005610	Sabattus PD	3/16/2014	3/16/2014	Stability fail?	No problem found	3/24/2014	rm
80-005610	Sabattus PD	11/9/2015	11/10/2015	No power	F.S. x3	2/9/2016	rm
80-005704	Sanford PD	7/11/2014	7/23/2014	No display, no power	F.S.	8/26/2014	rm
80-005675	Scarborough PD	3/23/2015	3/26/2015	Breath hose broken	Replaced breath hose	3/26/2015	rm
80-005680	Somerset SO	3/17/2014	3/17/2014	System error 010	F.S.	5/6/2014	rm
DR-2134	South Berwick PD	8/6/2014	8/14/2014	Simulator error 4	No problem found	8/15/2014	rm
80-005587	South Portland PD	6/6/2016	6/7/2016	No power	F.S.	6/28/2016	rm
68-013448	Togus PD	4/12/2016		Interferent on simulator solutions	F.S. by Togus PD	7/29/2016	rm
DR 2325	Westbrook PD	9/1/2016	9/14/2016	No power	F.S.	9/28/2016	rm
80-005608	Westbrook PD	8/30/2016	8/30/2016	No bar code reader light, sim loses pw	F.S.	11/22/2016	rm
80-005698	York SO	6/5/2015	6/6/2015	Purge fails, no power	F.S.	8/12/2015	rm
80-005698	York SO	9/8/2015	9/8/2015	Purge fails	F.S.	10/7/2015	rm