



NOTES:

- Place Tie Plates BR150-5B or 5C on Pipe BR150-5D as shown and listed.
- Thread Sleeve BR150-5F on pipe.
- Place end of Pipes BR150-5D in Plate BR150-5E and, with 2 1/2 holes to dimension, weld Plate BR150-5E. Care must be taken to keep 3 plates with 2 1/2 holes, in line as noted.
- Stress relieve after all welding has been finished.

APPROVED	DESIGNED	CHECKED	DATE	PROJECT	COMPLETE
MARK	REQ'D	MAT'L	REQ. NO.	NAME	REMARKS
BILL OF MATERIAL					
JOHN A. ROEBLING'S SONS CO., TRENTON, N. J.					
				DEER ISLE BRIDGE REINFORCEMENT	
				CARLE BAND CONNECTION	
				DETAILS	
BY	REVISIONS	DATE			
	General Revisions	4-30-44			
	General Revisions	2-16-44			
APPROVED			SCALE 3"=10'	SERIAL	SHEET
ROEBLING AND STEINMAN			DES		
FEB 28 1944			DR	6150	5
CH. DR.			TR		
ENG'R			CH		