

## Hollis

This report shows the 2023-2025 Work Plan entries for Hollis. The costs listed are the total cost of these projects – some of which may extend into neighboring towns. It also shows a listing of maintenance work specifically recorded to Hollis, as well as Local Road Assistance payments. Activities that are managed on a larger scale, such as snow & ice control, and maintenance work done by contract are not listed. The maintenance accomplishments may also extend into neighboring towns but are listed in the first town where the work was reported. Finally, any capital projects that were completed in 2022 are also listed.

### Planned Capital and Maintenance Work 2023-2025

**Work Plan Year:** 2023

**Municipalities(s):** Hollis

**Asset(s):** Route 202

**Description:** Beginning 0.13 of a mile north of Route 5 extending north 2.16 miles. Beginning 0.16 of a mile north of Main Street extending north 0.20 of a mile. Beginning 0.62 of a mile north of Osborne Road extending north 0.56 of a mile.

ID	Scope of Work	Highway Corridor Priority	Estimated Funding
022641.00	Highway Construction/Rehabilitation Rural Highways Reconstruction	HCP 1	\$11,300,000

**Work Plan Year:** 2024/25

**Municipalities(s):** Hollis

**Asset(s):** Route 202

**Description:** Salmon Falls Bridge (#3708) over Saco River. Located on the Hollis-Buxton town line.

ID	Scope of Work	Highway Corridor Priority	Estimated Funding
023643.00	Highway-Bridges Bridge Replacement	HCP 1	\$8,510,000

**Work Plan Year:** 2023

**Municipalities(s):** Hollis

**Asset(s):** West Buxton Road

**Description:** West Buxton Bridge (#3340) over the Saco River. Located 0.07 of a mile west of Route 112.

ID	Scope of Work	Highway Corridor Priority	Estimated Funding
025479.00	Highway-Bridges Bridge Improvements - PE Only	HCP 4	\$500,000

**Work Plan Year:** 2023

**Municipalities(s):** Hollis

**Asset(s):** Plains Road

**Description:** Beginning at Route 117 and extending west 2.30 miles to Shy Beaver Road.

ID	Scope of Work	Highway Corridor Priority	Estimated Funding
025853.00	Highway Paving Light Capital Paving	HCP 4	

**Work Plan Year:** 2023

**Municipalities(s):** Hollis

**Asset(s):** Route 4

**Description:** Beginning at the Lyman town line and extending north 2.23 miles to Stuart Lane.

ID	Scope of Work	Highway Corridor Priority	Estimated Funding
025853.00	Highway Paving Light Capital Paving	HCP 1	

**Work Plan Year:** 2023

**Municipalities(s):** Hollis

**Asset(s):** Route 117

**Description:** Beginning at Route 5/113 and extending north 11.28 miles.

ID	Scope of Work	Highway Corridor Priority	Estimated Funding
025853.00	Highway Paving Light Capital Paving	HCP 2, 4	

**Work Plan Year:** 2023

**Municipalities(s):** Hollis

**Asset(s):** Route 4A

**Description:** Beginning at Route 35 and extending north 2.33 miles.

ID	Scope of Work	Highway Corridor Priority	Estimated Funding
025853.00	Highway Paving Light Capital Paving	HCP 3	

Work Plan Year: 2023

Municipalities(s): Hollis

Asset(s): Route 202/Route 35

Description: Located at the intersection of Route 35 and Route 202.

ID	Scope of Work	Highway Corridor Priority	Estimated Funding
026021.00	Highway Safety and Spot Improvements Rural Highways Intersection Improvements W/ Signal	HCP 1	\$523,000

**Local Road Assistance – Fiscal Year – 2023**

\$53,948

**Maintenance Accomplishments – 2022**

Activities managed on a larger scale, such as snow & ice control, and work done by contract are not listed. *The maintenance accomplishments may extend into neighboring towns but are listed in the first town where the work was reported.*

5.00	Bridge(s) Washed
25.60	Ton(s) of Patch Applied
7,400.80	Ton(s) of Hot Mix Paving
3.00	Emergency Event Responses
30.30	Miles of Striping Applied
21.70	Shoulder Miles of Sweeping
1.00	Drainage Structures Repaired
1.00	Bridge Inspection(s) Performed
500.00	Linear Feet of Shoulder Rebuilt
1,555.00	Sq Feet of Pavement Legend Applied
1.00	Underwater Inspection(s) Performed
13.40	Mile(s) of Shoulder prepared for LCP
20.00	Sq Feet of Bridge Wearing Surface Repaired
200.00	Linear Feet of Guardrail or Fence Maintained