

Assessment for: Narrows Too Rec Center; ID ME0103527

Location: Trenton, Maine

Date: July 13, 2010

Summary of the Data used in our Assessment

Well type: unknown

Well identification number: 103527101

Well description: 275 ft deep

Overburden thickness (feet): 70

Positive bacteria test result(s): No

Nitrate test result(s) greater than 5 ppm: No

Septic system(s) within 300 feet of the well: No

Animal feedlots/manure piles(s) within 300 feet of the well: No

Risk Based on Well Type and Site Geology

Ranking:

Well type: unknown

Overburden thickness (feet): 70

*Existing risk of contamination
based on well type & site geology:*

Moderate risk

Existing Risk of Acute Contamination

Ranking:

Positive coliform test(s): No

Nitrate test(s) greater than 5 ppm: No

Septic system(s) within 300 feet of the well: No

Animal feedlot(s)/manure pile(s) within 300 feet of the well: No

Existing risk of acute contamination:

Low risk

Future Risk for Acute Contamination

Ranking:

Status of land control: The owner does own and control the land within the Well Head Protection Radius of 300 ft.

Future risk of acute contamination:

Low risk