

## Public Record – Summary Information On Motor Fuel Underground Storage Tanks (USTs)

### General Information

Public Record Posted Date: 2/6/09

Total Number Of UST Facilities: 1,551  
Total Number Of USTs: 3,102

### Summary Information For On-Site Inspections

Number Of UST Facilities Inspected: 360  
Inspection Period Dates: 10/1/07 To: 9/30/08  
Percent Compliance (Combined Measure): 54%

Note: Tank, facility, and on-site inspection information is based on inspections of UST motor fuel facilities only; heating oil USTs are not included. On-site inspections measure compliance with State of Maine and U.S. EPA regulations and laws governing the prevention and detection of petroleum releases or discharges.

### Summary Information For Releases

Number Of Confirmed UST Releases: 96  
Release Reporting Period Dates: 10/1/07 To: 9/30/08

### Summary Information For Release Sources And Causes (does not include bare steel tanks and piping)

Source			Cause											
			Spill/ Overfill		Phys/Mech Damage		Corrosion		Install Problem		Other		Unknown	
	#	%	#	%	#	%	#	%	#	%	#	%	#	%
Tank	10	19			4	19	1	25					5	26
Piping	12	22			1	5	2	50					9	47
Dispenser	20	36	1	11	16	76	1	25			1	100	1	6
Delivery Problem	9	16	8	89					1	100				
Unknown	4	7											4	21
Totals	55	100	9	100	21	100	4	100	1	100	1	100	19	100

# = number, % = percent of column total number

Note: Release, source and cause information is based on reported releases at motor fuel UST facilities constructed of approved corrosion resistant materials (no bare steel). Source and cause data were compiled from data collected in the course of investigating UST system releases and using EPA's LUST Site Release Reports.

For information about specific petroleum spills and releases in your town go to the Department's Hazardous and Oil Spill System (HOSS) online report service. For questions about the information on this page, please contact George Seel at (207) 287-2651 or [george.j.seel@maine.gov](mailto:george.j.seel@maine.gov).