



HOLTRACHEM MANUFACTURING  
 ORRINGTON, MAINE  
 SITE INVESTIGATION

WELL POINT LOCATIONS  
 LANDFILL #2

FIGURE 2

Approximate WP Location	Observed Distance from WP to Stream Edge
16	1'-5"
15	1'-5"
13/14	0'
9	2'-8"
8	1'-6"
2	0'
2A	0'
1	0'

Note: WP references are approximate since they are not field labeled and MDEP estimated locations in the field from this base map.

MDEP Site Inspection Figure 2.

Notes recorded by David Burns (MDEP) during a Mallinckrodt Landfill 1-5 site inspection on 4/1/10. Accompanied by Fred Lavallee and Stacy Ladner (MDEP) as well as Dave Tonini (CDM). Basemap taken from Joint-017 for BEP Hearing. Photo references are to photos taken by D. Burns during the inspection.

See MDEP Site Inspection Figure 1 for notes recorded for Landfills 1,3,4,&5.

0:\CAM\_IHW\0654\STBASE3.DWG

JOINT-017

JOINT-017.000012

