



## Public Record - Summary Information On Motor Fuel Underground Storage Tanks (USTs)

Public Record Posted Date: December 21, 2016

### General Information

Total Number of Active UST Facilities: 1,407  
 Total Number of Active USTs: 2,576

### Summary Information for On-Site Inspections<sup>1</sup>

Number of UST Facilities Inspected: 206  
 Inspection Period Dates: 10/1/15 To 9/30/16  
 Percent Compliance (Combined Measure): 70

Note: Tank, facility and on-site inspection information is based on inspections of UST motor fuel facilities only; heating oil USTs are not included. On-site inspections measure compliance with State of Maine and U.S. EPA laws and regulations governing the prevention and detection of petroleum releases or discharges.

### Summary Information for Releases<sup>2</sup>

Number of Confirmed UST Releases: 79  
 Release Reporting Period Dates: 10/1/15 To 9/30/16

### Summary Information for Release Sources and Causes<sup>3</sup>

(Information does not include bare steel tanks and piping)

Source			Cause											
			Spill/ Overfill		Physical/ Mechanical Damage		Corrosion		Installation Problem		Other		Unknown	
	#	%	#	%	#	%	#	%	#	%	#	%	#	%
Tank	15	19	2	3	3	4	-	-	1	1	1	1	9	11
Piping	4	5	-	-	1	1	1	1	-	-	-	-	2	3
Dispenser	38	48	22	28	12	15	-	-	-	-	-	-	3	4
Delivery Problem	-	-	-	-	-	-	-	-	-	-	-	-	-	-
Unknown	22	28	6	8	-	-	-	-	-	-	1	1	15	19
<b>Totals</b>	<b>79</b>	<b>100</b>	<b>30</b>	<b>39</b>	<b>16</b>	<b>20</b>	<b>1</b>	<b>1</b>	<b>1</b>	<b>1</b>	<b>2</b>	<b>2</b>	<b>29</b>	<b>37</b>

<sup>1</sup> Percent compliance is based only on the number of inspections conducted by Maine Department of Environmental Protection (MDEP) staff (206). An additional 1,409 inspections were conducted by Maine certified UST installers and inspectors for a total of 1,615 inspections.

<sup>2</sup> Release, source and cause information is based on reported releases at motor fuel UST facilities constructed of approved corrosion resistant materials (no bare steel). Source and cause data were compiled from data collected in the course of investigating UST system releases and using EPA's LUST Site Release Reports. For information about specific petroleum spills and releases in your town go to the MDEP's Hazardous and Oil Spill System (HOSS) online report service (<http://www.maine.gov/dep/rwm/hoss/>). For questions about the information on this page, please contact Victoria Eleftheriou at (207) 287-7688 or [Victoria.H.Eleftheriou@maine.gov](mailto:Victoria.H.Eleftheriou@maine.gov).

<sup>3</sup> # = number, Source % = percent of total number of sources, and Cause % = percent of total number of causes.