

Baileyville

This report shows the 2017-2019 Work Plan entries for Baileyville. The costs listed are the total cost of these projects – some of which may extend into neighboring towns. It also shows a listing of maintenance work specifically recorded to Baileyville in 2016, as well as any 2016 Local Road Assistance payments. Activities that are managed on a larger scale, such as snow & ice control, and maintenance work done by contract are not listed. The maintenance accomplishments may also extend into neighboring towns, but are listed in the first town where the work was reported. Finally, any capital projects that were completed in 2016 are also listed.

Planned Capital and Maintenance Work 2017-2019

Work Plan Year: 2017

Municipalities(s): Baileyville

Asset(s): Main Street

Description: No.5839 Main Street Wing Erosion (401)

ID	Scope of Work	Highway Corridor Priority	Estimated Funding
WR 32699	Maintenance	Corridor 5	\$10,000

Work Plan Year: 2018/19

Municipalities(s): Alexander, Baileyville, Baring Plt, Crawford

Asset(s): Route 9

Description: Beginning 0.28 of a mile north of Sucker Brook Road and extending northerly 13.81 miles.

ID	Scope of Work	Highway Corridor Priority	Estimated Funding
022400.00	1 1/4" Overlay	1	\$4,425,000

Local Road Assistance – Fiscal Year 2016

\$23,160

Maintenance Accomplishments – 2016

Activities managed on a larger scale, such as snow & ice control, and work done by contract are not listed. *The maintenance accomplishments may extend into neighboring towns, but are listed in the first town where the work was reported.*

- 91.0 Drainage Structures Cleaned
- 3,027.0 Linear Feet of Backhoe Ditching
- 6.0 Drainage Structures Repaired
- 8.2 Shoulder Miles of Sweeping
- 115.9 Shoulder Miles of Mowing
- 321.0 Sq Feet of Pavement Legend Applied
- 451.0 Linear Feet of Shoulder Rebuilt
- 1.0 Bridge(s) Cleaned
- 19.1 Ton(s) of Cold Patch Applied
- 512.5 Linear Feet of Guardrail or Fence Maintained
- 8.0 Emergency Event Responses
- 35,218.0 Linear Feet of Grader Ditching
- 1.0 Bridge(s) Washed
- 2.0 Minor Sign(s) Installed or Maintained
- 43.2 Center Lane Mile(s) Patrolling and Inspecting
- 3.0 Bridge Inspection(s) Performed
- 3.0 Drainage Structures Installed or Replaced
- 82.5 Miles of Striping Applied