

## Benton

This report shows the 2017-2019 Work Plan entries for Benton. The costs listed are the total cost of these projects – some of which may extend into neighboring towns. It also shows a listing of maintenance work specifically recorded to Benton in 2016, as well as any 2016 Local Road Assistance payments. Activities that are managed on a larger scale, such as snow & ice control, and maintenance work done by contract are not listed. The maintenance accomplishments may also extend into neighboring towns, but are listed in the first town where the work was reported. Finally, any capital projects that were completed in 2016 are also listed.

### Planned Capital and Maintenance Work 2017-2019

**Work Plan Year:** 2017

**Municipalities(s):** Benton, Winslow

**Asset(s):** Garland Road, Falls Road

**Description:** 71217 Clean under guardrail/Falls, Garland RD

ID	Scope of Work	Highway Corridor Priority	Estimated Funding
WR 32625	Maintenance	Corridor 5	\$10,000

**Work Plan Year:** 2017

**Municipalities(s):** Albion, Benton

**Asset(s):** Albion Road, Benton Road

**Description:** 71217 Grader Ditching Albion/Benton Rd

ID	Scope of Work	Highway Corridor Priority	Estimated Funding
WR 33596	Maintenance	Corridor 4	\$34,000

**Work Plan Year:** 2018/19

**Municipalities(s):** Augusta, Benton, Bowdoinham, Clinton, Fairfield, Gardiner, Richmond, Waterville, West Gardiner

**Asset(s):** Interstate 95/295 Bridges

**Description:** Interstate 95 bridges from Richmond to Waterville.

ID	Scope of Work	Highway Corridor Priority	Estimated Funding
021763.00	Bridge Protective Coating	Varies	\$1,000,000

**Work Plan Year:** 2018/19

**Municipalities(s):** Albion, Benton, Brooks, Burnham, Freedom, Knox, Montville, Oakland, Palermo, Troy, Unity, Winslow

**Asset(s):** Prairie Road, Route 23, Freedom Pond Road, Webb Road, Branch Mills Road, Albion Road, Benton Road, B

**Description:** Albion area 2018 LCP.

ID	Scope of Work	Highway Corridor Priority	Estimated Funding
022092.00	Light Capital Paving	Varies	\$2,083,800

**Work Plan Year:** 2018/19

**Municipalities(s):** Benton

**Asset(s):** Route 139

**Description:** Beginning at Falls Road and extending northeast 4.40 miles.

ID	Scope of Work	Highway Corridor Priority	Estimated Funding
022482.00	PMRAP DOT Pugmill	4	\$1,225,000

**Work Plan Year:** 2018/19

**Municipalities(s):** Benton, Clinton

**Asset(s):** Route 11

**Description:** Beginning at the north junction of Route 139 and extending northerly 4.23 miles.

ID	Scope of Work	Highway Corridor Priority	Estimated Funding
022484.00	PMRAP DOT Pugmill	4	\$1,055,000

**Work Plan Year:** 2018/19

**Municipalities(s):** Benton

**Asset(s):** Neck Road

**Description:** Located at the intersection of Benton Avenue and the Neck Road.

ID	Scope of Work	Highway Corridor Priority	Estimated Funding
022829.00	Traffic Signals	4	\$211,500

### Local Road Assistance – Fiscal Year 2016

\$28,744

### Maintenance Accomplishments – 2016

Activities managed on a larger scale, such as snow & ice control, and work done by contract are not listed. *The maintenance accomplishments may extend into neighboring towns, but are listed in the first town where the work was reported.*

- 29.1 Miles of Striping Applied
- 7,928.0 Linear Feet of Backhoe Ditching
  - 2.0 Shoulder Miles of Litter and Debris Removal
- 37.4 Shoulder Miles of Sweeping
- 5.0 Bridge(s) Washed
  - 1.0 Minor Sign(s) Installed or Maintained
- 49.0 Linear Feet of Guardrail or Fence Maintained
- 40.0 Linear Feet of Bridge/Main Support Members Replaced or Repaired
  - 2.0 Bridge Inspection(s) Performed
  - 7.0 Bridge(s) Sealed
  - 1.0 Mile(s) of Shoulder Graded
- 45.0 Sq Feet of Pavement Legend Applied
  - 1.7 Shoulder Miles of Herbicide Applied
- 5.0 Square Feet of Bridge Deck Repaired or Replaced
- 10.8 Ton(s) of Cold Patch Applied
- 260.0 Linear Feet of Grader Ditching
- 47.7 Shoulder Miles of Mowing
  - 1.0 Emergency Event Responses
- 15.0 Drainage Structures Installed or Replaced
- 4.0 Trees Removed
- 52.0 Linear Feet of Bridge Joints Repaired or Replaced
- 198.7 Center Lane Mile(s) Patrolling and Inspecting
  - 3.0 Bridge(s) Cleaned