

Fairfield

This report shows the 2017-2019 Work Plan entries for Fairfield. The costs listed are the total cost of these projects – some of which may extend into neighboring towns. It also shows a listing of maintenance work specifically recorded to Fairfield in 2016, as well as any 2016 Local Road Assistance payments. Activities that are managed on a larger scale, such as snow & ice control, and maintenance work done by contract are not listed. The maintenance accomplishments may also extend into neighboring towns, but are listed in the first town where the work was reported. Finally, any capital projects that were completed in 2016 are also listed.

Planned Capital and Maintenance Work 2017-2019

Work Plan Year: 2017

Municipalities(s): Fairfield, Waterville

Asset(s): Route 104

Description: Beginning at Sanger Avenue in Waterville and extending north 5.91 miles.

ID	Scope of Work	Highway Corridor	Priority	Estimated Funding
018800.00	1 1/4" Overlay		Varies	\$2,712,000

Work Plan Year: 2017

Municipalities(s): Fairfield

Asset(s): Route 139

Description: 22925.00 Replacing a Lrg Culvert on Rte.139

ID	Scope of Work	Highway Corridor	Priority	Estimated Funding
WR 33390	Maintenance	Corridor 3		\$175,000

Work Plan Year: 2018/19

Municipalities(s): Fairfield

Asset(s): Western Avenue

Description: Western Avenue/ Interstate 95 Bridge (No.5819) over Interstate 95. Located 0.34 of a mile west of Industrial Road.

ID	Scope of Work	Highway Corridor	Priority	Estimated Funding
022308.00	Bridge Painting		3	\$500,000

Work Plan Year: 2018/19

Municipalities(s): Fairfield

Asset(s): Interstate 95

Description: Interstate 95 Over 201 Bridge (No.5820) over Route 201. Located on Exit 133 Interstate 95 northbound.

ID	Scope of Work	Highway Corridor	Priority	Estimated Funding
022306.00	Bridge Painting		1	\$800,000

Work Plan Year: 2018/19

Municipalities(s): Augusta, Benton, Bowdoinham, Clinton, Fairfield, Gardiner, Richmond, Waterville, West Gardiner

Asset(s): Interstate 95/295 Bridges

Description: Interstate 95 bridges from Richmond to Waterville.

ID	Scope of Work	Highway Corridor	Priority	Estimated Funding
021763.00	Bridge Protective Coating		Varies	\$1,000,000

Work Plan Year: 2018/19

Municipalities(s): Fairfield, Waterville

Asset(s): Interstate 95 SB

Description: Beginning 0.35 of a mile south of the Benton town line and extending southerly 3.78 miles.

ID	Scope of Work	Highway Corridor	Priority	Estimated Funding
020382.10	Cold-In-Place Recycle		1	\$3,342,000

Work Plan Year: 2018/19

Municipalities(s): Fairfield

Asset(s): Interstate 95 NB

Description: Beginning 0.56 of a mile north of Route 139 and extending northerly 0.36 of a mile.

ID	Scope of Work	Highway Corridor Priority	Estimated Funding
022855.00	Guard Rail Installation And Replacement	1	\$130,000

Work Plan Year: 2018/19

Municipalities(s): Fairfield, Skowhegan

Asset(s): Route 104

Description: Beginning at Route 139 and extending northerly 8.15 miles.

ID	Scope of Work	Highway Corridor Priority	Estimated Funding
023052.00	Highway Cpr	4	\$1,100,300

Local Road Assistance – Fiscal Year 2016

\$73,032

Maintenance Accomplishments – 2016

Activities managed on a larger scale, such as snow & ice control, and work done by contract are not listed. *The maintenance accomplishments may extend into neighboring towns, but are listed in the first town where the work was reported.*

- 24.3 Shoulder Miles of Herbicide Applied
- 32.0 Linear Feet of Bridge Joints Repaired or Replaced
- 2.0 Bridge Inspection(s) Performed
- 5.0 Bridge(s) Cleaned
- 5.0 Bridge(s) Sealed
- 179.0 Linear Feet of Guardrail or Fence Maintained
- 15.0 Minor Sign(s) Installed or Maintained
- 15.0 Linear Feet of Shoulder Rebuilt
- 2.0 Shoulder Miles of Litter and Debris Removal
- 4.0 Trees Removed
- 153.9 Miles of Striping Applied
- 100.0 Linear Feet of Backhoe Ditching
- 61.0 Shoulder Miles of Sweeping
- 1.0 Channel(s) Maintained
- 460.0 Sq Feet of Pavement Legend Applied
- 21.1 Ton(s) of Cold Patch Applied
- 5,990.0 Linear Feet of Grader Ditching
- 2.0 Emergency Event Responses
- 3.0 Drainage Structures Installed or Replaced
- 4.0 Bridge(s) Washed
- 0.3 Mile(s) of Shoulder Graded
- 57.2 Shoulder Miles of Mowing
- 2,205.0 Linear Feet of Brush Removed
- 757.2 Center Lane Mile(s) Patrolling and Inspecting