

Farmington

This report shows the 2017-2019 Work Plan entries for Farmington. The costs listed are the total cost of these projects – some of which may extend into neighboring towns. It also shows a listing of maintenance work specifically recorded to Farmington in 2016, as well as any 2016 Local Road Assistance payments. Activities that are managed on a larger scale, such as snow & ice control, and maintenance work done by contract are not listed. The maintenance accomplishments may also extend into neighboring towns, but are listed in the first town where the work was reported. Finally, any capital projects that were completed in 2016 are also listed.

Planned Capital and Maintenance Work 2017-2019

Work Plan Year: 2017

Municipalities(s): Chesterville, Farmington

Asset(s): Route 41

Description: Farmington Falls Bridge (No.2273) over the Sandy River. Located on the Chesterville-Farmington Falls town line.

ID	Scope of Work	Highway Corridor Priority	Estimated Funding
022296.00	Bridge Improvement-PE Only	3	\$300,000

Work Plan Year: 2017

Municipalities(s): Farmington

Asset(s): Route 4

Description: Large culvert (No.46391) located 0.66 of a mile north of Town Farm Road.

ID	Scope of Work	Highway Corridor Priority	Estimated Funding
020352.00	Large Culvert Rehabilitation	2	\$425,000

Work Plan Year: 2017

Municipalities(s): Farmington, Temple

Asset(s): Route 43

Description: 71304 - WP 17 Ditching on Route 43 Temple Road

ID	Scope of Work	Highway Corridor Priority	Estimated Funding
WR 33013	Maintenance	Corridor 5	\$134,000

Work Plan Year: 2017

Municipalities(s): Farmington

Asset(s): Route 27

Description: Beginning at Maple Avenue and extending north 0.45 of a mile to Prescott Street.

ID	Scope of Work	Highway Corridor Priority	Estimated Funding
022690.00	New Construction	Varies	\$165,000

Work Plan Year: 2017

Municipalities(s): Farmington

Asset(s): Route 2

Description: Beginning 0.38 of a mile south of Stanwood Park Circle and extending northwesterly 1.97 miles.

ID	Scope of Work	Highway Corridor Priority	Estimated Funding
021986.00	Ultra Thin Bonded Wearing Surface	1	\$390,200

Work Plan Year: 2018/19

Municipalities(s): Farmington

Asset(s): Route 2

Description: Gower Farm Bridge (No.2324) over Beales Brook. Located 0.14 of a mile west of Dump Road.

ID	Scope of Work	Highway Corridor Priority	Estimated Funding
021880.00	Bridge Culvert Replacement	1	\$600,000

Work Plan Year: 2018/19

Municipalities(s): Farmington

Asset(s): Route 156

Description: Williams No.1 Bridge (No.2980) over Brook of Williams Brook. Located 0.19 of a mile southeast of Wilton town line.

ID	Scope of Work	Highway Corridor Priority	Estimated Funding
021690.00	Bridge Culvert Replacement	3	\$500,000

Work Plan Year: 2018/19

Municipalities(s): Farmington

Asset(s): Route 133

Description: Hamlin Bridge (No.3286) over Wilson Stream. Located 0.16 of a mile south of Wilton Road.

ID	Scope of Work	Highway Corridor Priority	Estimated Funding
022236.00	Bridge Replacement	3	\$1,750,000

Local Road Assistance – Fiscal Year 2016

\$160,924

Maintenance Accomplishments – 2016

Activities managed on a larger scale, such as snow & ice control, and work done by contract are not listed. *The maintenance accomplishments may extend into neighboring towns, but are listed in the first town where the work was reported.*

- 8.0 Emergency Event Responses
- 10,500.0 Linear Feet of Grader Ditching
- 19.4 Mile(s) of Shoulder Graded
- 999.5 Linear Feet of Guardrail or Fence Maintained
- 5.0 Linear Feet of Bridge Joints Repaired or Replaced
- 4.0 Channel(s) Maintained
- 1.0 Drainage Structures Repaired
- 6.0 Sq Feet of Bridge Wearing Surface Repaired
- 9.0 Bridge(s) Washed
- 7.8 Ton(s) of Cold Patch Applied
- 1,599.0 Center Lane Mile(s) Patrolling and Inspecting
- 4.0 Drainage Structures Installed or Replaced
- 648.0 Sq Feet of Bridge Painting
- 4.0 Mile(s) of Shoulder prepared for LCP
- 31,213.3 Linear Feet of Shoulder Rebuilt
- 164.4 Miles of Striping Applied
- 8,010.3 Ton(s) of Hot Mix Paving
- 7,420.0 Linear Feet of Backhoe Ditching
- 68.6 Shoulder Miles of Mowing
- 317.8 Shoulder Miles of Herbicide Applied
- 1,004.0 Linear Feet of Brush Removed
- 240.0 Sq Feet of Retaining Wall Repairs
- 16.2 Shoulder Miles of Sweeping
- 29.0 Minor Sign(s) Installed or Maintained

Completed Capital Projects – 2016

- 018987.00 FARMINGTON, FAIRBANKS BR No.2271 Fairbanks Bridge (No.2271) over the Sandy River. Located 0.27 of a mile southwest of the Strong Road.
- 020369.00 FARMINGTON - ROUTE 4 Beginning 0.23 of a mile north of Adams Circle and extending northerly 7.77 miles.
- 018609.00 STRONG AREA 2016 LCP STRONG AREA 2016 LCP