

Garland

This report shows the 2017-2019 Work Plan entries for Garland. The costs listed are the total cost of these projects – some of which may extend into neighboring towns. It also shows a listing of maintenance work specifically recorded to Garland in 2016, as well as any 2016 Local Road Assistance payments. Activities that are managed on a larger scale, such as snow & ice control, and maintenance work done by contract are not listed. The maintenance accomplishments may also extend into neighboring towns, but are listed in the first town where the work was reported. Finally, any capital projects that were completed in 2016 are also listed.

Planned Capital and Maintenance Work 2017-2019

Work Plan Year: 2017

Municipalities(s): Alton, Charleston, Corinth, Dexter, Garland, Greenbush, Greenfield Twp, Guilford, Hudson, Milford, Old Town, Sangerville

Asset(s): Route 94, Greenfield Road, Cambridge Road, Route 43, Hudson Avenue

Description: Corinth Area 2017 LCP

ID	Scope of Work	Highway Corridor	Priority	Estimated Funding
024010.00	Light Capital Paving		Varies	\$2,357,400

Work Plan Year: 2018/19

Municipalities(s): Bradford, Corinna, Corinth, Exeter, Garland, Kenduskeag, Levant, Milo, Newport, Orneville Twp, Palmyra, Pittsfield, Stetson

Asset(s): Peltoma Avenue, Route 11, Avenue Road, Nokomis Road, Williams Road, Madawaska Road, Garland Road, St

Description: Stetson Area 2018 LCP.

ID	Scope of Work	Highway Corridor	Priority	Estimated Funding
022110.00	Light Capital Paving		Varies	\$2,194,800

Local Road Assistance – Fiscal Year 2016

\$36,384

Maintenance Accomplishments – 2016

Activities managed on a larger scale, such as snow & ice control, and work done by contract are not listed. *The maintenance accomplishments may extend into neighboring towns, but are listed in the first town where the work was reported.*

- 1.0 Minor Sign(s) Installed or Maintained
- 4.1 Shoulder Miles of Sweeping
- 2.0 Bridge(s) Cleaned
- 7.5 Ton(s) of Cold Patch Applied
- 5.0 Drainage Structures Installed or Replaced
- 21,677.8 Linear Feet of Brush Removed
- 4.0 Emergency Event Responses
- 2.0 Drainage Structures Cleaned
- 1.0 Bridge(s) Sealed
- 15.8 Linear Feet of Shoulder Rebuilt
- 7.9 Center Lane Mile(s) Patrolling and Inspecting
- 6,559.6 Linear Feet of Backhoe Ditching
- 9.0 Trees Removed