

## Greenbush

This report shows the 2017-2019 Work Plan entries for Greenbush. The costs listed are the total cost of these projects – some of which may extend into neighboring towns. It also shows a listing of maintenance work specifically recorded to Greenbush in 2016, as well as any 2016 Local Road Assistance payments. Activities that are managed on a larger scale, such as snow & ice control, and maintenance work done by contract are not listed. The maintenance accomplishments may also extend into neighboring towns, but are listed in the first town where the work was reported. Finally, any capital projects that were completed in 2016 are also listed.

### Planned Capital and Maintenance Work 2017-2019

**Work Plan Year:** 2017

**Municipalities(s):** Alton, Charleston, Corinth, Dexter, Garland, Greenbush, Greenfield Twp, Guilford, Hudson, Milford, Old Town, Sangerville

**Asset(s):** Route 94, Greenfield Road, Cambridge Road, Route 43, Hudson Avenue

**Description:** Corinth Area 2017 LCP

ID	Scope of Work	Highway Corridor	Priority	Estimated Funding
024010.00	Light Capital Paving		Varies	\$2,357,400

**Work Plan Year:** 2018/19

**Municipalities(s):** Greenbush

**Asset(s):** Route 2

**Description:** Boom Bridge (No.3587) over Beach Bridge Brook. Located 2.43 miles north of Milford town line.

ID	Scope of Work	Highway Corridor	Priority	Estimated Funding
021727.00	Bridge Replacement		3	\$2,000,000

### Local Road Assistance – Fiscal Year 2016

\$30,812

### Maintenance Accomplishments – 2016

Activities managed on a larger scale, such as snow & ice control, and work done by contract are not listed. *The maintenance accomplishments may extend into neighboring towns, but are listed in the first town where the work was reported.*

- 15.3 Shoulder Miles of Herbicide Applied
  - 1.0 Minor Sign(s) Installed or Maintained
  - 9.2 Ton(s) of Cold Patch Applied
  - 5.0 Trees Removed
  - 1.0 Bridge(s) Cleaned
- 55,275.6 Linear Feet of Grader Ditching
  - 8.0 Drainage Structures Installed or Replaced
  - 2.0 Bridge Inspection(s) Performed
  - 1.0 Emergency Event Responses
  - 1.0 Drainage Structures Cleaned
- 205.0 Sq Feet of Bridge Pier Repairs
  - 10.0 Linear Feet of Shoulder Rebuilt
  - 15.0 Linear Feet of Guardrail or Fence Maintained
- 22.0 Center Lane Mile(s) Patrolling and Inspecting
  - 3.0 Bridge(s) Sealed
  - 2.0 Drainage Structures Repaired
- 300.0 Linear Feet of Brush Removed
  - 3.0 Bridge(s) Washed
- 8,133.3 Linear Feet of Backhoe Ditching

