

Mattawamkeag

This report shows the 2017-2019 Work Plan entries for Mattawamkeag. The costs listed are the total cost of these projects – some of which may extend into neighboring towns. It also shows a listing of maintenance work specifically recorded to Mattawamkeag in 2016, as well as any 2016 Local Road Assistance payments. Activities that are managed on a larger scale, such as snow & ice control, and maintenance work done by contract are not listed. The maintenance accomplishments may also extend into neighboring towns, but are listed in the first town where the work was reported. Finally, any capital projects that were completed in 2016 are also listed.

Planned Capital and Maintenance Work 2017-2019

Work Plan Year: 2017

Municipalities(s): Mattawamkeag

Asset(s): Route 157

Description: Large culvert (No.46619) located 0.37 of a mile north of Jordan Mills Road.

ID	Scope of Work	Highway Corridor Priority	Estimated Funding
022922.00	Large Culvert-PE Only	3	\$50,000

Work Plan Year: 2017

Municipalities(s): Benedicta Twp, Macwahoc Plt, Mattawamkeag, Medway, Molunkus Twp, North Yarmouth Academy Grant Twp, Reed Plt, Sherman

Asset(s): Route 116, Route 158, Route 2A, Route 2, Aroostook Road

Description: Medway Area 2017 LCP

ID	Scope of Work	Highway Corridor Priority	Estimated Funding
024014.00	Light Capital Paving	Varies	\$1,271,300

Work Plan Year: 2017

Municipalities(s): Macwahoc Plt, Mattawamkeag, Molunkus Twp

Asset(s): Route 2

Description: 71502 22937.00 Change 4 culverts on Rt 2.

ID	Scope of Work	Highway Corridor Priority	Estimated Funding
WR 33667	Maintenance	Corridor 4	\$190,000

Local Road Assistance – Fiscal Year 2016

\$8,116

Maintenance Accomplishments – 2016

Activities managed on a larger scale, such as snow & ice control, and work done by contract are not listed. *The maintenance accomplishments may extend into neighboring towns, but are listed in the first town where the work was reported.*

- 1.0 Bridge(s) Cleaned
- 260.0 Sq Feet of Pavement Legend Applied
- 20.0 Linear Feet of Bridge/Main Support Members Replaced or Repaired
- 1.0 Bridge(s) Sealed
- 1.0 Bridge Inspection(s) Performed
- 20.0 Mile(s) of Shoulder Graded
- 35.0 Linear Feet of Brush Removed
- 179.0 Center Lane Mile(s) Patrolling and Inspecting
- 2.0 Bridge(s) Washed
- 3.0 Drainage Structures Cleaned
- 35.0 Miles of Striping Applied