

## Porter

This report shows the 2017-2019 Work Plan entries for Porter. The costs listed are the total cost of these projects – some of which may extend into neighboring towns. It also shows a listing of maintenance work specifically recorded to Porter in 2016, as well as any 2016 Local Road Assistance payments. Activities that are managed on a larger scale, such as snow & ice control, and maintenance work done by contract are not listed. The maintenance accomplishments may also extend into neighboring towns, but are listed in the first town where the work was reported. Finally, any capital projects that were completed in 2016 are also listed.

### Planned Capital and Maintenance Work 2017-2019

**Work Plan Year:** 2017

**Municipalities(s):** Parsonsfield, Porter

**Asset(s):** Route 160

**Description:** Porter Bridge (No.3817) over the Ossipee River. Located on the Porter town line.

ID	Scope of Work	Highway Corridor Priority	Estimated Funding
016867.00	Bridge Beam Ends and Bearing Painting	5	\$100,000

**Work Plan Year:** 2017

**Municipalities(s):** Baldwin, Bridgton, Brownfield, Cornish, Hiram, Hollis, Limington, Porter, Sebago, Standish, Waterboro

**Asset(s):** Route 107, Route 11, Plains Road, Route 114, South Hiram Road, Route 160, Route 117

**Description:** Baldwin Area 2017 LCP.

ID	Scope of Work	Highway Corridor Priority	Estimated Funding
024001.00	Light Capital Paving	Varies	\$1,265,100

### Local Road Assistance – Fiscal Year 2016

\$46,040

### Maintenance Accomplishments – 2016

Activities managed on a larger scale, such as snow & ice control, and work done by contract are not listed. *The maintenance accomplishments may extend into neighboring towns, but are listed in the first town where the work was reported.*

- 2,440.0 Linear Feet of Brush Removed
- 70.0 Linear Feet of Bridge Joints Repaired or Replaced
- 2.0 Bridge(s) Washed
- 8,605.0 Linear Feet of Backhoe Ditching
- 16.5 Ton(s) of Cold Patch Applied
- 3.0 Emergency Event Responses
- 138.0 Center Lane Mile(s) Patrolling and Inspecting
- 4.0 Drainage Structures Installed or Replaced
- 430.0 Linear Feet of Guardrail or Fence Maintained
- 20.0 Linear Feet of Bridge Rail Repaired or Replaced
- 21,100.0 Linear Feet of Grader Ditching
- 9.0 Minor Sign(s) Installed or Maintained