

Roque Bluffs

This report shows the 2017-2019 Work Plan entries for Roque Bluffs. The costs listed are the total cost of these projects – some of which may extend into neighboring towns. It also shows a listing of maintenance work specifically recorded to Roque Bluffs in 2016, as well as any 2016 Local Road Assistance payments. Activities that are managed on a larger scale, such as snow & ice control, and maintenance work done by contract are not listed. The maintenance accomplishments may also extend into neighboring towns, but are listed in the first town where the work was reported. Finally, any capital projects that were completed in 2016 are also listed.

Planned Capital and Maintenance Work 2017-2019

Work Plan Year: 2017

Municipalities(s): Baring Plt, Berry Twp, Cathance Township, Cooper, East Machias, Jonesboro, Machias, Machiasport, Marion Twp, Mars Hill, Marshfield, Meddybemps, Northfield, Roque Bluffs, Wesley, Whitneyville

Asset(s): Route 191, Route 1A, Route 192, Roque Bluffs Road, Port Road, Kennebec Road, Route 92, Rim Road, Rid

Description: East Machias Area 2017 LCP

ID	Scope of Work	Highway Corridor Priority	Estimated Funding
024011.00	Light Capital Paving	Varies	\$3,886,200

Work Plan Year: 2017

Municipalities(s): Roque Bluffs

Asset(s): Roque Bluffs Road

Description: Cluvert replacment in Roque Bluffs (402)

ID	Scope of Work	Highway Corridor Priority	Estimated Funding
WR 33642	Maintenance	Corridor 5	\$21,000

Local Road Assistance – Fiscal Year 2016

\$10,572

Maintenance Accomplishments – 2016

Activities managed on a larger scale, such as snow & ice control, and work done by contract are not listed. *The maintenance accomplishments may extend into neighboring towns, but are listed in the first town where the work was reported.*

- 5.0 Ton(s) of Cold Patch Applied
- 139.0 Linear Feet of Shoulder Rebuilt
- 8.0 Minor Sign(s) Installed or Maintained
- 6,178.0 Linear Feet of Brush Removed
- 61.9 Center Lane Mile(s) Patrolling and Inspecting
- 195.0 Linear Feet of Backhoe Ditching
- 4.0 Drainage Structures Installed or Replaced
- 10.6 Miles of Striping Applied
- 13.8 Shoulder Miles of Mowing
- 2.0 Emergency Event Responses