

Saint George

This report shows the 2017-2019 Work Plan entries for Saint George. The costs listed are the total cost of these projects – some of which may extend into neighboring towns. It also shows a listing of maintenance work specifically recorded to Saint George in 2016, as well as any 2016 Local Road Assistance payments. Activities that are managed on a larger scale, such as snow & ice control, and maintenance work done by contract are not listed. The maintenance accomplishments may also extend into neighboring towns, but are listed in the first town where the work was reported. Finally, any capital projects that were completed in 2016 are also listed.

Planned Capital and Maintenance Work 2017-2019

Work Plan Year: 2017

Municipalities(s): Saint George, South Thomaston

Asset(s): Route 73

Description: 71212 Replacing Culverts on Rt.73 South Thomaston

ID	Scope of Work	Highway Corridor Priority	Estimated Funding
WR 33568	Maintenance	Corridor 4	\$29,000

Work Plan Year: 2017

Municipalities(s): Saint George

Asset(s): Route 131

Description: 71212 Culvert Work Rt. 131 Saint George

ID	Scope of Work	Highway Corridor Priority	Estimated Funding
WR 33569	Maintenance	Corridor 4	\$12,000

Work Plan Year: 2018/19

Municipalities(s): Saint George

Asset(s): Route 131

Description: Large culvert (No.46916) located 0.62 of a mile west of Glenmere Road.

ID	Scope of Work	Highway Corridor Priority	Estimated Funding
021822.00	Large Culvert Replacement	4	\$230,000

Local Road Assistance – Fiscal Year 2016

\$30,872

Maintenance Accomplishments – 2016

Activities managed on a larger scale, such as snow & ice control, and work done by contract are not listed. *The maintenance accomplishments may extend into neighboring towns, but are listed in the first town where the work was reported.*

- 8.5 Ton(s) of Cold Patch Applied
- 79.0 Sq Feet of Pavement Legend Applied
- 425.0 Linear Feet of Guardrail Installed
- 1.0 Drainage Structures Installed or Replaced
- 48.5 Miles of Striping Applied
- 300.0 Linear Feet of Shoulder Rebuilt
- 2,000.0 Linear Feet of Brush Removed
- 317.8 Ton(s) of Cold Patch Applied
- 1,630.1 Center Lane Mile(s) Patrolling and Inspecting
- 557.0 Linear Feet of Backhoe Ditching
- 1.0 Drainage Structures Cleaned
- 28.2 Shoulder Miles of Mowing