

Sangerville

This report shows the 2017-2019 Work Plan entries for Sangerville. The costs listed are the total cost of these projects – some of which may extend into neighboring towns. It also shows a listing of maintenance work specifically recorded to Sangerville in 2016, as well as any 2016 Local Road Assistance payments. Activities that are managed on a larger scale, such as snow & ice control, and maintenance work done by contract are not listed. The maintenance accomplishments may also extend into neighboring towns, but are listed in the first town where the work was reported. Finally, any capital projects that were completed in 2016 are also listed.

Planned Capital and Maintenance Work 2017-2019

Work Plan Year: 2017

Municipalities(s): Alton, Charleston, Corinth, Dexter, Garland, Greenbush, Greenfield Twp, Guilford, Hudson, Milford, Old Town, Sangerville

Asset(s): Route 94, Greenfield Road, Cambridge Road, Route 43, Hudson Avenue

Description: Corinth Area 2017 LCP

ID	Scope of Work	Highway Corridor Priority	Estimated Funding
024010.00	Light Capital Paving	Varies	\$2,357,400

Work Plan Year: 2017

Municipalities(s): Sangerville

Asset(s): Silver Mills Road

Description: No.5559 Brockway Mills Rail Repair (407)

ID	Scope of Work	Highway Corridor Priority	Estimated Funding
WR 32664	Maintenance		\$87,000

Local Road Assistance – Fiscal Year 2016

\$34,100

Maintenance Accomplishments – 2016

Activities managed on a larger scale, such as snow & ice control, and work done by contract are not listed. *The maintenance accomplishments may extend into neighboring towns, but are listed in the first town where the work was reported.*

- 13.1 Shoulder Miles of Mowing
- 130.0 Linear Feet of Guardrail or Fence Maintained
- 24.0 Drainage Structures Cleaned
 - 1.0 Bridge(s) Washed
- 6.6 Shoulder Miles of Sweeping
- 6.0 Bridge(s) Cleaned
- 1.0 Trees Removed
- 37.1 Center Lane Mile(s) Patrolling and Inspecting
 - 2.0 Bridge Inspection(s) Performed
- 9.5 Miles of Striping Applied
- 1.0 Ton(s) of Cold Patch Applied
- 1.0 Emergency Event Responses
- 2,486.6 Linear Feet of Brush Removed