

## Structures in the Municipality of Willimantic

### CONDITION RATINGS

<b>TOWN1:</b> <input type="text" value="Willimantic"/>	<b>TOWN2:</b> <input type="text" value="No town 2"/>	<b>SUBSTRUCTURE CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>BRIDGE NO.:</b> <input type="text" value="3052"/>	<b>BRIDGE REGION:</b> <input type="text" value="Eastern"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>LOCATION:</b> <input type="text" value="3.5 MI E TOWNLINE"/>	<b>YEAR BUILT:</b> <input type="text" value="1949"/>	<b>DECK CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>BRDGNAME:</b> SEARS	<b>SPAN MATERIAL:</b> <input type="text" value="1 Steel"/>	<b>CHANNEL CONDITION:</b> <input type="text" value="8"/> <input type="text" value="Very Good"/>
<b>OWNER:</b> <input type="text" value="4 Municipal"/>	<b>SPAN TYPE:</b> <input type="text" value="1 Girder"/>	<b>CULVERT CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>MAINTAINER:</b> <input type="text" value="4 Municipal"/>	<b>NUMBER OF MAIN SPANS:</b> <input type="text" value="1"/>	<b>APPROACH CONDITION:</b> <input type="text" value="5"/> <input type="text" value="Fair"/>
<b>FEATURE ON:</b> <input type="text" value="RIVER RD"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input type="text" value="64"/>	<b>DATE OF INSPECTION:</b> <input type="text" value="7/17/2012"/>
<b>FEATURE UNDER:</b> <input type="text" value="DAVIS BK"/>	<b>POSTING STATUS:</b> <input type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input type="text" value="79.2"/>
<b>ROAD INV NO:</b> <input type="text" value="0002100530"/>	<b>POSTING TYPE:</b> <input type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input type="text" value="00000"/>		
<b>ROAD WIDTH:</b> <input type="text" value="22"/> FEET	<b>FEDERAL BRIDGE INDICATOR:</b> <input type="text" value="Y"/>	
<b>CLASS:</b> <input type="text" value="LOW USE/REDUNDANT BRIDGE"/>		

## Structures in the Municipality of Willimantic

### CONDITION RATINGS

<b>TOWN1:</b> <input type="text" value="Willimantic"/>	<b>TOWN2:</b> <input type="text" value="No town 2"/>	<b>SUBSTRUCTURE CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>BRIDGE NO.:</b> <input type="text" value="3051"/>	<b>BRIDGE REGION:</b> <input type="text" value="Eastern"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>LOCATION:</b> <input type="text" value="0.5 MI W RTE 150"/>	<b>YEAR BUILT:</b> <input type="text" value="1950"/>	<b>DECK CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>BRDGNAME:</b> <input type="text" value="MONSON STREAM"/>	<b>SPAN MATERIAL:</b> <input type="text" value="1 Steel"/>	<b>CHANNEL CONDITION:</b> <input type="text" value="4"/> <input type="text" value="Poor"/>
<b>OWNER:</b> <input type="text" value="4 Municipal"/>	<b>SPAN TYPE:</b> <input type="text" value="6 Arch"/>	<b>CULVERT CONDITION:</b> <input type="text" value="3"/> <input type="text" value="Serious"/>
<b>MAINTAINER:</b> <input type="text" value="4 Municipal"/>	<b>NUMBER OF MAIN SPANS:</b> <input type="text" value="1"/>	<b>APPROACH CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>FEATURE ON:</b> <input type="text" value="WILLIMATIC/MONSON"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input type="text" value="19"/>	<b>DATE OF INSPECTION:</b> <input type="text" value="8/13/2012"/>
<b>FEATURE UNDER:</b> <input type="text" value="MONSON STR"/>	<b>POSTING STATUS:</b> <input type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input type="text" value="59.9"/>
<b>ROAD INV NO:</b> <input type="text" value="0002100521"/>	<b>POSTING TYPE:</b> <input type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input type="text" value="00000"/>		
<b>ROAD WIDTH:</b> <input type="text" value="0"/> FEET	<b>FEDERAL BRIDGE INDICATOR:</b> <input type="text" value="N"/>	
<b>CLASS:</b> <input type="text" value="MINOR SPAN ON TOWN WAY"/>		

## Structures in the Municipality of Willimantic

### CONDITION RATINGS

<b>TOWN1:</b> Willimantic	<b>TOWN2:</b> No town 2	<b>SUBSTRUCTURE CONDITION:</b> 8 Very Good
<b>BRIDGE NO.:</b> 2995	<b>BRIDGE REGION:</b> Eastern	<b>SUPERSTRUCTURE CONDITION:</b> 5 Fair
<b>LOCATION:</b> 200 FT NE OF JCT RTE 150	<b>YEAR BUILT:</b> 1937	<b>DECK CONDITION:</b> 5 Fair
<b>BRDGNAME:</b> EARLEYS	<b>SPAN MATERIAL:</b> 1 Steel	<b>CHANNEL CONDITION:</b> 7 Good
<b>OWNER:</b> 4 Municipal	<b>SPAN TYPE:</b> 1 Girder	<b>CULVERT CONDITION:</b> N Not Applicable
<b>MAINTAINER:</b> 4 Municipal	<b>NUMBER OF MAIN SPANS:</b> 1	<b>APPROACH CONDITION:</b> 8 Very Good
<b>FEATURE ON:</b> GREEN POINT RD	<b>STRUCTURE LENGTH IN FEET:</b> 83	<b>DATE OF INSPECTION:</b> 7/17/2012
<b>FEATURE UNDER:</b> WILSON STREAM	<b>POSTING STATUS:</b> 1 Open	<b>FEDERAL SUFFICIENCY RATING:</b> 21.8
<b>ROAD INV NO:</b> 0002100525	<b>POSTING TYPE:</b> 0 None needed	
<b>ROUTE NO:</b> 00000		
<b>ROAD WIDTH:</b> 14 FEET	<b>FEDERAL BRIDGE INDICATOR:</b> Y	
<b>CLASS:</b> LOW USE/REDUNDANT BRIDGE		

## Structures in the Municipality of Willimantic

### CONDITION RATINGS

<b>TOWN1:</b> <input type="text" value="Willimantic"/>	<b>TOWN2:</b> <input type="text" value="No town 2"/>	<b>SUBSTRUCTURE CONDITION:</b> <input type="text" value="4"/> <input type="text" value="Poor"/>
<b>BRIDGE NO.:</b> <input type="text" value="2317"/>	<b>BRIDGE REGION:</b> <input type="text" value="Eastern"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>LOCATION:</b> <input type="text" value="150 FT N OF JCT RTE 150"/>	<b>YEAR BUILT:</b> <input type="text" value="1932"/>	<b>DECK CONDITION:</b> <input type="text" value="5"/> <input type="text" value="Fair"/>
<b>BRDGNAME:</b> <input type="text" value="GOODELL"/>	<b>SPAN MATERIAL:</b> <input type="text" value="1 Steel"/>	<b>CHANNEL CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>OWNER:</b> <input type="text" value="1 State DOT"/>	<b>SPAN TYPE:</b> <input type="text" value="1 Girder"/>	<b>CULVERT CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>MAINTAINER:</b> <input type="text" value="1 State DOT"/>	<b>NUMBER OF MAIN SPANS:</b> <input type="text" value="1"/>	<b>APPROACH CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>FEATURE ON:</b> <input type="text" value="ELLIOTSVILLE ROAD"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input type="text" value="40"/>	<b>DATE OF INSPECTION:</b> <input type="text" value="9/24/2012"/>
<b>FEATURE UNDER:</b> <input type="text" value="DAVIS BROOK"/>	<b>POSTING STATUS:</b> <input type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input type="text" value="48.8"/>
<b>ROAD INV NO:</b> <input type="text" value="0002100687"/>	<b>POSTING TYPE:</b> <input type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input type="text" value="00000"/>		
<b>ROAD WIDTH:</b> <input type="text" value="19"/> FEET	<b>FEDERAL BRIDGE INDICATOR:</b> <input type="text" value="Y"/>	
<b>CLASS:</b> <input type="text" value="BRIDGE ON TOWN WAY OR STATE AID ROAD"/>		

## Structures in the Municipality of Willimantic

---

### CONDITION RATINGS

<b>TOWN1:</b> <input type="text" value="Willimantic"/>	<b>TOWN2:</b> <input type="text" value="No town 2"/>	<b>SUBSTRUCTURE CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>BRIDGE NO.:</b> <input type="text" value="2023"/>	<b>BRIDGE REGION:</b> <input type="text" value="Eastern"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>LOCATION:</b> <input type="text" value="2.6 MI NE MONSON TL"/>	<b>YEAR BUILT:</b> <input type="text" value="2008"/>	<b>DECK CONDITION:</b> <input type="text" value="8"/> <input type="text" value="Very Good"/>
<b>BRDGNAME:</b> <input type="text" value="ARNOLD"/>	<b>SPAN MATERIAL:</b> <input type="text" value="1 Steel"/>	<b>CHANNEL CONDITION:</b> <input type="text" value="8"/> <input type="text" value="Very Good"/>
<b>OWNER:</b> <input type="text" value="1 State DOT"/>	<b>SPAN TYPE:</b> <input type="text" value="5 Truss"/>	<b>CULVERT CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>MAINTAINER:</b> <input type="text" value="1 State DOT"/>	<b>NUMBER OF MAIN SPANS:</b> <input type="text" value="1"/>	<b>APPROACH CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>FEATURE ON:</b> <input type="text" value="WILLIMANTIC ROAD"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input type="text" value="118"/>	<b>DATE OF INSPECTION:</b> <input type="text" value="7/31/2012"/>
<b>FEATURE UNDER:</b> <input type="text" value="WILSON STREAM"/>	<b>POSTING STATUS:</b> <input type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input type="text" value="94"/>
<b>ROAD INV NO:</b> <input type="text" value="0002100521"/>	<b>POSTING TYPE:</b> <input type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input type="text" value="00000"/>		
<b>ROAD WIDTH:</b> <input type="text" value="20"/> FEET	<b>FEDERAL BRIDGE INDICATOR:</b> <input type="text" value="Y"/>	
<b>CLASS:</b> <input type="text" value="BRIDGE ON TOWN WAY OR STATE AID ROAD"/>		