





Color Indications:

- Non-Detect
- Detected below SL
- Detected above SL
- Detected above 10x SL
- Detected above 100x SL
- Detected above 1000x SL

Notes:
 Depicted concentrations represent the greatest exceedance of a regulatory value for the PFAS compounds with an applicable health based screening level or ecological risk assessment benchmark.
 See table 1-3 for more information about screening levels.

See table 1-3 for more information about screening levels.

SYMBOL KEY

-  Potential Aqueous Film Forming Foam Release Area
- Former Installation Boundary

- Gray Label** Indicates Shallow Groundwater / Hydric Soil Location

Media Symbology:

- Surface Water or Shallow Groundwater
 Porewater
 Sediment or Hydric Soil

Water Features:

- Stream
 ■ Surface Water Bodies

**Air Force Civil
Engineer Center**
261 Hughes Ave., Suite 163
JBSA Lackland, TX 78236



Figure 4-24D
Surface Water, Sediment, Hydric Soil, Shallow
Groundwater, and Porewater Analytical Results
Greenlaw Brook Drainage Basin
 Remedial Investigation Site Characterization Summary Report
 Former Loring Air Force Base, Limestone, ME

SOURCES:

-Aerial Imagery obtained from USDA-FSA.
Published September, 2021.

Drawn

AFA

Drawn Data

3/26/2026

--	--

PROJ: _____

Check
L.R.

LF

: Checked D
4/23/2026

4/22/2020