

**Photo 1:** Upland route looking east over the "horseback" roadway zone at the Eckrote property





Photo 2: Intertidal mud flats from the Eckrote property shore.





**Photo 4:** Example of a shoreline coffer cell and excavator on the mudflats.



**Photo 5:** Example of a spud barge with crane, clamshell suited for this work.