







**Pedestrian Ramp Report**  
**WIN 24471.00 – Farmingdale, Route 201**  
**February 12, 2020**

AERIAL	EXISTING	Notes
		<p><b>NORTHERN AVE (10+61)</b>  (2 EACH in this location)</p> <ul style="list-style-type: none"> <li>Install the DWF and regrade ramps to ADA compliance. May include resetting and/or replacing curb.</li> </ul>
		<p><b>SHELDON ST (20+64)</b>  (2 EACH in this location)</p> <ul style="list-style-type: none"> <li>Install the DWF and regrade ramps to ADA compliance. May include resetting granite curb and replacing bituminous curb.</li> </ul>

**Pedestrian Ramp Report**  
**WIN 24471.00 – Farmingdale, Route 201**  
**February 12, 2020**

		<p><b>GRANT ST (31+14)</b> (2 EACH in this location)</p> <ul style="list-style-type: none"><li>• Install the DWF and regrade ramps to ADA compliance. May include replacing bituminous curb.</li></ul>
		<p><b>BOWMAN ST (41+80)</b> (2 EACH in this location)</p> <ul style="list-style-type: none"><li>• Install the DWF and regrade ramps to ADA compliance. May include replacing bituminous curb.</li></ul>
		<p><b>HILL ST (54+24)</b> (2 EACH in this location)</p> <ul style="list-style-type: none"><li>• Install the DWF and regrade ramps to ADA compliance. May include replacing bituminous curb.</li></ul>

**Pedestrian Ramp Report**  
**WIN 24471.00 – Farmingdale, Route 201**  
**February 12, 2020**



**PARK ST (81+93)**

(2 EACH in this location)

- Install the DWF and regrade ramps to ADA compliance. May include replacing bituminous curb.